



anarumoinspection@gmail.com https://www.Anarumo.com





RESIDENTIAL INSPECTION

3360 Kallin Ave Long Beach, CA 90808

Caitlyn Cahill



Inspector

Frank Anarumo
Certified Master Inspector; NACHI14090311
(CPI); CREIA #166950; IAC2 Cert. #IAC2-03-7334; CRT # 2019121114; CCPIA-000545, Branch 2 & 3 Field Representative 65837
(Green Mantis Pest Control), NFPA Member 1113628417
3109256664

anarumoinspection@gmail.com



Agent
Blair Newman
(562) 822-6532
blair@newmanteam.com

TABLE OF CONTENTS

1: Inspection Details	8
2: InterNACHI Guarantee	9
3: General Information / Overview	10
4: Environmental Concerns	15
5: Exterior	18
6: Outdoor Living Spaces	29
7: Roof	31
8: Garage	40
9: Major Systems	46
10: Plumbing	51
11: Electrical	58
12: Kitchen	62
13: Bathroom - Downstairs	70
14: Bathroom - Master	75
15: Living Room	81
16: Dining Room	83
17: Family Room	84
18: Hall & Stairs - Upstairs	88
19: Hall - Downstairs	91
20: Bedroom - Downstairs Front	93
21: Bedroom - Downstairs Rear	95
22: Bedroom - Master	97
23: Attic	100
24: Additions	102
25: Home Maintenance	103
Standards of Practice	108

Anarumo Inspections Page 2 of 108

SUMMARY







○ 4.4.1 Environmental Concerns - Fungal Growth: A Fungal Growth Present on Surface(s)

○ 4.5.1 Environmental Concerns - Pest/Insect/Wildlife Concerns: Possible Flying Insect Nest Present

○ 4.5.2 Environmental Concerns - Pest/Insect/Wildlife Concerns: Wood Destroying Damage Present

5.2.1 Exterior - Walkways : Walkway Material - Deteriorated

5.2.2 Exterior - Walkways : Walkway Material - Expansive Cracks

5.2.3 Exterior - Walkways : Walkway Material - Minor Cracks

○ 5.2.4 Exterior - Walkways : Walkway - Trip Hazard

₱ 5.3.1 Exterior - Fence/Wall(s): Excessive Vegetation

₱ 5.3.2 Exterior - Fence/Wall(s): Fence and Wall Material - Deteriorated

○ 5.3.3 Exterior - Fence/Wall(s): Fence and Wall Material - Loose Material

₱ 5.3.4 Exterior - Fence/Wall(s): Soil to Wood Contact

₱ 5.4.1 Exterior - Gates: Gates Drag on Ground

○ 5.5.1 Exterior - Siding : Cracking

₱ 5.5.2 Exterior - Siding : Discoloration

5.5.3 Exterior - Siding : Patching Noted

○ 5.5.4 Exterior - Siding : Siding - Blistering

○ 5.6.1 Exterior - Trim: Deteriorated Wood

5.6.2 Exterior - Trim: Paint/Finish Failing

5.8.1 Exterior - Windows: Improperly Installed Glazing

₱ 5.9.1 Exterior - Window Screens: Torn Screen(s)

5.13.1 Exterior - Steps/Railings: Railing Spacing

○ 5.14.1 Exterior - Hose Bib(s): No Anti-Siphon Valve(s)

○ 5.15.1 Exterior - Foundation - (RAISED): Corrosion On Plumbing

○ 5.15.2 Exterior - Foundation - (RAISED): Deteriorated Concrete Foundation

5.15.3 Exterior - Foundation - (RAISED): Deteriorated Wood

5.15.4 Exterior - Foundation - (RAISED): Temporary Repair On Plumbing System

5.15.5 Exterior - Foundation - (RAISED): Vent Screens - Damaged

Anarumo Inspections Page 3 of 108

- 5.17.1 Exterior Grading and Drainage: Negative Grading
- 6.1.2 Outdoor Living Spaces Outdoor Living Spaces and Stairs: Electrical No GFI's
- 7.2.1 Roof Material / Type House: Damaged (General)
- 7.2.2 Roof Material / Type House: Damaged Rain Cap
- 7.2.3 Roof Material / Type House: Debris
- 7.2.5 Roof Material / Type House: Exposed Nail Heads
- 7.2.6 Roof Material / Type House: Old System
- 7.2.7 Roof Material / Type House: Patching
- 7.2.8 Roof Material / Type House: Recommend Sealing All Roof Projections
- 7.2.9 Roof Material / Type House: Two (2) Layers Of Roofing Material
- 7.2.10 Roof Material / Type House: Wires Laying on Roof
- 7.3.1 Roof Gutters / Downspouts: Recommend Gutters as Needed
- 7.4.1 Roof Flashings: Flashing Damaged
- 7.5.1 Roof Chimneys / Skylights: Chimney Cap Missing
- 7.5.2 Roof Chimneys / Skylights: Chimney Crown Damage
- 7.5.3 Roof Chimneys / Skylights: Chimney Missing Cricket
- 7.5.4 Roof Chimneys / Skylights: Chimney Should Have a 2" (Two Inch) Clearance
- 7.5.5 Roof Chimneys / Skylights: Sealant Cracked/Missing
- 8.2.1 Garage Siding : Cracking
- **№** 8.2.2 Garage Siding : Discoloration
- 8.2.3 Garage Siding : Paint/Finish Failing
- 8.3.1 Garage Trim: Paint/Finish Failing
- 8.4.1 Garage Garage Door: Panel Damage
- 8.6.1 Garage Walls: Damage Stud
- ▲ 8.12.1 Garage Firewalls: Holes in Firewall
- 8.13.1 Garage Electrical: Exposed Wires
- 8.13.2 Garage Electrical: Inoperable Outlet
- 8.13.3 Garage Electrical: Loose Light Fixture
- 8.13.4 Garage Electrical: Loose Light Switch
- 8.13.5 Garage Electrical: Missing Light Bulb
- 8.13.6 Garage Electrical: Unable to Determine Function of One Switch
- 8.18.1 Garage Comments: Crack in Stem Wall
- 9.1.1 Major Systems Heating Equipment: Gas To Unit Off
- △ 9.1.2 Major Systems Heating Equipment: Inoperable
- 9.5.1 Major Systems Chimneys and Fireplaces: C-Clamp
- 9.5.2 Major Systems Chimneys and Fireplaces: Damaged Brick Noted
- 9.5.3 Major Systems Chimneys and Fireplaces: Evidence of Improper Draft or Venting
- 4 9.5.4 Major Systems Chimneys and Fireplaces: Firebox Cracks
- 9.5.5 Major Systems Chimneys and Fireplaces: Missing Screen Or Glass Doors

Anarumo Inspections Page 4 of 108

- 9.5.6 Major Systems Chimneys and Fireplaces: Suggest Cleaning Fireplace
- O 10.1.1 Plumbing Drain, Waste, & Vent Systems: Drain Waste Vent Should Exceed Above Roof
- 10.2.1 Plumbing Main Water Shut-off Device & Water Supply Lines: Material Galvanized
- 2 10.3.1 Plumbing Water Heater, Controls, Flues & Vents: Annual Maintenance Flush Needed
- O 10.3.2 Plumbing Water Heater, Controls, Flues & Vents: Corrosion on Supply Lines
- 10.3.3 Plumbing Water Heater, Controls, Flues & Vents: No Earthquake Straps
- Θ
- 10.3.4 Plumbing Water Heater, Controls, Flues & Vents: No Electrical Disconnect For Electric Water Heater:
- O 10.3.5 Plumbing Water Heater, Controls, Flues & Vents: TPR Discharge Pipe Reduced In Size
- Θ
- 10.4.1 Plumbing Gas (Natural) Meter Information: Gas Lines (40+ Year Old Homes or Underground Lines)
- O 10.4.2 Plumbing Gas (Natural) Meter Information: Gas Pipes Not Bonded
- 10.4.3 Plumbing Gas (Natural) Meter Information: Gas Pipes Surface Rust
- 10.4.4 Plumbing Gas (Natural) Meter Information: NO Earthquake Shut Off Valve
- 11.1.1 Electrical Service Entrance Conductors: Electrical Drip Loop Is Improperly Installed
- (2) 11.1.2 Electrical Service Entrance Conductors: Electrical Mast Height Below 36"
- Θ
- 11.2.1 Electrical Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices: AFCI Breakers None
- 11.2.2 Electrical Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices: Breakers
 Appear To Be Over 30 Years Old
- 11.2.3 Electrical Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices: Doubled Up Circuitry
- (a) 11.2.4 Electrical Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices: Zinsco / GTE / Challenger / Murray / Sylvania / Stab Lok / Federal Pacific Panels / Bulldog Pushamatics
- 11.3.1 Electrical Branch Wiring Circuits: Cloth Branch Wiring Found
- 12.2.1 Kitchen Walls: Cracks Minor
- 12.2.2 Kitchen Walls: Patching Noted
- 12.3.1 Kitchen Ceilings: Cracks Minor
- 2 12.3.2 Kitchen Ceilings: Patching Noted
- 2 12.5.1 Kitchen Windows: Broken Window Lock
- 2 12.6.1 Kitchen Cabinets: Cabinets Need Adjusting
- 2 12.7.1 Kitchen Countertops: Countertop Damaged Material
- 12.8.1 Kitchen Electrical: Extension Cord Wiring
- 12.8.2 Kitchen Electrical: No GFIs
- (a) 12.8.3 Kitchen Electrical: Ungrounded Receptacles
- (a) 12.9.1 Kitchen Sink, Faucets, & Drains: Below Sink Corrosion
- (a) 12.9.2 Kitchen Sink, Faucets, & Drains: Faucet Leak at Base
- 12.10.1 Kitchen Garbage Disposal: Inoperable
- 2 12.11.1 Kitchen Dishwasher: Door Needs Adjusting
- 12.11.2 Kitchen Dishwasher: Inoperable

Anarumo Inspections Page 5 of 108

- 12.11.3 Kitchen Dishwasher: Rusted Trays
- 12.14.1 Kitchen Oven: Range Does Not Appear To Fastened
- 12.14.2 Kitchen Oven: Touch Screen is Unresponsive and Error Code
- 13.1.1 Bathroom Downstairs Floors: Flooring Damaged
- 13.2.1 Bathroom Downstairs Walls: Microbial Growth
- 13.2.2 Bathroom Downstairs Walls: Moisture Damage
- 2 13.5.1 Bathroom Downstairs Window(s): Window Does Not Open
- 13.6.1 Bathroom Downstairs Electrical: Ungrounded Receptacle
- 2 13.8.1 Bathroom Downstairs Tub: Enclosure Doors Have Been Removed
- 2 13.8.2 Bathroom Downstairs Tub: Flange Loose
- 13.8.3 Bathroom Downstairs Tub: Tub Drains Slowly
- 🖯 13.8.4 Bathroom Downstairs Tub: Water Temperature Below 100F
- 13.11.1 Bathroom Downstairs Toilet: Toilet Is To Close To The Wall and/or Sink
- 2 13.12.1 Bathroom Downstairs Counter/Cabinets: Cabinet Damaged
- 2 14.1.1 Bathroom Master Floors: High Spots Noted
- 14.2.1 Bathroom Master Walls: Cracks Minor
- 2 14.2.2 Bathroom Master Walls: Paint Flaking
- 2 14.4.1 Bathroom Master Doors: Broken Handle
- 14.9.1 Bathroom Master Shower: Tiles Cracked
- 14.10.1 Bathroom Master Sink/Faucet/Drains/Supply: Below Sink Corrosion
- 14.10.2 Bathroom Master Sink/Faucet/Drains/Supply: Sink Drains Slowly
- 14.12.1 Bathroom Master Counter/Cabinets: Handles Missing
- 2 15.1.1 Living Room Floors: High Spots Noted
- 15.1.2 Living Room Floors: Squeak Noted
- 15.2.1 Living Room Walls: Cracks Minor
- 2 15.5.1 Living Room Windows: Window Does Not Open
- 15.6.1 Living Room Electrical: Cover Plate Damaged
- 15.6.2 Living Room Electrical: Ungrounded Receptacle
- ₱ 16.1.1 Dining Room Floors: High Spots Noted
- 2 16.4.1 Dining Room Doors: Door Rubs on Jamb
- 16.6.1 Dining Room Electrical: Ungrounded Receptacle
- 2 17.1.1 Family Room Floors: High Spots Noted
- 17.2.1 Family Room Walls: Deteriorated Wood
- 17.2.2 Family Room Walls: Microbial Growth
- 2 17.3.1 Family Room Ceilings: Patching Noted
- 2 17.4.1 Family Room Doors: Door Rubs on Jamb
- 17.6.1 Family Room Electrical: Broken Outlet
- 2 17.6.2 Family Room Electrical: Cover Plate Loose
- 17.6.3 Family Room Electrical: Inoperable Outlet
- 2 18.1.1 Hall & Stairs Upstairs Floors: Squeak Noted

Anarumo Inspections Page 6 of 108

- 18.2.1 Hall & Stairs Upstairs Walls: Cracks Minor
- 18.2.2 Hall & Stairs Upstairs Walls: Microbial Growth
- 18.7.1 Hall & Stairs Upstairs Stairs and Railing: Railing Spacing Greater Than 4"
- 2 19.1.1 Hall Downstairs Floors: High Spots Noted
- 19.2.1 Hall Downstairs Walls: Paint Flaking
- 19.3.1 Hall Downstairs Ceilings: Cracks Minor
- 20.1.1 Bedroom Downstairs Front Floors: High Spots Noted
- 20.1.2 Bedroom Downstairs Front Floors: Squeak Noted
- 20.5.1 Bedroom Downstairs Front Windows: Window Does Not Open
- 20.6.1 Bedroom Downstairs Front Electrical: Cover Plate Damaged
- 21.1.1 Bedroom Downstairs Rear Floors: High Spots Noted
- 21.1.2 Bedroom Downstairs Rear Floors: Squeak Noted
- 21.5.1 Bedroom Downstairs Rear Windows: Window Inoperable Cranks
- 21.6.1 Bedroom Downstairs Rear Electrical: Cover Plate Damaged
- 22.1.1 Bedroom Master Floors: High Spots Noted
- 22.1.2 Bedroom Master Floors: Squeak Noted
- 22.2.1 Bedroom Master Walls: Cracks Minor
- 22.2.2 Bedroom Master Walls: Paint Flaking
- 22.3.1 Bedroom Master Ceilings: Water Stain(s) on Ceiling
- 22.6.1 Bedroom Master Electrical: Outlet Loose
- 🔗 22.6.2 Bedroom Master Electrical: Unable to Determine Function of One Switch
- 22.7.1 Bedroom Master Closet: Closet Door Off its Track
- 23.3.1 Attic Evidence of leakage: Possible Active Water stains in the attic
- 23.5.1 Attic Ventilation: Vent Damaged

Anarumo Inspections Page 7 of 108

1: INSPECTION DETAILS

			IN	NI	NP	0
	1.1	General	Χ			
ĺ	1.2	Utilities On/Off	Χ			

Information

General: How Many Levels General: In Attendance General: Standards of Practice

2 Client's Agent **Followed**InterNACHI

Click Here To View Our Standards

Of Practice

General: Type of Building
Single Family
General: Weather Conditions
Utilities On/Off: Utilities: All
Utilities On

All utilities were on at the time of

the inspection.

General: Clients Report

This report is for the person(s) named here in the report: Client(s) Caitlyn Cahill . Unauthorized use is prohibited with out said Client(s) Caitlyn Cahill and Anarumo Inspections Inc. permission. Liability under this report is limited to the party identified on the cover page of this report.

General: No Client Present

The client was not present at the time of inspection. As property conditions can change from the date of inspection to the date of closing, it is advised that the buyer reference this report during any final walk through.

General: Recommended Contractors & Professionals Information

It is HIGHLY recommended that licensed professionals are used for repairs, replacements, or further evaluations of defects referenced in this report, and copies of their receipts/invoices are provided to you for warranty purposes. The inspection company does not perform re-inspections of repairs as they can be invasive, limiting what I can visually see and report to you.

The term "Qualified Professional" or "Qualified Person" in this report relates to an individual, company, or contractor who is either licensed or certified in the field of concern. The term "evaluation" may be used in conjunction with repairs to be performed by contractors or other licensed professionals, as they may discover additional problems due to their repairs being invasive and they are specialists in their respective fields. This differs from the term "Full Evaluation", as a full evaluation is a recommendation for the referenced contractor/professional to fully look over all components, parts, and pieces of a component, system, or area. <u>Any listed items in this report concerning areas reserved for such experts should not be construed as a detailed, comprehensive, and/or exhaustive list of problems or areas of concern.</u>

General: Structure Orientation

For the sake of this inspection the front of the structure will be considered as the portion pictured in the above cover photo. References to the left or right of the structure should be construed as standing in the front yard, viewing the front of the structure.

Anarumo Inspections Page 8 of 108

2: INTERNACHI GUARANTEE

		IN	NI	NP	0
2.1	\$10,000 Honor Guarantee	Χ			

IN = Inspected

NI = Not Inspected

NP = Not Present

O = Observations

Information

\$10,000 Honor Guarantee: Honor Guarantee



InterNACHI is so certain of the integrity of our members that we back them up with our \$10,000 Honor Guarantee.

InterNACHI will pay up to \$10,000 USD for the cost of replacement of personal property lost during an inspection and stolen by an InterNACHI-certified member who was convicted of or pleaded guilty to any criminal charge resulting from the member's taking of the client's personal property.

For details, please visit www.nachi.org/honor.

Anarumo Inspections Page 9 of 108

3: GENERAL INFORMATION / OVERVIEW

		IN	NI	NP	0
3.1	General Information / Overview	Χ			

IN = Inspected NI = Not Inspected NP = Not Present O = Observations

Information

General Information / Overview: Disclaimers

DISCLAIMERS

<u>Asbestos:</u> The inspector, not holding an EPA license, cannot identify, report, or test for asbestos presence. Structures built before 1981 may contain asbestos materials. Responsibility for asbestos testing lies solely with the client, who must engage a licensed professional for assessment. Anarumo Inspection Services disclaims any claims related to asbestos.

Interior: Inspections of occupied/staged structures are limited. Personal belongings, furniture, and boxes are not moved, affecting the completeness of the inspection. We advise verifying permits for any modifications post-original construction. The inspector's responsibility for inspected items ends once inspected; no re-inspections are conducted. The inspector does not predict the interior conditions hidden by personal items, nor check for code violations. Central vacuum systems and interior window treatments are excluded from the inspection.

<u>Bathrooms:</u> Inspections do not include overflow drains or jet hoses of bathtubs and spa tubs; shower pan water-proofing and proper drainage pitch are not assessed. Accessibility limits inspection of exterior and interior access panels. Electrical outlets near water sources are recommended to be GFCI protected, which may not be required based on the home's age.

<u>Kitchen:</u> Appliance inspections are basic, focusing on functionality without disassembly or detailed efficiency evaluation. The inspector does not guarantee the performance of dishwashers, ovens, ranges, or microwaves. Water treatment systems are outside the inspection scope.

<u>Laundry:</u> Without a present washing machine, supply valves and vents remain untested. Washer and dryer units are excluded from inspections.

Attic: The inspector does not test or report on asbestos in attics. Limited access due to insulation or safety concerns restricts a full attic inspection. The efficiency of HVAC systems and ductwork is not determined.

<u>Garage</u>: Limited inspections are performed in garages due to storage, without moving personal items. Firewall ratings are not determined.

<u>Heating & Air Conditioning:</u> Recalls, efficiency, and internal components of HVAC systems are not evaluated. Refrigerant levels and system compatibility are not inspected.

<u>Water Heater:</u> Only a visual inspection is conducted; internal mechanisms and the condition of burners are not evaluated.

<u>Roof:</u> The inspector cannot predict leaks or assess the roof life expectancy. Inspections are limited for inaccessible roofs.

Electrical/Gas: Electrical panels are visually inspected without load calculation. GFCI functionality is tested where accessible; gas leaks and carbon monoxide detection are outside the inspection scope.

<u>Exterior Areas:</u> Inspections do not guarantee the exterior's water tightness; maintenance is recommended for stucco and siding. Boundary lines and encroachments are not evaluated.

Grounds: No guarantee on water tightness for patio roofs or balconies. Fences and gates are not evaluated for security purposes.

Foundation: Limited inspection scope for slab foundations; leaks and under-slab conditions are not assessed.

<u>Pool:</u> Basic inspection excludes detailed evaluation of equipment life expectancy and leaks. Safety compliance is the buyer's responsibility.

<u>Plumbing:</u> Visual inspections do not cover functionality or leaks; existing plumbing materials may require further evaluation.

This detailed approach maintains the specificity of each disclaimer while ensuring clarity on the inspection's scope and limitations.

Anarumo Inspections Page 10 of 108

General Information / Overview: How To Understand Your Inspection

Introduction:

A home inspection is a non-invasive, visual examination of the accessible areas of the property, designed to identify areas of concern within specific systems or components defined by the signed agreements and InterNACHI Standards of Practice, that are both observed and deemed material by the inspector at the exact date and time of inspection. Any and all recommendations for repair, replacement, evaluation, and maintenance issues found should be evaluated by the appropriate trades contractors within the client's inspection contingency window or prior to closing, which is contract applicable, in order to obtain proper dollar amount estimates on the cost of said repairs. Specialized evaluations by the appropriate trades contractors may reveal additional issues that are not able to be identified from a purely visual inspection of the property.

This inspection will not reveal every concern or issue that exists, but only those material defects that were observable on the day of the inspection. Cosmetic deficiencies in the home will not be noted unless they affect the functionality of the home, are indicative of a larger problem, or are so severe that they may affect the value of the home. This inspection is intended to assist in an evaluation of the overall condition of the dwelling only. A home inspection is not a code inspection. We recommend that you check with your local building department for any closed, voided, failed, or non-permitted work prior to closing on the home. This inspection report is not a prediction of future conditions and property conditions are subject to change at any time.

This inspection does not include the evaluation of additional structures unless you notified us and purchased inspections of additional structures, whether they include living spaces or not. This inspection also does not include specialized evaluations of private water supply equipment (well pumps, flow tests, etc), private septic equipment (drain fields, tanks, alarms, etc), sprinkler/irrigation systems, solar energy equipment, hot tubs, pools, generators, or other systems not covered under the Standards of Practice as established by the International Association of Certified Home Inspectors. Additionally, a home inspection does not include a pest inspection. You are encouraged to seek these evaluations by the relevant professionals prior to the conclusion of your inspection response period.

IMPORTANT: How To Read and Use Your Report

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this home. Any findings / comments that are listed under "Health and Safety / Major" by the inspector suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

Inspected (IN) = The item, component or system was visually inspected and if no other comments were made, then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI) = The item, component or system was not inspected and no representations made of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = The item, component or system is not in this home or building.

Findings = The item, component or system was inspected and a concern, observation and/or deficiency was found and falls under one of the categories below.

Note = The item or discovery indicated is considered cosmetic, nuisance or is "For Your Information". The items, although should be repaired, are not considered to be in need of immediate repair. Any items or recommendations in this category should not be considered as an enforceable repair or responsibility of the sellers, but designed only to provide you with specific information about the property.

Minor = The item, component, or system while perhaps functioning as intended is in need of minor repair, service, or maintenance; is showing signs of wear or deterioration that could result in an adverse condition at some point in the future; or considerations should be made in upgrading the item, component, or system to enhance the function, efficiency and / or safety. Items falling into this category can frequently be addressed by a homeowner or handyman and are considered to be routine homeowner maintenance (DIY) or recommended upgrades.

Moderate = The item, component, or system while perhaps functioning as intended is in need of moderate repair, service; is showing signs of wear or deterioration that could result in an adverse condition at some point in the future; or considerations should be made in upgrading the item, component, or system to enhance the function, efficiency and / or safety. Items falling into this category can frequently be addressed by a handyman or a qualified contractor and are not considered routine maintenance or DIY items.

Health and Safety / Major = The item, component or system poses a safety concern to occupants in or around the home. Some listed concerns will be considered acceptable for the time period of construction but pose a current risk.

Anarumo Inspections Page 11 of 108

These items listed in **BLUE**, **ORANGE**, or **RED** in the report should have a qualified professional provide you a cost to repair, replace, fix, or be maintained prior to release of your contingency period so you (Caitlyn Cahill) know the true cost of action.

The item, component, or system is Not functioning as intended, or needs further evaluation by a specialized qualified licensed contractor or can cause damage to the structure. Items, components or units that can be repaired to satisfactory condition may not need replacement.

PHOTOS - Can represent one or more areas. As the comment may detail a specific area or areas. Photos are in the report to provide a visual aid not a definite . They are used to help see what the inspector sees. If report says one or more areas make sure that whom ever may be doing repairs or the work checks to make sure what needs to be corrected or done. They person or company making the corrections may also find underlying issues that were not present at the time of the inspection.

Note: California has seasonable rains which occur at the end and the beginning of each calendar year. Occasionally, the rainfall is exceptionally high. This is called an El Nino year. In recent years Southern California has been going through a drought. During drought periods many conditions visible following rains do not appear. The duty of a home inspector is to disclose visible conditions. If a condition is not visible it cannot be reported.

Note: Read the Standards of Practice set forth by the InterNational Association of Certified Home Inspectors for an insight into the scope of the inspection.

Standards Of Practice

Note: The inspection represents the condition of the visually inspected areas of the property on the date of the inspection. Component conditions may change between the date of the inspection and the title transfer date. A thorough walk-through prior to title transfer helps protect against unexpected surprises, and is recommended. The purchase of a home warranty is recommended.

Notice to Third Parties: This report is copyright protected. This report is the exclusive property of Anarumo Inspections and the Client(s) Caitlyn Cahill and is not transferable to any third parties or subsequent buyers. Our Inspection Company will gladly answer any questions on the report for a 3rd party with written permission from Caitlyn Cahill. Our Inspection and this report have been performed with a written contract agreement that limits its scope and usefulness. Unauthorized recipients are therefore advised not to rely upon this report, but rather to retain the services of an appropriately qualified property inspector of their choice to provide them with their own inspection and report. Liability under this report is limited to the party identified as Caitlyn Cahill and no warranty or guarantee will be provide to anyone other than our client.

Note: For the purpose of this report, all directional references (left, right, rear, front) are based on when facing the front of the structure as depicted in the cover image above.

Note: The client is advised that a mold inspection / testing be performed by a qualified specialist if any evidence of past or current water leaks (plumbing, roof, intrusion or otherwise) are reported by the inspector.

ENVIRONMENTAL CONDITIONS: Client agrees what is being contracted for is a building inspection and not an environmental evaluation. The inspection is not intended to detect, identify, or disclose any health or environmental conditions regarding this building or property, including, but not limited to: the presence of asbestos, radon, lead, urea-formaldehyde, fungi, molds, mildew, feces, urine, vermin or pests, PCBs, "Chinese drywall" or other toxic, reactive, combustible, or corrosive contaminants, materials, or substances in the water, air, soil, or building materials. The Inspector is not liable for injury, health risks, or damage caused or contributed to by these conditions. If concerned with any of these conditions a professional in that field should be hired prior to the end of your contingency period for further examination.

TYPOGRAPHICAL ERRORS: This report is proofread before sending it out, but typographical errors may be present. If any errors are noticed, please feel free to contact me for clarification.

Please acknowledge to me once you have completed reading this report. At that time I will be happy to answer any questions you may have, or provide clarification. Non-acknowledgement implies that you understood all information contained in this report.

Anarumo Inspections Page 12 of 108

INACCESSIBLE AREAS: In the report, there may be specific references to areas and items that were inaccessible or only partly accessible. I can make no representations regarding conditions that may be present in these areas that were concealed or inaccessible for review. With access and an opportunity for inspection, reportable conditions or hidden damage may be found in these areas.

QUALITATIVE vs QUANTITATIVE: A home inspection is not quantitative, when multiple or similar parts of a system, item, or component are found to have a deficiency, the deficiency will be noted in a qualitative manner such as "multiple present" etc. A quantitative number of deficient parts, pieces, or items will not be given as the repairing contractor will need to evaluate and ascertain the full amount or extent of the deficiency or damage. This is not a technically exhaustive inspection.

REPAIRS VERSUS UPGRADES: I inspect homes to today's safety and building standards. Therefore some recommendations made in this report may have not been required when the home was constructed. Building standards change and are improved for the safety and benefit of the occupants of the home and any repairs and/or upgrades mentioned should be considered for safety, performance, and the longevity of the homes items and components. Although, I will address some recommended upgrades in the report, this should not be construed as a full listing of items that could potentially be upgraded. To learn of ALL the ways the home could be brought up to today's building and safety standards, full and exhaustive evaluations should be conducted by qualified tradespeople.

CONTRACTORS / FURTHER EVALUATION: It is recommended that licensed professionals be used for repair issues as it relates to the comments in this report, and copies of receipts are kept for warranty purposes. The use of the term "Qualified Person" in this report relates to an individual, company, or contractor whom is either licensed or certified in the field of concern. If I recommend evaluation or repairs by contractors or other licensed professionals, it is possible that they will discover additional problems since they will be invasive with their evaluation and repairs. Any listed items in this report concerning areas reserved for such experts should not be construed as a detailed, comprehensive, and/or exhaustive list of problems, or areas of concern.

CAUSES of DAMAGE / METHODS OF REPAIR: Any suggested causes of damage or defects, and methods of repair mentioned in this report are considered a professional courtesy to assist you in better understanding the condition of the home, and in my opinion only from the standpoint of a visual inspection, and should not be wholly relied upon. Contractors or other licensed professionals will have the final determination on the causes of damage/deficiencies, and the best methods of repairs, due to being invasive with their evaluation. Their evaluation will supersede the information found in this report.

A home inspection is a non invasive, visual examination of the accessible areas of the property, designed to identify areas of concern within specific systems or components defined by the InterNACHI Standards of Practice, that are both observed and deemed material by the inspector at the exact date and time of inspection. Any and all recommendations for repair, replacement, evaluation, and maintenance issues found, should be evaluated by the appropriate trades contractors within the clients inspection contingency window or prior to closing, which is contract applicable, in order to obtain proper dollar amount estimates on the cost of said repairs and also because these evaluations could uncover more potential issues than able to be noted from a purely visual inspection of the property. This inspection will not reveal every concern or issue that exists, but only those material defects that were observable on the day of the inspection. This inspection is intended to assist in evaluation of the overall condition of the dwelling only. This inspection is not a prediction of future conditions and conditions with the property are subject to change the moment we leave the premises.

Note on Thermal Imaging: A Thermal Imaging camera may be used as a means of evaluating certain suspect issues or systems. Any anomalies found are always verified by other means such as a moisture meter. Moisture must be present for infrared thermography to locate its existence. During dry times a leak may still be present but undetectable if materials have no moisture present. Thermal Imaging is not X-ray vision, cannot see through walls and cannot detect mold. An infrared camera may be used for specific areas or visual problems, and should not be viewed as a full thermal scan of the entire home. Additional services are available at additional costs and would be supplemented by an additional agreement/addendum. Temperature readings displayed on thermal images in this report are included as a courtesy and should not be wholly relied upon as a home inspection is qualitative, not quantitative. These values can vary +/- 4% or more of displayed readings, and these values will display surface temperatures when air temperature readings would actually need to be conducted on some items which is beyond the scope of a home inspection. If a full thermal scan of the home is desired, please reach out to me schedule this service.

Anarumo Inspections Page 13 of 108

General Information / Overview: Items Not Inspected and Other Limitations

EXCLUDED - ITEMS NOT INSPECTED: There are items that are not inspected in a home inspection such as, but not limited to; fences and gates, pools and spas, outbuildings or any other detached structure, refrigerators, generators, washers / dryers, storm doors and storm windows, screens, window AC units, Satellite TV or Cable TV, surface drains, solar systems, low voltage lighting systems (interior and/or exterior), interior fire sprinklers, audio system, CCTV, salt water pool / spa systems, security bars, electronic air cleaner at the furnace, fire pit, tool shed(s), telephone jacks, fountain(s), exterior barbecue, swing sets, boat docks or any type of dock / slip, kennel(s), children's play house, shutters/blinds, awnings, sump pump(s), condensation pump(s), Electronic Water Fill System(s), security system(s), electronic gate(s), Elevator(s), circulating pump on water heater(s), sauna / steamer(s), wall / floor safe(s), Instantaneous hot water, humidifier, above ground pool, chair lift on stairs, septic system, chicken coop, swamp cooler(s), heat sensors, koi pond(s), well system, basketball court, putting green, tree house, tennis court, kegerator, air purifier, trampoline, electric pool cover, playground equipment, gas furnace heat exchangers, central vacuum systems, water softeners and water purifiers, alarms, and intercom systems, Farm Buildings, Livestock Stables and areas, HVAC Systems for leakage, HVAC Zone Systems and any item that is not a permanent attached component of the home or part of our standard inspection. Also drop ceiling tiles are not removed, as they are easily damaged, and this is a noninvasive inspection. Subterranean systems are also excluded, such as but not limited to: sewer lines, septic tanks, water delivery systems, and underground fuel storage tanks.

Water and gas shut off valves are not operated under any circumstances. As well, any component or appliance that is unplugged or "shut off" is not turned on or connected for the sake of evaluation. I don't have knowledge of why a component may be shut down, and can't be liable for damages that may result from activating said components/appliances.

Also not reported on are the causes of the need for a repair; The methods, materials, and costs of corrections; Recalled appliances, items, and/or components; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; The insurability of the structure or any of its items or components; Any component or system that was not observed; Calculate the strength, adequacy, design, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility. Also excluded is the proper installation of Stucco and EIFS and the repercussions of improper installation including water damage to the structure.

Lastly a home inspection does not address environmental concerns such as, but not limited to: Asbestos, lead, lead based paint, radon, mold, wood destroying insects or organisms (termites, etc), cockroaches, rodents, pesticides, fungus, treated lumber, Chinese drywall, mercury, or carbon monoxide.

General Information / Overview: Systems Get Older And May Need Budgeting To Replace

During the inspection some systems could of appeared to be older and/or at the end of its service life. Reliability of one or more systems may possible. Ask the homeowner or occupant about any recent performance. Regular maintenance and monitoring of the homes systems and components condition is recommended. Budgeting for repairs and future replacement is always recommended. InterNACHI's Standard Estimate Life Expectancy Chart for Homes

Anarumo Inspections Page 14 of 108

4: ENVIRONMENTAL CONCERNS

		IN	NI	NP	0
4.1	Odors Present	Χ			
4.2	Asbestos	Χ			
4.3	Lead Based Paint	Χ			
4.4	Fungal Growth	Χ			Χ
4.5	Pest/Insect/Wildlife Concerns	Χ			Χ
4.6	Rodent/Vermin Concerns	Χ			

Information

Odors Present: Odor(s) Present in Fungal Growth: Fungal Growth

Yes

the Home Presence

Odors Present: Odors Information

No Discernible Odors

If any odors are noticed in the home I will include them in this section with recommendations made as needed. If no additional information is included in this report in respect to odors, then no discernible odors were present or noticed in the home at the time of inspection. However since odors are not part of the inspection this is a courtesy and because of recent events like COVID-19 and other health related issues that inspectors are subject to, there may be the possibility that no odor is detected at the time of the inspection. If you smell any odor during anytime at this property we would recommend you hire someone who specializes in seeking out odors and let you know a cost of remediation.

Asbestos: Asbestos Information

The possibility exists that homes built prior to 1981 may contain building components or items (textured ceiling material, adhesives, tile, tapes, insulation, etc) that contain asbestos and your home was built circa 1954 per online sources. In accordance with the Standards of practice these items are not reported on during a home inspection. If we see obvious signs of a material that we may believe to contain asbestos, we will recommend further evaluation as a courtesy, but these individual references should not be construed as an all-inclusive list. Furthermore, any remodeling or repairs that may take place in the future may reveal asbestos or other environmental hazards that were not visible at the time of inspection. If asbestos is a concern, you are advised to have a full environmental inspection by an environmental contractor prior to the end of your inspection contingency period.

More information can be found at this link: https://www.epa.gov/asbestos/protect-your-family-exposures-asbestos

Lead Based Paint: Lead Based Paint Information

The possibility exists that homes built prior to 1978 may contain paint that was lead based and your home was built circa 1954 per online sources. In accordance with the Standards of practice lead based paint is not reported on, or tested for during a home inspection. If lead based paint is a concern, you are advised to consult an environmental company prior to the end of your inspection contingency period and have additional inspections specializing in environmental hazards.

Fungal Growth: Client(s) Declined Mold Testing

FYI - The client(s) were notified as to the presence of fungal growth and/or a musty smell at the property and **declined** surface sampling and/or indoor air quality testing. The client(s) are solely responsible for any required remediation and/or resulting damages, including, but not limited to, any effects on health, due to mold at the property.

The client(s) release, indemnify, hold harmless and forever discharge Professional Home Inspections from any and all claims, liabilities, or causes of action of any kind that the client(s) may now have or at any time in the future may have resulting from the presence of mold at the Property.

Anarumo Inspections Page 15 of 108

Fungal Growth: Fungal Growth and Mold Information

EXCL - In accordance with the Standards of practice reporting on the presence of mold is excluded from a home inspection. **If I see obvious signs of fungal growth, I will recommend further evaluation and testing as a courtesy, but these individual references should not be construed as an all-inclusive listing of areas of fungal growth present**. Furthermore, the removal of personal belongings or any remodeling or repairs that may take place in the future may reveal fungal growth or mold that was not visible at the time of inspection. **If mold is a concern, you are advised to have a mold inspection and indoor air quality testing conducted by a certified mold inspector or industrial hygienist prior to the end of your inspection contingency period.**

Fungal Growth: Fungal Growth Present at Home

FYI - There were visible area(s) of fungal growth and/or related pathogenic organisms found at the home. Any referenced area(s) of fungal growth should not be viewed as an all-inclusive listing of areas containing fungal growth, as fungal growth could be present at areas that were not visible. Once spores from fungal growth are present in the home, they can collect at other "damp" locations and grow. **You are advised to have a mold inspection of the structure by a certified mold inspector or industrial hygienist prior to the end of your inspection contingency period.**

Pest/Insect/Wildlife Concerns: WDO-Termite Inspection Recommended

EXCLUDED - Inspecting for, and reporting on the presence of WDI activity (wood destroying organisms) including but not limited to; termites, powder post beetles, carpenter ants, carpenter bees, etc. is beyond the scope of a home inspection, is excluded by the Standards of Practice, and is excluded from this inspection. **It is highly recommended** that you have a WDI-Termite inspection prior to the end of your inspection contingency period. Any comments made in this report in regards to any such activity was done as a courtesy only, should not be viewed as an all-inclusive listing of activity, and requires further evaluation by a licensed pest control company.

Observations

4.4.1 Fungal Growth



A FUNGAL GROWTH PRESENT ON SURFACE(S)

There was fungal growth present on the referenced surface(s) or present in the referenced area(s).

- 1. Evaluation and repairs to the source of the moisture allowing the formation of the growth is recommended to be conducted by a qualified contractor.
- 2. Collecting samples of the growth and sending the samples to an accredited laboratory is recommended to be conducted by a mold inspector. If the testing results of the fungal growth are determined to be mold, evaluation and remediation are recommended to be conducted by an environmental contractor.

4.5.1 Pest/Insect/Wildlife Concerns



POSSIBLE FLYING INSECT NEST PRESENT

A presumed flying insect nest was present. Evaluation and removal as needed is recommended by a pest control company or other qualified person.



Anarumo Inspections Page 16 of 108

4.5.2 Pest/Insect/Wildlife Concerns



WOOD DESTROYING DAMAGE PRESENT

Presumed wood destroying damage was present at one or more areas. An evaluation of the activity is recommended to be conducted by a Termite company.



Anarumo Inspections Page 17 of 108

5: EXTERIOR

		IN	NI	NP	0
5.1	Driveways	Χ			
5.2	Walkways	Χ			Χ
5.3	Fence/Wall(s)	Χ			Χ
5.4	Gates	Χ			Χ
5.5	Siding	Χ			Χ
5.6	Trim	Χ			Χ
5.7	Exterior Doors	Χ			
5.8	Windows	Χ			Χ
5.9	Window Screens	Χ			Χ
5.10	Sprinklers			Χ	
5.11	Exterior Electrical	Χ			
5.12	Doorbell	Χ			
5.13	Steps/Railings	Χ			Χ
5.14	Hose Bib(s)	Χ			Χ
5.15	Foundation - (RAISED)	Χ			Χ
5.16	Foundation - (SLAB)			Χ	
5.17	Grading and Drainage	Χ			Χ
5.18	Exterior Comments	Χ			

IN = Inspected NI = Not Inspected NP = Not Present O = Observations

Block, Wood

Information

Driveways: Driveway Material Walkways: Walkway Material Fence/Wall(s): Material

Concrete Concrete

Gates: Material **Siding:** Siding Material Trim: Material

booW Stucco **Wood**

Windows: Windows Doorbell: Doorbell **Hose Bib(s):** Hose Bib(s)

Metal Yes Yes

Foundation - (RAISED): Access Foundation - (RAISED): Bolted to Foundation - (RAISED): Crippled

Location **Foundation**

Accessible, Rear, Right side Yes;, In Garage Recommend bracing as an upgrade

Foundation - (RAISED): Material Foundation - (RAISED): Plumbing Foundation - (RAISED):


Raised, Concrete, Pier and Post **Leak in Crawl Space** Ventilation No Adequate

Anarumo Inspections Page 18 of 108

Grading and Drainage: Grade at

Foundation

Grade at foundation needs attention



Grading and Drainage: Lot

Flat lot

Walkways: Addition

The walks appear to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Fence/Wall(s): Addition

This area appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Windows: Addition

This area appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Doorbell: Doorbells


Doorbells are sometimes operating through specialty systems like Wi-Fi. These are also utilizing a battery or a power source that is low-voltage and is not with in the realm of the home inspection. Doorbells have several components that have a tendency to stop working and may need a specialist to repair or replace.

Anarumo Inspections Page 19 of 108

Foundation - (RAISED): Crawl Space Limitations


There are many things that can be obscured by under-floor insulation and are excluded from this inspection (Examples: Such things as, but not limited too: joists, beams, piping, wiring and/or ducting).

It is not with in the realm of the inspection to have the inspector determine if columns, beams, joists, support posts, studs, trusses, are of the proper dimensions, span, and\or the proper spacing. The inspector does not guarantee or warrant that water will not accumulate in the crawl space in the future. Gutters can help prevent this. There are several areas in our territory that have higher than normal water tables. These homes may need sump pumps, fans, and/or other means to keep the crawl as dry as possible. This is not part of our inspection as it is not always visible. Our inspectors will attempt to find and locate all crawl access points and areas, however we may not be able to find all access due to floor coverings, personal belongings, and other things. In such cases, the client should ask the property owner where all access points are that are not described in this inspection, and have those areas inspected. The crawlspace should be checked periodically for several things like plumbing leaks, water intrusion, pests, termites, and other problems.



Foundation - (RAISED): Raised Foundation Ventilation Diagram

This is todays standards. You may have a home with vent spread further apart because of the construction methods of the time.



© Code Check 2020

Grading and Drainage: Expansive Soil

Expansive soil conditions are common in this area. As geological evaluations are beyond the scope of this report, client is advised to consult with an appropriate specialist if concerned by either the conditions listed in this report or those which you have observed.

Observations

Anarumo Inspections Page 20 of 108

5.2.1 Walkways

WALKWAY MATERIAL - DETERIORATED



Walkways show signs of deterioration in one or more areas.




5.2.2 Walkways

WALKWAY MATERIAL - EXPANSIVE CRACKS

Expansive cracks observed.







5.2.3 Walkways

WALKWAY MATERIAL - MINOR CRACKS

Minor cracks observed.





Anarumo Inspections Page 21 of 108

5.2.4 Walkways

WALKWAY - TRIP HAZARD



Trip hazards observed; due to uneven walks. Patch or repair recommended.



5.3.1 Fence/Wall(s)

EXCESSIVE VEGETATION



Excessive vegetation noted. Unable to fully evaluate. Recommend further evaluation.





5.3.2 Fence/Wall(s)

FENCE AND WALL MATERIAL - DETERIORATED






Anarumo Inspections Page 22 of 108

5.3.3 Fence/Wall(s)



FENCE AND WALL MATERIAL - LOOSE MATERIAL

Loose materials at wall found at one or more areas. Recommend correcting



5.3.4 Fence/Wall(s)

SOIL TO WOOD CONTACT



Soil to wood contact at various areas, which may allow wood to become susceptible to dry rot and/or termites.



5.4.1 Gates

GATES DRAG ON GROUND

1 or more gates drag on ground. Gates need adjusting



5.5.1 Siding

CRACKING



Cracking was observed at one or more points on the exterior. This is common in settling of a home. Recommend sealing cracks to prevent any water intrusion.

Anarumo Inspections Page 23 of 108






5.5.2 Siding

DISCOLORATION



There are signs of discoloration, algae, and/or mildew on the siding. This is a cosmetic issue and is not uncommon especially on shaded portions of the home. Recommend that said areas be washed or cleaned or a regular basis.



5.5.3 Siding

PATCHING NOTED



Evidence of patching noted. We are unable to determine the effectiveness of this repair.



5.5.4 Siding

SIDING - BLISTERING



Siding is flaking and/or blistering at one or more areas around home, this could be caused by water. Repairs maybe needed.

Anarumo Inspections Page 24 of 108



5.6.1 Trim

DETERIORATED WOOD



One or more sections of the trim are deteriorated. Recommend a Termite Company evaluate the whole home.



5.6.2 Trim

PAINT/FINISH FAILING



The paint or finish is failing. This can lead to deterioration and rot of the material. Recommend that the areas be properly prepared and painted / finished.

Anarumo Inspections Page 25 of 108






5.8.1 Windows IMPROPERLY INSTALLED GLAZING





5.9.1 Window Screens








5.13.1 Steps/Railings **RAILING SPACING**



Anarumo Inspections Page 26 of 108



Suggest closing all balusters to within 4 inches of each other, for safety.





5.14.1 Hose Bib(s)

NO ANTI-SIPHON VALVE(S)



One or more hose bibs may not have anti-siphon valves. Recommend adding anti-siphon valves to all hose bibs as needed as an upgrade.



5.15.1 Foundation - (RAISED)

CORROSION ON PLUMBING



Corrosion on plumbing lines and drain lines. No leak at time of inspection. This can decrease life expectancy.

5.15.2 Foundation - (RAISED)

DETERIORATED CONCRETE FOUNDATION



Deteriorated concrete noted at one or more areas of the foundation.

5.15.3 Foundation - (RAISED)

DETERIORATED WOOD



One or more sections under the home are deteriorated. Recommend a Termite Company evaluate the whole home.

Anarumo Inspections Page 27 of 108

5.15.4 Foundation - (RAISED)



TEMPORARY REPAIR ON PLUMBING SYSTEM

One or more temporary repairs noted on plumbing lines underneath house. No signs of leak at time of inspection.

5.15.5 Foundation - (RAISED)

Recommendation / Evaluation

VENT SCREENS - DAMAGED

1 or more vent screens are torn, damaged, and/or missing. Recommend correcting.



5.17.1 Grading and Drainage

Recommendation / Evaluation

NEGATIVE GRADING

Grading is sloping towards the home in some areas. This could lead to water intrusion and foundation issues. Recommend qualified landscaper or foundation contractor regrade so water flows away from home.

Here is a helpful article discussing negative grading.



Anarumo Inspections Page 28 of 108

6: OUTDOOR LIVING SPACES

		IN	NI	NP	0
6.1	Outdoor Living Spaces and Stairs	Χ			Χ

IN = Inspected

NI = Not Inspected

NP = Not Present

O = Observations

Information

Outdoor Living Spaces and Stairs: Outdoor Living Spaces and Stairs: Outdoor Living Spaces and Stairs:

Cover Decking Material Enclosure/Railing

Metal, Wood Concrete No

Outdoor Living Spaces and Stairs: Outdoor Living Spaces and Stairs: Outdoor Living Spaces and Stairs:

LocationTypeWindowsRearPatioNo

Outdoor Living Spaces and Stairs: Addition

This area appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Observations

6.1.1 Outdoor Living Spaces and Stairs

DECK - MINOR CRACKS

Cracking was observed at one or more points. This is common in settling of a home.





6.1.2 Outdoor Living Spaces and Stairs




ELECTRICAL - NO GFI'S

There is no ground fault interrupter in this area which may not have been standard at the time of construction. However, todays standards require ground fault interrupters at all areas within five feet of running water and external outlets. We suggest installing a ground fault interrupter in this area as a safety upgrade.

Anarumo Inspections Page 29 of 108

A GFCI receptacle can provide protection for other receptacles downstream on the circuit. GFCI protection can be provided by GFCI breakers, blank face devices, or GFCI receptacles





Anarumo Inspections Page 30 of 108

7: ROOF

		IN	NI	NP	0
7.1	Method	Χ			
7.2	Material / Type - House	Χ			Χ
7.3	Gutters / Downspouts	Χ			Χ
7.4	Flashings	Χ			Χ
7.5	Chimneys / Skylights	Χ			Χ

IN = Inspected NI = Not Inspected NP = Not Present O = Observations

Information

Method: Inspection Method

Walked Roof

Material / Type - House: Material Gutters / Downspouts: Gutters & Slope No

Slope: Pitched, Material: Composition Shingle

Method: Roof Limitations

Our inspections exclude areas not traversable or clearly visible due to restricted access. Items such as solar roofing components, debris, and roof coatings may limit our evaluation. Any observations regarding these systems are provided as a courtesy. We do not offer estimates on the remaining life of the roofing system or its materials, nor can we guarantee a leak-free roof, especially given the infrequent rainfall in our area. While we can spot potential old leaks through water stains on ceilings and attic spaces, we cannot confirm their current activity or whether they have been repaired. For precise identification of leak sources or stains, we strongly recommend consulting a roofer before releasing contingencies. Regular maintenance is crucial to prevent leaks; we advise having a roofer assess the roofing system every 2 to 5 years.

We cannot ascertain if the roof, skylights, or penetrations have leaked previously. Only active leaks, indicated by visible water or moisture during the inspection, can be detected. Past leaks are noted if observed. Anarumo Inspection Services does not warrant that the roof will remain leak-free.

Full access to roofs and attics may be impeded by factors such as steepness, debris, and obstructions. For older roofs, a professional evaluation by companies like Anarumo Inspections or a roofing contractor every 2 to 5 years is recommended for maintenance and repair.


The inspector cannot determine the functionality or leak status of gutters, downspouts, and extensions without significant rainfall during the inspection. Regular maintenance of the gutter system may be required. The inspector is unable to assess if a roof leaks under any conditions, as no water or hose testing is conducted. The condition of the roof underlayment is beyond the scope of this inspection. Concerns about roof leaks or the remaining roof lifespan should be addressed by a licensed roofer through further inspection. This applies to all inspected roof areas, including garages.

Material / Type - House: Addition


This area appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Anarumo Inspections Page 31 of 108

Material / Type - House: Visual Condition Documentation (Photos)



Anarumo Inspections Page 32 of 108



Chimneys / Skylights: Addition

This area appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Observations


7.2.1 Material / Type - House

DAMAGED (GENERAL)



Roof shows normal wear for its age and type. We recommend repairs be made in the few areas where roofing materials are damaged or missing. Recommend a qualified roofing professional evaluate and repair.

Anarumo Inspections Page 33 of 108



7.2.2 Material / Type - House **DAMAGED RAIN CAP**



Rain cap is damaged. Recommend replacing to prevent water intrusion and damage.




7.2.3 Material / Type - House

DEBRIS



Suggest clearing all debris from roof. Debris left on roof may retain moisture and cause that section of roof to age prematurely.



Anarumo Inspections Page 34 of 108

7.2.4 Material / Type - House



DISCOLORATION

Roofing is discolored, which can be caused by moisture, rust, or soot. Recommend a qualified roofing contractor evaluate and remedy with a roof cleaning or repair.

Here is a helpful article on common roof stains.




7.2.5 Material / Type - House

EXPOSED NAIL HEADS



Observed one or more exposed / under-driven nails/fasteners. Suggest sealing exposed nail heads. Recommend a qualified roofing contractor evaluate and repair.



7.2.6 Material / Type - House

OLD SYSTEM



I observed during my inspection that the system appeared to be old and at the end of its service life. It may not be reliable. Ask the homeowner or occupant about its recent performance. Regular maintenance and monitoring of its condition is recommended. Budgeting for repairs and future replacement is recommended. InterNACHI's Standard Estimate Life Expectancy Chart for Homes

7.2.7 Material / Type - House

PATCHING



Evidence of patching noted. We are unable to determine the effectiveness of this repair.

Anarumo Inspections Page 35 of 108







7.2.8 Material / Type - House

Recommendation / Fyaluation

RECOMMEND SEALING ALL ROOF PROJECTIONS

We advise resealing all through roof vents and projections as part of routine maintenance.





7.2.9 Material / Type - House

TWO (2) LAYERS OF ROOFING MATERIAL



There appeared to be multiple layers of composition roofing or composition roofing over wood shingle / shake roofing on this structure. This is not an allowed building practice. The roof structure may be overloaded as a result. Consult with a qualified contractor..


7.2.10 Material / Type - House


WIRES LAYING ON ROOF



Wires laying on the roof Are damaging roof. Recommend raising to proper height or removing wires.

Anarumo Inspections Page 36 of 108





7.3.1 Gutters / Downspouts

RECOMMEND GUTTERS AS NEEDED



Suggest adding a gutter and downspout system to divert water away from the homes foundation as needed and reduce or prevent water intrusion.

230.9A

7.4.1 Flashings

FLASHING - DAMAGED


Recommend corrections as needed.



7.5.1 Chimneys / Skylights

CHIMNEY CAP - MISSING

No spark arrester installed at chimney. We suggest installing a spark arrester as a fire safety upgrade. This is also important to protect from moisture intrusion and protect the chimney. Recommend a qualified roofer or chimney expert install.



Anarumo Inspections Page 37 of 108

7.5.2 Chimneys / Skylights



Recommendation / Evaluation

CHIMNEY CROWN - DAMAGE

Damage noted in chimney crown. Recommend repairing as needed.



7.5.3 Chimneys / Skylights

Recommendation / Evaluation

CHIMNEY - MISSING CRICKET

A chimney "cricket" or "saddle" was not present. A cricket (water diverter) is recommended on chimneys over 30 inches wide, to prevent water and debris from settling behind the chimney, possibly damaging sheathing / framing in the area. The installation of a cricket is recommended to be performed by a roofing contractor or other qualified contractor.



7.5.4 Chimneys / Skylights

CHIMNEY SHOULD HAVE A 2" (TWO INCH) CLEARANCE



Recommendation / Evaluation

Anarumo Inspections Page 38 of 108

Suggest implementing a two inch clearance around flue pipe or chimney of any combustible materials as a safety upgrade.



7.5.5 Chimneys / Skylights



Recommendation / Evaluation

SEALANT - CRACKED/MISSING

Sealant was cracked or missing in one or more areas. Recommend repairs as needed by a qualified professional.



Anarumo Inspections Page 39 of 108

8: GARAGE

		IN	NI	NP	0
8.1	General	Χ			
8.2	Siding	Χ			Χ
8.3	Trim	Χ			Χ
8.4	Garage Door	Χ			Χ
8.5	Garage Door Opener	Χ			
8.6	Walls	Χ			Χ
8.7	Ceiling	Χ			
8.8	Slab	Χ			
8.9	Window(s)	Χ			
8.10	Access Door	Χ			
8.11	Fire Door			Χ	
8.12	Firewalls	Χ			Χ
8.13	Electrical	Χ			Χ
8.14	Vent Screen(s)			Χ	
8.15	Laundry Tub			Χ	
8.16	Washer Hook up			Χ	
8.17	Dryer Hook Up			Χ	
8.18	Comments	Х			Χ

Information

General: Garage is: Siding : Siding Material Trim: Material

Attached To Home Stucco Wood

Garage Door: Material Garage Door Opener: No Firewalls: Plaster

Metal, Non-insulated

Automatic Door Opener Noted

Carago vehicle door is manually

Garage vehicle door is manuallyoperated.

General: Storage

storage area(s) appear(s) to be an addition. Unable to determine if permitted; we suggest consulting with the local municipality for further review.

Garage Door: Garage Door Information

Regular maintenance of garage doors, including their hardware and springs, is essential. It's recommended to periodically ensure all components are properly lubricated and securely fastened.

Observations

8.2.1 Siding

CRACKING



Anarumo Inspections Page 40 of 108

Cracking was observed at one or more points on the exterior. This is common in settling of a home. Recommend sealing cracks to prevent any water intrusion.





8.2.2 Siding

DISCOLORATION



There are signs of discoloration, algae, and/or mildew on the siding. This is a cosmetic issue and is not uncommon especially on shaded portions of the home. Recommend that said areas be washed or cleaned or a regular basis.



8.2.3 Siding

PAINT/FINISH FAILING



The paint or finish is failing. This can lead to deterioration and rot of the material. Recommend that the areas be properly prepared and painted / finished.



8.3.1 Trim

PAINT/FINISH FAILING



Anarumo Inspections Page 41 of 108

The paint or finish is failing. This can lead to deterioration and rot of the material. Recommend that the areas be properly prepared and painted / finished.



8.4.1 Garage Door

PANEL DAMAGE



Garage door panel is damaged and may need repair/replacement.



8.6.1 Walls

DAMAGE STUD





8.12.1 Firewalls


HOLES IN FIREWALL



Hole(s) in wall noted. Suggest sealing all holes and around all penetrations with an approved material.

Anarumo Inspections Page 42 of 108





8.13.1 Electrical

EXPOSED WIRES



Exposed wires noted. Recommend covering for safety.



8.13.2 Electrical

INOPERABLE OUTLET



One or more outlets are not working at time of inspection.



8.13.3 Electrical

LOOSE LIGHT FIXTURE

Recommendation / Evaluation

One or more fixtures are loose. Recommend securing.

Anarumo Inspections Page 43 of 108



8.13.4 Electrical

LOOSE LIGHT SWITCH



Loose light switch noted at one or more areas. Recommend securing.



8.13.5 Electrical

MISSING LIGHT BULB



Missing lightbulb to one or more fixtures. Unable to test. not limited to just stated defect. Recommend repairs or replacement if needed.



8.13.6 Electrical

UNABLE TO DETERMINE FUNCTION OF ONE SWITCH



During the inspection, it was noted that there was one or more light switches whose function could not be determined at the time of our evaluation. Despite testing and examination of the surrounding areas, the specific appliance, fixture, or area controlled by this switch remained unclear. This situation may occur due to various reasons, such as wiring issues, a disconnected fixture, or the switch being part of a more complex electrical system not immediately apparent without further investigation.

Anarumo Inspections Page 44 of 108

8.18.1 Comments

CRACK IN STEM WALL



Crack noted in one or more areas of stem walls. Recommend a qualified professional review prior to close of escrow.



Anarumo Inspections Page 45 of 108

9: MAJOR SYSTEMS

		IN	NI	NP	0
9.1	Heating Equipment	Χ			Χ
9.2	Cooling Equipment			Χ	
9.3	Thermostat	Χ			
9.4	Distribution System			Χ	
9.5	Chimneys and Fireplaces	Χ			Χ
9.6	Smoke Detectors	Χ			
9.7	Carbon Monoxide Detectors	Χ			
9.8	Disclosures	Χ			

Information

Heating Equipment: Disconnects
Electronic Disconnect, Gas Shut
Off

Heating Equipment: Infrared Photo Of Heater ON



Chimneys and Fireplaces: Fireplace Type / Location Wood, Living Room, Gas **Heating Equipment: Energy Source**

Electric, Natural Gas

Heating Equipment: LocationMaster Bedroom

Heating Equipment: Heater - TypeRadiant Heat, Floor Furnace


Thermostat: Location


Living room, Family room, Master Bedroom

Anarumo Inspections Page 46 of 108

Smoke Detectors: Locations

Each Bedroom, Hall







Carbon Monoxide Detectors:

Locations

Master Bedroom, Hall





Heating Equipment: Filter Type

None

If your HVAC system does use a filter it is a great idea to change the filter once you take possession of your new home. Generally we find most filters do not have a installed date or change date on them. Most air filter manufacturers and HVAC companies will recommend changing your air filter every 90 days or 3 months. That can change based on where your home is located (ex. dusty, dry climates) and if you have any pets. The age of your system and equipment may also effect it.

Thermostat: Thermostats / Remotes

Some thermostats and remotes state "COOL" or "HEAT", This can sometimes believed to be a sign that there might be heating or cooling for the home. This does not mean that it does either one. Some may only be for "HEAT" or "COOL" only. Please refer to the report to verify that there was either or and its operating condition.

Chimneys and Fireplaces: Addition

This area appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Anarumo Inspections Page 47 of 108

Chimneys and Fireplaces: This Fireplace Inspection Is NOT Based On A NFPA 211 Level 1, 2, or 3 Inspection

This is a limited visual inspection, we may check some items based on a similar amount of items as a level 1 inspection. The National Fire Protection Agency or NFPA recommendation is a level 2 inspection on the sale or transfer of a home. A NFPA level 1, 2, or 3 inspection was not preformed by Anarumo Inspection Services and a level 2 inspection is highly recommend. We can send an inspector back to preform a more in-depth inspection or Chimney Scan for an additional fee.

Disclosures: Disclosure

Our evaluation of major systems is both visual and functional provided power and/or fuel is supplied to the component. Identifying or testing for the presence of asbestos, radon, lead based products, or other potentially hazardous materials is not within the scope of this report. These materials were used prior to 1982, and should you be concerned, we suggest having an independent inspection performed prior to the close of escrow. Judging the sufficiency of water flow in plumbing or the cooling efficiency of air conditioning is a subjective evaluation, therefore, we only note a poor condition if, in the inspector's opinion, the adequacy seems to be less than normal. We urge you to evaluate these systems prior to closing. Not all major systems started with gas drip legs / sediment traps; However today it is common practice we recommend adding them.

DISMANTLING AND/OR EXTENSIVE INSPECTION OF INTERNAL COMPONENTS OF ANY APPLIANCE, INCLUDING HEATERS AND HEAT EXCHANGERS, IS BEYOND THE SCOPE OF THIS REPORT. THE LOCAL UTILITY COMPANY WILL CONDUCT SUCH AN INSPECTION UPON REQUEST.

Observations

9.1.1 Heating Equipment



Recommendation / Evaluation

GAS TO UNIT OFF

At the time of the inspection, fuel was off to this unit. Fuel or power is not restored to appliances that are shut down. Most utility companies will, upon request, conduct a free inspection. Verification of this systems performance prior to closing is suggested.




9.1.2 Heating Equipment



INOPERABLE

Heater was inoperable at time of inspection. Recommend qualified HVAC professional evaluate & ensure functionality.



Anarumo Inspections Page 48 of 108

9.5.1 Chimneys and Fireplaces



C-CLAMP

Suggest adding a c-clamp to the fireplace damper as a safety upgrade, so that fireplace damper does not close completely during use.

9.5.2 Chimneys and Fireplaces

DAMAGED BRICK NOTED

Recommend repairs as needed.





9.5.3 Chimneys and Fireplaces

EVIDENCE OF IMPROPER DRAFT OR VENTING



Black marks at top of fireplace on the room side is an evidence of improper venting. Recommend having this corrected for safety.



9.5.4 Chimneys and Fireplaces

FIREBOX - CRACKS



Cracks observed in one or more areas around the firebox. This presents a safety/fire hazard. Urge repair by qualified chimney specialist before fireplace can be used. Recommend a NFPA 211 level 2 chimney inspection.




Anarumo Inspections Page 49 of 108

9.5.5 Chimneys and Fireplaces



MISSING SCREEN OR GLASS DOORS

Recommend adding permanent doors or permanent screens for safety



9.5.6 Chimneys and Fireplaces



SUGGEST CLEANING FIREPLACE

Suggest cleaning fireplace/chimney prior to first use. Possible creosote build-up noted in chimney from burning wood. We advise obtaining a professional cleaning.



Anarumo Inspections Page 50 of 108

10: PLUMBING


		IN	NI	NP	0
10.1	Drain, Waste, & Vent Systems	Χ			Χ
10.2	Main Water Shut-off Device & Water Supply Lines	Χ			Χ
10.3	Water Heater, Controls, Flues & Vents	Χ			Χ
10.4	Gas (Natural) Meter Information	Χ			Χ
10.5	Laundry Area	Χ			
10.6	Disclosure	Χ			

Information

Main Water Shut-off Device & Water Supply Lines: Location

Front

Pressure Regulator



Main Water Shut-off Device & Water Supply Lines: PSI

60

Main Water Shut-off Device & Water Supply Lines: Material - Copper

Copper is preferred for durability and low maintenance.


Main Water Shut-off Device & Water Supply Lines: Material Visible

Galvanized, Copper

Anarumo Inspections Page 51 of 108

Main Water Shut-off Device & Water Supply Lines: Water Shut Off Valve Type - Gate Valve


Water Heater, Controls, Flues & Vents: Capacity & Data Plate 40 Gallons



P008

Water Heater, Controls, Flues & Vents: Flue

Not Applicable



Water Heater, Controls, Flues & Vents: Location

Master Bedroom Closet

Water Heater, Controls, Flues & Vents: Safety Requirements


Cold Water Shut Off, Temperature And Pressure Relief

Valve




Anarumo Inspections Page 52 of 108


Water Heater, Controls, Flues & **Vents: Type - Electric Tanked Water Heater**



Bonding Connection Observed Unknown/Not visible



Gas (Natural) Meter Information: Gas (Natural) Meter Information: **Location of Fuel Source** Right





Gas (Natural) Meter Information: Laundry Area: Dryer Fuel

Material Observed

Iron

Gas, 220 Electric

Laundry Area: Dryer Location

Kitchen

Laundry Area: Dryer Vent Laundry Area: Washer Hook Up

Location Vent - Intact Kitchen

Drain, Waste, & Vent Systems: Inspected Drain, Waste, Vent Pipes

During the inspection we attempt to inspect the drain, waste, and vent pipes. Not all of the pipes and components were accessible and observed. Ask the homeowner about water and sewer leaks or blockages in the past. The inspection was restricted because not all of the pipes were exposed, readily accessible, and observed. For example, most of the drainage pipes were hidden within the walls or below ground.


Drain, Waste, & Vent Systems: Sewer Line

Suggest having a sewer camera inspection done on all single family homes. As we can not determine if there is any obstructions in the lines. Back ups normally will not present during an inspection.

Page 53 of 108 Anarumo Inspections

Main Water Shut-off Device & Water Supply Lines: Bonding Interior Piping

This may not have been required at the time this home was built. It is a good upgrade.



Main Water Shut-off Device & Water Supply Lines: Water Supply Is Public

The water supply to the house appeared to be from the public water supply source based upon the observed indications at the time of the inspection. To confirm and be certain, I recommend asking the homeowner for details.

Water Heater, Controls, Flues & Vents: Addition

This area appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Gas (Natural) Meter Information: Gas Leak Information

It is advised to contact the gas supplier for a safety inspection of all gas systems and appliances either during the contingency period or before finalizing the purchase and moving in. The inspector is unable to detect gas leaks within the home or underground at any point during the inspection process.

Gas (Natural) Meter Information: Gas Meter Information

The gas meter was inspected looking for damage and the regulator vents' clearance from ignition sources and air inlets into the home. No indications of deficiencies were present at the time of inspection unless otherwise noted in this report.

Laundry Area: Disclosure

In the Laundry area, we do not test clothes dryers, nor washing machines
And their water connections and drainpipes. However, you should be
Aware that water supply to washing machines is usually left on, and their
hoses can leak or burst under pressure and continue to flow. Therefore,
We recommend using modern braided stainless steel type water hoses that
are more dependable as an upgrade when you take possession of this property.

Disclosure: Disclosure

Since main shut-off valves are operated infrequently, it is not unusual for them to become frozen over time. They often leak or break when operated after a period of inactivity. For this reason main shut-off valves are not tested during a home inspection. We suggest caution when operating shut-offs that have not been turned for a long period of time. All shut-off valves and angle stops should be turned regularly to ensure free movement in case of emergency. Pressure regulators are beyond the inspectors scope of practice.

Anarumo Inspections Page 54 of 108

Observations

10.1.1 Drain, Waste, & Vent Systems



Recommendation / Evaluation

DRAIN WASTE VENT SHOULD EXCEED ABOVE ROOF

Drain waste vent should exceed roofline find a minimum of 6 inches or per local municipalities code. Recommend extending.



10.2.1 Main Water Shut-off Device & Water Supply Lines



Recommendation / Evaluation

MATERIAL - GALVANIZED

Galvanized water pipes rust from the inside out and can become restricted over time. When low water flow is noted at plumbing fixtures, or, if in your opinion the water flow is low, some restriction may have occurred. If concerned, we advise further review by a licensed plumber. These pipes can also display sediment in the plumbing fixtures after running the water.



10.3.1 Water Heater, Controls, Flues & Vents

ANNUAL MAINTENANCE FLUSH NEEDED



Water heaters should be flushed annually to prevent sediment buildup and maintain efficiency. Recommend a qualified plumber service and flush.

Here is a DIY link to help.

10.3.2 Water Heater, Controls, Flues & Vents



Recommendation / Evaluation

CORROSION ON SUPPLY LINES

Corrosion was noted at supply lines. One or more lines may need replacement. No leak at time of inspection.

Anarumo Inspections Page 55 of 108



10.3.3 Water Heater, Controls, Flues & Vents

Recommendation / Evaluation

NO EARTHQUAKE STRAPS

No Earthquake straps Present at time of inspection. Recommend installing as a safety upgrade.

10.3.4 Water Heater, Controls, Flues & Vents



NO ELECTRICAL DISCONNECT FOR ELECTRIC WATER HEATER:

The electric water heater does not appear to have a dedicated electrical disconnect located within sight of the unit. According to modern safety standards (NEC 422.31), a local disconnect is recommended when the appliance is not in the direct line of sight from the main electrical panel. This allows for convenient and safe servicing. While the current setup may have functioned as-is for some time, adding a local disconnect would improve serviceability and bring the installation closer to current safety practices. Consider evaluation and upgrade by a qualified electrician.



10.3.5 Water Heater, Controls, Flues & Vents



TPR - DISCHARGE PIPE REDUCED IN SIZE

Extension pipe at temperature relief valve reduces in size. Recommend having corrected.



Anarumo Inspections Page 56 of 108

10.4.1 Gas (Natural) Meter Information



GAS LINES (40+ YEAR OLD HOMES OR UNDERGROUND LINES)

The gas piping system in this home appears to be original or over 40 years old. While no immediate issues were observed at the time of inspection, it is important to note that older gas lines—particularly those made of black iron, galvanized steel, or other legacy materials—are prone to corrosion, leaks, and deterioration over time.

Additionally, if any portion of the gas piping is underground, it may be subject to soil conditions, moisture exposure, and external damage that are not visible during a standard home inspection. Underground gas lines, particularly those made of older materials, may be more susceptible to hidden leaks or failures.

Because gas line integrity is outside the scope of this inspection, we strongly recommend having a licensed plumbing or gas contractor evaluate the system to check for leaks, corrosion, or other potential hazards. A pressure test or gas leak detection may be advised to ensure the system is safe and in compliance with current standards.

For safety, homeowners should also be aware of the location of the gas shutoff valve and consider installing a seismic shut-off valve if not already present, as required in many areas of California.

If you have any concerns about the condition or safety of the gas piping, we recommend further evaluation prior to finalizing the purchase to avoid unexpected repairs or safety issues.

10.4.2 Gas (Natural) Meter Information

Recommendation / Evaluation

GAS PIPES NOT BONDED

Gas pipes were not bonded to the home electrical system. Recommend a qualified plumber evaluate and correct.

10.4.3 Gas (Natural) Meter Information



GAS PIPES - SURFACE RUST

Some degree of surface rust was present on the gas piping in the area of the gas meter. Sanding and painting the pipes with rust-inhibiting paint is recommended to extend the life of the pipes.



10.4.4 Gas (Natural) Meter Information

NO EARTHQUAKE SHUT OFF VALVE

Recommendation / Evaluation

The gas main does not have an automatic seismic shut-off valve. This device is required in some jurisdictions, and is a recommended upgrade for safety. Also some insurance companies are requiring this to be installed, recommend consulting with your insurance company to see if they want or require this to be installed.

Anarumo Inspections Page 57 of 108

11: ELECTRICAL

		IN	NI	NP	0
11.1	Service Entrance Conductors	Χ			Χ
11.2	Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices	Χ			Χ
11.3	Branch Wiring Circuits	Χ			Χ

IN = Inspected

NI = Not Inspected


NP = Not Present

O = Observations

Information


Service Entrance Conductors: Electrical Service

Overhead



Grounding, & Overload Protection Devices: Distribution (Sub) Panel Location(s)

None



Main Panel, Distribution Panel(s), Main Panel, Distribution Panel(s), **Grounding, & Overload Protection Devices: Infrared Of Interior Of Electrical Panels**




Grounding, & Overload Protection Devices: Main Disconnect

Yes

Grounding, & Overload Protection Devices: Main Panel Location

Rear



Main Panel, Distribution Panel(s), Main Panel, Distribution Panel(s), Main Panel, Distribution Panel(s), **Grounding, & Overload Protection Devices: Overload Protection / Futures**

> Circuit Breaker, No Futures For Expansion

Anarumo Inspections Page 58 of 108

Main Panel, Distribution Panel(s), Branch Wiring Circuits: Copper **Grounding, & Overload Protection Devices: Panel**

Capacity 100 Amp **Branch Circuit**

Copper branch circuits are preferred for durability and low maintenance.

Branch Wiring Circuits: Wiring

Copper



Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices: Addition

This area appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices: Arc-Fault Circuit **Interrupters - Also Known As AFCIs**

The National Electrical Code (NEC) wants Arc-Fault Circuit Interrupters (AFCI) protection in several areas around your home. AFCI protection is currently required for all 15 and 20 amp branch circuits providing power to outlets* in residential family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreation rooms, closets, hallways, and similar rooms or areas. Home inspectors are not a code enforcement. However we try to find all the areas that they are located and recommend adding them. Please keep in mind that codes are ever evolving and are subject to change. Sometimes the year after a home is built or decades after. Sometimes builders, contractors, or even city inspectors miss or oversee that they are missing AFCIs. We recommend wherever AFCI protection is required, that it be installed as a safety upgrade by an electrician.

* An "outlet" is defined in the National Electric Counsel (NEC) as "A point on the wiring system at which current is taken to supply utilization equipment." This might mean a light, a smoke alarm, or a 'receptacle'. A receptacle is what normal people call an outlet.

Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices: Ground Fault interrupters

- Also Known As GFIs or GFCIs

The National Electrical Code (NEC) wants GFIs or ground fault circuit interrupter (GFCI) protection in many areas around your home. This is to dramatically reduce the dangers associated with electrical hazard and shock. The most common places will be for outdoors electrical, Air Conditioners, Garages, Kitchens, Bathrooms, Laundry Areas, with in six feet (6') of running water, and is subject to change to more areas at anytime. Home inspectors are not a code enforcement. However we try to find all the areas that they are located and recommend adding them. Please keep in mind that codes are ever evolving and are subject to change. Sometimes the year after a home is built or decades after. Sometimes builders, contractors, or even city inspectors miss or oversee the missing GFIs. We recommend wherever GFCI protection is required, that they be installed as a safety upgrade by an electrician.

Observations


Page 59 of 108 Anarumo Inspections

11.1.1 Service Entrance Conductors



ELECTRICAL DRIP LOOP IS IMPROPERLY INSTALLED

Recommend contacting local municipality on having corrected.



11.1.2 Service Entrance Conductors



Recommendation / Evaluation

ELECTRICAL MAST HEIGHT - BELOW 36"

This might have been normal construction at the time of installation. Today we install an electrical that provides the wires 36" or more of clearance to the roof.



11.2.1 Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices



Recommendation / Evaluation

AFCI BREAKERS - NONE

AFCI protection is currently recommended and maybe required in some municipalities for all 15 and 20 amp branch circuits providing power to receptacles* in residential family rooms. Like dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreation rooms, closets, hallways, and similar rooms or areas. This may not have been required at the time of construction or upgrade.

11.2.2 Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices



Recommendation / Evaluation

BREAKERS APPEAR TO BE OVER 30 YEARS OLD

Most of these panels that are still in use, are more than 30 years old now and manufacturers say that breakers have a life expectancy of abot 30 years. Due to this we recommend budgeting to upgrade the electrical panel(s) in the future.


Anarumo Inspections Page 60 of 108

11.2.3 Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices




DOUBLED UP CIRCUITRY


Double-Tapped Breakers







Doubled-up circuitry at one or more breakers noted. This condition can add to the load of the affected electrical circuits causing a possible overload and tripping of the breakers. Ideally, doubled-up circuitry should be independently fused. We advise contacting a licensed electrician for review and/or repair.





11.2.4 Main Panel, Distribution Panel(s), Grounding, & Overload Protection Devices



ZINSCO / GTE / CHALLENGER / MURRAY / SYLVANIA / STAB LOK / FEDERAL PACIFIC PANELS / BULLDOG PUSHAMATICS

Most of these panels that are still in use, are more than 40 years old now and manufacturers say that breakers have a life expectancy of 40 years. As time has passed, insurances companies, electricians, and home inspectors have found that some of the panels can work fine for many years. However as our electrical demands have increased as the years have gone on, some of these panels have had problems with overheating, melted components, and arcing. Due to this fact we recommend budgeting to upgrade the electrical panel(s) in the future.

11.3.1 Branch Wiring Circuits

CLOTH BRANCH WIRING FOUND



Cloth wiring is considered an obsolete wiring material and some insurance companies are not insuring homes with it. Cloth wiring uses cloth for insulation were as today we use plastic. Cloth wiring may require, Cloth wiring in the past has used certain products in it which make it more prone to animals trying to eat it.

Anarumo Inspections Page 61 of 108

12: KITCHEN

		IN	NI	NP	0
12.1	Floors	Χ			
12.2	Walls	Χ			Χ
12.3	Ceilings	Χ			Χ
12.4	Doors	Χ			
12.5	Windows	Χ			Χ
12.6	Cabinets	Χ			Χ
12.7	Countertops	Χ			Χ
12.8	Electrical	Χ			Χ
12.9	Sink, Faucets, & Drains	Χ			Χ
12.10	Garbage Disposal	Χ			Χ
12.11	Dishwasher	Χ			Χ
12.12	Vent	Χ			
12.13	Range/Cooktop	Χ			
12.14	Oven	Χ			Χ
12.15	Built-in Microwave			Χ	
12.16	Disclosure	Χ			

Information

Sink, Faucets, & Drains: Under Sink Photo



Vent: Exhaust Hood TypeVented

Range/Cooktop: Range Fuel
Source
Gas



Anarumo Inspections Page 62 of 108

Oven: Oven Fuel Source

Gas



Sink, Faucets, & Drains: Hot Water Temperature (100 to 114F and/or 126F or Higher)

120 degrees Fahrenheit is the safety recommendation against scalding, but 140° is the common default setting. Most experts agree that anything below 115 degrees creates a risk for bacteria to develop inside your water heater from stagnant water. This is an indication that the water heater may need adjustments or maintenance.



Garbage Disposal: Garbage Disposal Information

The inspection of the garbage disposal is restricted in scope. It does not extend to forecasting the lifespan of the unit or assessing its effectiveness in grinding food and other materials. Furthermore, the evaluation does not cover the condition or efficiency of the internal blades.

Dishwasher: Dishwasher Information

The dishwasher inspection is confined to basic operations, specifically limiting checks to a single fill and drain cycle. It excludes detailed evaluations of internal components such as the water pump and hoses. As such, the inspector cannot provide forecasts on the lifespan of the dishwasher or its internal parts. Additionally, the efficiency of the dishwasher in cleaning or drying dishes falls outside the scope of this inspection, which does not encompass full operational cycles.

Vent: Exhaust Hood Information

The exhaust fan/vent is evaluated using standard controls alone, without conducting smoke tests or other methods to measure airflow (CFMs) or effectiveness in air evacuation. The inspector is unable to estimate the remaining lifespan of the unit.

Range/Cooktop: Range Information

The inspection of the range or cooktop is confined in scope. It does not include predictions about the appliance's longevity, assessments of the BTU output of the burners, or evaluations of cooking performance. For gas models, this inspection does not cover the detection of gas leaks. A comprehensive examination by the Gas Company for all gaspowered appliances is advised beyond this basic inspection.

Anarumo Inspections Page 63 of 108

Oven: Oven Information

During the home inspection, only the oven's "Bake" feature is tested; other functions such as convection, browning, rotisserie, and warming drawers are not evaluated. The inspection verifies basic operation of the heating elements without testing every temperature setting, assessing if accurate cooking temperatures are reached, or confirming calibration with the oven settings. The effectiveness of the oven in cooking food and the lifespan of the unit remain undetermined. For gas models, this inspection does not include gas leak detection. A thorough review by the Gas Company for all gas-powered appliances is recommended beyond this inspection.

Disclosure: Disclosure

The kitchen inspection is both visual and functional. Appliances are operated, if power is supplied. Clocks, timers and other pre-setting devices on stoves and ovens are not within the scope of this inspection. Calibrations to cooking systems are not evaluated nor life expectancies given to dishwashers. Note: Dishwashers can fail at any time due to their complexity. Our review is to determine if the system is free of leaks and excessive corrosion.

The presence and/or odor of mold and/or mildew are possible anywhere there is moisture, such as: under sinks and plumbing at kitchens and bathrooms, plumbing leaks, crawl spaces, other rooms, etc. Often the moisture is hidden from view by personal property or if it is present within walls, under flooring, inside cabinets or in an inaccessible area. Determination of the presence of mold and/or mildew, or possible health hazards resulting from exposure to these organisms is not within the scope of this inspection. If client has any concerns regarding the presence of mold and/or mildew, we advise consulting with an Indoor Air Quality specialist or other qualified person, for any testing, evaluations and/or removal which may be desired prior to close of escrow.

Observations

12.2.1 Walls

CRACKS - MINOR



Minor cracks in walls. Some settling is not unusual in a home of this age and these cracks are not a structural concern.




12.2.2 Walls

PATCHING NOTED

Maintenance Item

Patched areas observed on walls in one or several locations.



Anarumo Inspections Page 64 of 108

12.3.1 Ceilings

CRACKS - MINOR



Minor cracks in walls. Some settling is not unusual in a home of this age and these cracks are not a structural concern.

12.3.2 Ceilings

PATCHING NOTED

Patched areas observed on Ceilings in one or several locations.



12.5.1 Windows

BROKEN WINDOW LOCK





12.6.1 Cabinets


CABINETS NEED ADJUSTING



Maintenance Item

12.7.1 Countertops

COUNTERTOP - DAMAGED MATERIAL





Anarumo Inspections Page 65 of 108

12.8.1 Electrical

EXTENSION CORD WIRING



Recommendation / Evaluation

Extension cord is used for a power supply. This is not a proper installation. Recommend correcting.




12.8.2 Electrical

NO GFIS



There is no ground fault interrupter in this area (which should be the entire counter) which may not have been standard at the time of construction. However, todays standards require ground fault interrupters at all areas within six feet of running water and external outlets. We suggest installing a ground fault interrupter in this area as a safety upgrade. If it is connected to a GFI and NOT labeled this is still improper.

A GFCI receptacle can provide protection for other receptacles downstream on the circuit. GFCI protection can be provided by GFCI breakers, blank face devices, or GFCI receptacles



Anarumo Inspections Page 66 of 108





12.8.3 Electrical

UNGROUNDED RECEPTACLES



Recommendation / Evaluation

One or more outlets were found to be ungrounded or open ground in this home and may not be limited to just one area. We will attempt to name all the areas that have them, however sometimes outlets maybe hidden, used, or not tested as we are only required to check a representative number of receptacles or outlets around the property. All receptacles or outlets ideally should be grounded and due to the age or configuration of this system, we are unable to determine if proper grounding is in place or can occur. Suggest consulting a licensed electrician for further review of the entire electrical system prior to release of contingencies.



12.9.1 Sink, Faucets, & Drains

BELOW SINK - CORROSION



Recommendation / Evaluation

Corrosion on sink faucet, drain, and/or angle stops. No signs of leak at time of inspection. Repairs maybe needed.



12.9.2 Sink, Faucets, & Drains


FAUCET - LEAK AT BASE



Recommendation / Evaluation

Faucet is leaking at base and sink connection. Repair or replacement is needed.

Anarumo Inspections Page 67 of 108





12.10.1 Garbage Disposal



INOPERABLE

Garbage disposal was inoperable at the time of inspection. Recommend qualified handyman repair. Here is a DIY resource for troubleshooting.

12.11.1 Dishwasher

DOOR NEEDS ADJUSTING



12.11.2 Dishwasher

INOPERABLE



Dishwasher was inoperable using standard controls. Recommend a qualified plumber or contractor evaluate.

12.11.3 Dishwasher

RUSTED TRAYS



Rusted trays noted. No signs of leaks at time of inspection. Replacement maybe needed.

12.14.1 Oven



RANGE DOES NOT APPEAR TO FASTENED

Range was not fastened to the floor/wall/cabinet. This poses a safety hazard to children. Recommend a qualified contractor secure range so it can't tip.

12.14.2 Oven



TOUCH SCREEN IS UNRESPONSIVE AND ERROR CODE

Anarumo Inspections Page 68 of 108



Anarumo Inspections Page 69 of 108

13: BATHROOM - DOWNSTAIRS

		IN	NI	NP	0
13.1	Floors	Χ			Χ
13.2	Walls	Χ			Χ
13.3	Ceiling	Χ			
13.4	Doors	Χ			
13.5	Window(s)	Χ			Χ
13.6	Electrical	Χ			Χ
13.7	Exhaust Fan / Electric Heater			Х	
13.8	Tub	Χ			Χ
13.9	Shower	Χ			
13.10	Sink/Faucet/Drains/Supply	Χ			Χ
13.11	Toilet	Χ			Χ
13.12	Counter/Cabinets	Χ			Χ
13.13	Disclosure	Χ			

Information

Sink/Faucet/Drains/Supply: Photo Under Sink



Anarumo Inspections Page 70 of 108

Sink/Faucet/Drains/Supply: Hot Water Temperature (100 to 114F and/or 126F or Higher)

120 degrees Fahrenheit is the safety recommendation against scalding, but 140° is the common default setting. Most experts agree that anything below 115 degrees creates a risk for bacteria to develop inside your water heater from stagnant water. This is an indication that the water heater may need adjustments or maintenance.



Disclosure: Disclosure

Our focus in bathrooms is directed at identifying visible water damage and/or problems. We may not always mention common faults such as stuck stoppers or dripping faucets. If considered important, you should check these items independently.

The presence and/or odor of mold and/or mildew are possible anywhere there is moisture, such as: under sinks and plumbing at kitchens and bathrooms, plumbing leaks, crawl spaces, other rooms, etc. Often the moisture is hidden from view by personal property or if it is present within walls, under flooring, inside cabinets or in an inaccessible area. Determination of the presence of mold and/or mildew, or possible health hazards resulting from exposure to these organisms is not within the scope of this inspection. If client has any concerns regarding the presence of mold and/or mildew, we advise consulting with an Indoor Air Quality specialist or other qualified person, for any testing, evaluations and/or removal which may be desired prior to close of escrow.

Observations

13.1.1 Floors

FLOORING - DAMAGED



During the inspection, damaged flooring was noted in one or more areas. This can included cracks, chips, torn, dings, and a broken material. These conditions, while not alarming, can be addressed to maintain minor safety concerns and aesthetics. We recommend consulting a flooring professional for necessary repairs or replacement.



13.2.1 Walls

MICROBIAL GROWTH

Recommendation / Evaluation

Evidence of Microbial growth noted and testing was waived by clients. This is a health and safety concern. We advise obtaining further evaluation from a qualified expert to determine the extent of the necessary corrective measures required.

Anarumo Inspections Page 71 of 108





13.2.2 Walls

MOISTURE DAMAGE



Stains on the walls visible at the time of the inspection appeared to be the result of moisture intrusion. The source of moisture may have been corrected. Recommend further examination by a qualified contractor to provide confirmation.



13.5.1 Window(s)

WINDOW - DOES NOT OPEN



The window is unable to open, possibly due to being painted shut or stuck. We were unable to test the window. It is recommended to have the window adjusted and necessary corrections applied.



13.6.1 Electrical

UNGROUNDED RECEPTACLE



Anarumo Inspections Page 72 of 108

One or more outlets were found to be ungrounded or open ground in this home and may not be limited to just one area. We will attempt to name all the areas that have them, however sometimes outlets maybe hidden, used, or not tested as we are only required to check a representative number of receptacles or outlets around the property. All receptacles or outlets ideally should be grounded and due to the age or configuration of this system, we are unable to determine if proper grounding is in place or can occur. Suggest consulting a licensed electrician for further review of the entire electrical system prior to release of contingencies.



13.8.1 Tub

ENCLOSURE DOORS - HAVE BEEN REMOVED






13.8.2 Tub

FLANGE - LOOSE

One or more faucet flanges are loose, suggest correcting.





13.8.3 Tub

TUB DRAINS SLOWLY

Recommendation / Evaluation

The tub is draining slowly, and the cause cannot be determined at this time. It may be necessary to clear the drain to address this issue.


Anarumo Inspections Page 73 of 108

13.8.4 Tub

Recommendation / Evalu

WATER TEMPERATURE BELOW 100F

During the inspection, it was observed that the water temperature is below 100°F, which may indicate a malfunctioning valve. It is recommended to consult a plumber for further evaluation and necessary repairs.




13.11.1 Toilet

TOILET IS TO CLOSE TO THE WALL AND/OR SINK



toilet flange at least 15-1/2 inches from the center of the flange to the wall framing. The standard distance from the back wall is 12 inches, or 12-1/2 inches. Taking into account 1/2" drywall





13.12.1 Counter/Cabinets

CABINET - DAMAGED



Anarumo Inspections Page 74 of 108

14: BATHROOM - MASTER

		IN	NI	NP	0
14.1	Floors	Χ			Χ
14.2	Walls	Χ			Χ
14.3	Ceiling	Χ			
14.4	Doors	Χ			Χ
14.5	Window(s)	Χ			
14.6	Electrical	Χ			
14.7	Exhaust Fan / Electric Heater	Χ			
14.8	Tub			Х	
14.9	Shower	Χ			Χ
14.10	Sink/Faucet/Drains/Supply	Χ			Χ
14.11	Toilet	Χ			
14.12	Counter/Cabinets	Χ			Χ
14.13	Disclosure	Χ			

Information

Exhaust Fan / Electric Heater:


Electric Heater - Operable



Anarumo Inspections Page 75 of 108

Shower: Hot Water Temperature (100 to 114F or 126F or Higher)

120 degrees Fahrenheit is the safety recommendation against scalding, but 140° is the common default setting. Most experts agree that anything below 115 degrees creates a risk for bacteria to develop inside your water heater from stagnant water. This is an indication that the water heater or valves may need adjustments, maintenance, or replacement.



Sink/Faucet/Drains/Supply: Hot Water Temperature (Between 115F - 125F)





Sink/Faucet/Drains/Supply: Photo Under Sink





Anarumo Inspections Page 76 of 108

Disclosure: Disclosure

Our focus in bathrooms is directed at identifying visible water damage and/or problems. We may not always mention common faults such as stuck stoppers or dripping faucets. If considered important, you should check these items independently.

The presence and/or odor of mold and/or mildew are possible anywhere there is moisture, such as: under sinks and plumbing at kitchens and bathrooms, plumbing leaks, crawl spaces, other rooms, etc. Often the moisture is hidden from view by personal property or if it is present within walls, under flooring, inside cabinets or in an inaccessible area. Determination of the presence of mold and/or mildew, or possible health hazards resulting from exposure to these organisms is not within the scope of this inspection. If client has any concerns regarding the presence of mold and/or mildew, we advise consulting with an Indoor Air Quality specialist or other qualified person, for any testing, evaluations and/or removal which may be desired prior to close of escrow.

Observations

14.1.1 Floors

HIGH SPOTS NOTED



During the inspection, it was noted that high spots were present in certain areas . These high spots can be attributed to various factors such as settlement, natural wood movement, construction practices, or flooring material.

High spots in the flooring are common in buildings and are typically a result of natural processes or construction practices. While they may affect the aesthetics of the flooring, they do not necessarily indicate significant structural issues.

14.2.1 Walls

CRACKS - MINOR



Minor cracks in walls. Some settling is not unusual in a home of this age and these cracks are not a structural concern.



14.2.2 Walls

PAINT FLAKING



Noticed areas of paint flaking off in various sections, indicating potential aging or exposure to elements. Further evaluation or repainting may be necessary to maintain aesthetics and protect underlying surfaces.

Anarumo Inspections Page 77 of 108



14.4.1 Doors
BROKEN HANDLE






14.9.1 Shower

needed.

TILES - CRACKED

Enclosure has one or more cracked tiles. Recommend a bathroom contractor or handyman repair or replace.



14.10.1 Sink/Faucet/Drains/Supply

BELOW SINK - CORROSION

Corrosion on sink faucet, drain, and/or angle stops. No signs of leak at time of inspection. Repairs maybe

Anarumo Inspections Page 78 of 108







14.10.2 Sink/Faucet/Drains/Supply



Recommend a plumber





14.10.3 Sink/Faucet/Drains/Supply

SINK-MISSING STOPPER



14.12.1 Counter/Cabinets

HANDLES - MISSING



Recommend installing handles as needed

Anarumo Inspections Page 79 of 108



Anarumo Inspections Page 80 of 108

15: LIVING ROOM

		IN	NI	NP	0
15.1	Floors	Χ			Χ
15.2	Walls	Χ			Χ
15.3	Ceilings	Χ			
15.4	Doors	Χ			
15.5	Windows	Χ			Χ
15.6	Electrical	Χ			Χ
15.7	Disclosure	Χ			

Observations

15.1.1 Floors

HIGH SPOTS NOTED



During the inspection, it was noted that high spots were present in certain areas. These high spots can be attributed to various factors such as settlement, natural wood movement, construction practices, or flooring material.

High spots in the flooring are common in buildings and are typically a result of natural processes or construction practices. While they may affect the aesthetics of the flooring, they do not necessarily indicate significant structural issues.

15.1.2 Floors

SQUEAK NOTED



During the inspection, it was observed that squeaking noises were present in certain areas of the flooring. Squeaking in flooring can be caused by various factors such as natural movement of the subfloor, loose fasteners, or uneven installation of flooring materials.

Squeaking is a common occurrence in many homes and does not necessarily indicate serious structural issues. It is often a result of normal wear and tear, changes in humidity, or minor imperfections in the installation process.

To address the squeaking, it is recommended to evaluate the affected areas and determine the underlying cause. This may involve tightening loose fasteners, reinforcing subflooring if necessary, or addressing any moisture-related issues.

15.2.1 Walls



CRACKS - MINOR

Minor cracks in walls. Some settling is not unusual in a home of this age and these cracks are not a structural concern.

Anarumo Inspections Page 81 of 108



15.5.1 Windows

WINDOW - DOES NOT OPEN



The window is unable to open, possibly due to being painted shut or stuck. We were unable to test the window. It is recommended to have the window adjusted and necessary corrections applied.

15.6.1 Electrical

COVER PLATE - DAMAGED



One or more receptacles have a damaged/cracked cover plate. Recommend replacement.



15.6.2 Electrical

UNGROUNDED RECEPTACLE



One or more outlets were found to be ungrounded or open ground in this home and may not be limited to just one area. We will attempt to name all the areas that have them, however sometimes outlets maybe hidden, used, or not tested as we are only required to check a representative number of receptacles or outlets around the property. All receptacles or outlets ideally should be grounded and due to the age or configuration of this system, we are unable to determine if proper grounding is in place or can occur. Suggest consulting a licensed electrician for further review of the entire electrical system prior to release of contingencies.

Anarumo Inspections Page 82 of 108

16: DINING ROOM

		IN	NI	NP	0
16.1	Floors	Χ			Χ
16.2	Walls	Χ			
16.3	Ceilings	Χ			
16.4	Doors	Χ			Χ
16.5	Windows	Χ			
16.6	Electrical	Χ			Χ
16.7	Disclosure	Χ			

Observations

16.1.1 Floors

HIGH SPOTS NOTED



During the inspection, it was noted that high spots were present in certain areas. These high spots can be attributed to various factors such as settlement, natural wood movement, construction practices, or flooring material.

High spots in the flooring are common in buildings and are typically a result of natural processes or construction practices. While they may affect the aesthetics of the flooring, they do not necessarily indicate significant structural issues.

16.4.1 Doors



DOOR RUBS ON JAMB

The door is rubbing against the jamb, suggesting a need for adjustment.

Here is a helpful DIY article on how to fix a sticking door.

16.6.1 Flectrical



UNGROUNDED RECEPTACLE

One or more outlets were found to be ungrounded or open ground in this home and may not be limited to just one area. We will attempt to name all the areas that have them, however sometimes outlets maybe hidden, used, or not tested as we are only required to check a representative number of receptacles or outlets around the property. All receptacles or outlets ideally should be grounded and due to the age or configuration of this system, we are unable to determine if proper grounding is in place or can occur. Suggest consulting a licensed electrician for further review of the entire electrical system prior to release of contingencies.

Anarumo Inspections Page 83 of 108

17: FAMILY ROOM

		IN	NI	NP	0
17.1	Floors	Χ			Χ
17.2	Walls	Χ			Χ
17.3	Ceilings	Χ			Χ
17.4	Doors	Χ			Χ
17.5	Windows	Χ			
17.6	Electrical	Χ			Χ
17.7	Disclosure	Χ			

Observations

17.1.1 Floors

HIGH SPOTS NOTED



During the inspection, it was noted that high spots were present in certain areas. These high spots can be attributed to various factors such as settlement, natural wood movement, construction practices, or flooring material.


High spots in the flooring are common in buildings and are typically a result of natural processes or construction practices. While they may affect the aesthetics of the flooring, they do not necessarily indicate significant structural issues.

17.2.1 Walls

DETERIORATED WOOD



One or more sections of the wall are deteriorated. Recommend a Termite Company evaluate the whole home.



17.2.2 Walls

MICROBIAL GROWTH



Evidence of Microbial growth noted and testing was waived by clients. This is a health and safety concern. We advise obtaining further evaluation from a qualified expert to determine the extent of the necessary corrective measures required.

Anarumo Inspections Page 84 of 108




17.3.1 Ceilings

PATCHING NOTED







17.4.1 Doors **DOOR RUBS ON JAMB**



Anarumo Inspections Page 85 of 108

The door is rubbing against the jamb, suggesting a need for adjustment.

Here is a helpful DIY article on how to fix a sticking door.



17.6.1 Electrical

BROKEN OUTLET



One or more outlets are broken. Recommend replacing for safety.




17.6.2 Electrical

COVER PLATE - LOOSE



One or more cover plates are loose and need securing.



17.6.3 Electrical

INOPERABLE OUTLET



One or more outlets are not working at time of inspection. Recommend further review.

Anarumo Inspections Page 86 of 108



Anarumo Inspections Page 87 of 108

18: HALL & STAIRS - UPSTAIRS

		IN	NI	NP	0
18.1	Floors	Χ			Χ
18.2	Walls	Χ			Χ
18.3	Ceilings	Χ			
18.4	Doors			Χ	
18.5	Windows	Χ			
18.6	Electrical	Χ			
18.7	Stairs and Railing	Χ			Χ
18.8	Disclosure	Χ			

Information

Disclosure: Addition

This area appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Observations

18.1.1 Floors

SQUEAK NOTED



During the inspection, it was observed that squeaking noises were present in certain areas of the flooring. Squeaking in flooring can be caused by various factors such as natural movement of the subfloor, loose fasteners, or uneven installation of flooring materials.

Squeaking is a common occurrence in many homes and does not necessarily indicate serious structural issues. It is often a result of normal wear and tear, changes in humidity, or minor imperfections in the installation process.

To address the squeaking, it is recommended to evaluate the affected areas and determine the underlying cause. This may involve tightening loose fasteners, reinforcing subflooring if necessary, or addressing any moisture-related issues.

18.2.1 Walls



CRACKS - MINOR

Minor cracks in walls. Some settling is not unusual in a home of this age and these cracks are not a structural concern.

Anarumo Inspections Page 88 of 108



18.2.2 Walls

MICROBIAL GROWTH



Evidence of Microbial growth noted and testing was waived by clients. This is a health and safety concern. We advise obtaining further evaluation from a qualified expert to determine the extent of the necessary corrective measures required.






18.7.1 Stairs and Railing


RAILING SPACING GREATER THAN 4"

Recommendation / Evaluation

We recommend closing all balusters to within a 4-inch proximity to ensure safety. This adjustment aims to minimize the risk of accidents and enhance the overall security of the property.



Anarumo Inspections Page 89 of 108



Anarumo Inspections Page 90 of 108

19: HALL - DOWNSTAIRS

		IN	NI	NP	0
19.1	Floors	Χ			Χ
19.2	Walls	Χ			Χ
19.3	Ceilings	Χ			Χ
19.4	Doors	Χ			
19.5	Windows			Χ	
19.6	Electrical	Χ			
19.7	Stairs and Railing			Χ	
19.8	Disclosure	Χ			

IN = Inspected NI = Not Inspected NP = I

NP = Not Present

O = Observations

Observations

19.1.1 Floors

HIGH SPOTS NOTED



During the inspection, it was noted that high spots were present in certain areas. These high spots can be attributed to various factors such as settlement, natural wood movement, construction practices, or flooring material.

High spots in the flooring are common in buildings and are typically a result of natural processes or construction practices. While they may affect the aesthetics of the flooring, they do not necessarily indicate significant structural issues.

19.2.1 Walls

PAINT FLAKING



Noticed areas of paint flaking off in various sections, indicating potential aging or exposure to elements. Further evaluation or repainting may be necessary to maintain aesthetics and protect underlying surfaces.



19.3.1 Ceilings

CRACKS - MINOR



Minor cracks in walls. Some settling is not unusual in a home of this age and these cracks are not a structural concern.

Anarumo Inspections Page 91 of 108



Anarumo Inspections Page 92 of 108

20: BEDROOM - DOWNSTAIRS FRONT

		IN	NI	NP	0
20.1	Floors	Χ			Χ
20.2	Walls	Χ			
20.3	Ceilings	Χ			
20.4	Doors	Χ			
20.5	Windows	Χ			Χ
20.6	Electrical	Χ			Χ
20.7	Closet	Χ			
20.8	Disclosure	Χ			

Observations

20.1.1 Floors

HIGH SPOTS NOTED



During the inspection, it was noted that high spots were present in certain areas. These high spots can be attributed to various factors such as settlement, natural wood movement, construction practices, or flooring material.

High spots in the flooring are common in buildings and are typically a result of natural processes or construction practices. While they may affect the aesthetics of the flooring, they do not necessarily indicate significant structural issues.

20.1.2 Floors

SQUEAK NOTED



During the inspection, it was observed that squeaking noises were present in certain areas of the flooring. Squeaking in flooring can be caused by various factors such as natural movement of the subfloor, loose fasteners, or uneven installation of flooring materials.

Squeaking is a common occurrence in many homes and does not necessarily indicate serious structural issues. It is often a result of normal wear and tear, changes in humidity, or minor imperfections in the installation process.

To address the squeaking, it is recommended to evaluate the affected areas and determine the underlying cause. This may involve tightening loose fasteners, reinforcing subflooring if necessary, or addressing any moisture-related issues.

20.5.1 Windows

Maintenance Item

WINDOW - DOES NOT OPEN

The window is unable to open, possibly due to being painted shut or stuck. We were unable to test the window. It is recommended to have the window adjusted and necessary corrections applied.

Anarumo Inspections Page 93 of 108

20.6.1 Electrical



COVER PLATE - DAMAGED

One or more receptacles have a damaged/cracked cover plate. Recommend replacement.



Anarumo Inspections Page 94 of 108

21: BEDROOM - DOWNSTAIRS REAR

		IN	NI	NP	0
21.1	Floors	Χ			Χ
21.2	Walls	Χ			
21.3	Ceilings	Χ			
21.4	Doors	Χ			
21.5	Windows	Χ			Χ
21.6	Electrical	Χ			Χ
21.7	Closet	Χ			
21.8	Disclosure	Χ			

IN = Inspected NI = Not Inspected NP = Not Present O = Observations

Observations

21.1.1 Floors

HIGH SPOTS NOTED



During the inspection, it was noted that high spots were present in certain areas. These high spots can be attributed to various factors such as settlement, natural wood movement, construction practices, or flooring material.

High spots in the flooring are common in buildings and are typically a result of natural processes or construction practices. While they may affect the aesthetics of the flooring, they do not necessarily indicate significant structural issues.

21.1.2 Floors

SQUEAK NOTED



During the inspection, it was observed that squeaking noises were present in certain areas of the flooring. Squeaking in flooring can be caused by various factors such as natural movement of the subfloor, loose fasteners, or uneven installation of flooring materials.

Squeaking is a common occurrence in many homes and does not necessarily indicate serious structural issues. It is often a result of normal wear and tear, changes in humidity, or minor imperfections in the installation process.

To address the squeaking, it is recommended to evaluate the affected areas and determine the underlying cause. This may involve tightening loose fasteners, reinforcing subflooring if necessary, or addressing any moisture-related issues.

21.5.1 Windows

Recommendation / Evaluation

WINDOW - INOPERABLE CRANKS

One or more cranks are malfunctioning and require adjustments to operate correctly.

Anarumo Inspections Page 95 of 108



21.6.1 Electrical

COVER PLATE - DAMAGED



One or more receptacles have a damaged/cracked cover plate. Recommend replacement.



Anarumo Inspections Page 96 of 108

22: BEDROOM - MASTER

		IN	NI	NP	0
22.1	Floors	Χ			Χ
22.2	Walls	Χ			Χ
22.3	Ceilings	Χ			Χ
22.4	Doors	Χ			
22.5	Windows	Χ			
22.6	Electrical	Χ			Χ
22.7	Closet	Χ			Χ
22.8	Disclosure	Χ			

Information

Disclosure: Addition

This area appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Observations

22.1.1 Floors

HIGH SPOTS NOTED



During the inspection, it was noted that high spots were present in certain areas . These high spots can be attributed to various factors such as settlement, natural wood movement, construction practices, or flooring material.

High spots in the flooring are common in buildings and are typically a result of natural processes or construction practices. While they may affect the aesthetics of the flooring, they do not necessarily indicate significant structural issues.

22.1.2 Floors

SQUEAK NOTED



During the inspection, it was observed that squeaking noises were present in certain areas of the flooring. Squeaking in flooring can be caused by various factors such as natural movement of the subfloor, loose fasteners, or uneven installation of flooring materials.

Squeaking is a common occurrence in many homes and does not necessarily indicate serious structural issues. It is often a result of normal wear and tear, changes in humidity, or minor imperfections in the installation process.

To address the squeaking, it is recommended to evaluate the affected areas and determine the underlying cause. This may involve tightening loose fasteners, reinforcing subflooring if necessary, or addressing any moisture-related issues.

Anarumo Inspections Page 97 of 108

22.2.1 Walls

CRACKS - MINOR



Minor cracks in walls. Some settling is not unusual in a home of this age and these cracks are not a structural concern.





22.2.2 Walls

PAINT FLAKING



Noticed areas of paint flaking off in various sections, indicating potential aging or exposure to elements. Further evaluation or repainting may be necessary to maintain aesthetics and protect underlying surfaces.



22.3.1 Ceilings

WATER STAIN(S) ON CEILING

Recommendation / Ev

There is a stain on ceiling that shows no signs of moisture at time of inspection.



Anarumo Inspections Page 98 of 108

22.6.1 Electrical

OUTLET - LOOSE




One or more outlets are loose. Recommend securing.



22.6.2 Electrical

UNABLE TO DETERMINE FUNCTION OF ONE SWITCH



During the inspection, it was noted that there was one or more light switches whose function could not be determined at the time of our evaluation. Despite testing and examination of the surrounding areas, the specific appliance, fixture, or area controlled by this switch remained unclear. This situation may occur due to various reasons, such as wiring issues, a disconnected fixture, or the switch being part of a more complex electrical system not immediately apparent without further investigation.

22.7.1 Closet

CLOSET DOOR - OFF ITS TRACK



One or more closet doors are off the track. Recommend correction to prevent door from falling down.



Anarumo Inspections Page 99 of 108

23: ATTIC

		IN	NI	NP	0
23.1	Access Location	Χ			
23.2	Sheathing	Χ			
23.3	Evidence of leakage	Χ			Χ
23.4	Attic Insulation	Χ			
23.5	Ventilation	Χ			Χ
23.6	Attic Comments	Χ			

Information

Access Location: Attic

Master Bedroom Closet,

Downstairs Rear Bedroom Closet

Limited

Sheathing: Material

1x6 boards

Evidence of leakage: Leaking

See roof comments, Dry Water

Stains

Attic Insulation: Approximate

Average Thickness


3

Attic Insulation: Insulation

Yes

Ventilation: Ventilation

Adequate



Access Location: Attic Information

Certain sections of the attic may remain unseen or unreachable due to restrictions on access.

Attic Comments: Could Not See Everything in Attic

I could not see and inspect everything in the attic space. The access is restricted and my inspection is limited.

Observations

23.3.1 Evidence of leakage

POSSIBLE ACTIVE WATER STAINS IN THE ATTIC



Water stains noted in the attic. Due to the condition of the roof recommend further consultation. There's a possibility roof is not watertight.

23.5.1 Ventilation

VENT DAMAGED



Anarumo Inspections Page 100 of 108

Vent was damaged, which could allow pests to enter. Recommend a qualified attic or ventilation contractor repair.

Anarumo Inspections Page 101 of 108

24: ADDITIONS

		IN	NI	NP	0
24.1	Recommend Checking For Property Permits	Χ			

Information

Recommend Checking For Property Permits: Recommend Checking On Permits

This home appears to have addition (s) to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits for any and all modifications to the structure and its components before the close of escrow. We are not able to verify if these were all done with permits.

Anarumo Inspections Page 102 of 108

25: HOME MAINTENANCE

		IN	NI	NP	0
25.1	Home Maintenance	Χ			
25.2	Your Job As a Homeowner	Χ			

Information


Anarumo Inspections Page 103 of 108

Home Maintenance: Easy Seasonal Maintenance



Anarumo Inspections Page 104 of 108

Your Job As a Homeowner: Read Your Digital Home Maintenance Manual



I have provided you a digital home maintenance manual. It includes information on how your home works, how to maintain it, and how to save energy. Please write my contact information within the book's inside cover, so that you can always contact me.

We're neighbors! So, feel free to reach out whenever you have a house question or issue.

REPLACE THIS VIDEO WITH A VIDEO OF YOU Talking About R...



Share



Anarumo Inspections Page 105 of 108

Your Job As a Homeowner: Schedule a Home Maintenance Inspection



Even the most vigilant homeowner can, from time to time, miss small problems or forget about performing some routine home repairs and seasonal maintenance. That's why an Annual Home Maintenance Inspection will help you keep your home in good condition and prevent it from suffering serious, long-term and expensive damage from minor issues that should be addressed now.

The most important thing to understand as a new homeowner is that your house requires care and regular maintenance. As time goes on, parts of your house will wear out, break down, deteriorate, leak, or simply stop working. But none of these issues means that you will have a costly disaster on your hands if you're on top of home maintenance, and that includes hiring an expert once a year.

Just as you regularly maintain your vehicle, consider getting an Annual Home Maintenance Inspection as part of the cost of upkeep for your most valuable investment your home.

Your InterNACHI-Certified Professional Inspector can show you what you should look for so that you can be an informed homeowner. Protect your family's health and safety, and enjoy your home for years to come by having an Annual Home Maintenance Inspection performed every year.

Schedule next year's maintenance inspection with your home inspector today!

Every house should be inspected every year as part of a homeowner's routine home maintenance plan. Catch problems before they become major defects.

REPLACE THIS VIDEO WITH A VIDEO OF YOU Talking About ...



Share



Anarumo Inspections Page 106 of 108

Your Job As a Homeowner: What Really Matters in a Home Inspection

Now that you've bought your home and had your inspection, you may still have some questions about your new house and the items revealed in your report.

Home maintenance is a primary responsibility for every homeowner, whether you've lived in several homes of your own or have just purchased your first one. Staying on top of a seasonal home maintenance schedule is important, and your InterNACHI Certified Professional Inspector can help you figure this out so that you never fall behind. Don't let minor maintenance and routine repairs turn into expensive disasters later due to neglect or simply because you aren't sure what needs to be done and when.

Your home inspection report is a great place to start. In addition to the written report, checklists, photos, and what the inspector said during the inspection not to mention the sellers disclosure and what you noticed yourself it's easy to become overwhelmed. However, it's likely that your inspection report included mostly maintenance recommendations, the life expectancy for the home's various systems and components, and minor imperfections. These are useful to know about.

But the issues that really matter fall into four categories:

- 1. major defects, such as a structural failure;
- 2. things that can lead to major defects, such as a small leak due to a defective roof flashing;
- 3. things that may hinder your ability to finance, legally occupy, or insure the home if not rectified immediately; and
- 4. safety hazards, such as an exposed, live buss bar at the electrical panel.

Anything in these categories should be addressed as soon as possible. Often, a serious problem can be corrected inexpensively to protect both life and property (especially in categories 2 and 4).

Most sellers are honest and are often surprised to learn of defects uncovered during an inspection. It's important to realize that sellers are under no obligation to repair everything mentioned in your inspection report. No house is perfect. Keep things in perspective as you move into your new home.

And remember that homeownership is both a joyful experience and an important responsibility, so be sure to call on your InterNACHI Certified Professional Inspector to help you devise an annual maintenance plan that will keep your family safe and your home in good condition for years to come.

REPLACE THIS VIDEO OF ME WITH YOU talking about what r...



Share



Anarumo Inspections Page 107 of 108

STANDARDS OF PRACTICE

Anarumo Inspections Page 108 of 108