
Building No.	Street		City		Zip	Date of Inspection	Number of Pages
132	Quail Way		Avila Beach		93424	09/25/2025	1 of 8
	PO Box 969	and PEST CO 9, Atascadero, CA 9 / 805-466-8026 fax	3423-0969			ER FIELD. TIVE TO TH LD BE REF ER.	EXPERT IN QUESTIONS
Ordered by: BHGRE   I Juvy Salce	Haven Properties edo	Irene M Cha 132 Quail V	Property Owner and Party of Interest: Irene M Chadwick 132 Quail Way Avila Beach, CA 93424		Report sent to: BHGRE Haven F Mike Oliver 1161 Price Stree Pismo Beach, C	et, #100	
COMPLETE	E REPORT ⊠	LIMITED REPORT	SUPPLEMEN	ITAL REPORT	☐ REINS	PECTION REF	PORT 🗌
General Descript Single story occupied.		exterior; Composition s	shingle roof; Furnisl	ned and	Inspection Tag Posted: WATER HEATE	R CLOSET	
					Other Tags Posted:		
	has been made of the structu  other structures not on the d	ire(s) shown on the diagram ir liagram were not inspected.	n accordance with the St	ructural Pest Cor	ntrol Act. Detached por	ches, detached s	teps, detached
	ean Termites 🗵 Dry bove boxes are checked, it indic	ywood Termites 🛭 cates that there were visible prob	Fungus/Dryrot 🛭 Diems in accessible areas.	Other Fin	dings 🗵 Furth	ner Inspection	
Key: 1 = Subter	rranean Termites 2 = 1	Drywood Termites	3 = Fungus/Dryrot	4 = Other Find	inas 5 = Uni	nown Further Inspe	ction

#### \*\*\*Complete Inspection Report\*\*\*

Diagram not to scale Finding locations approximate



Inspected By:	Bard Kreider	State License No.: _	FR46840	Signature:	
You are entitled to	obtain copies of all reports and complet	tion notices on this property	reported to the Struc	tural Pest Control Board during t	ne preceding two years. To obtain

Building No.	Street	City	Zip	Date of Inspection	Number of Pages
132	Quail Way	Avila Beach	93424	09/25/2025	2 of 8

#### **General Comments**

THIS IS A COMPLETE INSPECTION and includes structure(s) of the property as described on page one of this report. The inspection is limited to visible and accessible areas of the structure(s) drawn in diagram space. Other structures of the property were not included in this report. See the statements on the final page of this report for further information as to the scope of this inspection.

NOTE: Prices quoted on this report reflect all work being completed at the same time. If individual items are requested the price for those items are subject to change to our minimum job price in order to account for the appropriate labor and materials cost. This applies to repair items only.

NOTE: All prices quoted quoted on this report reflect cash/check pricing, any credit or debit card payments made will incur a 3% processing fee.

NOTE: This structure was furnished and occupied at the time of this inspection. Areas covered by normal storage or furnishings were not accessible for visual inspection. Further inspection will be completed upon request after storage has been removed by others. There may be a fee charged for this reinspection.

NOTE: The substructure framing below the mobile home was completely inaccessible for inspection due to insulation and the insulation cover. If further inspection of framing is desired, all or desired portions of the insulation and the cover must be removed to allow for access to inspect these areas. A reinspection fee will be charged.

NOTE: Earth to wood contact exists at treated wood pads and/or supports below the structure. This appears to comply with local building code for mobile home installations. No correction needed at this time. Periodic inspection of these wood members is recommended.

NOTE: The fumigation process will involve workman walking on the metal roof to install and remove tarps. A specific roof release must be obtained from the property owner prior to fumigation. The Fumigation crew will exercise reasonable caution in walking on the roof. However, Key Termite and Pest Control, Inc. nor its fumigator assumes any liability for damages to the roof caused by the fumigation process.

NOTE: Portions of the eaves were inaccessible due to boxed eave construction.

Building No.	Street	City	Zip	Date of Inspection	Number of Pages
132	Quail Way	Avila Beach	93424	09/25/2025	3 of 8

This is a separated report which is defined as Section I/Section II conditions evident on the date of the inspection. Section I contains items where there is visible evidence of active infestation, infection or conditions that have resulted in or from infestation of infection. Section II items are conditions deemed likely to lead to infestation or infection but where no visible evidence of such was found. Further inspection items are defined as recommendations to inspect area(s) which during the original inspection did not allow the inspector access to complete the inspection and cannot be defined as Section II.

#### **Description of Findings**

# SECTION: I

#### **SUBTERRANEAN TERMITES**

NOTE: DUE TO THE RISE IN COST OF MATERIALS, ALL PRICES FOR REPAIR ITEMS ARE SUBJECT TO CHANGE.

Finding: 1A Evidence of Subterranean Termite infestation was found at the exterior and indicates an

infestation in the soil below the structure.

Recommendation: Chemically treat the soil in areas of Subterranean Termite activity using Taurus SC

(fipronil). In addition, an application will be made to the soil adjacent to the exterior wall around the complete perimeter of the structure. Holes may be drilled through concrete, paving or masonry adjacent to the foundation in areas such as, but not limited to; patios, sidewalks, porches and driveways, to allow for chemical treatment of the soil below. We will exercise reasonable caution when drilling but assume no liability for damage to hidden plumbing, electrical, or other utility below these areas. The location of such utilities should be identified prior to our arrival. Regardless of locations of Subterranean Termite

infestation found, control of the entire structure is guaranteed. Control is guaranteed by Key Termite and Pest Control for a period of 5 years from the date of treatment. NOTE: Any exterior storage must be moved away at least 3 feet from the perimeter of the

structure prior to our arrival.

Price: \$1,221.00

Finding: 1B Subterranean Termite damage was noted at the trim.

Recommendation: Remove and replace the damaged wood members noted.

Note: Cost included in item 3D. Price: Included as noted in recommendation.

#### **DRYWOOD TERMITES**

Finding: 2A Evidence of Drywood Termite infestation was found at the exterior and appears to extend

into inaccessible areas of the structure.

Recommendation: Seal the structure and fumigate with a gas lethal to Drywood Termites (Sulfuryl Fluoride).

All occupants and pets must vacate the structure until the fumigation is complete. This company will exercise reasonable caution, but cannot be held responsible for damage to plants, TV antennas or roofing due to the fumigation. Further terms and instructions will be supplied upon request or upon scheduling of the fumigation. Information may also be

obtained from the fumigation page on our website at www.keytermite.com
\*\*\*Fumigations are guaranteed for 5 years from the date completed\*\*\*

Building No.	Street	City	Zip	Date of Inspection	Number of Pages
132	Quail Way	Avila Beach	93424	09/25/2025	4 of 8

Note: NOTE: All plant growth at the perimeter of the structure must be cut back to allow 12"-18"

of clearance for tarp fumigation. Tree branches must be cut back 4 - 5 feet up from the roof surface if overhanging onto the roof. Plant growth growing on or against the structure which cannot be adequately pulled away from the structure may be covered by the tarp and die as a result of the fumigation process. Additional charges may apply if these preparations are not completed prior to the fumigation date. Labor will be billed at \$135 per

hour for preparations.

NOTE: To minimize escape of the fumigant through the soil, remove all ground cover (bark, gravel, decorative rock, etc.), remove storage away from building perimeter and wet the soil adjacent to the structure prior to the fumigation. Labor will be billed at \$135 per hour for preparations. will be billed to the homeowner for ground preparations completed

by Key Termite and Pest Control.

Price: \$1,764.00

Finding: 2B Drywood Termite damage was found at the rafter end.

Recommendation: Remove and replace the damaged portion of the rafter end as needed.

Note: Cost included in item 3D.

Price: Included as noted in recommendation.

Finding: 2C Minor Drywood Termite damage was found at the fascia.

Recommendation: Repair the minor damage of the wood member with a wood filler.

Price: \$94.00

Finding: 2D Evidence of Drywood Termite infestation was found at the substructure.

Recommendation: Refer to item 2A for recommendation. Cost included in item 2A.

Price: Included as noted in recommendation.

#### **FUNGUS/DRYROT**

Finding: 3A Fungus damage was found at the fascia of the eave area.

Recommendation: Replace the fungus damaged portions of fascia as needed.

Note: If damage is found to be extending into inaccessible areas, a supplemental report may be

issued with further findings, recommendations, and costs.

Price: \$2,244.00

Finding: 3B Fungus damage was found at the rafter end of the eave area.

Recommendation: Replace the fungus damaged portions of the rafter end as needed.

Price: \$408.00

Finding: 3C Fungus damage was found at the wood siding.

Recommendation: Remove and replace the damaged portions of the wood siding and add trim. Efforts will be

made to match existing siding material type. Replacement materials may not match existing type. Additional costs may apply if damage extends into inaccessible wood

members.

Price: \$612.00

Finding: 3D Fungus damage was found at the exterior wood trim.

Recommendation: Replace the damaged portions of the trim as necessary.

Note: If damage is found to be extending into inaccessible areas, a supplemental report may be

issued with further findings, recommendations, and costs.

Price: \$2,142.00

Building No.	Street	City	Zip	Date of Inspection	Number of Pages
132	Quail Way	Avila Beach	93424	09/25/2025	5 of 8

Finding: 3E Fungus damage has occurred to the sheathing at the skylight due to leakage at the gutter.

Recommendation: Remove and replace the damaged portions of the sheathing at the skylight as needed to

eliminate the fungus infection. Make necessary corrections to the gutter to eliminate the

excessive moisture condition.

Note: If damage is found to be extending into inaccessible areas, a supplemental report may be

issued with further findings, recommendations, and costs.

Price: \$1,632.00

Finding: 3F Fungus damage was found at the skirt.

Recommendation: Remove and replace the damaged portions of the skirt as needed to eliminate the fungus

infection and damage.

Price: \$1,734.00

Finding: 3G Fungus damage was found at the wood siding.

Recommendation: Remove and replace the damaged portions of the wood siding. Efforts will be made to

match existing siding material type. Replacement materials may not match existing type.

Additional costs may apply if damage extends into inaccessible wood members.

Note: If damage is found to be extending into inaccessible areas, a supplemental report may be

issued with further findings, recommendations, and costs.

Price: \$306.00

OTHER FINDINGS

Finding: 4A Dampwood Termite damage was found at the fascia at the skylight.

Recommendation: Remove and replace or reinforce the Dampwood Termite damaged wood members.

Note: Cost included in item 3A.

Price: Included as noted in recommendation.

# SECTION: II OTHER FINDINGS

Finding: 4B An excessive moisture condition exists due to leakage at the roof at the skylight. Recommendation: Make the necessary corrections to eliminate the excessive moisture condition.

Note: Cost included in item 3E.

Price: Included as noted in recommendation.

Finding: 4C Moisture damage was noted at the sheathing and appears to have been caused by a

previous moisture condition.

Recommendation: Remove and replace the damaged portions of the sheathing as needed.

Price: \$408.00

Finding: 4D Earth to wood contact exists at the skirt.

Recommendation: Lower the adjacent soil grade as necessary to eliminate the earth to wood contact.

Price: \$470.00

Finding: 4E Moisture damage was noted at boxed eave.

Recommendation: Remove and replace or fill the damaged boxed eave.

Price: \$306.00

Finding: 4F Loose cellulose debris (wood scraps/paper) were found in the substructure area. This may

lead to Subterranean termite infestation.

Building No.	Street	City	Zip	Date of Inspection	Number of Pages
132	Quail Way	Avila Beach	93424	09/25/2025	6 of 8

Recommendation: Remove and dispose of all loose cellulose debris from under the dwelling of such size that

it will not pass through an ordinary garden rake.

Price: \$329.00

Finding: 4G An excessive moisture condition exists due to the dryer venting into the substructure area.

Recommendation: Install the proper dryer vent line to the exterior of the structure.

Price: No Bid offered at this time. Owner should contact appropriate tradesman to complete

recommended corrections.

Finding: 4H The toilet was found to be loosely bolted to the floor. This creates a potential source of

leakage.

Recommendation: Reset the toilet using a new wax seal and bolts. Additional costs may apply if the toilet

flange is found to be damaged or if existing supply line/valve cannot be reused.

Price: No Bid offered at this time. Owner should contact appropriate tradesman to complete

recommended corrections.

Section I Total: \$12,157.00 Section II Total: \$1,513.00

Grand Total: \$13,670.00 (totals include items priced above only)

Building No.	Street	City	Zip	Date of Inspection	Number of Pages
132	Quail Way	Avila Beach	93424	09/25/2025	7 of 8

#### Informational Items

INFORMATIONAL ITEMS listed below are items where the inspector wishes to inform parties in interest about questionable conditions or report exclusions. These disclosures may be of concern to parties in interest, but did not qualify as a required finding or correction as defined by the Structural Pest Control Act. All parties in interest should satisfy themselves as to these disclosures prior to the close of escrow.

INFORMATIONAL ITEM> N1: Moisture stains were noted at the wood members of the eave overhang and indicate possible roof leakage. The area was dry at the time of inspection. The stains may be old and the original cause may have already been corrected. The roofing was not inspected by our company. It was not possible to determine active leakage at the time of inspection. If repairs have not been made or cannot be verified, we recommend that a qualified Home Inspector and/or licensed Roofing Contractor be contacted for further evaluation and recommendation.

INFORMATIONAL ITEM> N2: The deck is not attached and was not included in this report.

INFORMATIONAL ITEM> N3: The abutted arbor was not inspected. Parties in interest should satisfy themselves as to this condition prior to the close of escrow.

INFORMATIONAL ITEM > N4: Portions of the exterior eave were not inspected due to the construction of the abutted arbor. Buyer and Seller are to satisfy themselves to this condition prior to the close of escrow.

INFORMATIONAL ITEM> N5: Old Dampwood termite evidence was noted at the exterior Parties in interest should satisfy themselves as to this condition prior to the close of escrow.

INFORMATIONAL ITEM> N6: The steps and landing are not attached and was not included in this report.

INFORMATIONAL ITEM> N7: Moisture stains were noted at the wood members of the patio cover sheathing at the skylight and indicate previous roof leakage. The area was dry at the time of inspection. The stains may be old and the original cause may have already been corrected. The roofing was not inspected by our company. It was not possible to determine active leakage at the time of inspection. If repairs have not been made or cannot be verified, we recommend that a qualified Home Inspector and/or licensed Roofing Contractor be contacted for further evaluation and recommendation.

INFORMATIONAL ITEM> N8: Moisture stains were noted at the wood members of the patio cover and indicate previous roof leakage. The area was dry at the time of inspection. The stains may be old and the original cause may have already been corrected. The roofing was not inspected by our company. It was not possible to determine active leakage at the time of inspection. If repairs have not been made or cannot be verified, we recommend that a qualified Home Inspector and/or licensed Roofing Contractor be contacted for further evaluation and recommendation.

INFORMATIONAL ITEM> N9: Moisture stains were noted at the interior heater closet ceiling and indicate previous roof leakage. The area was dry at the time of inspection. The stains may be old and the original cause may have already been corrected. The roofing was not inspected by our company. It was not possible to determine active leakage at the time of inspection. If repairs have not been made or cannot be verified, we recommend that a qualified Home Inspector and/or licensed Roofing Contractor be contacted for further evaluation and recommendation.

INFORMATIONAL ITEM> N10: Dry moisture stains were noted at the water heater closet and ceiling. It appears to have been caused by a previous leak. This leak may have already been corrected. It was not possible to determine the activity or cause of leakage at the time of inspection.

INFORMATIONAL ITEM> N11: The entry deck is not attached and was not included in this report.

INFORMATIONAL ITEM > N12: Excessive moisture was noted at the substructure due to seasonal weather. No recommendation is needed at this time. Periodic inspection of this area is advised. Buyer and Seller to satisfy themselves to this condition prior to the close of escrow.

Building No.	Street	City	Zip	Date of Inspection	Number of Pages
132	Quail Way	Avila Beach	93424	09/25/2025	8 of 8

- 1. This inspection is limited to the visible and accessible portions of the structure as noted on the diagram only. Although a full diagram may be drawn for reference purposes, all areas may not have been inspected. Please read the entire report to determine the limitations of the inspection. All findings will pertain to infestation and/or infection by wood destroying pests and/or organisms and does not include reference to other structural pests such as, but not limited to; Rats, Mice, Bats, Fleas, Cockroaches, Ants, Etc.. This inspection does not include opinions as to the condition of plumbing, roofing, electrical, gas, heating, air conditioning, or other such structural elements. If such information is desired, we suggest that a qualified Home Inspector and Contractors be contacted. Inspection of fences is not included in this report unless otherwise stated. The exterior surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractors' State License Board.
- 2.The following areas were not inspected, as indicated in Section #1990, paragraph (j) of the Structural Pest Control Act and Rules and Regulations: Portions of furnished interiors concealed by personal property, inaccessible attics, insulated attics, and portions thereof; the interior of hollow walls; spaces between a floor or porch deck and the ceiling or soffit below; stall showers over finished ceilings: such structural segments as porte-cocheres, enclosed bay windows, buttresses and similar areas to which there is no access without defacing or tearing out lumber, masonry and finished work; built-in cabinet work, floor beneath coverings; areas where storage conditions or locks makes inspection impractical; portions of the structure covered by plant growth. The inspector did not move storage or furnishings during inspection. NEITHER KEY TERMITE AND PEST CONTROL, INC. NOR IT'S EMPLOYEES OR SUBCONTRACTORS MAKES ANY GUARANTEE AGAINST FUTURE OR HIDDEN INFESTATION(S), INFECTION(S), OR ADVERSE CONDITION(S) PRESENT BUT NOT EVIDENT AT THE TIME OF INSPECTION(S). Routine inspection does not include opening windows, opening all exterior doors or inspecting interior of cabinets. Further inspection of these areas may be completed upon request and at additional expense.
- 3.CERTIFICATION applies to visible and accessible areas of the structure observed at the time of original inspection. This certification does not constitute a guarantee that parties in interest will not inherit hidden infestations, infections or adverse conditions. Key Termite and Pest Control, Inc. assumes no liability for such hidden conditions. If a problem is discovered that was not disclosed during our inspections, do not disturb the area. Contact our office immediately to inspect the problem area and allow proper determination.
- 4.REINSPECTIONS; "This Company will reinspect repairs done by others within 4 months of the Original inspection. A charge, if any can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs." Consultation appointments will be made upon request. On site appointments will be billed at a minimum of \$45.00 per appointment. Telephone calls to discuss the report findings are no charge.
- 5.The structure was inspected from the ground level only. Portions of the structure that extend more than 10 feet from the ground level were visually inspected only. Accuracy above this point cannot be guaranteed. Wood members showing visible signs of infestation or infection were pick-tested to determine the nature and extent of the finding. The inspector did not get up on the roof to inspect wood members accessible from the roof.
- 6.NOTICE: The structural Pest Control Board encourages competitive business practices among registered companies. Reports on this structure prepared by various companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary company to company. You have a right to seek a second opinion from another company.
- 7.NOTICE: The charge for service that this company subcontracts to another person or entity may include the company's charges for arranging and administering such services that are in addition to the direct costs associated with paying the subcontractor. YOU MAY ACCEPT KEY TERMITE & PEST CONTROL'S BID OR YOU MAY CONTRACT DIRECTLY WITH ANOTHER REGISTERED COMPANY LICENSED TO PERFORM THE WORK. IF YOU CHOOSE TO CONTRACT DIRECTLY WITH ANOTHER REGISTERED COMPANY, KEY TERMITE & PEST CONTROL WILL NOT BE RESPONSIBLE FOR ANY ACT OR OMISSION IN THE PERFORMANCE OF WORK THAT YOU DIRECTLY CONTRACT WITH ANOTHER TO PERFORM.
- 8. This property WAS NOT inspected for the presence or absence of health related molds or fungi. By California Law, we are neither qualified, authorized nor licensed to inspect for health related molds. If you desire information about the presence or absence of health related molds, contact the California Department of Health Related Services. A link may be found in our web site at the following web address http://www.keytermite.com/Realtors/mold.html
- 9.Peticides are the products Key Termite & Pest Control uses to control the target pests listed in your Inspection Report. Pesticides are indespensable tools our industry uses to control disease carrying pests and wood destroying insects, thus protecting your health and property. When properly used, pesticides pose minimal risk to humans or the environment. Your Technician is a State certified applicator whose knowledge is constantly being upgraded through regularly scheduled training sessions. If you have any questions, please call us at: 805-466-2451 or write to: Key Termite & Pest Control, PO BOX 969, Atascadero, CA 93423. Key Termite & Pest Control will not apply any compound not authorized for use in California. Please refer to the Inspection Report above for proposed materials to be used.
- 10.CAUTION: PESTICIDES ARE TOXIC CHEMICALS. Structural Pest Control Operators are licensed and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the State finds that based on existing scientific evidence there are no appreciable risks if proper use conditions are followed or that the risks are outweighed by the benefits. The degree of risk depends upon the degree of exposure, so exposure should be minimized. If within 24 hours following an application you experience symptoms similar to common seasonal illness, comparable to the flu, contact Key Termite & Pest Control (805-466-2451), your physician, and/or your Poison Control Center. For the Poison Control Center, contact the following: (1-800-876-4766). FURTHER INFORMATION: Contact any of the following: Your pest control operator is Key Termite & Pest Control, (805-466-2451); for Regulatory Information call the Structural Pest Control Board (916-561-8708), or write 2005 Evergreen Street, Suite 1500, Sacramento, CA 95815. For answers to your health questions, call the County Health Department; Santa Barbara County Health Dept (805-681-5102); San Luis Obispo County Health Dept (805-781-5940).
- 11. Under the California Mechanics Lien Law any structural pest control company which contracts to do work for you, any contractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractor, laborers or suppliers remain unpaid.
- 12.To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice". Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. It's purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.
- 13.NOTICE: Invoices are due and payable within 30 days. 1.5% per month will be added to account balances beyond 30 days from the date of work completed. This is an annual percentage rate of 18%. (Interest charged persuant to the Robinson-Patman Act). Interest amounts for balances billed to an Escrow Company as a course of a Real Estate sale will be waived up to 4 months from the date of work completed so long as the property remains in escrow. Should an Escrow transaction cancel, the full account balance is due and payable upon the Escrow cancellation date.

# **WORK ORDER AGREEMENT (PAGE 1 OF 2)**

Building No.	Street	City	Zip	Date
132	Quail Way	Avila Beach	93424	09/29/25
	PO Box	E and PEST CONTROL 969, Atascadero, CA 93423-0969 51 / 805-466-8026 fax / 800-548-5599	OPERATO	FIELD. ANY QUESTIONS E TO THIS REPORT BE REFERRED TO
Ordered by:		Property Owner and/or Party of Interest:	Completion sent to:	
BHGRE   Haven Properties   Ire Juvy Salcedo   13		Irene M Chadwick 132 Quail Way Avila Beach, CA 93424	BHGRE Haven Mike Oliver 1161 Price Stre Pismo Beach, O	et, #100

COS	COST FOR WORK RECOMMENDED FOR TERMITE REPORT #: 111761 (please circle desired item numbers)						
	SECTION I				SECT	TION II	SECTION NOT DETERMINED OR FURTHER INSPECTION RECOMMENDED
1A 1B 2A 2B 2C 2D 3A 3B 3C 3D	\$1,221.00 INCLUDED \$1,764.00 INCLUDED \$94.00 INCLUDED \$2,244.00 \$408.00 \$612.00 \$2,142.00	3E 3F 3G 4A	\$1,632.00 \$1,734.00 \$306.00 INCLUDED	4B 4C 4D 4E 4F 4G 4H	INCLUDED \$408.00 \$470.00 \$306.00 \$329.00 NO BID NO BID		
	Total Section	I: \$12	2,157.00		Total Section	II: \$1,513.00	

I HEREBY AUTHORIZE KEY TERMITE & PEST CONTROL TO PERFORM THE FOLLOWING ITEMS: (please list item numbers below)

PLEASE INITIAL HERE	USE SPACE BELOW TO DESCRIBE FURTHER INSTRUCTIONS:
FLEASE INTHAL FIERE	USE SPACE BELOW TO DESCRIBE FURTHER INSTRUCTIONS.

Thank you for choosing Key Termite and Pest Control for your pest control needs. Feel free to call our office to answer any questions you may have concerning the Inspection Report, the Work to be completed or the Terms of this Contract. PLEASE INITIAL THIS PAGE AND RETURN BOTH PAGES OF THIS AGREEMENT TO OUR OFFICE.

# **WORK ORDER AGREEMENT (PAGE 2 OF 2)**

Building No.	Street	City	Zip	Date
132	Quail Way	Avila Beach	93424	09/29/25

\*\*\*\*\*State law requires that you be given the following information\*\*\*\*\*

CAUTION-PESTICIDES ARE TOXIC CHEMICALS. Structural Pest Control Companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation Agency and the United States Environmental Protection Agency. Registration is granted when the State finds that, based on existing scientific evidence, there are no appreciable risks if proper use conditions are followed or that the risks are outweighed by the benefits. The degree of risk depends upon the degree of exposure, so exposure should be minimized." If within 24 hours following application you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or Poison Control Center and Key Termite and Pest Control, Inc. (805) 466-2451 immediately. For further information contact any of the following:

For health questions: The County Health Department (805) 781-5500 For application information: The County Agricultural Commissioner (805) 781-5910 For regulatory information: The Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, CA 95815-3831, (916) 561-8700

Prices for structural repair include replacement of damaged wood members visible at the time of inspection only. Structural improvements necessary to upgrade the existing construction to current building code or corrections of hidden conditions exposed during repairs will be completed at additional expense. This company assumes no liability for improper or non compliant structure(s) on which we complete repairs. Parties in interest should contact the county building department and/or qualified home inspector concerning the structures' compliance with building code. The property owner is responsible to pay for all costs associated with building permits and engineering fees needed and is not included in the repair bid. There will also be additional costs if upgrades are required by the local building department prior to or during the course of repairs. These costs should be determined and appropriated by parties in interest prior to the close of escrow. Reasonable effort will be taken to match existing material being replaced with the same or similar type. However, Key Termite and Pest Control Inc. does not guarantee new material will match the existing material. Special order materials may delay the completion of recommended work and certification date. Painted wood members that are replaced by this company (except stained or varnished wood, and redwood decking) will be painted unless otherwise requested and will be billed as quoted in report recommendation. This company makes no guarantee of color match. The buyer or seller is responsible to choose paint color prior to commencement of repairs. Structural repair recommendations not priced above may be completed upon request and will be billed at \$85.00 per hour which will include basic construction materials (doors, windows and redwood deck materials would be additional). Key Termite and Pest Control, Inc. nor its employees or subcontractors assumes no liability for distribution of molds, dusts or other allergens as a result of repairs performed to the property. Parties in interest should contact a Certified Industrial Hygienist for further information and advice prior to commencement of repairs. We will exercise reasonable caution with adjacent plant growth during the completion of repairs, however, neither Key Termite and Pest Control, Inc. nor its employees or subcontractors assumes any liability for damages to adjacent plant growth as a result of the completion of repairs. Prices authorized after 30 days from the date of issuance of the inspection report are void and must be re-bid. Our minimum job fee is \$145.00 (to cover trip costs and completion notice paperwork). If repairs completed total less that \$145.00, we will bill the \$145.00 minimum fee.

Under the California Mechanics Lien Law any structural pest control company which contracts to do work for you, any contractor, subcontractor, laborer, supplier, or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractor, laborers, or suppliers remain unpaid.

To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice." Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of person(s) who may have a right to file a lien against your property if they are not paid.

NOTICE: Invoices are due and payable within 30 days. 1.5% per month will be added to account balances beyond 30 days from the date of work completed. This is an annual percentage rate of 18%. (Interest charged pursuant to the Robinson-Patman Act). Interest amounts for balances billed to an Escrow Company as a course of a Real Estate sale will be waived up to 4 months from the date of work completed so long as the property remains in escrow. Should an Escrow transaction cancel, the full account balance is due and payable upon the Escrow cancellation date.

By executing this work authorization contract, customer acknowledges that he or she has been advised of the forgoing and has had the opportunity to consult with a qualified professional.

UNLESS OTHERWISE STATED IN THE INSPECTION REPORT OR THIS CONTRACT, ALL WORK COMPLETED BY KEY TERMITE AND PEST CONTROL IS GUARANTEED FOR TWO YEARS FROM THE DATE OF COMPLETION AGAINST DEFECTS IN MATERIALS AND/OR WORKMANSHIP. ELIMINATION OF REPORTED WOOD DESTROYING PESTS BY STRUCTURAL FUMIGATION AND "PERIMETER PLUS" SUBTERRANEAN TERMITE TREATMENT IS GUARANTEED FOR FIVE YEARS FROM THE DATE OF COMPLETION.

BY SIGNING BELOW, I ACKNOWLEDGE THAT I HAVE READ, UNDERSTAND AND AGREE TO THE TERMS OF THIS CONTRACT AND THE REPORT IT REFERS TO.

BY OWNER/AGENT/BUYER	Key Termite & Pest Control					
PHONE:	By:	Bard Kreider				
		B. C.				
SIGNATURE:	Signature:					
PRINT NAME:	Lic. #:	FR46840				
NOTE: WORK WILL NOT COMMENCE UNTIL DELIVERY OF YOUR WOOD DESTROYING PESTS AND ORGANISMS REPORT. FOR DETAILS						