



Your Sewer Inspection Report

Prepared for: Caren Ong

Inspected by: Aaron Venzor, (858) 257-2888

Date: 08/06/2026

Click [here](#) to view your electronic report and videos.

434 L Street, Chula Vista, CA 91911

ABS under the house is open and in serviceable condition. ABS outside of the house is damaged (area was located and marked with a flag, about 4' deep). Cast Iron outside of the house has buildup which is restricting the visibility. Clay outside of the house to the city main is open and in serviceable condition.

Recommendations:

- 1) Recommend further evaluation and repair of all damaged ABS as needed by a reputable plumbing contractor.
- 2) Recommend hydro jetting by a reputable plumbing contractor to remove buildup and help prevent backups.
- 3) Recommend a re-inspection after the hydro jetting has been done.
- 4) Recommend extending main line cleanout for under the house for the right side restroom by a reputable plumbing contractor to allow proper access to the entire sewer line.
- 5) Recommend further evaluation and repair of the vent line for right side restroom by a reputable plumbing contractor.



No title

434 L St 91911 - Job Location



No title

Two way cleanout access in the front yard



No title

Small roof vent access



2026-08-06-14-04-44

Damaged connection on small vent line



2026-08-06-13-51-47.mp4-thumb

End of the main line under the house



2026-08-06-14-02-17.mp4-thumb


Branch line connection to main line under house



2026-08-06-13-49-19
Damaged ABS to Cast Iron connection



2026-08-06-13-46-34
Heavy buildup in the Cast Iron



2026-08-06-13-49-49
Cast Iron to Clay connection



2026-08-06-13-45-55
Connection to the city main



No title
Flag marking an area of the damaged ABS (about 4' deep)



2026-08-06-13-44-50



2026-08-06-13-51-47



2026-08-06-14-02-17

Maintenance Tips

- Do not flush paper towels, feminine products, or grease down the toilet.
- Limit the use of the garbage disposal and always run water for several minutes after use.
- Use screens on drains in the tub and shower to catch hair and other debris from going down the drain.
- Do not pour grease or oil down the drain.
- Have The Sewer Pros clean your sewer line annually to prevent mainline backups.

Helpful Information

- Clay sewer lines are prone to root growth due to the connections not being completely sealed. Cabling the sewer on an annual basis is recommended for Clay sewer lines to help keep the roots under control and prevent sewer backups.
- Cast Iron and PVC sewer lines are sealed at the connections and should not allow roots into the line unless they are damaged. Roots in Cast Iron and PVC will generally warrant a repair of the damaged area but they can be managed with a foaming root killer (Root-X) to help prolong the life of the sewer. This is only considered a temporary solution because repair will ultimately be required (especially with Cast Iron).
- Cast Iron & Clay were used for almost all sewer lines until around 35 years ago when PVC became the material of choice for most plumbers. We are still using PVC today for sewer lines.

Disclaimer

The Sewer Pros, LLC does not offer any guarantee or warranty as part of the sewer camera inspection. Our sewer camera inspects the underground main sewer lateral waste line. This line ordinarily runs underneath the property's structure and grounds before connecting to the city's main sewer line or the property's septic system. Typically, this is the section of the main line the property owner is responsible for maintaining. The inspector uses a camera to perform a visual inspection of the accessible main sewer line from no more than three access points. It is our goal to inspect the entire main sewer line however; obstructions, debris, roots, buildup, damage, or partial access can all limit the scope of the inspection.

The inspection report is based solely on the technician's opinion with the information and access they have available at the time of the inspection. The inspection report and findings are limited to the date and time of the inspection only as sewer lines are subject to condition changes that may be immediate or progress over a period of time. No secondary lines (kitchen, laundry, etc.) will be inspected or included as part of the standard report. Drain lines that are 2" in diameter or smaller and traps that are less than 6" in diameter will also not be inspected. Secondary sewer lines can be inspected upon request for an additional fee.

Areas that have been located and marked are for reference only and may not be exact due to signal interference and/or depth of the sewer line. All damaged areas may not be marked and damage may extend beyond the marked areas (especially in Cast Iron). The Sewer Pros always recommend having the repair

contractor re-locate prior to repair which will help insure accuracy.