
# Maffei Property Inspections Property Inspection Report



120 Wine Blossom Dr, Chico, CA Inspection prepared for: All & Debta Ottone Real Estate Agent: Bankara Weiber Condwell Banker Driff ou Really

Date of Inspection: 3/16/2018 Time: 9am
Age of Home: approx 14 yrs Size: approx 1550 sf
Weather: Sunny and Dry
For the purpose of this report the front of the home faces west. It rained the day before the inspection.

Inspector: David Maffei
236 W East Ave. Suite A, PMB 178, Chico, CA 95926
Phone: 530-588-2826

Email: david@maffeipropertyinspections.com www.MaffeiPropertyInspections



Received/Reviewed

STATE LECTION

#### Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expenses to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all of the pages of the report as the summary alone does not explain all the issues. All repairs must be done by a licensed &bonded trade or profession. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

	eipis, warranties and permits for the work done.
Grounds Electrical	• Reverse polarity noted in the outlet on the northeast support post for the back patio roof. ADDALA
Roof Condition	• Evidence of hail damage noted. • Recommend contacting a licensed roofing contractor for further evaluation. • A 150 ( A 10)
Flashing	• The bottom edges of the toof jacks around the bathroom plumbing vents have raised up. Recommend nailing down.
Structure	• Moisture stains noted around the dryer vent where it passes through the roof. Moisture stains were also found on the HVAC plenum below this area.
Electrical A	Open junction box noted next to the chimney chase.  Recommend covering.
Insulation Condition	There was space around the whole house fan where the insulation was missing. It may have been pulled back to install the fan. Recommend replacing.
Strapping AND	The water heater was braced, however, not in accordance with current standards. The method used may have been acceptable at time of construction. Recommend upgrading to today's water heater straps.
Dishwasher	Recommend installing a high loop in the dishwasher drain line.
Dryer Vent	• Recommend having vent pipe cleaned. VDDC-60 ADD
	Grounds Electrical  Roof Condition  Flashing  Structure  Electrical  Insulation Condition  Strapping  Dishwasher

## Inspection Details DEFINITIONS

Apparent Conditions: Systems and components are rated as follows:

Satisfactory (Sat.)- Indicates the component is functionally consistent with its original purpose but may show signs of normal wear and tear and deterioration.

Fair- indicates the component could require repair or replacement within five years.

Poor- Indicates the component will need repair or replacement now or in the very near future.

N/A- Not applicable or the component is not present.

None- Not present.

#### 1 Attendance

In Attendance: Client present • Buyer Agent present

#### 2. Home Type


Home Type: Single Family Home • Single Story • Attached 2 Car Garage

#### Occupancy

Occupancy: Occupied - Furnished. Furniture and personal items can restrict view of the home. • The utilities were on at the time of inspection.

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 120 Wine Blossom Dr. Chico, CA Maffer Property Inspections Grounds 1. Driveway and Walkway Condition Materials: Concrete Driveway Noted Χ Concrete Walkway Noted Observations: · Appeared functional at time of inspection. 2. Grading Fair Poor NA None Observations: Χ • The exterior drainage is generally away from foundation. 3 Vegetation Observations Fair Observations: Х Tree branches overhanging roof and/or against siding. Trim trees that are in contact or proximity to home, as branches can abrade siding and damage · Maintenance Tip: When landscaping keep plants, even at full growth, at least a foot (preferably 18 inches) from house siding and windows. Keep trees away from foundation and roof. Plants in contact or proximity to home can provide pathways to wood destroying insects and abrade and damage siding, screens and roofs. 4. Patio and Porch Deck Observations: Х Appeared functional at time of inspection Material: Concrete Stairs & Handrail Poor NΑ None Х 6. Patic and Porch Condition Materials: The patio/porch roof is the same as main structure. 7. Balcony NΑ 8 Patio Enclosure Fair Poor NΑ Х 9. Grounds Electrical Fair Observations: X · Reverse polarity noted in the outlet on the northeast support post for the

back patio roof.



## 10 GFCI

	Sat.	Fair	Poor	N/A	None	
1						Observations:
1				1	1 1	
1	X		İ	1	1 1	• GFCI tested functional at time of inspection.
- 3			:	1		


## 11. Main Gas Valve Condition

	Sat.	Fair	Poor	NΑ	None	
1		l				Materials: Located on the south side of home.
	Х					Observations:
		<u> </u>	L	<u> </u>		American Africa Strain

· Appeared functional at time of inspection.

## 12, Plumbing

Sat.	Fair	Poor	₩A	None	<b>5</b> 1
					Observations:
	Х				<ul> <li>Appeared functional at time of inspection.</li> </ul>
1 1	_ ^				- Appeared injectional at time of inspection



## 13. Exterior Faucet Condition

	 , 001	14/3	1	Observations:
X				<ul> <li>Appeared functional at time of inspection.</li> </ul>

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 120 Wine Blossom Dr, Chico, CA Maffei Property Inspections **Exterior Areas** 1. Doors Sat. Observations: Χ · Appeared functional at time of inspection. 2. Window Condition Poor Observations: Χ · Appeared functional at time of inspection. 3. Siding Condition Poor Materials: Material: Fiber-cement Χ Observations: Appeared functional at time of inspection. · Caulk and seal all gaps, cracks and openings. 4. Eaves/Facia/Trim Observations: Χ · Appeared functional at time of inspection. 5. Exterior Paint Poor Observations: Χ Appeared in functional at time of inspection.

Maffei Property Inspections 120 Wine Blossom Dr, Chico, (
Garage
1. Roof Condition  Sat. Fair Poor N/A None Materials: Decling in the cases of project structure.
Materials: Roofing is the same as main structure.  X Observations:
See roof section for comment.
2. Walls/Firewall Sat. Fair Poor N/A None Carterian Common
X Observations:  Appeared functional at time of inspection.
3. Fire door
Sat. Fair Poor N/A None Observations:
Fire door could not be verified, but all indications are that it is a fire rated
door.
4. Floor Condition  Sat. Fair Poor NA None Materials: Concrete floors noted.
X Observations:
Appeared functional at time of inspection.
5. Rafters & Ceiling  Sat.   Fair   Poor   NA   None
X Appeared functional at time of inspection.
6. Electrical Sat. Fair Poor N/A None Col.
Observations:  • Appeared functional at time of inspection.
7. GFCI
Sat. Fair Poor NA None Observations:  X   GFCI appeared functional at time of inspection.
8. 240 Volt
Sat, Fair Poor N/A None
With the state of
9. Door(s)satFairPoorN/ANone
Observations:  Appeared functional at time of inspection.
10. Garage Door Condition
Sat. Fair Poor N/A None Materials: Metal X   Observations:
• Appeared functional at time of inspection.
11. Garage Opener Status
Sat. Fair Poor NA None Observations:  X
X Appeared functional at time of inspection.

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 Maffei Property Inspections 120 Wine Blossom Dr, Chico, CA 12. Garage Door's Reverse Status Poor N/A None Observations: Χ · Appeared functional at time of inspection. 13. Ventilation Fair Poor NΆ None Χ 14, Vent Screens Fair Poor N/A None Χ 15. Cabinets Fair NΑ None Χ 16. Counters Fair Poor NΑ None Χ 17. Wash Basin None Χ

Page 7 of 29

#### Roof


## 1. Roof Condition

Sat.	Fair	Poor	N/A	None
		Х		

Materials: Roof was inspected from ontop the roof. Materials: Asphalt shingles noted.

Observations:

Evidence of hail damage noted.
Recommend contacting a licensed roofing contractor for further evaluation.



Evidence of hail damage

## 2. Flashing

Sat.	Fair	Poor	N/A	None
	Y			
1	/\	1	İ	l

Observations:

• The bottom edges of the roof jacks around the bathroom plumbing vents have raised up. Recommend nailing down.



## 3. Chimney

	Sat.	Fair	Poor	N/A	None
-	X				
1	· * `				

Observations:

· Appeared functional at time of inspection.

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 Maffei Property Inspections 120 Wine Blossom Dr, Chico, CA 4. Spark Arrestor Poor N/A None Observations: Χ · Appeared functional at time of inspection. 5. Sky Lights Fair Poor N/A None Х 6. Vent Caps Fair Poor N/A None Observations: Χ · Appeared functional at time of inspection. 7. Gutter Fair Poor NA None Observations: Χ Appeared functional at time of inspection. · Recommend adding extensions to downspouts to direct water away from foundation.

Page 9 of 29

#### Attic

#### 1. Access

Sat.	Fair	Poor	N/A	None
Х				

Observations:


- Appeared functional at time of inspection.
- Scuttle Hole located in/on: Laundry
- Access to much of the attic space is limited by the framing and duct work.

#### 2. Structure

Sat.	Fair	Poor	N/A	None
	X			

Observations:

• Moisture stains noted around the dryer vent where it passes through the roof. Moisture stains were also found on the HVAC plenum below this area.



Moisture stains on plenum

#### 3. Ventilation

Sat.	Fair	Poor	NΑ	None
Х				

Observations:

- Under eave soffit inlet vents noted.
- · Gable louver vents noted.

#### 4. Vent Screens

Sat.	Fair	Poor	N/A	None
Х				

Observations:

Appeared functional at time of inspection.

#### 5. Duct Work

Sat.	Fair	Poor	N/A	None	
Х	-				

Observations:

- Appeared functional at time of inspection.
- · Insulated flexible ducting installed.

#### 6. Electrical

Sat.	Fair	Poor	N∕A	None
	Х			

Observations:

Open junction box noted next to the chimney chase. Recommend covering.



Open junction box

## 7. Attic Plumbing

Sat.	Fair	Poor	N⁄Α	None
X				

Observations:

- · Appeared functional at time of inspection.
- ABS plumbing vents

## 8. Insulation Condition


Sat.	Fair	Poor	N/A	None
	Х			

Materials: Loose fill insulation noted.

Depth: Insulation averages about 14-16 inches in depth

Observations:

· There was space around the whole house fan where the insulation was missing. It may have been pulled back to install the fan. Recommend replacing.



Missing insulation

## 9. Chimney

Sat.	Fair	Poor	N/A	None	
	Х				

Observations:

- View restricted by duct work and framing.Appeared functional at time of inspection.

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 Maffei Property Inspections 120 Wine Blossom Dr. Chico, CA 10. Exhaust Vent Observations:

Not visible. Fair Poor N/A Χ Page 12 of 29

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 120 Wine Blossom Dr, Chico, CA Maffei Property Inspections Slab Foundation 1. Slab Foundation Observations: Χ • View of the slab foundation was obstructed by the floor coverings. 2. Foundation Perimeter Poor Observations: · Appeared functional at time of inspection, where visible. 3. Anchor Bolts Fair Χ

120 Wine Blossom Dr, Chico, CA

#### Electrical


Service Commence	2009	A STATE OF THE PARTY OF THE PAR	State of the	0.000	694,0535
1 F	223410	48.0	100	200	
	100		7 21	200	

Sat.	Fair	Poor	N/A	None
X		l		l

Location: Main Location: South side of home.

Observations:

· Appeared functional at time of inspection.



## 2. Main Amp Breaker

	Sat.	Fair	Foor	N/A	None	_
ſ						V
1	X					• ]

bservations:

200 amp

#### 3. Breakers in off position

	Sat.	rair	Poor	N/A	None	<b>○</b> 1
į						Observations:
	Χ					• 0

#### 4. Cable Feeds

Sat.	Fair	Poor	WA	None
	Х			
i				1

Observations:

- There is an underground service lateral noted.
  Appeared functional at time of inspection.

#### 5. Breakers

Sat.	Fair Poor		N/A	None	
Х					

Materials: Copper Romex cable noted. Observations:

· Appeared functional at time of inspection.

#### 6. Fuses

Sat.	Fair	Poor	N/A	None
			X	
1	•	1		1

120 Wine Blossom Dr. Chico, CA


#### Heat/AC

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

1. Heater Condition
Sat. Fair Poor NA None Materials: Located: Attic Materials: Gas fired forced hot air. Observations:  • Appeared functional at time of inspection. • Make: Bryant
2. Heater Base
Sat Fair Poor NVA None  X Observations: Appeared functional at time of inspection.
3. Enclosure
Sat. Fair Poor N/A None  Observations:  Appeared functional at time of inspection.
4 Venting
Sat. Fair Poor N/A None  X   Observations:  • Appeared functional at time of inspection.
5. Gas Valves
Sat. Fair Poor N/A None    X
6. AC Compress Condition
Sat. Feir Poor N/A None Compressor Type: Electric Location: The compressor is located on east side of home.  Observations:  • Make: Lennox • Because outside temperature was less than 65 degrees fahrenheit the AC

was not tested.



Ref			

Sat.	Fair	Poor	N/A	None	01 11
					Observations:
X					<ul> <li>Appeared functional at time of inspection.</li> </ul>

#### 8. Air Supply

Sat.	Fair	1,00	N/A	None	01 "
			Ī		Observations:
		3	ĺ		A I I I I I I I I I I I I I I I I I I I
1 7 1		1	[		<ul> <li>Appeared functional at time of inspection.</li> </ul>
		L	<u>L</u>		· · · · · · · · · · · · · · · · · · ·

#### 9. Registers

Jai.	र था	POU!	IVA	MONE	A to the second of the second
-	1				Observations:
	1	i .			
1 V	i	Į.	Į.	1 1	- Annagrad functional at time of increation
	1	i	ŧ	ŧ 1	<ul> <li>Appeared functional at time of inspection.</li> </ul>
Ĺ	1	1	f	L	

#### 10. Filters

<b>581</b> ,	ran	POOR	IWA	LKM6	1 47 5 4 3 5 mag says a sa	
			1		Location: Located in a filter grill in a hallway.	
1		ł	1	1 1	Education: Educated in a mich gins in a nativay,	
l Y			1	1 1	Channistians:	
		1	ł		Observations:	
L	L					

• MAINTENANCE: The air filter(s) should be inspected at least monthly and cleaned or replaced as required. There are two types of filters commonly used: (1) Washable filters, (constructed of aluminum mesh, foam, or reinforced fibers) these may be cleaned by soaking in mild detergent and rising with water. Or (2) Fiberglass disposable filters that must be REPLACED before they become clogged. Remember that dirty filters are the most common cause of inadequate heating or cooling performance.

#### 11 Thermostats

	Sat.	Fair	Poor	N/A	None	A 1
ı						Observations:
	Х					<ul> <li>Location: Hallway.</li> </ul>
		<del></del>	· · · · · · · · · · · · · · · · · · ·		h	<ul> <li>Appeared functional at time of inspection</li> </ul>

#### Water Heater

The second second second	er Heal	S28400-234-2360	100000000000000000000000000000000000000	
BOOK STORES IN THE BUILDING		Market Company		
6 PR 6 PR 9 PR 8 PR 9 PR 9 PR 9 PR 9 PR 9 PR 9		1000		

Sat. Fair Poor N/A None

Х

Heater Type: Gas.


Location: Water heater located in garage.

Observations:

- · Appeared functional at time of inspection.
- Make: State

40 gallons

· Water heater appears to be original to home.



2. E	lase				
Sat.	Fair	Poor	N/A	None	Observations:
Х					Appeared functional at time of inspection.
	1	<u> </u>	<u> </u>		The Appeared Infictional at time of inspection.
9 L	ملمما	. c.	مامما		
Sat.	leate Fair	Poor	UIUSI NA	De-Established Street	
Sat.	T an	FOOT		None	
			Х		
Marandado	hian hikang haliba	chischerrebrosekolen	erusioner auchen	december versions	
4. C	omb	usio	n		
Sat.	Fair	Poor	N/A	None	· Oboonations
X					Observations:
	<u></u>				Appeared functional at time of inspection.
	'entir				
Sat.	Fair	Poor	N/A	None	Observations:
X					Appeared functional at time of inspection.
MATERIAL SECTION	electron and a second			z koloni v z konok p ko	
6. T	PRV				
Sat.	Fair	Poor	NΑ	None	
Х					Observations:
	<u> </u>				Appeared functional at time of inspection.
110101111111111111111111111111111111111			Contraction of the Contract of	llons	
Sat.	Fair	Poor	N/A	None	Observations:

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 Maffei Property Inspections 120 Wine Blossom Dr. Chico. CA 8. Gas Valve Fair Poor N/A None Observations: Χ · Appeared functional at time of inspection. 9. Plumbina Poor N/A None Observations: Χ · Appeared functional at time of inspection. 10. Overflow Condition Fair Poor N/A None Observations: Χ · Appeared functional at time of inspection. 11. Strapping N/A None Observations: Χ • The water heater was braced, however, not in accordance with current standards. The method used may have been acceptable at time of construction. Recommend upgrading to today's water heater straps.

120 Wine Blossom Dr, Chico, CA

#### Bedrooms

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.
1. Bar
Sat. Feir Poor N/A None
2. Cabinets Sat. Fair Poor N/A None
3 Closets
Sat. Fair Poor NA None Observations:
X Appeared functional at time of inspection.
4. Doors
Sat. Fair Poor N/A None Observations:  X
<u> </u>
5. Electrical Sat. Fair Poor N/A None Observations
Observations:  - Switches and outlets operated properly went tested.
6. Fireplace
Sat. Fair Poor N/A None X
7. Floor Condition
Sat. Fair Poor NA None Observations:
X Appeared functional at time of inspection.
8. Security Bars
Sat. Fair Poor N/A None
9. Smoke Detectors Sat. Fair Poor N/A None Observations
Observations:  The smoke detectors operated during the inspection.
New guidelines advise replacing smoke alarms that are more than 10 yrs old.
10. Wall Condition
Sat. Fair Poor N/A None Observations:
X Appeared functional at time of inspection.

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 Maffei Property Inspections 120 Wine Blossom Dr. Chico, CA 11. Ceiling Condition Poor N/A None Observations: Χ · Appeared functional at time of inspection. 12. Ceiling Fans Poor None Observations: Χ · Appeared functional at time of inspection. 13. Window-Wall AC or Heat Poor N/A None Χ 14. Window Condition Observations: Χ · Appeared functional at time of inspection. 15. Patio Doors None Poor N/A Observations: Χ · Appeared functional at time of inspection. 16, Screen Doors Χ

120 Wine Blossom Dr, Chico, CA

#### Bathrooms

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring.

problems within the walls of under the hoofing
1 Cabinets  Sat. Fair Poor NA None  Chapter Compared Functional at time of inspection.
2. Counters
Sat. Fair Poor N/A None    X
3. Wall Condition
Sat. Fair Poor N/A None Observations:  X
4. Ceiling Condition
Sat. Fair Poor N/A None    X
5. Doors
X Description Observations:  Appeared functional at time of inspection.
6. Electrical
Set. Fair Poor N/A None    X   Switches and outlets appeared functional at time of inspection.
7. GFCI
Sat. Fair Poor N/A None   Observations:  X   Appeared functional at time of inspection.
8. Exhaust Fan
Sat. Fair Poor N/A None Observations:  X
9. Floor Condition
Sat. Fair Poor N/A None  X Observations:  • Appeared functional at time of inspection.
10. Heating
Sat. Fair Poor NA None Observations:
Central heating and cooling noted in these rooms. At the time of the inspection, all appeared to be functioning and in service able condition.

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 Maffei Property Inspections 120 Wine Blossom Dr. Chico, CA 11 Mirrors Poor NΑ None Observations: Χ Appeared functional at time of inspection. 12. Plumbing None Observations: Χ Appeared functional at time of inspection. 13 Security Bars Poor None Χ 14 Showers Observations: Χ Appeared functional at time of inspection. 15. Shower Walls None Observations: Х Appeared functional at time of inspection. 16. Bath Tubs Observations: Χ Appeared functional at time of inspection. 17. Enclosure None Poor N/A Observations: Х Appeared functional at time of inspection. 18. Sinks NΑ None Observations: Х Appeared functional at time of inspection. 19. Toilets None Fair Poor N/A Observations: Χ Appeared functional at time of inspection. 20. Window Condition Observations:

Appeared functional at time of inspection.

Χ

Kitchen The kitchen is used for food preparation and often for entertainment. Kitchens typically include a
stove, dishwasher, sink and other appliances.
1. Cabinets Sat. Fair Poor NA None Observations
Observations:  Appeared functional at time of inspection.
2. Counters Sat. Fair Poor N/A None
Observations:  X
3. Dishwasher Sat. Fair Poor N/A None C
Observations:  • Recommend installing a high loop in the dishwasher drain line.
4. Doors _sat. Fair Poor N/A None_
5. Garbage Disposal Sat. Fair Poor N/A None CL
Observations:  • Appeared functional at time of inspection.
6. Microwave Sat. Fair Poor N/A None C
Observations:  Appeared functional at time of inspection.
7. Cook top condition
Observations:  - Appeared functional at time of inspection.  Gas cook top noted.
8. Oven & Range
Sat. Fair Poor NA None  Observations:  Oven(s): Electric  Appeared functional at time of inspection.
9. Sinks Sat. Fair Poor N/A None Co
Observations:  Appeared functional at time of inspection.
10. Vent Condition  Sat. Fair Poor NA None
Materials: Exterior Vented  Observations:  • Appeared functional at time of inspection.
11. Floor Condition
X Poor N/A None Observations:  Appeared functional at time of inspection.

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 Maffei Property Inspections 120 Wine Blossom Dr. Chico, CA 12. Plumbing Poor N/A None Observations: · Appeared functional at time of inspection. 13. Electrical NΑ None Observations: Χ • Switches and outlets appeared functional at time of inspection. 14. GFCI Poor N/A None Observations: Χ · Appeared functional at time of inspection. 15. Wall Condition Observations: Χ Appeared functional at time of inspection. 16, Ceiling Condition Poor Observations: Χ · Appeared functional at time of inspection. 17. Window Condition Observations: Χ · Appeared functional at time of inspection. 18. Security Bars Fair Poor Х 19. Patio Doors Poor None Fair NΑ Χ

## 20. Screen Doors

Sat.	Fair	Poor	N/A	None
			X	
	L	L	l	ii

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 120 Wine Blossom Dr. Chico, CA Maffei Property Inspections Laundry 1. Cabinets Fair Poor NΑ None Observations: Χ · Appeared functional at time of inspection. 2. Counters Fair Poor NΑ None X 3. Dryer Vent Fair N/A None Observations: Χ Recommend having vent pipe cleaned. 4. Electrical N/Α Observations: Χ Appeared functional at time of inspection. 5. GFCI Fair Poor NΑ None Х 6. Exhaust Fan None Observations: Х Appeared functional at time of inspection. 7. Gas Valves N/A None Observations: Х Appeared functional at time of inspection. 8. Wash Basin NA None Х 9. Window Condition Fair Poor NA Sat. None Χ 10. Floor Condition Poor N/A Observations: Χ · Appeared functional at time of inspection. 11. Plumbing Poor NΑ None Observations: Χ Appeared functional at time of inspection. 12. Wall Condition

Observations:

· Appeared functional at time of inspection.

Х

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 Maffei Property Inspections 120 Wine Blossom Dr, Chico, CA 13. Ceiling Condition Poor N/A None Observations: Х · Appeared functional at time of inspection. 14. Security Bars Fair Poor N/A None Χ 15. Doors Fair Poor N/A None Observations: Χ · Appeared functional at time of inspection.

Page 26 of 29

120 Wine Blossom Dr. Chico, CA

#### Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should

be consulted if you would like further testing.
1. Bar
Sat. Fair Poor N/A None
2. Cabinets
Sat. Fair Poor N/A None
3. Closets
Sat Fair Prov. N/A None
Observations:  Appeared functional at time of inspection.
4. Door Bell Sat. Fair Poor NA None
Observations:  Appeared functional at time of inspection.
5 Daors Sat. Fair Poor N/A None C
Observations:  Appeared functional at time of inspection.
6. Electrical Sat. Fair Poor N/A None
Observations:
• Appeared functional at time of inspection.
7. Security Bars
Sat. Fair Poor N/A None
8. Smoke Detectors
Sat. Fair Poor N/A None Observations:
<ul> <li>X</li> <li>Smoke alarm and CO detector worked when tested.</li> <li>New guidelines advise replacing smoke alarms that are more than 10 yrs</li> </ul>
old.
9. Stairs & Handrail
Sat. Fair Poor N/A None

DigiSign Verified: BA66BC82-9851-4383-8E76-1FDCD4B67781 Maffei Property Inspections 120 Wine Blossom Dr. Chico, CA 10. Window-Wall AC or Heat Poor NA None Х 11. Window Condition Poor Observations: Χ Appeared functional at time of inspection. 12. Wall Condition Poor NΑ None Observations: Χ Appeared functional at time of inspection. 13. Ceiling Condition Poor NA Observations: Χ Appeared functional at time of inspection. 14. Ceiling Fans Poor None Observations: Х Appeared functional at time of inspection. 15. Patio Doors Poor None Observations: Х · Appeared functional at time of inspection. 16. Screen Doors Fair Poor NΑ None X 17. Fireplace NΑ None Materials: Family Room Χ Materials: Gas fireplace noted. Observations: Appeared functional at time of inspection. 18. Whole House Fan Condition Observations: Χ Appeared functional at time of inspection. 19. Floor Condition Observations: Χ Appeared functional at time of inspection.

120 Wine Blossom Dr. Chico, CA

## Glossary

Term	Definition
ABS	Acronym for acrylonitrile butadiene styrene; rigid black plastic pipe used only for drain lines.
GFCI	A special device that is intended for the protection of personnel by de-energizing a circuit, capable of opening the circuit when even a small amount of current is flowing through the grounding system.