

9709 Artesia Boulevard, Suite 101 Bellflower, CA 90706 (562) 804-0443 (800) 439-1978 ned@houseinspector.com

Inspection No. : 202002013 Inspector : Ned McTaggart

Inspection Date : February 06, 2020 Client : The Estate of Merle T. Hanson

Address : 2611 Nearcliff Street, Torrance, CA 90505

THIS REPORT IS <u>NOT</u> A SUBSTITUTE FOR THE DISCLOSURES (SELLER AND AGENTS) REQUIRED BY CIVIL CODE 112 et.seq., NOR IS IT A SUBSTITUTE FOR THE REAL ESTATE TRANSFEREE DISCLOSURE STATEMENT (TDS-14). PLEASE CONSULT WITH YOUR AGENT TO IDENTIFY WHICH PARTIES ARE RESPONSIBLE FOR DISCLOSING THOSE ASPECTS OF THIS TRANSACTION THAT WOULD BE OF IMPORTANCE TO YOU.


When reading the inspection report: Serviceable means that the materials and workmanship are acceptable and

in generally satisfactory condition. We will occasionally point out a minor item and still note Serviceable, such as a light fixture with no globe.

Non-Applicable means that the item does not apply to this property.

The buyer was not present at the time of inspection. As property conditions can change from the date of inspection to the date of closing, it is advised that the buyer reference this report during any final walk through.

This is a single-family dwelling, one story structure built on a hillside lot. Estimated age is approximately 64 to 68 years old. Weather at the time of inspection was sunny.



NHI SERVICES
This Is A Confidential Report, Any Use By Unauthorized Persons Prohibited

100 EXTERIOR

Our exterior evaluation is visual in nature and is based on our experience and understanding of common building methods and materials. Our review does not take into consideration the normal wear associated with virtually all properties.

101 Driveway:	Concrete. Common cracks noted.
102 Walks:	Serviceable; concrete.
103 Fences/Walls:	Serviceable; chain link.
103a Gates:	Serviceable; vinyl/wood.
104 Siding:	Serviceable; stucco/wood.
105 Trim:	Serviceable; wood.
106 Window Frames:	Serviceable; vinyl. House is equipped with thermo-pane windows for added insulation. Verifying the seal between the two panes of glass is beyond the scope of this inspection.
106a Screens:	Serviceable.
107 Electrical Fixtures:	There is no ground fault interrupter noted at all rear outlets which may not have been standard at the time of construction. However, today's standards require ground fault interrupters at all areas within five feet of running water and external outlets. We suggest installing a ground fault interrupter in this area as a safety upgrade.
108 Gutters/Downspouts:	Metal. Rust and deterioration noted at front gutter.
	Suggest clearing all debris from gutters as part of routine maintenance to insure proper drainage.
109 Sprinklers:	A timing device controls this sprinkler system. Timing devices are beyond the

A timing device controls this sprinkler system. Timing devices are beyond the scope of this inspection. We advise that you obtain verification of this system's performance prior to closing.

Leak noted one rear sprinkler valve; we advise making necessary corrections.



NHI SERVICESThis Is A Confidential Report, Any Use By Unauthorized Persons Prohibited

100	EXTERIOR – CONTINUED
110 Exterior Doors:	Serviceable.
111 Bell/Chime:	Non-Applicable.
112 Chimney:	A spark arrester is installed as a safety feature.
	Top of chimney has loose brick, concrete and grout; we advise making necessary corrections.



112a Steps/Railing:	Serviceable.
112b Hose Bib:	Serviceable.
113 Lot grade/Drainage:	Home is built on a hillside lot. Grade at foundation appears to be adequate. This building is located within a slope or hillside. Geological evaluations are beyond the scope of this report. We advise consulting with a geotechnical engineer if concerned by conditions listed in this report or which you have observed.
114 Gas Meter:	Serviceable. Located at left side.
115 Foundation:	Serviceable; concrete/raised foundation.
115a Ventilation:	Ventilation appears to be adequate.
115b Bolted to Foundation:	Yes, under house.

115c Cripple Walls:

Yes, front right and left walls noted not braced.



116 Sub-Floor:

Accessible at rear. Plumbing leaking: Corrosion and slight leak noted at drain lines; suggest consulting with specialist for further review prior to close of escrow.





NHI SERVICES

100

EXTERIOR - CONTINUED

116a Sub-Floor Comments: Corrosion noted at supply lines; no evidence of leakage at time of inspection.



117 Exterior Comments: Non-Applicable.

118 Beyond Scope of Insp.: Satellite TV noted is beyond the scope of this inspection.

Our evaluation of the roof is to determine if portions are missing and/or deteriorating and, therefore, subject to possible leaking. Portions of underlayment and decking are hidden from view and cannot be evaluated by our visual inspection; therefore, our review is not a guarantee against roof leaks or a certification.

126 Type/Material: Composition shingle/pitched construction.

127 Roof Comments: Roof shows normal wear for its age and type; appears to be in serviceable condition.

We advise trimming all trees and vegetation away from roof noted at left side to prevent damage and premature deterioration of roofing materials.



130 ROOF ABOVE LAUNDRY AREA

131 Type/Material: Rolled roofing/flat construction.

132 Roof Comments: Rolled roofing is lifting noted at right side; we advise making necessary corrections.



NHI SERVICES
This Is A Confidential Report, Any Use By Unauthorized Persons Prohibited


1	35	ATTIC
136	Hatch Location:	Hall.
137	Accessible:	Yes.
138	Sheathing:	Serviceable; 1x6.
139	Evidence of Leaking:	No.
140	Insulation:	Yes, where visible approximate thickness is 1-3 inches.
141	Ventilation:	Appears to be adequate.
142	Attic Comments:	Open splices were observed in attic. This is a safety concern. Whenever an

electric wire is cut and reconnected, the "splice" should be encased in a covered junction box to prevent shocks and separation of the splice. Client is advised to consult with a licensed electrician prior to closing for repairs/replacement as needed to ensure safety.



	200	FRONT PORCH
20	01 Cover:	Serviceable; stucco.
20)2 Enclosure:	Non-Applicable.
20)3 Electrical:	Serviceable.
20)4 Windows:	Non-Applicable.
20)5 Deck/Slab:	Serviceable; concrete.
20	06 Stairs:	Non-Applicable.
20)7 Railing:	Top of railing is less than 42 inches from the floor which may have been standard

Top of railing is less than 42 inches from the floor which may have been standard at the time of construction; however, today's standards require top of railing be 42 inches from the floor.




208 Comments:

21	0	REAR DECK
211	Cover:	Non-Applicable.
212	Enclosure:	Non-Applicable.
213	Electrical:	Open ground noted; please see number 408.
		There is no ground fault interrupter noted in this area which may not have been standard at the time of construction. However, today's standards require ground fault interrupters at all areas within five feet of running water and external outlets. We suggest installing a ground fault interrupter in this area as a safety upgrade.
214	Windows:	Non-Applicable.
215	Deck/Slab:	Wood. Deteriorated wood noted at deck.
216	Stairs:	Deteriorated wood noted at stairs.
217	Railing:	Top of railing is less than 42 inches from the floor which may have been standard at the time of construction; however, today's standards require top of railing be 42 inches from the floor.
218	Comments:	Rear deck noted appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

	30	0	GARAGE - ATTACHED
3	01	Exterior:	Serviceable; stucco.
3	02	Roof:	Please see roof comments.
3	03	Slab:	Serviceable; concrete.
3	04	Overhead Door:	Serviceable; metal.
3	05	Garage Door Hardware:	Serviceable.
3	06	Door Opener:	This garage door opener is equipped with a safety reverse device that operated when tested at the time of our inspection. The U.S. Product Safety Commission recommends these devices be checked monthly.

Suggest adjusting photocells to within four (4) inches of ground as a safety upgrade.



307	Windows:	Serviceable.
308	Access Door:	Non-Applicable.
309	Fire Door:	Non-Applicable.
310	Fire Wall:	Serviceable; plaster.
311	Vent Screens:	Serviceable.
312	Walls:	Serviceable.
313	Ceiling:	Water stains noted at various areas; unable to determine age of stains.

300	GARAGE – ATTACHED - CONTINUED
314 Electrical:	Exposed Romex wiring noted at some areas. This may be a safety concern if used where it could be subject to physical damage. Client may wish to encase as a safety upgrade.
	Loose outlet noted at rear; suggest securing.
	There is no ground fault interrupter noted in this area which may not have been standard at the time of construction. However, today's standards require ground fault interrupters at all areas within five feet of running water and external outlets. We suggest installing a ground fault interrupter in this area as a safety upgrade.
315 Laundry Tub:	Non-Applicable.
316 Washer H/Up:	Non-Applicable.
317 Dryer H/Up:	Non-Applicable.
318 Garage Comments:	Tool shed in garage noted appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

Our evaluation of major systems is both visual and functional provided power and/or fuel is supplied to the component. **IDENTIFYING OR TESTING FOR THE PRESENCE OF ASBESTOS, RADON, LEAD BASED PRODUCTS, OR OTHER POTENTIALLY HAZARDOUS MATERIALS IS NOT WITHIN THE SCOPE OF THIS REPORT. THESE MATERIALS WERE USED PRIOR TO 1982, AND SHOULD YOU BE CONCERNED, WE SUGGEST HAVING AN INDEPENDENT INSPECTION PERFORMED PRIOR TO THE CLOSE OF ESCROW.** Judging the sufficiency of water flow in plumbing or the cooling efficiency of air conditioning is a subjective evaluation, therefore, we only note a poor condition if, in the inspector's opinion, the adequacy seems to be less than normal. We urge you to evaluate these systems prior to closing.

DISMANTLING AND/OR EXTENSIVE INSPECTION OF INTERNAL COMPONENTS OF ANY APPLIANCE, INCLUDING HEATERS AND HEAT EXCHANGERS, IS BEYOND THE SCOPE OF THIS REPORT. THE LOCAL UTILITY COMPANY WILL CONDUCT SUCH AN INSPECTION UPON REQUEST.

California Senate Bill No. 407, <u>requires on or before January 1, 2017</u>, that a Seller or Transferor of a <u>single-family residential</u> <u>real property, multifamily residential, or commercial real property</u> disclose to a Purchaser or Transferee, <u>in writing</u>, <u>specified requirements for replacing plumbing fixtures</u>, <u>and whether the real property includes noncompliant plumbing</u>. The bill would require, on or after January 1, 2017, a Seller of certain residential real property to make a specified disclosure in this regard.

The bill would require, on or before January 1, 2017, that all noncompliant plumbing fixtures in any single-family residential real property shall be replaced by the property owner with water-conserving plumbing fixtures.

Please be advised that verification of these requirements are beyond the scope of our inspection. We advise obtaining the proper written verification from Seller confirming the plumbing fixtures in this home comply with the requirements set forth in Senate Bill No. 407. More information may be obtained by referencing Senate Bill No. 407 of the California Civil Code relating to water conservation.

<u>Definitions:</u> Noncompliant plumbing fixture means - Any toilet manufactured to use more than 1.6 gallons of water per flush; Any urinal manufactured to use more than 1 gallon of water per flush; Any showerhead manufactured to have a flow capacity of more than 2.5 gallons of water per minute; Any interior faucet that emits more than 2.2 gallons of water per minute."

401 Heating: Gas. Floor furnace located in living room. Gas shut off noted.

Suggest replacing rigid gas line with flexible gas line as a safety upgrade.



401a Venting: Serviceable.

402 Air Conditioning: Non-Applicable.

NHI SERVICES

40	0	MAJOR SYSTEMS - CONTINUED
403	Thermostat:	Operable. Located in dining area.
404	Ducting:	Non-Applicable.
405	Plumbing:	Piping where visible is copper. Copper is preferred for durability and low maintenance. Main shut-off is located at front. PSI 110.
		When testing the water pressure to the home, the pounds per square inch (PSI) were higher than 100. This condition may cause plumbing fixtures to leak. Client may wish to install a regulator to reduce the PSI; or, if a regulator is present, client may wish to make proper adjustments to reduce the PSI.
		Since main shut-off valves are operated infrequently, it is not unusual for them to become frozen over time. They often leak or break when operated after a period of inactivity. For this reason main shut-off valves are not tested during a home inspection. We suggest caution when operating shut-offs that have not been turned for a long period of time. All shut-off valves and angle stops should be turned regularly to ensure free movement in case of emergency.
406	Drain/Waste Vent:	Serviceable.
407	Water Heater:	Approximately 40 gallons, gas water heater located in left side closet. Cold water

Approximately 40 gallons, gas water heater located in left side closet. Cold water shut-off: Intact. Temperature and pressure relief valve installed as a safety feature. Two earthquake straps are installed as a safety measure.

Earthquake straps noted are loose; suggest securing.

Rust noted in burner compartment which indicates the water heater is getting older; no leak noted at time of inspection.

Slight leak noted at drain plug; suggest consulting with specialist for further review prior to close of escrow.



NHI SERVICES
This Is A Confidential Report, Any Use By Unauthorized Persons Prohibited

407a Venting:

Disconnected vent pipe noted. This will allow products of combustion to escape, which is a safety hazard requiring immediate attention by a licensed contractor for repairs/replacement as required to ensure safety.



Exhaust vent is too short. The 2-2-10 rule states that the appliance vent should extend at least 2 ft. above the roof opening (measured at the uphill side on sloped roofs) and at least 2 ft. above the roof's (or any other structure's) highest point within 10 ft. for proper drafting. Simple repairs and/or modifications can usually be made to most exhaust vents to correct the problem. Advise a qualified specialist for repair or modification, as necessary, prior to close.



NHI SERVICES
This Is A Confidential Report, Any Use By Unauthorized Persons Prohibited

408 Electrical:

Unable to determine amperage; not posted. Service entrance is overhead with main panel located at right side. Overload protection is provided by breakers. Main disconnect <u>NOT</u> noted. Wiring where visible is copper. Copper is preferred for durability and low maintenance.

Open ground noted at receptacles, which may have been standard at the time of construction. Receptacles near water sources and at exterior locations ideally should be grounded. Due to the age or configuration of this system, we are unable to determine if grounding is in place or can occur. Suggest consulting a licensed electrician for further review.

Exposed splices noted in garage sub panel. This condition is not generally allowed in the service panel. Client may wish to consult a licensed electrician for further review.

Exposed splices noted in main panel. This condition is not generally allowed in the service panel. Client may wish to consult a licensed electrician for further review.




Please see additional comments for Electrical on the next page.


NHI SERVICES

408 Electrical Cont'd:

Missing interior safety cover noted.



Federal Pacific brand electrical panel noted at garage sub panel. This equipment is associated with known product defects and is problematic. We advise consulting with a licensed electrician for complete review and replacement as necessary.



As a safety upgrade, we always recommend installing GFCI outlets, in all areas that they are currently required; such as garages, laundry areas, exterior outlets, pool and spa lights and all outlets within five feet of running water.

NHI SERVICES

400)	MAJOR SYSTEMS - CONTINUED
409	Smoke Detector:	Serviceable. Located in all bedrooms.
	Smoke Detector:	Inoperable. Located in hall.
410	CO Detector:	No carbon monoxide detector(s) noted at the time of the inspection; suggest adding carbon monoxide detectors to areas centrally located outside of each sleeping area and on every level including basements within which fuel-fired appliances are installed and in dwelling units that have attached garages.
411	Fireplace:	Located in living room. Burns wood.
		Dirty fireplace noted; suggest cleaning as necessary.
412	Comments:	

500 KITCHEN

The kitchen inspection is both visual and functional. Appliances are operated, if power is supplied. Clocks, timers and other pre-setting devices on stoves and ovens are not within the scope of this inspection. Calibrations to cooking systems are not evaluated nor life expectancies given to dishwashers. **Note: Dishwashers can fail at any time due to their complexity**. Our review is to determine if the system is free of leaks and excessive corrosion.

The presence and/or odor of mold and/or mildew are possible anywhere there is moisture, such as: under sinks and plumbing at kitchens and bathrooms, plumbing leaks, crawl spaces, etc. Often the moisture is hidden from view by personal property or if it is present within walls, under flooring, inside cabinets or in an inaccessible area. Determination of the presence of mold and/or mildew, or possible health hazards resulting from exposure to these organisms is not within the scope of this inspection. If client has any concerns regarding the presence of mold and/or mildew, we advise consulting with an Indoor Air Quality specialist or other qualified person, for any testing, evaluations and/or removal which may be desired prior to close of escrow.

California Senate Bill No. 407, <u>requires on or before January 1, 2017</u>, that a Seller or Transferor of a <u>single-family residential</u> <u>real property</u>, <u>multifamily residential</u>, <u>or commercial real property</u> disclose to a Purchaser or Transferee, <u>in writing</u>, <u>specified requirements for replacing plumbing fixtures</u>, <u>and whether the real property includes noncompliant plumbing</u>. The bill would require, on or after January 1, 2017, a Seller of certain residential real property to make a specified disclosure in this regard.

The bill would require, on or before January 1, 2017, that all noncompliant plumbing fixtures in any single-family residential real property shall be replaced by the property owner with water-conserving plumbing fixtures.

<u>Please be advised that verification of these requirements are beyond the scope of our inspection</u>. We advise obtaining the proper written verification from Seller confirming the plumbing fixtures in this home comply with the requirements set forth in Senate Bill No. 407. More information may be obtained by referencing Senate Bill No. 407 of the California Civil Code relating to water conservation.

<u>Definitions:</u> *Noncompliant plumbing fixture means* - Any toilet manufactured to use more than 1.6 gallons of water per flush; Any urinal manufactured to use more than 1 gallon of water per flush; Any showerhead manufactured to have a flow capacity of more than 2.5 gallons of water per minute; Any interior faucet that emits more than 2.2 gallons of water per minute."


501 Floor:	Chips and dings noted.
502 Walls:	Serviceable.
503 Ceiling:	Serviceable.
504 Doors:	Serviceable.
505 Windows:	Serviceable.
506 Cabinets:	Two (2) pullouts noted are off their runners.
507 Counter Tops:	Tile. Chips and dings noted.
508 Electrical:	Inoperable light noted at microwave; we advise making necessary corrections.
	Open ground noted; please see number 408.
	There is no ground fault interrupter noted in this area which may not have been standard at the time of construction. However, today's standards require ground fault interrupters at all areas within five feet of running water and external outlets. We suggest installing a ground fault interrupter in this area as a safety upgrade.
	Three (3) inoperable overhead lights noted; suggest correcting.

NHI SERVICES

500	KITCHEN - CONTINUED
509 Sinks:	Serviceable.
510 Faucets:	Serviceable.
511 Traps/Drains/Supplies:	Serviceable.
512 Disposal:	Serviceable; ISE.
513 Dishwasher:	Whirlpool. Inoperable dishwasher noted; suggest consulting with specialist for further review prior to close of escrow.
	Dishwashers most commonly fail internally at the pump, motor or seals. We do not disassemble these units to inspect these components. Our inspection is limited to operating the unit on the "normal wash" cycle only.
514 Stove/Cook Top:	Serviceable; gas.
515 Oven:	Serviceable; gas.
516 Hood/Fan:	Serviceable.
517 Microwave:	Serviceable; Whirlpool.
518 Trash Compactor:	Non-Applicable.
519 Kitchen Comments:	

600	LAUNDRY AREA	
601 Floor:	Serviceable.	
602 Walls:	Serviceable.	
603 Ceiling:	Serviceable.	
604 Doors:	Doors noted are chipped and deteriorated.	
605 Windows:	Non-Applicable.	
606 Cabinets:	Non-Applicable.	
607 Electrical:	Loose outlet noted behind dryer; suggest securing.	

Exposed Romex wiring noted at various areas. This may be a safety concern if used where it could be subject to physical damage. Client may wish to encase as a safety upgrade.



608 Exhaust Fan:	Non-Applicable.
609 Laundry Tub:	Non-Applicable.
610 Washer Hook-up:	Serviceable.
611 Dryer Hook-up:	Serviceable; gas. Vent: Intact.
612 Comments:	Laundry area noted appears to be an addition to the original structure. We are unable to determine if permits were issued at the time of construction. We advise checking city records to verify the existence of permits before the close of escrow.

700 BATHROOM

Our focus in bathrooms is directed at identifying visible water damage and/or problems. We may not always mention common faults such as stuck stoppers or dripping faucets. If considered important, you should check these items independently.

The presence and/or odor of mold and/or mildew are possible anywhere there is moisture, such as: under sinks and plumbing at kitchens and bathrooms, plumbing leaks, crawl spaces, etc. Often the moisture is hidden from view by personal property or if it is present within walls, under flooring, inside cabinets or in an inaccessible area. Determination of the presence of mold and/or mildew, or possible health hazards resulting from exposure to these organisms is not within the scope of this inspection. If client has any concerns regarding the presence of mold and/or mildew, we advise consulting with an Indoor Air Quality specialist or other qualified person, for any testing, evaluations and/or removal which may be desired prior to close of escrow.

California Senate Bill No. 407, <u>requires on or before January 1, 2017</u>, that a Seller or Transferor of a <u>single-family residential</u> <u>real property, multifamily residential, or commercial real property</u> disclose to a Purchaser or Transferee, <u>in writing</u>, <u>specified requirements for replacing plumbing fixtures</u>, <u>and whether the real property includes noncompliant plumbing</u>. The bill would require, on or after January 1, 2017, a Seller of certain residential real property to make a specified disclosure in this regard.

The bill would require, on or before January 1, 2017, that all noncompliant plumbing fixtures in any single-family residential real property shall be replaced by the property owner with water-conserving plumbing fixtures.

<u>Please be advised that verification of these requirements are beyond the scope of our inspection</u>. We advise obtaining the proper written verification from Seller confirming the plumbing fixtures in this home comply with the requirements set forth in Senate Bill No. 407. More information may be obtained by referencing Senate Bill No. 407 of the California Civil Code relating to water conservation.

Definitions: Noncompliant plumbing fixture means - Any toilet manufactured to use more than 1.6 gallons of water per flush; Any urinal manufactured to use more than 1 gallon of water per flush; Any showerhead manufactured to have a flow capacity of more than 2.5 gallons of water per minute; Any interior faucet that emits more than 2.2 gallons of water per minute."

Serviceable.	
Serviceable.	
Serviceable.	
Serviceable.	
Missing screen noted at window.	
Open ground noted; please see number 408.	
There is no ground fault interrupter noted in this area which may not have been standard at the time of construction. However, today's standards require ground fault interrupters at all areas within five feet of running water and external outlets. We suggest installing a ground fault interrupter in this area as a safety upgrade.	
Serviceable.	
Non-Applicable.	
Serviceable.	

NHI SERVICES

700	BATHROOM - CONTINUED
714 Sink:	Serviceable.
715 Sink Faucet:	Serviceable.
716 Traps/Drains/Supply:	Serviceable.
717 Toilet:	Toilet noted is not flushing properly; we advise making necessary corrections.
718 Counter/Cabinets:	Serviceable.
719 Comments:	

Our interior review is visual and evaluated with similarly aged homes in mind. Seals in double-pane, insulated glass can fail at any time and although the glass is examined, lighting conditions, window coverings, and atmospheric conditions at the time of the inspection can cause the defect to be undetectable. Cosmetic considerations and minor flaws such as a torn screen or an occasional cracked window can be overlooked, thus we suggest you double check these items, if concerned. Note: As pointed out in the Inspection Agreement, materials regularly used in residential construction may contain potentially hazardous substances such as asbestos and formaldehyde. Our report will not identify these substances since laboratory testing is necessary to detect their presence.

900	LIVING ROOM	
901 Floor:	Serviceable.	
902 Walls:	Serviceable.	
903 Ceiling:	Serviceable.	
904 Doors:	Serviceable.	
905 Windows:	Serviceable.	
906 Electrical:	Serviceable.	
907 Wet Bar:	Non-Applicable.	
908 Comments:		

1000 DINING AREA

1001 Floor:

Deteriorated wood and water damage noted at rear.



1002 Walls:	Serviceable.
1003 Ceiling:	Serviceable.

1000	DINING AREA – CONTINUED
1004 Doors:	Loose frame noted at rear door; suggest securing.
_	Doors noted are out of alignment; suggest consulting with specialist for further review prior to close of escrow.
1005 Windows:	Serviceable.
1006 Electrical:	Serviceable.
1007 Wet Bar:	Non-Applicable.
1008 Comments:	

1200	HALL
1201 Floor:	Serviceable.
1202 Walls:	Serviceable.
1203 Ceiling:	Serviceable.
1204 Doors:	Serviceable.
1205 Windows:	Non-Applicable.
1206 Electrical:	Inoperable overhead light noted; suggest correcting.
1207 Stairs:	Non-Applicable.
1208 Comments:	

1300	FRONT LEFT BEDROOM
1301 Floor:	Serviceable.
1302 Walls:	Serviceable.
1303 Ceiling:	Serviceable.
1304 Doors:	Both closet doors noted are inoperable.
1305 Windows:	Serviceable.
1306 Electrical:	Serviceable.
1307 Closet:	Serviceable.
1308 Comments:	

1310	FRONT RIGHT BEDROOM
1311 Floor:	Serviceable.
1312 Walls:	Serviceable.
1313 Ceiling:	Serviceable.
1314 Doors:	Serviceable.
1315 Windows:	Serviceable.
1316 Electrical:	Serviceable.
1317 Closet:	Serviceable.
1318 Comments:	

1320	REAR BEDROOM	
1321 Floor:	Serviceable.	
1322 Walls:	Serviceable.	
1323 Ceiling:	Serviceable.	
1324 Doors:	Serviceable.	
1325 Windows:	Serviceable.	
1326 Electrical:	Serviceable.	
1327 Closet:	Serviceable.	
1328 Comments:		

AS INDICATED IN OUR INSPECTION AGREEMENT AND COVER LETTER, LIMITATIONS EXIST WITH THIS INSPECTION. UNFAMILIARITY WITH THE PROPERTY WILL ALWAYS IMPACT DISCLOSURE. WE SUGGEST YOU OBTAIN WRITTEN DISCLOSURE FROM THE SELLER REGARDING ANY CONDITIONS THAT MAY NOT BE APPARENT AND ONLY PREVIOUS KNOWLEDGE COULD DISCLOSE.

This inspection and report have been undertaken and prepared in conformity with the standards of the American Society of Home Inspectors. However, it is only visual in nature and is not an architectural, geological, or engineering inspection. Such an evaluation would cost many times more. Also, this inspection is not intended to relieve the seller or the involved real estate agents of their respective duties of full disclosure and due diligence; nor relieve them of such liability {as would be provided in California Civil Code section 1102.4}. This inspection does not constitute a warranty, an insurance policy, or a guarantee of any kind.

NHI Services has prepared this report subject to the following exclusions and limitations:

Condition as of Inspection Date -The Inspection Report is based on conditions of the property existing and apparent on the inspection date. As not all conditions are apparent on the inspection date, it is recommended that buyer consult with seller regarding any significant defects/malfunctions known to exist regarding the major structural components, operating systems, and mechanical components of the home prior to closing the transaction. NHI Services is not responsible for the non-discovery of any patent or latent defects in materials, workmanship, or other aspects of the property, or any problems that may occur or become evident after the inspection date. NHI Services is not responsible for future failure and repair. You are advised to operate and check all systems and equipment just before closing on the property as failures and defects sometimes occur in the time period between the inspection and the closing. You are further advised with regard to vacant houses, to have all systems operational for careful checking just prior to closing. Systems, particularly heating and plumbing, and plumbing connected appliances have been known to fail in vacant houses.

Limit of Liability -If you or any third party claim NHI Services is liable for negligently making the inspection and/or preparing the Inspection Report, or if for any other reason, you claim we have not fully satisfied all of our obligations under this Agreement, our liability to you is limited to the lesser of the cost to repair adjusted for the remaining life of the item or two times the fee paid for the inspection services, and you release us from any additional liability. You agree to indemnify, defend, and hold us harmless if any third party brings a claim against us relating to our inspection or the Inspection Report.

Exclusions and Limitations –NHI Services is only making a **visual** inspection and the following are specifically excluded from this inspection:

1. General Exclusions --The following items, systems and components are excluded: the inspection and/or testing of underground or concealed pipes, electrical lines or circuits, sewer lines and/or on-site waste disposal systems; water softeners, intercom systems, security systems, telephone and cable TV cables, low voltage lighting systems, any timing systems, water purification systems, well systems {other than visible above ground equipment}, solar systems, swimming pools, spas {other than equipment in visible plumbing system}, back flushing of pool equipment, instant water heating devices, pressure tests or central air conditioning systems, furnace heat exchangers, radiant heating systems, free standing appliances and other personal property; the conducting of any soils or geological tests; the dismantling of any object or any portions of the property; the inspection of concealed or inaccessible portions of the property other than readily accessible service panels; and except as modified by separate written agreement, the inspection or testing for termites, dry rot, fungus, or other wood destroying pests or organisms or for household pests or rodents. Electrical receptacles, windows, doors and other multiple items are tested by examining a representative sampling as opposed to specific functionality of every single item. Inspectors do not light pilots or activate any system that is not operational.

- 2. **Title or Code Compliance** –NHI Services will not investigate nor give any opinion concerning easements, conditions of title, zoning matters, or compliance of the property's improvements with any governmental building code requirements or permits. You should contact the appropriate governmental agencies if you desire such information.
- 3. **Latent Defects** -Defects such as cracking, leaking, surface dislocations, or landslides resulting from latent defects such as, without limitation, water leaks, land subsistence, or other geological problems are excluded.
- 4. **Product Defects and Environmental Hazards** -Our inspection is not a chemical analysis or a search for defective products or environmental hazards, such as radon gas. Materials regularly used in residential construction may contain potentially hazardous substances such as asbestos, lead and formaldehyde. Except as modified by separate written agreement, our Inspection Report excludes chemical analysis, defective products, and environmental hazards including, without limitation, radon gas, asbestos, lead, lead paint and formaldehyde. You should perform any such additional inspection regarding these matters at your own expense and risk.
- 5. **Cosmetic Features** -Cosmetic features such as, without limitation, paint, wall coverings, carpeting, floorings, paneling, lawn, and shrubs are excluded.
 - 6. Secondary or Consequential Damages -Secondary or consequential damages are excluded.

THE INSPECTION REPORT DOES NOT CONSTITUTE A WARRANTY, AN INSURANCE POLICY, OR A GUARANTEE OF ANY KIND. THE INSPECTION REPORT REFLECTS AN OBSERVATION OF CERTAIN LISTED ITEMS OF THE PROPERTY AS OF THE DATE AND TIME OF THE INSPECTION AND IS NOT A LISTING OF REPAIRS TO BE MADE. THE INSPECTION REPORT IS NOT INTENDED FOR USE AS A GUIDE IN RE-NEGOTIATING THE SALES PRICE OF THE PROPERTY, NOR SHOULD IT BE CONSTRUED AS AN OPINION OF THE VALUE OF THE PROPERTY. THE SELLER MAY OR MAY NOT BE REQUIRED TO REPAIR DEFICIENCIES REFLECTED IN THIS INSPECTION REPORT, AND THAT DETERMINATION SHOULD BE MADE BY YOU, THE SELLER, YOUR REAL ESTATE AGENT{S}, AND YOUR ATTORNEYS. WE RECOMMEND THAT YOU ATTEND THE ACTUAL INSPECTION.