WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

| BUILDING NO. | STREET, CITY, STATE, ZIP | | | Date of Inspection | No. of Pages | | |
|---|---|---|---------------------------------------|---|----------------|--|--|
| 44040 | Soler Court, Temecula CA 92592 | | | 9/18/2018 | 4 | | |
| DeANZA TERMITE & PEST CONTROL, INC. P.O. Box 291, Murrieta, CA 92564-0291 Tax ID 33-0826800 (951) 677-8770 (951) 677-7540 Fax | | | | | | | |
| Firm Registration N | lo. PR 3424 | Report No. 65229 | E | Escrow No. | | | |
| Ordered By: Realty One Group \$ 41463 Margarita Rc Temecula, CA 9258 Attn: Marcia/Kim M kim@kimmeeker.cc | oad #100 91 1eeker | Property Owner/Party of Interest Norma Castellanos 44040 Soler Court Temecula, CA 92592 lopez.n1009@yahoo.com | Re 41 Te At | eport Sent To: ealty One Group Southwest 1463 Margarita Road #100 emecula, CA 92591 ttn: Marcia/Kim Meeker m@kimmeeker.com | | | |
| COMPLETE REPORT | LIMITED REPORT | X SUPPLEMENTAL REP | ORT 🗌 | REINSPECTION REPORT | | | |
| General Description: Ins | | | Garage | Inspection Tag Posted: | | | |
| | | | Other Tags Posted: None Noted | | | | |
| An inspection has l steps, detached de | been made to the structure(s) shecks and any other structures | nown on the diagram in accordance wind not on the diagram were not inspe | th the Structural Percepted. | est Control Act. Detached por | ches, detached | | |
| Subterranean Tern | | ites Fungus/Dryrot Cothere were visible problems in accessi | Other Findings ible areas, Read the | Further Inspection | on items | | |
| | | Clearance | Report | | | | |
| Inspected by D | avid Browne | State License No. OPR 12004 | Sigr | nature Jan | 7 | | |

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceeding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California 95815.

| 44040 | Soler Court, Temecula CA 92592 | 9/18/2018 | 65229 |
|--------------|--------------------------------|-----------------|------------|
| BUILDING NO. | STREET, CITY, STATE, ZIP | INSPECTION DATE | REPORT NO. |

There are certain areas of a structure which are considered impractical for inspection: the interior of hollow walls, spaces between a floor or porch deck, attics with less than 18" of clear crawl space. Stall showers over finished ceilings, abutments or floors beneath coverings are considered inaccessible and were not inspected at this time. Second story showers are not water tested unless there is evidence of a leak at ceiling below. Sunken or below grade showers are not water tested due to their construction. NOTE: Eaves requiring the use of an extension ladder are considered impractical for inspection. Appliances and/or plumbing over finished ceilings and decks are not water tested and we do not certify against leakage, unless otherwise noted in this report. No opinion is rendered, nor guarantee is implied concerning the future watertightness of the roof. This firm makes no guarantee against any infestation, leaks or other adverse conditions which may exist or which may develop in inaccessible areas and become visibly evident after the date of this inspection. This inspection is only on the structures indicated on the diagram. If requested, a reinspection of this property will be performed by this firm at additional cost. The exterior surface of the roof will not be inspected. If you want water tightness of the roof determined, you should contact a roofing contractor who is licensed by the contractors state license board. Our job estimate for work is good for 30 days. The original report is valid for a period of four months.

This Wood Destroying Pests & Organisms Report DOES NOT INCLUDE MOLD, fungi or any mold-like conditions. By California law we are neither qualified, authorized nor licensed to inspect for health related molds or fungi. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. No reference will be made to mold or mold-like conditions. If you wish your property to be inspected for mold-like conditions or you desire information about the presence of health related molds, you should contact an industrial hygienist or the appropriate mold professional.

This company will re-inspect repairs done by others within four months of the original inspection. A re-inspection is \$65 in addition to the original inspection fee for each re-inspection. The re-inspection must be done within ten (10) working days of request. The re-inspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

- A. This inspection pertains only to the specific address indicated and does not include any attached or adjacent units.
- B. The exterior surface of the roof and condition of plumbing will not be inspected. If you want the water tightness of the roof or condition of plumbing determined, you should contact a roofing or plumbing contractor who is licensed by the Contractor's State License Board.
- C. Slab floor construction has become more prevalent in recent years. Floor coverings may conceal cracks in the slab that will allow infestation to enter. Infestation in the walls may be concealed by plaster so that a diligent inspection may not disclose the true condition. These areas are not practical for inspection due to health hazards, damage to the structure or inconvenience. They were not inspected unless described in this report. We recommend further inspection if there is any question about the above areas.
- D. This company does not concern itself with prior building permits. If anyone has any questions as to whether this structure or parts of this structure are permitted, we suggest they contact the proper county or city departments.

| 44040 | Soler Court, Temecula CA 92592 | 9/18/2018 | 65229 |
|--------------|--------------------------------|-----------------|------------|
| BUILDING NO. | STREET, CITY, STATE, ZIP | INSPECTION DATE | REPORT NO. |

- E. Some structures do not comply with building code requirements or may have structural, electrical, plumbing, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pests and Organisms Inspection Report does not contain information on such a defect, if any, as they are not within the scope of our license.
- F. This proposal includes a primer coat of paint only. An effort will be made to match the color but a match is not guaranteed.
- G. During the process of treatment or replacement, it may be necessary to drill holes through ceramic tiles or other floor covering. These holes will then be sealed with concrete. We will exercise due care but assume NO RESPONSIBILITY for cracks, chipping or other damage to floor coverings.
- H. In the event damage or infestation described therein is later found to extend further than anticipated, our bill will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF AND/OR HERSELF.
- I. All pesticides and fungicides must be applied by a state certified applicator (sec. 8555 Business and Professions Code Division 3) and in accordance with the manufacturer's label requirements.
- J. DeAnza assumes NO RESPONSIBILITY for damage to any Plumbing, Gas or Electrical lines, etc., in the process of pressure treatment of concrete slab areas or replacement of concrete or structural timbers.
- K. If building permits are required for any repair work, it is the owner's responsibility to contact the appropriate government agency, schedule and pay all fees prior to repair work being performed by this company or others.
- L. When a fumigation is recommended, a FUMIGATION NOTICE will be left with or mailed to the owner of the property or his designated agent which states, among other things, that ALL FOODS AND MEDICINES MUST BE REMOVED from the property PRIOR to the fumigation being performed. We will assume no responsibility for damage to shrubbery, trees, plants, antennas, satellite dishes, or roofs.
- M. NOTICE...The charge for service that this company subcontracts to another company may include the company's charges for arranging and administering such services that are in addition to the direct costs associated with paying the subcontractor. You may accept DeAnza's bid or you may contract directly with another registered company licensed to perform the work. If you choose to contract directly with another company, DeAnza will not in any way be responsible for any act or omission in the performance of work that you directly contract with another to perform.
- N. If repairs are completed by others, this company recommends the proper licensed bonded insured contractor, in good standing with the State of California, be hired to perform any repairs on the property.
- O. This company DOES NOT GUARANTEE work performed by others, recommended or not, including by the Owner or Contractors. Bills should be submitted to Escrow as certification of work performed by others.
- P. NOTICE...Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company...You...have the right to seek a second opinion...from another company.

| 44040 | Soler Court, Temecula CA 92592 | 9/18/2018 | 65229 |
|--------------|--------------------------------|-----------------|------------|
| BUILDING NO. | STREET, CITY, STATE, ZIP | INSPECTION DATE | REPORT NO. |

- Q. Arbitration of Disputes...By relying on this wood destroying organisms report, you agree that any controversy or claim arising out of or relating to DeAnza's inspection and/or this report shall be settled by arbitration in accordance with the construction industry arbitration rules of the American Arbitration Association, and judgment upon the award rendered by the arbitrator(s) may be entered in any court having jurisdiction thereof.
- R. Please call our office if you should have any questions pertaining to this report. Our office is open Monday through Friday from 8:00 a.m. to 5:00 p.m.
- S. THE EPA REQUIRES THAT HOMES AND OTHER BUILDINGS CONSTRUCTED PRIOR TO 1978 ARE PRESUMED TO HAVE LEAD PAINT THAT MAY CAUSE SERIOUS HEALTH ISSUES IF DISTURBED DURING REPAIRS. SPECIAL PROCEDURES ARE REQUIRED BY THE US EPA IN REPAIRING PAINTED AREAS WHERE MORE THAN 6 SQUARE FEET IN AN INTERIOR OR 20 SQUARE FEET ON AN EXTERIOR ARE DISTURBED. LOCAL AND STATE REQUIREMENTS MAY BE MORE RESTRICTIVE. THOSE DOING THE REPAIRS ARE REQUIRED BY LAW TO BE LICENSED LEAD RENOVATORS AND AS SUCH FOLLOW STRICT TESTING, CONTAINMENT, REPAIR, CLEAN UP AND DEBRIS DISPOSAL PRACTICES. THE PENALTIES FOR VIOLATIONS OF THE EPA REGULATIONS ARE SEVERE. IF THIS STRUCTURE WAS BUILT PRIOR TO 1978, YOU WILL BE PROVIDED WITH THE EPA PAMPHLET ENTITLED "RENOVATE RIGHT-IMPORTANT LEAD HAZARD INFORMATION FOR FAMILIES", PRIOR TO THE START OF REPAIRS. IN ADDITION, YOU WILL BE NOTIFIED OF THE ADDITIONAL COSTS OF COMPLIANCE.

Condominiums: This report is limited at the agent, Kim Meeker's request, to the internal and external walls, attic spaces (if accessible) immediately above the unit, any subarea spaces immediately below, balconies abutting or attached to the unit and garage interior and exterior. The Structural Pest Control Board has instructed all pest control companies to recommend further inspection of the remaining units or rooms of the structure even if areas already inspected are free of active infestation or infections.

THIS IS TO CERTIFY THAT THE ABOVE PROPERTY WAS INSPECTED ON 09/18/2018, IN ACCORDANCE WITH THE STRUCTURAL PEST CONTROL ACT AND RULES AND REGULATIONS ADOPTED THERETO, AND THAT NO EVIDENCE OF ACTIVE INFESTATION OR INFECTION WAS FOUND IN THE VISIBLE AND ACCESSIBLE AREAS, AND COMPLIES WITH THE REQUIREMENT OF THE STRUCTURAL PEST CONTROL ACT, STATE OF CALIFORNIA, THE VETERANS ADMINISTRATION AND FHA.