
WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT


110	OD DESTROIT	ING I LOTO AND O	CAINON	O IIIOI L	CHONINE	·	<u>L</u>	
Building No. 26	Street Parkside Ct.	City Chico	0	Zip 95928	Date of Inspe 04/27/20		Number of Pag 3	es
DETECTIVE TERMINE CONTROL	HOU		E CT. SUITI CA 95928 (530) 591-7	E 10 7079	. INC	Regis Escro	rt # : 11279 tration # : PR59 w # : DRRECTED REPOR	
Ordered by: Deb Sprague Deb Sprague Realtor 28 Hanover Lane Suite C Chico CA 95973 United States		Property Owner and/or Par David Aust 26 Parkside Ct. Chico CA 95928 United States	ty of Interest:	Repo	ort sent to:			
COMPLETE REPORT	☐ LIMITED REP	ORT SUPPLEMENT	AL REPORT	REINS	SPECTION RE	PORT	X	
GENERAL DESCRIPTION: This is a re-inspection re	eport.		A	nspection Tag t the water he other Tags Po	eater			
		shown on the diagram in account on the diagram were not in		e Structural P	est Control Act.	Detach	ed porches, deta	ched
Subterranean Termites	s Drywood		/ Dryrot \Box				er Inspection or details on che	
		Diagram Not	To Scale					



Inspected By: Gregory D Hosler State License No.

OPR10012

Signature:



HOUSE DETECTIVE TERMITE CONTROL INC

Page 2 of	3 inspection report			
26	Parkside Ct.	Chico	CA	95928
Address of	f Property Inspected	City	State	Zip
04/27/2017	7	11279		·
Date of Ins	spection	Corresponding Report No.	Escr	ow No.

WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

HOUSE DETECTIVE TERMITE CONTROL INC

Page 3 of 3 inspection report			
26 Parkside Ct.	Chico	CA	95928
Address of Property Inspected	City	State	Zip
04/27/2017	11279		·
Date of Inspection	Corresponding Report No.	Escr	ow No.

This is a separated report which is defined as Section I/Section II conditions evident on the date of the inspection. Section I contains items where there is visible evidence of active infestation, infection or conditions that have resulted in or from infestations or infections. Section II items are conditions deemed likely to lead to infestation or infection but where no visible evidence of such was found. Further inspection items are defined as recommendations to inspect area(s) which during the original inspection did not allow the inspector access to complete the inspection and cannot be defined as Section I or Section II.

SECTION I CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

SECTION II ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

SECTION III / FURTHER INSPECTION ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(s) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

This is a reinspection report to original report dated 01/12/2017, report #11062.

NOTES

Note A

Items 3A, 3B, 3C and 3D were completed by others. The House Detective Termite Control Inc. assumes no liability for repairs done by others.

This is to certify that the above property is now free of evidence of active infestations and infections in the visible and accessible areas and is in compliance with the Structural Pest Control Act.



INVOICE / STATEMENT HOUSE DETECTIVE TERMITE CONTROL

INC

11 COMMERCE CT. SUITE 10 CHICO CA 95928

(530) 894-7900 (530) 591-7079 hdetective@att.net Fax (530) 894-7902 Date: 04/27/2017

Report Number: 11279 Invoice Number: 11279-1

Escrow Number:

Property 26 Parkside Ct. Inspected: Chico , CA 95928

Bill To: Deb Sprague

Deb Sprague Realtor 28 Hanover Lane Suite C Chico, CA 95973 United States

deb@debsprague.com

Total Due:	\$ 85.00
Additional Charge:	\$ 0.00
Payments:	\$ 0.00
Invoice Total:	\$ 85.00
Inspection:	\$ 85.00

<u>Description of Service</u> Re-inspection report.

RETAIN THIS COPY FOR YOUR RECORDS

THANK YOU FOR YOUR BUSINESS

CUT HERE CUT HERE CUT HERE



INVOICE / STATEMENT
HOUSE DETECTIVE TERMITE CONTROL
INC

11 COMMERCE CT. SUITE 10 CHICO CA 95928

(530) 894-7900 (530) 591-7079 hdetective@att.net Fax (530) 894-7902 Date: 04/27/2017
Report Number: 11279
Invoice Number: 11279-1

Escrow Number:

Property 26 Parkside Ct. Inspected: Chico , CA 95928

Bill To: Deb Sprague

Deb Sprague Realtor 28 Hanover Lane Suite C

Chico, CA 95973 United States

deb@debsprague.com

Inspection:	\$ 85.00
Invoice Total:	\$ 85.00
Payments:	\$ 0.00
Additional Charge:	\$ 0.00
Total Due:	\$ 85.00

<u>Description of Service</u> Re-inspection report.

RETURN THIS COPYWITH REMITTANCE