
WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Destruita a No	Ohrand	O:F :	710	D-44	I	North an of Dance	
Building No. 6021	Street Dawn Creek #3	^{City} Playa Vista	ZIP 90094		Inspection 6/2022	Number of Pages 4	
0021	Dawn Creek #3	•		1		4	
Re Per	st Contrag	2	Anteater Termite & Pest Control, Inc. 2038 Venice Blvd Los Angeles CA 90006			t # : 9364 tration # : PR7579	
	1 1 1 2						
J.C	92	` ,	(323) 870-5414 (213) 454-1617			w # :	
WTE	ATE		anteatertermite@gmail.com Fax (323) 870-5415			☐ CORRECTED REPORT	
Ordered by: Kevin Lin MOBILE: (909) 215 kevinlin8889@gma		Property Owner a	ind/or Party of Interest:	Re	port sent to:		
COMPLETE REPO	DRT LIMITED	REPORT 🔀	SUPPLEMENT	TAL REPORT	REINSF	PECTION REPORT	
GENERAL DESCRIPTION: Single-family, three-story, frame/stucco, townhouse residence, attached garage, composition roof. Inspection Tag Posted: Garage Other Tags Posted:							
An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.							
Subterranean Term	nites Drywood Te	rmites 🔀 Fui	ngus / Dryrot 🔲	Other Find	dings 🔀	Further Inspection	
If any of the above	boxes are checked, it indica		<u> </u>		Read the report f	or details on checked items.	
		Diagr	am Not To Scale)			





Inspected By: In Woo Moon (Alex) State License No. FR37899 Signature:

ANTEATER TERMITE & PEST CONTROL, INC.

Page 2 of 4 inspec	tion report					
6021	Dawn Creek #3		Playa Vista	CA	90094	
Address of Propert	y Inspected		City	State	ZIP	
02/26/2022		9364				
Date of Inspection	ction Corresponding F		ort No.	E	scrow No.	

WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

ANTEATER TERMITE & PEST CONTROL, INC.

Page 3 of 4 inspection report

6021	Dawn Creek #3	Playa Vista	CA	90094	
Address of Pro	operty Inspected	City	State	ZIP	
02/26/2022	9364				
Date of Inspec	ction Correspondi	ng Report No.	E	scrow No.	

SECTION I CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

SECTION II ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

FURTHER INSPECTION ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(s) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

INSPECTED AREAS

- 1. SUBAREA Concrete slab.
- 2. STALL SHOWER Not tested due to 2nd floor.
- 3. FOUNDATION Concrete.
- 4. PORCHES/STEPS Concrete.
- 5. VENTILATION Adequate.
- 6. ABUTMENTS None.
- 7. ATTIC SPACES Partially accessible due to state of construction.
- 8. GARAGES Attached. Partially inspected due to storage.
- 9. DECKS/PATIOS None.
- 10. OTHER/INTERIOR Inspected.
- 11. OTHER/EXTERIOR Not inspected due to HOA.

SECTION I:

7A - Attic Spaces

FINDING: Evidence of drywood termite infestation was noted at the time of inspection at the attic area wood member(s) as indicated on the diagram.

RECOMMENDATION: Chemically treat visible and accessible infestations. Remove or cover accessible pellets. Proposed Pesticide(s): Termidor SC, Fipronil 9.1%, BoraCare Disodium Octaborate Tetrahydrate 40%, or Cy-Kick, Cyfluthrin 0.1%. This treatment will not control/prevent infestation of drywood termites in non-treated areas. One year warranty is limited to the treated area(s) only.

SECTION II:

10A - Other / Interior

FINDING: Evidence of water damage was noted at the time of inspection at the bath room, base molding of the 2nd floor as indicated on the diagram.

RECOMMENDATION: Owner should employ an appropriate trades-person to inspect and perform any corrective work needed as necessary in accordance with applicable building codes.

Thank you for selecting us to perform a structural pest control inspection on your property. Should you have any questions regarding this report, please call us directly by the contact information provided on the first page of the inspection report.

Please take a few moments to read and become familiar with the following content. State law requires that you be given the following information:

CAUTION - PESTICIDES ARE TOXIC CHEMICALS. Structural pest control companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the state finds that, based on scientific evidence, there are no appreciable risks if proper use conditions are followed or that risks are weighted by benefits. The degree of risk depends on the degree of exposure, so exposure should be minimized.

ANTEATER TERMITE & PEST CONTROL, INC.

Page 4 of 4 inspection report

6021	Dawn Creek #3	Playa Vista	CA	90094	
Address of Proper	ty Inspected	City	State	ZIP	
02/26/2022		9364			
Date of Inspection Corresponding		sponding Report No.	E	scrow No.	

If within 24 hours following application of pesticides, you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or your pest control center (800) 876-4766 and your pest control company immediately. For further information, contact any of the following agencies in your area:

Poison Control Center (800) 222-1222
Agricultural Department (626) 575-5471
Health Department (213) 989-7140
Structural Pest Control Board (916) 561-8700

2005 Evergreen Street, Ste. 1500. Sacramento, CA 95815

Report #: 9364

PATEATER

Owner's Agent:

Anteater Termite & Pest Control, Inc.

2038 Venice Blvd

Los Angeles CA 90006 (323) 870-5414 (213) 454-1617 anteatertermite@gmail.com Fax (323) 870-5415

WORK AUTHORIZATION

•	6021 Dawn Creek #3	reement has been	receiveu.			
• • • •	Playa Vista					
-	CA 90094					
The inspection report of the comparties of the comparties of the company is authorized to proceed t	any dated, <u>02/26/2022</u> is incorp	e items circled below fi	om the Termite Inspection	n Report for the property inspec	cted, for a total sum of	
To guarantee all repair completed sixty (60) days. We assume no report to exceed 30 days, to use reasor to any shrubs, plants, or roof.	esponsibility for work performed	l by others, to be boun	except for caulking, groud to perform this work fo	r the price quoted in our cost br	eakdown for a period	
To pay for services rendered and palance to be paid in full on the portion of any month, annual internterest in the property to secure profilection shall be paid by owner, we consider the property to secure profilection shall be paid by owner, we consider the property to secure profilection shall be paid by owner, we can be set to be provided the property to secure profilection shall be paid by owner, we can be set to be paid by owner, we can be set to	any additional services requeste day of completion. With an ur lest rate of twenty-four percent payment sum for work and inspe	npaid balance there wi (24%) on accounts ex	50% of grand total to be a service charge of ceeding the day of comp	two percent (2%) interest per me letion. The Owner grants to The	onth of grand total, or Company a security	
f any additional work is deemed gent. This contract price does no mount above:	, ,	•	will not be performed wi			
Under the California Mechanics Lither person who helps to improve a court hearing, your propert aid your structural pest control co	e your property, but is not paid to your property, but is not paid to you could be sold by a court office mpany in full if the subcontractous or lien against your property	for his or her work or ser and the proceeds of r, laborers or suppliers r, certain claimants su	ontracts to do work for you supplies, has a right to end the sale used to satisfy remain unpaid. ch as subcontractors or	nforce a claim against your prop the indebtedness. This can hap material suppliers are required	erty. This means that open even if you have to provide you with a	
locument entitled "Preliminary No property. Its purpose is to notify yo		•	•	•	ot a lien against your	
		ITEMS	3			
Pre	fix	Section I	Section II	Further Inspection	Other	
'A - Attic Local Treatment (d		450.00		- artifor moposition	<u> </u>	
।0A - Water Damage - bath । loor.		0.00	n/a			
Fotal:		450.00				
Grand Total:		450.00				
Property Owner:		Date:	Inspected By:		te:	

Date: