

## Sprinkler System Inspection

TRC Global Mobility  
7270 S 13th Street Suite 201  
Oak Creek, WI 53154

11/04/2022  
Client File # 17459-2176  
FICS File # 3048792

**Inspection Address**

Tony Accardo  
507 Sapphire street  
Redondo Beach, ca 90277


In accordance with your request a Sprinkler Inspection was conducted on **11/04/2022** at the above captioned property. All visible components of the 6 zone sprinkler system were evaluated. The following is a summary of the inspector's findings.

CONDITION OF COMPONENTS	
<b>Automatic Timer</b>	Acceptable
<b>Manual Controls</b>	Acceptable
<b>Shut Off/Draining Valves</b>	Acceptable
<b>Individual Zones/Pop up Heads</b>	The sprinkler head in Zone 1 is broken.
Corrective Action	Contractor to replace the broken sprinkler head
<div style="display: flex; border: 1px solid black; padding: 5px;"> <div style="width: 30%; text-align: center;">  <p>Broken head</p> </div> <div style="width: 70%;"></div> </div>	
<b>Water Pressure Flow</b>	The head at the front/left planter in Zone 1 had low flow.
Corrective Action	Contractor to head at the front left paltner.

			
Low flow at head			
<b>Additional Comments</b>			

If you should have any questions, please do not hesitate to contact me.

Sincerely,

  
Jim Morrissey  
Account Manager

**ADDITIONAL PHOTOS**



**Overviews**



