Property Condition Report

Address:

Case Number: 048-442535 Contract Area: 5S

Current Step:

1c-Ready to Show Condition

Inspected peaks, valleys, ridge lines/caps, chimneys, soffits, decking, boots and vents; Pass with no deficiencies found

Step Date:

10776 TOLLIVER ST

HOC:

Roof:

--Other:

07/03/2025 Santa Ana

OK

N/A

Roofing in acceptable

condition?:

City, St Zip: ADELANTO, CA 92301-0000

Property Condition Report	
----------------------------------	--

Item Description/Condition		Item Functionality		Functionality/Test Notes
Cooling/Air-ConditioneHeating/Furnace:HVAC System Duct:	r: OK OK OK	HVAC tested and functional?:	Yes	Generator/220 Plug/Breaker Panel
Electrical Wiring:Other:Other:	OK N/A N/A	Electric supply tested and functional?:	Yes	Generator/220 Plug/Breaker Panel
Stove/Range/Oven:Kitchen Cabinets:Other:	OK OK N/A	Built-in appliances tested and functional?:	Yes	Generator/220 Plug/Breaker Panel
Plumbing: Sink: Other:	OK OK N/A	Water supply tested and functional?:	Yes	Pressure test; Pass
Water Heater:	ОК	Water heater functional?:	Yes	Inspected HWH components; pass with no deficiencies found
Sewer/Septic System:Toilet:Other:	OK N/A N/A	Sanitary & plumbing system functional?:	Yes	Pour Water/Antifreeze in Drains; Pass

Yes