
WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No. 9242	Street Holland Avenue	City Durham	ZIP 95938	Date of Ins 03/15/2		Number of Pages 4
9242 Ordered by: Traci Cooper eXp Realty San Ramon CA	Holland Avenue	i O (termite@		com	Repor Regist Escrov	4 t # : 11218 tration # : PR 7460 w # : RRECTED REPORT
COMPLETE REPOR		REPORT	SUPPLEMENT			PECTION REPORT
GENERAL DESCR					spection Tag	g Posted:
	vel residence, attached ga					ermite 3/7/22
An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.						
Subterranean Termi	ites 🗙 Drywood Tern	nites 🗌 🛛 🛛 Fu	ngus / Dryrot 🗌	Other Finding	gs 🗙	Further Inspection
If any of the above b	ooxes are checked, it indicat	es that there were	visible problems in acce	ssible areas. Rea	d the report	for details on checked items.
Diagram Not To Scale						



Inspected By: Bud R. Prather State License No. OPR13973 Signature:

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California, 95815-3831. NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be

directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov. 43M-41 (Rev. 04/2015)

HOBBS PEST SOLUTIONS, INC

Page 2 of 4 inspect	ion report		·			
9242	Holland Avenue		Durham	CA	95938	
Address of Property	/ Inspected		City	State	ZIP	
03/15/2022		11218				
Date of Inspection		Corresponding Report	No.		Escrow No.	

WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

HOBBS PEST SOLUTIONS, INC

Page 3 of 4 inspection re	port				
9242	Holland Avenue	Durham	CA	95938	
Address of Property Insp	ected	City	State	ZIP	
03/15/2022		11218			
Date of Inspection	Corres	sponding Report No.		Escrow No.	

SECTION I CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

SECTION II ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

FURTHER INSPECTION ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(s) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

1. SUBSTRUCTURE AREA:

1A - Section I

FINDING - Subterranean termite evidence noted at sub flooring and other wood members.

RECOMMENDATION -Treat subsoil with an State approved chemical per State regulations and label instructions for control of subterranean termites.

1B - Section I

FINDING - Minor subterranean termite damage noted to sub flooring.

RECOMMENDATION -Cut out damage and/or repair as needed.

1C - Section II

FINDING - Portions of sub area are inaccessible for physical inspection due to inadequate clearance between soil and plumbing, these areas were visually inspected only.

RECOMMENDATION - There is no economically practical method to make the area accessible, however, it may be subject to attack by wood destroying pests or organisms.

1D - Notes

FINDING - Sub flooring is insulated. Areas of loose and unsecured insulation noted throughout sub area.

RECOMMENDATION - Owners information.

4. PORCHES - STEPS

4A - Section I

FINDING - Fungus damage noted to porch steps.

RECOMMENDATION -Cut out damage and/or repair as needed.

4B - Section II

FINDING - Deck sub framing is inaccessible due to type of construction. It is not practical to open deck for inspection of sub framing.

RECOMMENDATION - No opinion is expressed or implied as to the absence or presence of adverse conditions. Owners information.

One or more of the following chemicals may be used on your property: Premis 75-WP (Imidacloprid) Termidor SC (Fipronil) Timbor (Disodium Octaborate tetrahydrate)

HOBBS PEST SOLUTIONS, INC

Page 4 of 4 inspection re	eport					
9242	Holland Avenue		Durham	CA	95938	
Address of Property Insp	ected		City	State	ZIP	
03/15/2022		11218				
Date of Inspection	(Corresponding Repo	ort No.		Escrow No.	

Vikane (Sulfuryl Fluoride)

Thank you for selecting us to perform a structural pest control inspection on your property. Should you have any questions regarding this report, please call us directly by the contact information provided on the first page of the inspection report.

Our inspectors have determined that your property will benefit from a safe application of chemicals commonly used for structural pest control. In accordance with the laws and regulations of the State of California, we are required to provide you and your occupants with the following information prior to any application of chemicals to such property.

Please take a few moments to read and become familiar with the content. State law requires that you be given the following information:

CAUTION - PESTICIDES ARE TOXIC CHEMICALS. Structural pest control companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the state finds that based on scientific evidence, there are no appreciable risks weighted by the benefits. The degree of risk depends on the degree of exposure, so exposure should be minimized.

If within 24 hours following application, you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center and your pest control operator immediately.

For further information, contact any of the following agencies in your area:

Poison Control Center Agricultural Department Health Department Structural Pest Control Board (800) 222-1222 (530) 538-7381 (530) 538-7581 (916) 561-8700 2005 Evergreen Street, Ste. 1500. Sacramento, CA 95815 P. O. Box 2486

Oroville CA 95965 (530) 624-5390

termite@hobbspestsolutions.com

WORK AUTHORIZATION

Report #: 11218

No work will be	performed until a	signed copy	of this agreement h	as been received.

Address of Property :	9242 Holland Avenue
City:	Durham
State/ZIP:	CA 95938

The inspection report of the company dated, <u>03/15/2022</u> is incorporated herein by reference as though fully set forth. The company is authorized to proceed with the work outlined in the items circled below from the Termite Inspection Report for the property inspected, for a total sum of \$ ______. This total amount is due and payable within 30 days from completion repair work and/or chemical application.

THE COMPANY AGREES

To guarantee all repair completed by this company for one year from date of completion except for caulking, grouting, or plumbing, which is guaranteed for a period of **ninety (90) days**. We assume no responsibility for work performed by others, to be bound to perform this work for the price quoted in our cost breakdown for a period not to exceed 30 days, to use reasonable care in the performance of our work but to assume no responsibility for damage to any hidden pipes, wiring, or other facilities or to any shrubs, plants, or roof.

THE OWNER OR OWNER'S AGENT AGREES

To pay for services rendered in any additional services requested upon completion of work to pay a service charge of one and one-half percent (1 1/2%) interest per month, or portion of any month, annual interest rate of eighteen percent (18%) on accounts exceeding the ten (10) day full payment schedule. The Owner grants to The Company a security interest in the property to secure payment sum for work and inspection fee completed. In case of non-payment by The owner, reasonable attorney fees and costs of collection shall be paid by owner, whether suit be filed or not.

ALL PARTIES AGREE

If any additional work is deemed necessary by the local building inspector, said work will not be performed without additional authorization from owner or owner's agent. This contract price does not include the charge of any Inspection Report fees. Circle the items you wish performed by The Company, below and enter total amount above:

NOTICE TO OWNER

Under the California Mechanics Lien Law, any structural pest control company which contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractor, laborers or suppliers remain unpaid.

To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice." Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

ITEMS						
n Other	S	Section I	Prefix			
0.00		975.00	1A			
0.00		250.00	1B			
0.00		0.00	1C			
0.00		225.00	4A			
0.00		0.00	4B			
0.00		1,450.00	Total:			
			4B Total:			

GRAND TOTAL: 1,450.00

INVOICE / STATEMENT

Hobbs Pest Solutions, Inc P. O. Box 2486 Oroville CA 95965 (530) 624-5390 termite@hobbspestsolutions.com Date: 03/17/2022 Report Number: 11218 Invoice Number: 11218-1 Escrow Number:

Property 9242 Holland Avenue Inspected: Durham, CA 95938

Bill To: Mike Tozier 9242 Holland Avenue Durham, CA 95938 United States

Total Due: \$	0.00
Payments: \$	160.00
Invoice Total: \$	160.00
Inspection: \$	160.00

mtozier@yahoo.com

Description of Service 3/21/2022: Inspection fee paid by credit card transaction. Thank you, Darlene

RETAIN THIS COPY FOR YOUR RECORDS THANK YOU FOR YOUR BUSINESS

CUT HERE **INVOICE / STATEMENT** Date: 03/17/2022 **Hobbs Pest Solutions, Inc** Report Number: 11218 P. O. Box 2486 Invoice Number: 11218-1 Oroville CA 95965 Escrow Number: (530) 624-5390 termite@hobbspestsolutions.com Property 9242 Holland Avenue Inspected: Durham, CA 95938 Inspection: \$ 160.00 Invoice Total: \$ 160.00 Bill To: Mike Tozier Payments: \$ 160.00 Total Due: \$ 9242 Holland Avenue 0.00 Durham, CA 95938 **United States** mtozier@yahoo.com Description of Service 3/21/2022: Inspection fee paid by credit card transaction. Thank you, Darlene