

EQUITY BUILDING INSPECTION

310-872-0037 inspmike@gmail.com

http://www.equityinspection.com



RESIDENTIAL BUILDING INSPECTION

27013 Springcreek Rd Rancho Palos Verdes, CA 90275

> Wei Chung Peng 04/11/2024



Inspector
Michael Boeger
ASHI, CREIA, NACHI
310-540-0200
inspmike@gmail.com

TABLE OF CONTENTS

1: Inspection Details	
2: Utility Shutoff Locations	9
3: Exterior	10
4: Grounds	12
5: Electrical	14
6: Plumbing	19
7: Heating	23
8: Water Heater	25
9: Garage	27
10: Attic/Roof Structure	28
11: Built-In Appliances	29
12: Interior - Doors / Windows	31
13: Laundry Room	33
14: Roofing	34
15: Foundation & Structure	36
16: Fireplace & Chimney	38
17: Conclusion	40
18: Vendors	42
Standards of Practice	43

Equity Building Inspection Page 2 of 43

Client: Wei Chung Peng

How to read this report

The defects within the report are organized into three categories. They are Minor Concern (in blue), Moderate Concern (in orange), and Major Concern (in red). The category that each defect is in does not determine the importance of the recommended repair. All defects noted on this report should be addressed. Health and safety concerns will be in the Moderate Concern or Major Concern, depending on how the perceived danger but these should be addressed ASAP. All repairs should be performed by licensed and/or qualified contractors in order to ensure the repairs are done safely and properly.

Minor Concern: Items or components of the home that are defective and, in the opinion of the inspector, may be considered general maintenance or are typical for the age of the home. Any recommended improvements to the home may also be in this category.

Moderate Concern: Items or components that were found to be defective and, if not addressed, these could lead to further problems. These defects are not considered to be routine maintenance. This category may also contain safety hazards or concerns. Major Concern: Items or components that were defective and may require major/costly repairs. This category may also contain serious safety hazards or concerns that are in need of immediate attention.

These categories are based on the inspectors professional judgement and are based on the conditions at the time of the inspection. This categorization should not be construed as to mean that items designated as a Minor Concern or Moderate Concern do not need need repaired or addressed. The recommendation in each comment is more important than the category in which the defect was placed in.

We have inspected the major structural components and mechanical systems for signs of significant non- performance, excessive or unusual wear and general state of repair. Our inspection is conducted in accordance with the Standards of Practice of the American Society of Home Inspectors. You will also find a copy at the end of this inspection report. The following report is an overview of the conditions observed.

Limitations: In the event that the inspector was not able to inspect/test certain areas or components of the home, there may be a Limitations tab in that section of the report. The Limitations tab may show things that need to be further evaluated after the inspection. I recommend reading any Limitations in the report and addressing them as necessary.

In the report, there may be specific references to areas and items that were inaccessible. We can make no representations regarding conditions that may be present but were concealed or inaccessible for review. With access and and opportunity for inspection, reportable conditions may be discovered. Inspection of the

Equity Building Inspection Page 3 of 43

inaccessible areas will be performed upon arrangement and at additional cost after access is provided.

Photographs: Several photos are in your inspection report. These photos are for informational purposes and may not include every instance or occurrence of a defect. For example, if the report has three photos of hail damage on the roof, this does not mean that there is only hail damage in those areas.

This report should be read in its entirety. Not all information is in the Summary section.

Equity Building Inspection Page 4 of 43

SUMMARY

SUMMARY

This is a summary review of the inspector's findings during this inspection. However, it does not contain every detailed observation. This is provided as an additional service to our client, and is presented in the form of a listing of the items which, in the opinion of your inspector, merit further attention, investigation, or improvement. Some of these conditions are of such a nature as to require repair or modification by a skilled craftsman, technician, or specialist. Others can be easily handled by a homeowner such as yourself.

THE CONDITIONS OUTLINED IN THIS REPORT SHOULD BE EVALUATED BY A QUALIFIED TRADESPERSON PRIOR TO THE END OF THE CONTINGENCY PERIOD! This is important in order to give the tradesperson the opportunity to not only provide you with an estimate for repair or replacement, but also allows him an opportunity to further inspect the item in question. In doing so, they may find the scope of the repair or replacement to be greater than originally thought. This allows you to make a more informed purchase decision.

Please read the entire report. The COMPLETE REPORT consists of: Action Items, Full Report and Inspection Agreement.

Often, following the inspector's advice will result in improved performance and/or extended life of the component(s) in question. In listing these items, your inspector is not offering any opinion as to who, among the parties to this transaction, should take responsibility for addressing any of these concerns. As with most of the facets of your transaction, we recommend consultation with your Real Estate Professional for further advice with regards to the following items:

- 3.4.1 Exterior Trim and Flashing: Trim Damaged
- 4.8.1 Grounds Stairs Guardrails Handrails: Guardrails Missing
- 4.9.1 Grounds Planters: No Drains
- △ 5.3.1 Electrical Service Panel(s) / Wiring: Federal Pacific / Stab-Lok / Sylvania
- 5.5.1 Electrical Branch Wiring : Conduit In Need of Repair
- ⊙ 5.7.1 Electrical Receptacles: Receptacles 3 Prong Ungrounded 2 Wire
- 5.8.1 Electrical Lighting: Light Fixture Unsecured
- ▲ 5.11.1 Electrical Smoke & Carbon Monoxide Alarms: Carbon Monoxide Alarms Missing
- ▲ 5.11.2 Electrical Smoke & Carbon Monoxide Alarms: Smoke Alarm Missing
- ▲ 5.12.1 Electrical GFCI & AFCI: GFCI Protection Not Installed
- 6.3.1 Plumbing Water Supply: Supply Not properly secured
- 6.4.1 Plumbing Drain, Waste, & Vent Systems: Drain Stop Defective
- 6.4.2 Plumbing Drain, Waste, & Vent Systems: Cast Iron Crawl Warning
- 6.5.1 Plumbing Faucets: Faucet In Need of Repair

Equity Building Inspection Page 5 of 43

- 6.8.1 Plumbing Bathtub: Jetted Tub Inoperable
- ♠ 6.11.1 Plumbing Gas Supply: No earthquake shutoff
- 7.2.1 Heating Forced Air Furnace: No walkway to unit
- 2 11.2.1 Built-In Appliances Range Hood: Light Inoperable
- 11.4.1 Built-In Appliances Dishwasher: Dishwasher Airgap Leaking
- 11.5.1 Built-In Appliances Cooktop: Cooktop Burner Not Operating
- 12.4.1 Interior Doors / Windows Windows: Failed Seal
- 14.2.1 Roofing Asphalt Roofing: Roofing surface Cracked and/or Brittle
- 14.8.1 Roofing Gutters: Damage
- 14.9.1 Roofing Chimneys & Other Roof Penetrations: No rain cap/spark arrestor
- ◆ 15.6.1 Foundation & Structure Ventilation/Insulation: Decorative screen covers
- 16.3.1 Fireplace & Chimney Gas Log: Fireplace Damper Missing or Not Locked Open
- 2 16.3.2 Fireplace & Chimney Gas Log: Clean & Service
- 16.3.3 Fireplace & Chimney Gas Log: Flie dirty

Equity Building Inspection Page 6 of 43

1: INSPECTION DETAILS

Information

General: Overview

A building inspection is a non invasive, visual examination of the accessible areas of the property, designed to identify areas of concern within specific systems or components defined by the ASHI Standards of Practice, that are both observed and deemed material by the inspector at the exact date and time of inspection. Any and all recommendations for repair, replacement, evaluation, and maintenance issues found, should be evaluated by the appropriate trades contractors within the clients inspection contingency window or prior to closing, which is contract applicable, in order to obtain proper dollar amount estimates on the cost of said repairs and also because these evaluations could uncover more potential issues than able to be noted from a purely visual inspection of the property.

This inspection will not reveal every concern or issue that exists, but only those material defects that were observable on the day of the inspection. This inspection is intended to assist in evaluation of the overall condition of the dwelling only. This inspection is not a prediction of future conditions and conditions with the property are subject to change the moment we leave the premises.

Repair Estimates

If your inspector provides repair estimates understand that these are just that....ESTIMATES! These estimates can vary greatly depending on a number of factors. These estimates are provided as a courtesy only and should not be the sole source of estimating total repair or replacements needed.

For Agents

Viewing the summary may be a more efficient use of your time! You can click the summary button under my name for viewing online or on the right side is the PDF button that allow you to view or print the summary only. On the top edge is the "Agent Tools" button that opens a window you can easily copy/paste from. Scroll up to the top of the report to choose the options shown in the picture below.



General: Clients NameWei Chung Peng

General: Type of InspectionPre-Listing

General: Type of BuildingSingle Family Residence

General: What really matters in a Home or Building Inspection

Relax. Most of your inspection will be maintenance recommendations, life expectancies for various systems and components, and minor imperfections. These are useful to know about. However, the issues that really matter will fall into these areas:

Major defects. An example of this would be a structural failure or things that lead to major defects, such as a small roof-flashing leak, for example.

Things that may hinder your ability to finance, legally occupy, or insure the home; and safety hazards, such as an exposed, live buss bar at the electrical panel or expose, accessible live wires.

Anything in these categories should be addressed. Often, a serious problem can be corrected inexpensively to protect both life and property.

Most sellers are honest and are often surprised to learn of defects uncovered during an inspection. Realize that sellers are under no obligation to repair everything mentioned in the report. No home is perfect. Keep things in perspective. Do not kill your deal over things that do not matter. It is inappropriate to demand that a seller address deferred maintenance, conditions already listed on the seller's disclosure, or nit-picky items.

Equity Building Inspection Page 7 of 43

General: In Attendance

Listing Agent

General: Things To Know

Scope: The scope of this inspection is limited to reasonably accessible areas. We make no attempt to move furnishings, stored personal property, and or vegetation.

Note: California has seasonable rains which occur at the end and the beginning of each calendar year. Occasionally, the rainfall is exceptionally high. This is called an El Nino year. The duty of a home inspector is to disclose visible conditions. If a condition is not visible it cannot be reported.

Note: Read the Standards of Practice set forth by the American Society of Home Inspectors for an insight into the scope of the inspection.

Note: The inspection represents the condition of the visually inspected areas of the property on the date of the inspection. Component conditions may change between the date of the inspection and the title transfer date. A thorough walk-through prior to title transfer helps protect against unexpected surprises, and is recommended. **The purchase of a home warranty is recommended.**

LIFE EXPECTANCIES

The following link will give you a chart of the life expectancies of most home products and materials. Click HERE

Notice to Third Parties: This report is the exclusive property of Equity Building Inspection and the Client(s) listed above and is not transferable to any third parties or subsequent buyers. Our Inspection and this report have been performed with a written contract agreement that limits its scope and usefulness. Unauthorized recipients are therefore advised not to rely upon this report, but rather to retain the services of an appropriately qualified property inspector of their choice to provide them with their own inspection and report.

Note: For the purpose of this report, all directional references (left, right, rear, front) are based on when facing the front of the structure as depicted in the cover image above.

Limitations

General

OCCUPIED/FURNISHED DISCLAIMER

If during the inspection, the building was furnished, staged, occupied, or had the current occupants belongings present. This limited the inspectors visibility and access to areas of the building, therefore not all receptacles, windows, wall surfaces, floor surfaces, countertop areas, etc. were tested or inspected.

Equity Building Inspection Page 8 of 43

2: UTILITY SHUTOFF LOCATIONS

Information

Gas - Main Shut Off Valve: Location

Right side

I recommend that everyone living in the home familiarizes themselves with the location of the gas meter and the disconnect used to shut off the gas to the whole house.



Water - Main Shut Off Valve: Location

Front of building

I recommend that everyone living in the home familiarizes themselves with the location of the main water supply.



Equity Building Inspection Page 9 of 43

3: EXTERIOR

Information

General: Exterior Notes

The visible exterior surfaces and materials of the building were observed to determine their current condition. Areas concealed from view by any means are excluded from this report. Moisture intrusion through cracks or openings in the exterior siding, trim, windows, and doors are the source of moisture deterioration and damage. We recommend sealing all cracks or openings in, and between the exterior siding and trim materials, especially around windows and doors. Keep in mind that if this is a condo or townhome, we may make a specific comment concerning a deck or balcony but this would not include an entire exterior inspection as these areas would be covered under the Homeowners Association.

General: Ok, Items to note

The exterior components were found to be in fair to good condition based on their age with exceptions noted here or in other sections of this report.

General: Construction Material

Wood Frame

Stucco: Stucco ok

The stucco siding was found to be in acceptable condition with possible exceptions noted here in the report.

Wood Siding: Wood siding ok

The wood siding was found to be in overall good condition based on its age. With exceptions noted herein the report.

Trim and Flashing: Trim ok

The numerous building trim components, including eaves, facia, door and window trim, were found to be in acceptable condition with exceptions found here in this report.

Doors: Ok both doors and windows

Both the exterior doors and windows were found to be in serviceable condition except where noted and other parts of this report.

Windows: Caulk all windows

We recommend periodic inspection of all exterior window frames. We recommend ensuring there is proper caulking around all of the window frames to prevent water intrusion.

Observations

3.4.1 Trim and Flashing

TRIM - DAMAGED

NUMEROUS LOCATIONS



Areas of the building trim are damaged. I recommend having these areas evaluated and repaired/replaced as necessary by a licensed contractor. Please see your termite report for possible further information.

Equity Building Inspection Page 10 of 43

Recommendation

Contact a qualified siding specialist.



Equity Building Inspection Page 11 of 43

4: GROUNDS

Information

Grading: Grading Outline

Grading / Lot Drainage: Grading / Drainage Overview The grading around the home was inspected to determine that it was designed to allow rainwater to adequately drain away from the structure. The soil is recommended to slope away from the home, with a 6 inch drop in elevation, in the first 10 feet away from the structure (5% grade). When the 5% grade can not be achieved, swales or drains should be used as needed to properly divert rainwater runoff. Any flat or low areas around the home should be backfilled and sloped away from the foundation, to prevent potential moisture infiltration into areas below grade. No reportable deficiencies were observed at the time of inspection unless otherwise noted in this report. Grading / Lot Drainage: Grading Limitations The performance of lot drainage and the grading are limited to the conditions existing at the time of the inspection only. I cannot guarantee this performance as conditions constantly change. Heavy rain or other weather conditions may reveal issues that were not visible or foreseen at the time of inspection. Furthermore, items such as leakage in downspouts and gutter systems are impossible to detect during dry weather and can add moisture to the soil in the area around the foundation. The inspection of the grading and drainage performance in relation to moisture infiltration through foundation walls, therefore, is limited to the visible conditions at the time of inspection, and evidence of past problems. I recommend consulting with the sellers as to any previous moisture intrusion into the home, and / or ensuring that the Sellers disclosure has no mention of moisture infiltrating the structure.

Grading: Grading OK

The grading of the lot appears to properly and adequately drain excess surface water and roof runoff away from the structure with exceptions noted herein.

Grading: Subsurface Drainage

The surface water drainage system is below grade and cannot be viewed. Designs and materials for these systems vary widely, making it impossible to evaluate the integrity of the system with any certainty. We recommend inquiries of the seller regarding past performance of these drains.

Driveway - Patio, Walkways: Driveway - OK

The driveway was in good condition based on its age. Small cracks are normal.

Driveway - Patio, Walkways: Walkways - OK

The walkways were found to be in good condition based on their age unless noted in other parts of this report. Minor cracking is normal.

Driveway - Patio, Walkways: Grounds / Drive / Walkways General Information

Driveway and Walkway Condition: Driveway/Walkway Information The driveways and walkways (if applicable) were inspected to determine their affect on the structure of the home only. I will also report on any visible deficiencies that may be present such as; cracking, displacement, or other damage. Any comments relating to damage to the concrete, asphalt, and/or masonry surfaces should be viewed as a courtesy and may not be an all-inclusive listing. No deficiencies were present at the time of inspection unless otherwise noted in this report.

Fence - Gates: Fences Gates ok

The fences and or gates were found to be in serviceable condition when inspected.

Irrigation: Irrigation System Not Tested

The irrigation, if installed, is not within the scope of this general building inspection.

Observations

Equity Building Inspection Page 12 of 43

4.8.1 Stairs - Guardrails - Handrails



GUARDRAILS - MISSING

REAR

Areas on the exterior are missing guardrails. Areas higher than 30 inches from the ground are recommended to have guardrails in order to prevent accidents/injuries. I recommend having guardrails added by a licensed contractor.

Recommendation

Contact a qualified professional.



4.9.1 Planters

NO DRAINS



The planter lacks the proper "weep" holes at its bottom. These drain holes should be installed about every 6' to allow water to drain away from the building. We recommend repair.

Recommendation

Contact a qualified landscaping contractor





Equity Building Inspection Page 13 of 43

5: ELECTRICAL

Information

Basic Information: Electrical Notes

An electrical system consists of the service, distribution, wiring and convenience outlets (switches, lights, and receptacles). Our examination of the electrical system includes the exposed and accessible conductors, branch circuitry, panels, overcurrent protection devices, and a random sampling of convenience outlets. We look for adverse conditions such as improper installation, exposed wiring, running splices, reversed polarity and circuit protection devices. We do not evaluate fusing and/or calculate circuit loads. The hidden nature of the electrical wiring prevents inspection of every length of wire.

Basic Information: Electrical Service Conductors:

Overhead service, Copper, 120/240 volt service

Basic Information: Service
Grounding Electrode:
None visible

Basic Information: Service Panel

Ampacity: 100 amps

Appears adequate for this building.

Basic Information: Ground Fault Circuit Interruptor (GFCI) Protection:

NO

Basic Information: Service

Disconnect Type:

Breaker

Basic Information: Service
Disconnect Location:
At Service Panel

Basic Information: Arc Fault Circuit Interruptor (AFCI) Protection:

NO

Basic Information: Recommend further evaluation by qualified electrician

Based on one or more portions of the electrical system, we recommend a licensed electrical contractor be consulted for further information and inspection.

Service Panel(s) / Wiring: Picture of Service Panel

Branch Wiring: Branch Wiring


Copper

Equity Building Inspection Page 14 of 43

Receptacles: Exterior Light Fixtures Disclaimer

Exterior light fixtures can be on motion detectors, from dusk to dawn sensors, timers, etc. For this reason, we are not always able to confirm whether exterior lights work.

Smoke & Carbon Monoxide Alarms: CA Health and Safety Code 13113.7



California Health and Safety Code 13113.7 and 17926 and 310.9.1.4 of the California Building Code.

Smoke and Carbon Monoxide Detectors:

Proper placement requires one smoke detector for each floor of dwellings where no sleeping quarters are located, in addition to one smoke detector in each sleeping quarters and one smoke detector in all hallways adjacent to sleeping quarters. Enclosed stairwells that provide service to multiple dwellings are required to have a smoke detector. These smoke detectors must be the type that have the 10 year battery life, have a hush feature and a place to write the installation date. Exception being if the existing units are hard wired.

Carbon Monoxide Detectors:

Proper placement requires one carbon monoxide detector in all hallways adjacent to sleeping quarters in dwellings that have gas burning appliances and on every level of the building.

Smoke & Carbon Monoxide Alarms: Units not tested

The actual testing of smoke and carbon monoxide detectors is beyond the scope of this inspection. We report on the proper location of the individual units only. We recommend testing your units every six months. Also, if your detectors are more than 3 years, we recommend replacement.

Smoke & Carbon Monoxide Alarms: Not tested

We do not actually test the smoke or carbon monoxide detectors. Testing of These devices during a home inspection will not provide definitive proof that these detectors will respond as needed in the event of a fire or a carbon monoxide leak. The batteries (if any) should be replaced with new ones when you move into the house, and tested on a monthly basis thereafter.

Limitations

Grounding

COULD NOT LOCATE

We could not visually confirm grounding of the electrical system. Confirmation will require further inspection by a qualified electrician.

Observations

5.3.1 Service Panel(s) / Wiring

FEDERAL PACIFIC / STAB-LOK / SYLVANIA



Equity Building Inspection Page 15 of 43

One or more panels were manufactured by the Federal Pacific Electric company (also none as Sylvania brand and Zinsco) and used "Stab-Lok" circuit breakers. Due to the safety issues involved, we do not open these panels. There is evidence that both double and single pole versions of these circuit breakers fail by not tripping when they are supposed to, which in term often leads to breakers overheating and in some cases, electrical fires. Due to evidence of safety issues, it is recommended that a qualified electrician carefully evaluate all Federal Pacific panels and make recommendations. Some insurance companies in the state are not offering property insurance with this manufacturer's panel installed in single family homes that require a 4 point insurance inspection. For more information on the issues with these panels, you can go HERE and HERE



Recommendation

Contact a qualified electrical contractor.

5.5.1 Branch Wiring

Recommendation

CONDUIT - IN NEED OF REPAIR

The electrical conduit in need of repair. I recommend having the circuit evaluated and the conduit repaired/replaced as necessary by a licensed electrician. (not properly attached to the building.)

Recommendation

Contact a qualified electrical contractor.



5.7.1 Receptacles

RECEPTACLES - 3 PRONG UNGROUNDED 2 WIRE


NUMEROUS LOCATIONS

3-slot receptacles (outlets) were installed in one or more areas without a ground wire hookup. These do not have an equipment ground. These outlets should either be upgrade to grounded receptacles, which typically requires installing new wiring from the main panel. The NEC (National Electric Code) also allows these outlets to be replaced with GFCI protection as a repair to use grounded appliances with them. Appliances that require a ground should not be used with ungrounded receptacles. Examples of such appliances include computers and related hardware, refrigerators, freezers, portable air conditioners, clothes washers, aquarium pumps, and electrically operated gardening tools. The client should be aware of this limitation when planning use for various rooms, such as an office. Consult with a qualified electrician about upgrading to 3-wire, grounded circuits or installing GFCI protection.

Recommendation

Contact a qualified electrical contractor.





Equity Building Inspection Page 16 of 43

5.8.1 Lighting

LIGHT FIXTURE - UNSECURED



GARAGE

The light fixture(s) was loose and/or not properly secured to the box. I recommend having the fixtures properly secured by a licensed electrician.

Recommendation

Contact a qualified handyman.



5.11.1 Smoke & Carbon Monoxide Alarms

CARBON MONOXIDE ALARMS MISSING



No (or insufficient number) of permanently installed carbon monoxide alarms were found (or are in the incorrect location). This is a potential safety hazard. Recommend installing approved CO alarms outside of each separate sleeping area in the immediate vicinity of the bedrooms, on each level of the structure and in accordance with the manufacturer's recommendations.

Recommendation

Contact a handyman or DIY project

5.11.2 Smoke & Carbon Monoxide Alarms

A Safety Hazard

SMOKE ALARM - MISSING

There were missing smoke alarms in the home. They are required in each bedroom, outside each bedroom within 15 feet of the bedroom and one on each floor of the home.

Recommendation

Contact a qualified professional.

5.12.1 GFCI & AFCI



GFCI PROTECTION NOT INSTALLED


GARAGE, KITCHEN, BATHROOMS

The receptacle(s) was not GFCI protected at the following areas. Although, these receptacles may not have been required at the original time of construction, we highly recommend they be installed in order to protect against electrical shock. Note: Anytime you upgrade or remodel an area, that area shall conform to the current building standard.

Recommendation

Contact a qualified electrical contractor.

Equity Building Inspection Page 17 of 43



Equity Building Inspection Page 18 of 43

6: PLUMBING

Information

Basic Information: Plumbing Notes

A plumbing system consists of the domestic water supply lines, drain, waste and vent lines and gas lines. Inspection of the plumbing system is limited to visible faucets, fixtures, valves, drains, traps, exposed pipes and fittings. These items are examined for excessive or unusual wear, leakage, and general state of repair. The hidden nature of piping prevents inspection of every pipe and joint. The actual shut off valves are not operated during our visual inspection. A sewer lateral test, necessary to determine the condition of the underground sewer lines, is beyond the scope of this inspection If desired, a qualified individual could be retained for such a test. Our review of the plumbing system does not include landscape watering, fire suppression systems, operating any shutoff valves, private water supply/waste disposal systems, or recalled plumbing supplies. Review of these systems requires a qualified and licensed specialist.

Basic Information: Main Water

Line

Copper

Basic Information: Supply Water Line

Copper

The type of supply piping is listed above. This is only a small visible section of the supply plumbing. Other plumbing materials may be present buy were not detected at the time of the inspection. There are many variables as to the exact lifespan of various supply plumbing materials.

Basic Information: Water Service Basic Information: Drain Line

Drain Type Materials

Public ABS, Cast Iron

Basic Information: Ok, With Exceptions

The plumbing system was found to be in serviceable condition with the possible exceptions noted herein.

Service / Water Pressure: Service / Water Pressure: Water

Pressure Regulator Present Pressure
No 60-70 PSI

Water Supply: Water Supply Serviceable

The water supply plumbing was inspected and found to be in working order with exceptions noted within this report.

Drain, Waste, & Vent Systems: Plumbing Drainage System

The buildings plumbing drains, and their related equipment, were found to be in working order with possible exception noted herein.

Faucets: Low Flow Fixtures Toilet: Low Flow Toilets Installed Bathtub: Jetted Tub

Installed Yes The jetted tub was filled and the

Can Not Determine jets were then tested for

function.

Gas Supply: Overall Gas line condition

The visible gas line were found in good condition bases on the age of the building.

Limitations

Equity Building Inspection Page 19 of 43

Wei Chung Peng 27013 Springcreek Rd

Service / Water Pressure

NOT TESTED

The main shut-off valve was located but testing the operation of this valve is not within the scope of our inspection. Operation of the valve from time to time will keep it functional and maximize its useful life.

Observations

6.3.1 Water Supply

SUPPLY - NOT PROPERLY SECURED



UNDER BEDROOM

Sections of the visible supply plumbing we not properly supported or attached. We recommend repair to prevent possible damage to the supply plumbing.

Recommendation

Contact a qualified plumbing contractor.



6.4.1 Drain, Waste, & Vent Systems

DRAIN STOP DEFECTIVE

HALL BATHROOM TUB

The drain stop is either defective for missing. We recommend further inspection and repair or replacement. Clcik HERE for information on how to easily repair your drain stop.

Recommendation

Contact a qualified handyman.

6.4.2 Drain, Waste, & Vent Systems

CAST IRON CRAWL WARNING





Equity Building Inspection Page 20 of 43

Some or all of the drain lines and vent pipes are made of cast iron. This material has a useful life span of 50-75+ years depending on conditions. No observable leaks were found at time of inspection but client should plan on budgeting for replacement of drain lines in the future. Periodic checkups in the crawl space should be performed to ensure that waste-water is not leaking into crawlspace areas.

Recommendation

Contact a qualified plumbing contractor.



6.5.1 Faucets

FAUCET - IN NEED OF REPAIR



The faucet(s) is in need of repair. I recommend having the faucet evaluated and repaired/replaced as necessary by a qualified plumbing contractor.

Recommendation

Contact a qualified plumbing contractor.



6.8.1 Bathtub

JETTED TUB - INOPERABLE



The jetted tub was not functioning during the inspection. I recommend having it evaluated and repaired as necessary by a licensed contractor.

Recommendation

Contact a qualified professional.

6.11.1 Gas Supply

NO EARTHQUAKE SHUTOFF



Equity Building Inspection Page 21 of 43

There was no earthquake gas shutoff valve. Some jurisdictions require this safety device.

Recommendation

Contact a qualified professional.

Equity Building Inspection Page 22 of 43

7: HEATING

Information

General Information: Your Responsibility

Most HVAC (heating, ventilating and air-conditioning) systems in houses are relatively simple in design and operation. They consist of four components: controls, fuel supply, heating or cooling unit, and distribution system. The adequacy of heating and cooling is often quite subjective and depends upon occupant perceptions that are affected by the distribution of air, the location of return-air vents, air velocity, the sound of the system in operation, and similar characteristics.

It is important to get the HVAC system inspected and serviced every year. And if you're system as an air filter, be sure to keep that filter cleaned.

General Information: Heating Notes

A heating system consists of the heating equipment, operating and safety controls, venting and the means of distribution. These items are visually examined for proper function, excessive or unusual wear and general state of repair. This is a non-evasive, basic function review only. We do not dismantle, uncover or calculate efficiency of any system. Regular servicing and inspection of heating systems is encouraged.

General Information: Heating

Type

Gas Fired Forced Air

General Information: AFUE Rating

AFUE (Annual fuel utilization efficiency) is a metric used to measure furnace efficiency in converting fuel to energy. A higher AFUE rating means greater energy efficiency. 90% or higher meets the Department of Energy's Energy Star program standard.

Forced Air Furnace: Equipment Photo

Forced Air Furnace: Heater Age

Unknown

Forced Air Furnace: Thermostat Location

Hallway

Forced Air Furnace: Energy

Source

Natural Gas

Forced Air Furnace: Operating Properly

The heating system(s) were tested and operated properly with possible exceptions noted below. We recommend periodic maintenance by a qualified technician.

Forced Air Furnace: Ductwork Ducts and Registers: Type

Insulated Ducts and Registers

Limitations

Equity Building Inspection Page 23 of 43

Ducts and Registers

NOT VISIBLE

Some or all of the ducting were inaccessible and could not be viewed or inspected.

Observations

7.2.1 Forced Air Furnace

Recommendation

NO WALKWAY TO UNIT

Every attic installed heating system must have a platform that you can crawl or walk to from the attic entry to the unit. The attic is also too small to properly install a new heater or remove the old one. The entry must be 30° x 22° minimum. We recommend repair.

Equity Building Inspection Page 24 of 43

8: WATER HEATER

Information

Water Heater: Water Heater Notes

The water heater(s) was visually inspected in order to ensure proper installation and that no leaks, rust, or corrosion were present. The temperature of the water was also checked to ensure the water heater was functioning properly. The American Society of Sanitary Engineering recommends setting the temperature of home water heaters to 135 degrees to 140 degrees Fahrenheit, a range shown to destroy bacteria such as Legionella. At those temperatures, bacteria can neither thrive or survive to contaminate fixtures downstream from the heater. Adjusting a water heater to a higher temperature must always be accompanied by the installation of anti-scald devices in the home by a licensed plumber to prevent potential burn injuries.

Any defects are noted below.

Here is a nice maintenance guide from Lowe's to help.

Water Heater: Energy Source / Water Heater: Capacity Water Heater: Water Heater

Type 40 Gallon **Age(s)**Gas, Tank 2024

Water Heater: Location

Garage

Water Heater: Ok

The water heater(s) was installed properly and operated as designed with exceptions noted below.

Water Heater: Earthquake straps Water Heater: Equipment Photo

Yes



Water heater gas/TPR: TPR Valve

A TPR valve was in place. These are not tested due to the fact that once they are tested, they tend to form a drip leak. These valves allow the water heater to expel water and pressure if the tank reaches a pressure over 150psi, or the water temperature exceeds 210 degrees. No deficiencies were observed with the valve unless otherwise noted in this report.

Equity Building Inspection Page 25 of 43

Earthquake Straps: Earthquake Straps

Earthquake straps are required in the state of California. These straps are required to be installed in a specific method. Escrow can not close unless there is documentation that these straps are indeed installed properly.

Equity Building Inspection Page 26 of 43

9: GARAGE

Information

General: Vehicle DoorSectional, Roll-up

General: Method of Operation
Automatic Garage Door Opener

Garage Door Opener and Safety: Photo Eye Safety Feature

The garage door opener(s) were equipped with photo eyes. This is a safety feature that prevents the door from closing if the beam in between the photo eyes is broken. This feature was tested and any defects are noted below.

Garage Door Opener and Safety: Auto Reverse Safety Feature

The garage door opener(s) are equipped with a safety feature known as Auto Reverse. If resistance is placed on the bottom of the garage door while coming down, the door automatically reverses and goes back up. This feature was tested, any defects are noted below.

Floor: Material Concrete

Equity Building Inspection Page 27 of 43

10: ATTIC/ROOF STRUCTURE

Information

Access: Access Location(s)

Hallway

Access: How Viewed

No Walking Surface / Viewed

From Hatch

Access: Attic ok

The attic's major components were inspected and found to be in serviceable condition with exceptions noted to herein.



Attic Insulation: Insulation Type

Fiberglass Roll

Attic Insulation: Estimated R

Value

Not Determined

Exhaust & Ventilation: Sufficient

The existing attic ventilation system appeared to be serviceable.

Equity Building Inspection Page 28 of 43

11: BUILT-IN APPLIANCES

Information

General: All ok

All of the built-in appliances were operated using normal controls and found to be in good condition with exceptions noted herein.

Range Hood: Range Hood

The range hood was visually inspected and the exhaust fan and light were tested. Any defects are noted below.

Range Hood: Venting Method

Vented to Exterior

Dishwasher: Dishwasher

When able, dishwashers are visually inspected and then tested by running them through a brief cycle. The areas around the dishwasher and under the kitchen sink are then checked for leaks. Any defects are noted below.

Cooktop: Cooktop

The cooktop was visually inspected and each burner was tested to ensure that they functioned properly. Any built-in exhaust systems present were tested. Any defects are noted below.

Cooktop: Power Source Cooktop: Vent Method

Natural Gas Range Hood

Wine Refrigerator: Wine Refrigerator

The miniature refrigerator was checked to ensure that it was cooling properly and that it was in good physical condition.

Observations

11.2.1 Range Hood

LIGHT-INOPERABLE



The range hood light(s) were inoperable. I recommend having the bulbs replaced and the circuit addressed if necessary.

Recommendation

Contact a qualified handyman.

11.4.1 Dishwasher



DISHWASHER - AIRGAP LEAKING

The air gap for the dishwasher was leaking during operation. I recommend having this evaluated and repaired as necessary by a qualified appliance repair contractor.

Recommendation

Contact a qualified professional.

Equity Building Inspection Page 29 of 43

11.5.1 Cooktop

Recommendation

COOKTOP - BURNER NOT OPERATING

The burner(s) were not functioning. I recommend having this evaluated and repaired/replaced as necessary by a qualified appliance repair technician.

Recommendation

Contact a qualified appliance repair professional.



Equity Building Inspection Page 30 of 43

12: INTERIOR - DOORS / WINDOWS

Information

General: Interiors overall

Our review of the interior includes inspection of walls, ceiling, floors, doors, windows, steps, stairways, balconies and railing. These features are visually examined for proper function, excessive wear and general state of repair. Some of these components may not be visible/accessible because of furnishings and/or storage. In such cases these items are not inspected.

General: Overall Ok

The interior walls, floors, and ceiling surfaces were properly installed and generally in serviceable condition, taking into consideration normal wear and tear with exceptions noted herein this report.

General: Obvious addition or modification.

There are one or more areas that have been work done which may not be permitted. We recommend further review of any and all permits and plans.

Surfaces Overall: Normal Wear and Tear

The interior wall, floor, and ceiling surfaces were properly installed and generally in serviceable condition, taking into consideration normal wear and tear. Exceptions are noted in other areas of the report.

Doors: Doors and windows ok

Both the interior doors and windows were inspected and found to be in serviceable condition except for items noted elsewhere in this report.

Windows: MaterialVinyl, Double Glazed

Observations

12.4.1 Windows

FAILED SEAL





The window(s) appeared to have a failed seal. Some windows have two or more sheets of glass separated by a spacer and sealant system creating a sealed airspace. A break in this seal anywhere along the edge can allow moisture between the glass panes, which can then evaporate and leave a fog or haze. I recommend having the windows evaluated and repaired/replaced as necessary by a licensed window contractor.

Recommendation

Contact a qualified window repair/installation contractor.

Equity Building Inspection Page 31 of 43









Equity Building Inspection Page 32 of 43

13: LAUNDRY ROOM

Information

General: Unit installed

None

General: All ok

Both the washer and dryers visible hookups were found to be in acceptable condition where visible. We recommend cleaning the dryer vent on a regular basis to prevent buildup. the operation of these units is outside the scope of this type of inspection.

General: Dryer Power Source General: Dryer Vent

110 Volt, Gas Metal

Dryer Vent: Dryer Vent Information

Dryer Vents

o Duct length - The maximum developed length of a clothes dryer exhaust duct shall not exceed 35 feet from the dryer location to the wall or roof termination. The maximum length of the duct shall be reduced 2.5 feet for each 45-degree (0.8 rad) bend, and 5 feet for each 90-degree (1.6 rad) bend. The maximum length of the exhaust duct does not include the transition duct.

o Termination Point Clearances - Dryer vent termination point should be a minimum of **3 feet from any other opening**; window, door, other vents, etc. Dryer vents termination point should be at least **6 feet from the A/C condensing unit.** Dryer vents should not terminate within **3 feet from the gas regulator**, since they could blow lint or moisture on the vent, which could then freeze. The dryer vent termination should be at least **12 inches from the ground**.

- o No screws should be used as they can catch lint.
- o Dryer ducts are required to be metal with a smooth interior. So no flexible materials (foil or semi-rigid aluminum).
- o PVC can not be used. The static will cause lint to cling to it.

Dryer Transition Vents

o Can not be longer than 8ft and a solid piece (no seams).

Equity Building Inspection Page 33 of 43

14: ROOFING

Information

General: Pictures of the Roof









General: Roof Notes

NOTE: We are not licensed roofing contractors. Feel free to hire one prior to closing. A roof system consists of the surface materials, connections, penetrations and drainage (gutters and downspouts). We visually review these components for damage and deterioration and do not perform any destructive testing. If we find conditions suggesting damage, improper application, or limited remaining service life, these will be noted. We may also offer opinions concerning repair and replacement. Opinions stated herein concerning the roof are based on a limited visual inspection. These do not constitute a warranty that the roof is, or will remain, free of leaks.

General: Inspection Method General: Roofing Material

Climed onto surface Asphalt

Asphalt Roofing: Roofing surface ok

The roofing surface was found to be in acceptable condition based on its age with possible exceptions noted herein. Periodic maintenance will prolong its life.

Flashings & Seals: Flashings ok

All visible accessible flashings were inspected and found to be in serviceable condition. These flashings may need maintenance from time to time.

Observations

Equity Building Inspection Page 34 of 43

14.2.1 Asphalt Roofing



Recommendation

ROOFING SURFACE CRACKED AND/OR BRITTLE

Numerous areas of the roofing surface were cracked and/or brittle. This is an indication that the roof covering is in its advanced years and may have approximately 1-2 years of total life remaining. For further information and repair, we recommend contacting a qualified licensed roofing contractor.

Recommendation

Contact a qualified roofing professional.



14.8.1 Gutters

DAMAGE

Damage was observed on areas of the gutters. I recommend having these sections evaluated and repaired/replaced as necessary by a licensed gutter contractor.

Recommendation

Contact a qualified gutter contractor



14.9.1 Chimneys & Other Roof Penetrations

NO RAIN CAP/SPARK ARRESTOR



The rain cap and or spark arrestor was missing from the chimney. We recommend repair.

Recommendation

Contact a qualified professional.




Equity Building Inspection Page 35 of 43

15: FOUNDATION & STRUCTURE

Information

Access: How Viewed
Viewed From Hatches

Access: Crawlspace Views







Foundation: Foundation/Crawl Space

The crawl space is where most of the building's structural elements and portions of its mechanical systems are located. These include foundation, structural framing, electrical, plumbing and heating. Each accessible and visible component and system is examined for proper function, excessive or unusual wear and general state of repair. It is not unusual to find occasional moisture and dampness in crawl spaces. Significant and/or frequent water accumulation can adversely affect the building foundation and support system and would indicate the need for further evaluation by a specialist. Although observed in the crawl space, some items will be reported under the individual systems to which they belong.

Foundation: Style
Crawlspace

Foundation: Location of Crawl Space Entrance NA Ventilation/Insulation: Insulated

No

Equity Building Inspection Page 36 of 43

Ventilation/Insulation: Ventilation OK

The sub area ventilation was found to be installed properly and provides adequate ventilation to the area.

Limitations

Access

PARTIALLY INSPECTED

The crawl space was only able to be partially inspected due to height, framing configuration, insulation levels, ductwork, or a combination of any of the afore-mentioned. The inspector makes every attempt to inspect the entire crawl space however, the comments herein are limited to what the inspector could gain access to when inspecting.

Observations

15.6.1 Ventilation/Insulation



DECORATIVE SCREEN COVERS

NUMEROUS LOCATIONS

There are one or more decorative sub area ventilation screen covers installed. These restrict the flow of air to the sub area. We recommend removing these covers for better ventilation.

Recommendation

Contact a qualified professional.



Equity Building Inspection Page 37 of 43

16: FIREPLACE & CHIMNEY

Information

General: NOTE:

We recommend that all wood burning fireplaces have a Level II Chimney Inspection performed by a certified chimney sweep prior to closing. The inspection of a chimney during a whole home inspection can account for less than 20% of the system.

General: Serviceble Condition

The fireplace, and it's related components, are in in serviceable condition, with exceptions noted herein, at the time of the inspection.

Gas Log: Photo of Gas Log(s)



Limitations

Gas Log

NOT OPERATED

The gas burning fireplace was not tested as this is outside the scope of this type of inspection.

Observations

16.3.1 Gas Log

FIREPLACE DAMPER - MISSING OR NOT LOCKED OPEN



The damper clamp is missing or the fireplace damper is not locked in the open position. A damper is meant to open and close, but is meant for wood burning fireplaces. Once a gas log is installed, the damper should be locked in the open position. This is to prevent the gas log from being lit with the damper closed, which could cause carbon monoxide to back up into the home. I recommend having the fireplace evaluated and the damper locked in the open position by a qualified fireplace contractor.

Click here to find an NFI (National Fireplace Institute) Certified Specialist

16.3.2 Gas Log

CLEAN & SERVICE



Equity Building Inspection Page 38 of 43

I recommend having the gas logs(s) cleaned and serviced by a qualified fireplace contractor.

Click *here* to find an NFI (National Fireplace Institute) Certified Fireplace Specialist.

16.3.3 Gas Log

FLIE DIRTY



The chimney flue showed signs of excessive dirt and soot buildup. We recommend having a chimney expert come in further evaluating the chimney and having it cleaned.

Equity Building Inspection Page 39 of 43

17: CONCLUSION

Information

General: Pre Closing Checklist

PRE-CLOSING WALK-THROUGH RECOMMENDATIONS

The following are recommendations for the pre-closing walk-through of your new house (if applicable).

The home inspection report states the condition of the home at the time of inspection. It does not state future events and the home is in the possession of the seller many times for 60 days or more after the inspection is complete. The inspection report does not predict or state the remaining life expectancy of any component of the home. It does states (when data plates are available) the date of manufacture for your water heater, heating and cooling air handler (in door unit) and condenser (outdoor unit). These major components are mechanical in nature and can fail without warning. Re-evaluating them at the closing walk through is a good idea.

Document your findings for future reference and address any new concerns with the seller prior to closing.

Check the heating and cooling system. By means of the thermostat, operate the heating and shut the system down, wait approximately 20 minutes and operate the cooling system. Operate all appliances.

Run the water at all fixtures including the hot water, check below sinks for new leaks and flush all toilets.

Operate all exterior doors, windows and locks. Ensure all exterior doors lock and consider installing new exterior door locks.

Ask for all remote controls to any garage door openers, fans, gas fireplaces, etc.

Inspect areas that may have been blocked by furniture and personal property at the time inspection including electrical outlets. An outlet tester can be purchased for around \$15.00.

Operate any gas fireplaces by both remote and manually. Request operator's manuals for all appliances including the water heater, HVAC systems and gas fire places. In the event the seller does not have them; most can be found online by using the manufactures name and type of appliance.

Ask the seller questions about anything that was not covered during the home inspection.

Enjoy your new home!

General: Refer to Summary

Most of the items that are in need of immediate attention and/or possible major cost items that would require repair in the near future are listed in the Summary Section of the report. Please be sure to refer to this document for further useful information.

Equity Building Inspection Page 40 of 43

General: Home Reference Links

The links listed below are provided to help you better understand the systems of your building.

ROOFING

ELECTRICAL

EXTERIOR

STRUCTURE

HEATING

AIR CONDITIONING

INSULATION

PLUMBING

INTERIORS

APPLIANCES

SYSTEM LIFE CYCLES

SUPPLEMENTARY INFORMATION

HOME SETUP AND MAINTENANCE

MORE ABOUT THE HOME INSPECTION PROCESS

General: Thank You!

We appreciate your business!

Equity Building Inspection Page 41 of 43

18: VENDORS

Information

Recommended Vendors: General Handyman/Contractor

D-Lux Home Services - Dean Lux 310-890-8162 deanlux4@gmail.com Gerritse Construction - Corey Gerritse 909-529-1056 gerritseconstruction.com

Recommended Vendors: Plumber Recommended Vendors: Video

Al Garcia Plumbing

Sewer Line Inspections

310-533-9325

West Coast Sewer Inspection -Bronzon Pichlik

310-876-4653

Recommended Vendors: Roofing Contractor / Repairs Replacement

America's Best Roofing Ron Karu O - (310) 792-1261 C - (310) 405-5445 Ronk.abrc@gmail.com www.americasbestroofco.com

Recommended Vendors: Stuctural, soils or geotechnical engineer

L.A. Private Eyes Engineering 866-436-3647

Alpha Sturctural, Inc. (323) 258-5482 www.alphastructrual.com

Recommended Vendors:

Recommended Vendors: Mold

Foundation Inspection and Repair Remediation

Alpha Structural Inc. 323-258-5482

Advanced Environmental 310-378-6347

www.moldwhatnow.com

Ray Castro

Recommended Vendors:

Asbestos & Lead

JLM Environmental 310-978-8281

Recommended Vendors: Pool

Services

Discount Pool & Spa Supply Mike Bullock 310-3530-3393

Heat (ceiling electric)

Tugman Radiant Heat, Southbay, John, @ 661-373-8633

Inspection and Repair

All Cities Termite Corey Gerrsitse (714) 895-1113

Recommended Vendors: Radiant Recommended Vendors: Termite Recommended Vendors: Chimney Inspection

Oliver Twist Chimney Sweep David Handel info@olivertwist.net 310-377-8163

Page 42 of 43 Equity Building Inspection

STANDARDS OF PRACTICE

Equity Building Inspection Page 43 of 43