

WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

BUILDING NO. 3566	STREET, CITY, STATE, ZIP Mount Vernon Avenue, Riverside CA 92507	Date of Inspection 3/24/2023	No. of Pages 6
-----------------------------	--	--	--------------------------

	P.O. Box 291 Murrieta, CA 92564-0291 Call/Text (951) 677-8770 Email: mail@deanzatermite.com Tax ID 33-0826800
--	---

Firm Registration No. PR 3424	Report No. 84366	Escrow No.
Ordered By: First Team Real Estate - Corona 200 Main Street #100 Corona, CA 92882 Attn: Kathleen Rapoza	Property Owner/Party of Interest Lacey 3566 Mount Vernon Avenue Riverside, CA 92507	Report Sent To: First Team Real Estate - Corona 200 Main Street #100 Corona, CA 92882 Attn: Kathleen Rapoza


COMPLETE REPORT
 LIMITED REPORT
 SUPPLEMENTAL REPORT
 REINSPECTION REPORT

General Description: One story, stucco framed, residence, concrete slab, composition roof, occupied	Inspection Tag Posted: Garage
	Other Tags Posted: None Noted

An inspection has been made to the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.

Subterranean Termites
 Drywood Termites
 Fungus/Dryrot
 Other Findings
 Further Inspection

If any of above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked items.



Inspected by Vincent Cummings
 State License No. OPR 11986
 Signature *Vincent Cummings*

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California 95815.
 NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control board at (916) 561-8708, or (800) 737-8188 or www.pestboard.ca.gov.

3566

Mount Vernon Avenue, Riverside CA 92507

3/24/2023

84366

BUILDING NO.

STREET, CITY, STATE, ZIP

INSPECTION DATE

REPORT NO.

There are certain areas of a structure which are considered impractical for inspection: the interior of hollow walls, spaces between a floor or porch deck, attics with less than 18" of clear crawl space. Stall showers over finished ceilings, abutments or floors beneath coverings are considered inaccessible and were not inspected at this time. Second story showers are not water tested unless there is evidence of a leak at ceiling below. Sunken or below grade showers are not water tested due to their construction. NOTE: Eaves requiring the use of an extension ladder are considered impractical for inspection. Appliances and/or plumbing over finished ceilings and decks are not water tested and we do not certify against leakage, unless otherwise noted in this report. No opinion is rendered, nor guarantee is implied concerning the future watertightness of the roof. This firm makes no guarantee against any infestation, leaks or other adverse conditions which may exist or which may develop in inaccessible areas and become visibly evident after the date of this inspection. This inspection is only on the structures indicated on the diagram. If requested, a reinspection of this property will be performed by this firm at additional cost. The exterior surface of the roof will not be inspected. If you want water tightness of the roof determined, you should contact a roofing contractor who is licensed by the contractors state license board. Our job estimate for work is good for 30 days. The original report is valid for a period of four months.

This Wood Destroying Pests & Organisms Report DOES NOT INCLUDE MOLD, fungi or any mold-like conditions. By California law we are neither qualified, authorized nor licensed to inspect for health related molds or fungi. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. No reference will be made to mold or mold-like conditions. If you wish your property to be inspected for mold-like conditions or you desire information about the presence of health related molds, you should contact an industrial hygienist or the appropriate mold professional.

This company will re-inspect repairs done by others within four months of the original inspection. A re-inspection is \$85 in addition to the original inspection fee for each re-inspection. The re-inspection must be done within ten (10) working days of request. The re-inspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

A. This inspection pertains only to the specific address indicated and does not include any attached or adjacent units.

B. The exterior surface of the roof and condition of plumbing will not be inspected. If you want the water tightness of the roof or condition of plumbing determined, you should contact a roofing or plumbing contractor who is licensed by the Contractor's State License Board.

C. Slab floor construction has become more prevalent in recent years. Floor coverings may conceal cracks in the slab that will allow infestation to enter. Infestation in the walls may be concealed by plaster so that a diligent inspection may not disclose the true condition. These areas are not practical for inspection due to health hazards, damage to the structure or inconvenience. They were not inspected unless described in this report. We recommend further inspection if there is any question about the above areas.

D. This company does not concern itself with prior building permits. If anyone has any questions as to whether this structure or parts of this structure are permitted, we suggest they contact the proper county or city departments.

3566

Mount Vernon Avenue, Riverside CA 92507

3/24/2023

84366

BUILDING NO.

STREET, CITY, STATE, ZIP

INSPECTION DATE

REPORT NO.

E. Some structures do not comply with building code requirements or may have structural, electrical, plumbing, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pests and Organisms Inspection Report does not contain information on such a defect, if any, as they are not within the scope of our license.

F. This proposal includes a primer coat of paint only. An effort will be made to match the color but a match is not guaranteed.

G. During the process of treatment or replacement, it may be necessary to drill holes through ceramic tiles or other floor covering. These holes will then be sealed with concrete. We will exercise due care but assume NO RESPONSIBILITY for cracks, chipping or other damage to floor coverings.

H. In the event damage or infestation described therein is later found to extend further than anticipated, our bill will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF AND/OR HERSELF.

I. All pesticides and fungicides must be applied by a state certified applicator (sec. 8555 Business and Professions Code Division 3) and in accordance with the manufacturer's label requirements.

J. DeAnza assumes NO RESPONSIBILITY for damage to any Plumbing, Gas or Electrical lines, etc., in the process of pressure treatment of concrete slab areas or replacement of concrete or structural timbers.

K. If building permits are required for any repair work, it is the owner's responsibility to contact the appropriate government agency, schedule and pay all fees prior to repair work being performed by this company or others.

L. When a fumigation is recommended, a FUMIGATION NOTICE will be left with or mailed to the owner of the property or his designated agent which states, among other things, that ALL FOODS AND MEDICINES MUST BE REMOVED from the property PRIOR to the fumigation being performed. We will assume no responsibility for damage to shrubbery, trees, plants, antennas, satellite dishes, or roofs.

M. NOTICE...The charge for service that this company subcontracts to another company may include the company's charges for arranging and administering such services that are in addition to the direct costs associated with paying the subcontractor. You may accept DeAnza's bid or you may contract directly with another registered company licensed to perform the work. If you choose to contract directly with another company, DeAnza will not in any way be responsible for any act or omission in the performance of work that you directly contract with another to perform.

N. If repairs are completed by others, this company recommends the proper licensed bonded insured contractor, in good standing with the State of California, be hired to perform any repairs on the property.

O. This company DOES NOT GUARANTEE work performed by others, recommended or not, including by the Owner or Contractors. Bills should be submitted to Escrow as certification of work performed by others.

P. NOTICE...Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company...You...have the right to seek a second opinion...from another company.

3566	Mount Vernon Avenue, Riverside CA 92507	3/24/2023	84366
BUILDING NO.	STREET, CITY, STATE, ZIP	INSPECTION DATE	REPORT NO.

Q. Arbitration of Disputes...By relying on this wood destroying organisms report, you agree that any controversy or claim arising out of or relating to DeAnza's inspection and/or this report shall be settled by arbitration in accordance with the construction industry arbitration rules of the American Arbitration Association, and judgment upon the award rendered by the arbitrator(s) may be entered in any court having jurisdiction thereof.

R. Please call our office if you should have any questions pertaining to this report. Our office is open Monday through Friday from 8:00 a.m. to 5:00 p.m.

S. THE EPA REQUIRES THAT HOMES AND OTHER BUILDINGS CONSTRUCTED PRIOR TO 1978 ARE PRESUMED TO HAVE LEAD PAINT THAT MAY CAUSE SERIOUS HEALTH ISSUES IF DISTURBED DURING REPAIRS. SPECIAL PROCEDURES ARE REQUIRED BY THE US EPA IN REPAIRING PAINTED AREAS WHERE MORE THAN 6 SQUARE FEET IN AN INTERIOR OR 20 SQUARE FEET ON AN EXTERIOR ARE DISTURBED. LOCAL AND STATE REQUIREMENTS MAY BE MORE RESTRICTIVE. THOSE DOING THE REPAIRS ARE REQUIRED BY LAW TO BE LICENSED LEAD RENOVATORS AND AS SUCH FOLLOW STRICT TESTING, CONTAINMENT, REPAIR, CLEAN UP AND DEBRIS DISPOSAL PRACTICES. THE PENALTIES FOR VIOLATIONS OF THE EPA REGULATIONS ARE SEVERE. IF THIS STRUCTURE WAS BUILT PRIOR TO 1978, YOU WILL BE PROVIDED WITH THE EPA PAMPHLET ENTITLED "RENOVATE RIGHT-IMPORTANT LEAD HAZARD INFORMATION FOR FAMILIES", PRIOR TO THE START OF REPAIRS. IN ADDITION, YOU WILL BE NOTIFIED OF THE ADDITIONAL COSTS OF COMPLIANCE.

This is a wood destroying organisms inspection only. Rodents and general pest are not included in this report.

IF A SEPARATED REPORT HAS BEEN REQUESTED, IT IS DEFINED AS SECTION 1 & SECTION 2 CONDITIONS EVIDENT ON THE DATE OF INSPECTION.

SECTION 1: CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

SECTION 2: SECTION 2 ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION, BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

FURTHER INSPECTION/UNKNOWN: FURTHER INSPECTION/UNKNOWN ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREAS WHICH DURING THE ORIGINAL INSPECTION, DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE THE INSPECTION AND CANNOT BE DEFINED AS SECTION 1 OR SECTION 2.

Fungus/Dryrot:

FINDING 3A

Fungus Damage noted at left and rear fascia and trim. Marked 3a on diagram.

RECOMMENDATION 3A

Remove and replace approximately 2', 6', & 8' of 2" x 6" and 8' of 1" x 2". **Paint tan primer-see note. NOTE: Wood not guaranteed to match due to milling changes and availability. NOTE: Wood used will be Douglas Fir and/or Spruce unless otherwise noted.

***** This is a Section 1 Item *****

3566

Mount Vernon Avenue, Riverside CA 92507

3/24/2023

84366

BUILDING NO.

STREET, CITY, STATE, ZIP

INSPECTION DATE

REPORT NO.

Fungus/Dryrot:

FINDING 3B

Fungus Damage noted at rear room/patio header and joist. Marked 3b on diagram.

RECOMMENDATION 3B

Others to remove and replace damaged wood.

***** This is a Section 1 Item *****

FINDING 3C

Fungus Damage noted at rear siding. Marked 3c on diagram.

RECOMMENDATION 3C

Remove and replace approximately (4) 10' of 1" x 8" shiplap. **Paint tan primer-see note. NOTE: Wood not guaranteed to match due to milling changes and availability. NOTE: Wood used will be Douglas Fir and/or Spruce unless otherwise noted.

***** This is a Section 1 Item *****

FINDING 3D

Fungus Damage noted at front roof sheathing. Marked 3d on diagram.

RECOMMENDATION 3D

Remove and replace approximately (2) 4' of 1" x 8" shiplap. **Paint tan primer-see note. This company guarantees roofing materials over replaced wood only. NOTE: Wood not guaranteed to match due to milling changes.

***** This is a Section 1 Item *****

Other Findings:

FINDING 4A

Water Damage noted at garage trims. Marked 4a on diagram.

RECOMMENDATION 4A

Others to remove and replace damage.

***** This is a Section 2 Item *****

** PAINT NOTE: One coat of paint will be applied to all wood where indicated on this report. This initial coat of paint should be considered a primer coat and additional coats should be added. Although, to preserve the aesthetics of your home, color matching will be provided in the cost estimate given unless otherwise stated. This company will use the brand of paint that is standard to us. If the homeowner wishes to supply exact paint to match, credit may be given. Color and sheen are not guaranteed to match.

3566

Mount Vernon Avenue, Riverside CA 92507

3/24/2023

84366

BUILDING NO.

STREET, CITY, STATE, ZIP

INSPECTION DATE

REPORT NO.

SECTION 1

SECTION 2

FURTHER INSPECTION

3A \$ 1098.00

3B *OTHERS*

3C \$ 445.00

3D included-3a

4A *OTHERS*

Proposed Cost Section 1: \$1,543.00

Proposed Cost Section 2: \$0.00

Proposed Cost Fur. Insp: \$0.00