



# Invoice

**Leak Detection . Underwater Repairs**  
**(800) 996-5325**  
 6444 E. Spring St. # 329 Long Beach, Ca. 90815

**PAYED**  
**02/16/2022**

|                         |           |
|-------------------------|-----------|
| Date                    | Invoice # |
| 2/16/2022               | 7062      |
| Contractors Lic. 898296 |           |

|                                                                          |
|--------------------------------------------------------------------------|
| Bill To                                                                  |
| Clement Driscoll<br>2636 Via Carrillo<br>Palos Verdes Estates, Ca. 90274 |

|                                                      |
|------------------------------------------------------|
| Job Site                                             |
| 2636 Via Carrillo<br>Palos Verdes Estates, Ca. 90274 |

|          |                |             |
|----------|----------------|-------------|
| P.O. No. | Terms          | Referred By |
|          | Due on receipt |             |

| Description Of Work                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | Amount                       |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|
| <p>Leak detection survey of the pre-fab fiberglass spa only.</p> <p>The suction and return pipes for the pool circulation pump were pressure tested to 25psi. The pipes held pressure and are leak free at this time.</p> <p>The suction and return pipes for the spa booster/jet pump were pressure tested to 25psi. The suction pipes held pressure and are leak free at this time. The return pipe did not hold pressure, the approximate area of the leak/pressure loss appears to be located in a jet see the attached picture. Recommend repairing the pipe then re-testing for additional leaks that may or may not exist.</p> <p>There appears to be an abandoned pipe next to the step that will not hold pressure. recommend capping this pipe to stop water loss.</p> <p>Due to the condition of the spa and the water quality the spa was not dye tested at this time.</p> | 500.00                       |
| <p>WORK AUTHORIZATION: I/We hereby authorize the work described and any necessary materials and parts.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <p><b>Total</b> \$500.00</p> |

DISCLOSURES & WARRANTY: NO GUARANTEE ON MATCHING TILE, CEMENT OR PLASTER. Leak Specialists injection process is a highly successful repair process however; if the pool structure has undergone sever degradation, Leak Specialists recommends consulting a civil engineer. Leak Specialists is not responsible for cutting plumbing, electrical or other items. All items should be built to code, which is a minimum of 6" below grade level. Concealed pipeline leaks may "Over Shadow" the sounds of other leaks in the same pipe, will need to reestimate if additional leaks are found. Leak Specialists provides a one year warranty on all repairs; unless otherwise noted. Earthquake damage voids warranty. POOL EMPTIED AT CUSTOMERS RISK.