Comments	nsfall a	Al (A)	out let	on L	mle-	
a f	this time		ci 545	tem	well	world
P	roperly	Passe o	/			
Sketch:						
		įs.				
	Leach PC CEN	Back of	Harsa			
		Fron 7				
		9	rive way			
	J	(				
Job Addre	ess: <u>3021 1</u>	Bay A	NE.	chii		
		/	4			





SEPTIC SYSTEM INSPECTION REPORT

SEPTIC STSTEW INSPECTION REPORT						
Date: <u>05-02-22</u> Service Person: <u>Sa/</u> Invoice #: <u>14515</u>						
Job Adress: 3021 Bay Ave Chico						
Inspection Requested By: <u>  Cemie Fostev</u>						
Escrow Company: Escrow #:						
Escrow Company: Escrow #: Escrow #: Escrow #: Repairs:						
System Inspection: Passed: Failed:						
TANK CONSTRUCTION						
All Cement: Steel: Fiberglass: Redwood Top:						
Tank baffle intact: Yes No						
Tank inlet elbow intact: Yes No						
Tank outlet elbow intact: Yes No						
Approximate tank size: 1500 Gallons. Tank was cleared: Yes Vo						
Tank should be cleared in approximately years.						
House was: Vacant Occupied						
LEACH LINE EVALUATION						
Functioning at the time of inspection Failed						
I declare that the information herein is true and correct to the best of my knowledge and belief. The report is based on performance at the time of inspection. No guarantee is expressed or implied against future problems.						
Signature: Sal @ Payless SepteDate: 05-07-77						
Business Lic: #33884 Comments and sketch on back of this report.						