

**THRIFTY ROOTER  
SEPTIC SYSTEM INSPECTION**

Date: 3-8-23 Serviceman: Will Invoice # 195099

Job Address: 6743 COUNTY RD 19 ORLAND

Inspection requested by: DAN HENRY

Escrow Company: \_\_\_\_\_ Escrow #: \_\_\_\_\_

Inspection Fee: 318<sup>00</sup> Tank Pumping Fee: \_\_\_\_\_ Dumping fee  
Reports: 200<sup>00</sup>

**SYSTEM INSPECTION:**  Passed  Failed  Marginal

\*\*\*\*\*

**TANK CONSTRUCTION:**

TANK is:  Redwood  Concrete  Steel  Fiberglass

LIDS are:  Concrete  Steel  Redwood  Other

Tank baffle intact:  Yes  No

Tank inlet elbow intact:  Yes  No

Tank outlet elbow intact:  Yes  No

RISERS?  Yes  No Riser Condition:  Good  Fair  Poor

Approximate tank size: 1200 gallons Tank was cleaned?  Yes  No

Tank should be cleaned in approximately NOW years Tank depth: 13

House was:  Vacant  Occupied

\*\*\*\*\*

**LEACH LINE EVALUATION:**

Functioning at time of inspection  Failed  Marginal

I declare that the information herein is true and correct to the best of my knowledge and belief. Report is based on performance at the time of inspection. No guarantee is expressed or implied against future problems.

Signature Will H O Date 3-8-23

Lic. #712800

\*\*Comments and sketch on back of this report.\*\*

865-2579 OWNER CURT FOSBERG  
743-4295 BUILDER JOHN FLEMING  
518-4692

4211 C/R MM  
A.P. 0470300210

