

Waples Construction Septic Service

P.O.Box 447 Ramona 92065

760-789-5791

SEPTIC TANK INSPECTION WORKSHEET

Date: 9/10/2025

Name (Customer or Firm): Sharon Quisenberry

Job Address: 2165 Lilac Rd Ramona CA

Telephone: _____

1. Made of: ☐ Concrete ☐ Fiberglass ☐ Plastic Other _____
2. Full access: yes, 1 1/2 feet deep
3. # of comp: 2 # of lids: 2 Condition of lids: ok
4. Liquid level before test: normal outlet level
5. Length of test (minimum of 20 minutes) 30 minutes
6. Liquid Level after test normal outlet level
7. Walked suspected leaching area yes
8. Does the tank appear to be located per present code? ☒ YES ☐ NO
9. Excessive sludge in last compartment ☒ YES ☐ NO
10. Baffle Condition ok
11. Inlet ok Outlet ok
12. Approx. capacity in gallons 1000 gallon
13. Previous pump date unknown
14. Any evidence of previous back-up? ☐ YES ☒ NO
15. Constant water flow from house: ☐ YES ☒ NO
16. Comments: The septic system is functioning normally.
17. **This is a pump lift system. Septic effluent is pumped to a higher location east of the house. There is a high water level alarm. If this alarm sounds call for service. There would be approximately 24 hours of use before the system backs up.**

MAP

NOTE: Much of the information compiled in this report is obtained verbally from the owner or agent. We cannot guarantee its accuracy. This form is standard within the industry in San Diego County. Most all questions are asked in effort to determine the viability of the system. However, the determination is based only upon what we found this day which could change dramatically in as little as a few days, depending on its use. We offer no guarantee of future performance.

INSPECTOR Todd Waples CUSTOMER _____
DATE _____

INVOICE WILL FOLLOW