
WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No.	Street	City	ZIP		e of Inspection	Number of Pages
68	Via Marisma	Camarillo	93012	00	6/14/2024	4
		Grayson Te	rmite & Pest Cor	trol, Ind	c. Repor	t # : 22678
GRAY	SON	Nev	PO Box 932 vbury Park CA 91319		Regist	ration # : PR 7203
TERN	,		(805) 716-3011		Escrov	N # :
& PEST CO			@graysontermite.com Fax (805) 262-0455	ı	□co	RRECTED REPORT
Ordered by: Julianne Mendoza		Property Owner a 68 Via Marisma Camarillo CA 930 United States	nd/or Party of Interest:		Report sent to: Zussel Marroquin Keller Williams	
COMPLETE REPOR	RT 🔀 LIMITED F	REPORT 🗌	SUPPLEMENT	AL REPOR	RT REINSF	PECTION REPORT
FOUNDATION An inspection has be	TILE HOME/ FURNISHED een made of the structure(s)	shown on the diagr	am in accordance with		Inspection Tag Water Heater Cl Other Tags Po	Posted: oset sted:
	detached steps, detached decks and any other structures not on the diagram were not inspected.					
Subterranean Termit	_		ngus / Dryrot 🗌		~ _	Further Inspection
If any of the above b	oxes are checked, it indicat	es that there were v	isible problems in acce	ssible area	is. Read the report f	or details on checked items.

Diagram Not To Scale



Inspected By: Nicholas Grayson State License No. OPR12033 Signature:

GRAYSON TERMITE & PEST CONTROL, INC.

Page 2 of 4 inspection report

68	Via Marisma	Camarillo	CA	93012	
Address of Property Inspected		City	State	ZIP	
06/14/2024 22678		678			
Date of Inspection Corresponding R		onding Report No.	E	scrow No.	

WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

GRAYSON TERMITE & PEST CONTROL, INC.

Page 3 of 4 inspection report

68	Via Marisma		Camarillo	CA	93012	
Address of Property Inspected			City	State	ZIP	
06/14/2024 22678		22678				
Date of Inspection Corresponding R		rresponding Repor	t No.	E	scrow No.	

FINDINGS AND RECOMMENDATIONS

This is a separated report which is defined as Section I/Section II conditions evident on the date of the inspection.

KEY

SECTION I CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

SECTION II ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

FURTHER INSPECTION ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(s) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

1=Subterranean Termites 2=Drywood Termites 3=Fungus/Dryrot 4=Other Findings 5=Further Inspection

SECTION I:

1A - Subterranean

FINDING - Evidence of active subterranean termite infestation noted at subarea skirt siding, as indicated on the diagram.

RECOMMENDATION - Treat soil at probable entry points by down drilling or trenching. Inject into the soil a State registered termiticide solution (Termidor SC, Active ingredient: Fipronil) as directed by the product label for control of Subterranean Termites. This service is offered with a 2-year warranty to treated locations.

2A - Drywood

FINDING - Drywood termite infestation noted at porch framing, as indicated on the diagram.

RECOMMENDATION - Cover with tarp and seal entire structure including attached garages and attached appurtenances. Fumigate as a primary method of control using Vikane Gas (Active Ingredient - Sulfuryl Flouride, and Chloropicrin as warning agent) in accordance with the manufacturer's label. The structure must be vacated until release for re-entry by licensed fumigator. This service is offered with a 3-year full structure warranty. The customer is advised to mask over or remove all accessible pellets/frass. Grayson Termite & Pest Control will perform this service for an additional fee.

SECTION II:

4A - Other Findings

FINDING - Weathering noted at fascia boards, as indicated on the diagram.

RECOMMENDATION - Interested party should engage the services of an appropriate tradesperson to inspect and correct as they deem necessary.

4B - Other Findings

FINDING - Moisture damage noted at cellulose siding, as indicated on the diagram.

RECOMMENDATION - Interested party should engage the services of an appropriate tradesperson to inspect and correct as they deem necessary.

4C - Other Findings

FINDING - Moisture stains noted at interior ceiling, as indicated on the diagram.

RECOMMENDATION - Interested party should engage the services of an appropriate tradesperson to inspect and correct as they deem necessary.

4D - Other Findings

FINDING - Moisture damage noted at enclosed patio wall panels, as indicated on the diagram.

GRAYSON TERMITE & PEST CONTROL, INC.

Page 4 of 4 inspection report

r ago i oi i mopooi	ion report				
68	Via Marisma	Camarillo	CA	93012	
Address of Property Inspected		City	State	ZIP	
06/14/2024 22678		22678			
Date of Inspection Corresponding R		esponding Report No.	E	scrow No.	

RECOMMENDATION - Interested party should engage the services of an appropriate tradesperson to inspect and correct as they deem necessary.

4E - Other Findings

FINDING - Cellulose debris noted in the subarea, as indicated on the diagram.

RECOMMENDATION - Interested party should engage the services of an appropriate tradesperson to inspect and correct as they deem necessary.

4F - Other Findings

FINDING - Plumbing leak noted at subarea, as indicated on the diagram.

RECOMMENDATION - Interested party should engage the services of an appropriate tradesperson to inspect and correct as they deem necessary.

4G - Other Findings

FINDING - Excessive moisture noted at subarea, as indicated on the diagram.

RECOMMENDATION - Interested party should engage the services of an appropriate tradesperson to inspect and correct as they deem necessary.

Thank you for selecting us to perform a structural pest control inspection on your property. Should you have any questions regarding this report, please call us directly by the contact information provided on the first page of the inspection report.

Our inspectors have determined that your property will benefit from a safe application of chemicals commonly used for structural pest control. In accordance with the laws and regulations of the State of California, we are required to provide you and your occupants with the following information prior to any application of chemicals to such property.

Please take a few moments to read and become familiar with the content. State law requires that you be given the following information:

CAUTION - PESTICIDES ARE TOXIC CHEMICALS. Structural pest control companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the state finds that based on scientific evidence, there are no appreciable risks weighted by the benefits. The degree of risk depends on the degree of exposure, so exposure should be minimized.

If within 24 hours following application, you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center and your pest control operator immediately.

For further information, contact any of the following agencies in your area:

Poison Control Center	(800) 222-1222
Agricultural Department	(805) 388-4343
Health Department	(805) 981-5101
Structural Pest Control Board	(916) 561-8700

2005 Evergreen Street, Ste. 1500. Sacramento, CA 95815



Grayson Termite & Pest Control, Inc.

PO Box 932 Newbury Park CA 91319 (805) 716-3011 info@graysontermite.com Fax (805) 262-0455

WORK AUTHORIZATION

Report #: 22678

•	
Address of Property:	68 Via Marisma
City:	Camarillo
State/7ID:	CA 93012

The inspection report of the company dated, 06/14/2024 is incorporated herein by reference as though fully set forth.

No work will be performed until a signed copy of this agreement has been received.

THE COMPANY AGREES

To guarantee all repair completed by this company for one year from date of completion except for caulking, grouting, or plumbing, which is guaranteed for a period of **ninety (90) days**. We assume no responsibility for work performed by others, to be bound to perform this work for the price quoted in our cost breakdown for a period not to exceed 30 days, to use reasonable care in the performance of our work but to assume no responsibility for damage to any hidden pipes, wiring, or other facilities or to any shrubs, plants, or roof.

THE OWNER OR OWNER'S AGENT AGREES

To pay for services rendered in any additional services requested upon completion of work to pay a service charge of one and one-half percent (1 1/2%) interest per month, or portion of any month, annual interest rate of eighteen percent (18%) on accounts exceeding the ten (10) day full payment schedule. The Owner grants to The Company a security interest in the property to secure payment sum for work and inspection fee completed. In case of non-payment by The owner, reasonable attorney fees and costs of collection shall be paid by owner, whether suit be filed or not.

ALL PARTIES AGREE

If any additional work is deemed necessary by the local building inspector, said work will not be performed without additional authorization from owner or owner's agent. This contract price does not include the charge of any Inspection Report fees. Circle the items you wish performed by The Company, below and enter total amount above:

NOTICE TO OWNER

Under the California Mechanics Lien Law, any structural pest control company which contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractor, laborers or suppliers remain unpaid.

To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice." Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

		ITEMS		
Prefix	Section I	Section II	Further Inspection	Other
A	395.00	0.00	0.00	0.00
A	1,880.00	0.00	0.00	0.00
A	0.00	NO BID	0.00	0.00
В	0.00	NO BID	0.00	0.00
C	0.00	NO BID	0.00	0.00
D	0.00	NO BID	0.00	0.00
E	0.00	NO BID	0.00	0.00
F	0.00	NO BID	0.00	0.00
łG	0.00	NO BID	0.00	0.00
Total:	2,275.00	0.00	0.00	0.00

GRAND TOTAL: 2,275.00

Property Owner:	Date:	Inspected By:	Date:
Owner's Agent:	Date:		



INVOICE / STATEMENT

Grayson Termite & Pest Control, Inc.

PO Box 932 Newbury Park CA 91319 (805) 716-3011 info@graysontermite.com Fax (805) 262-0455 Date: 06/14/2024

Report Number: 22678

Invoice Number: 22678-1

Escrow Number:

Property 68 Via Marisma Inspected: Camarillo, CA 93012

Bill To: Julianne Mendoza

Inspection: \$	95.00
Invoice Total: \$	95.00
Payments: \$	0.00
Total Due: \$	95.00

Description of Service WDO inspection and report fee

RETAIN THIS COPY FOR YOUR RECORDS THANK YOU FOR YOUR BUSINESS

CUT HERE _____ CUT HERE _____ CUT HERE



Property 68 Via Marisma Inspected: Camarillo, CA 93012

Bill To: Julianne Mendoza

INVOICE / STATEMENT

Grayson Termite & Pest Control, Inc.

PO Box 932 Newbury Park CA 91319 (805) 716-3011 info@graysontermite.com Fax (805) 262-0455 Date: 06/14/2024

Report Number: 22678 Invoice Number: 22678-1

Escrow Number:

Inspection: \$	95.00
Invoice Total: \$	95.00
Payments: \$	0.00
Total Due: \$	95.00

Description of Service
WDO inspection and report fee