STANDARD NOTICE OF WORK COMPLETED AND NOT COMPLETED

NOTICE - All recommendations may not have been completed. - See below - Recommendations not completed. This form is prescribed by the Structural Pest Control Board.

		This	form is prescribed by the	Structural Pest Cont	rol Board.	
Buidling No	Street, City, State, Zip					Date of Completion
2157	Edinburg A	ve, Car	diff CA 92007			09/23/2024
A P	ENNEDY EST ONTROL	Tel: Toll:	3 Sterling Cou (760)233-205 (800)420-73 il: inbox@ken	55 Fax: (7) 78	60)233-2	2029 2090
Firm Registration N	No. PR 1932	Report No.	. 64717	Escrow No.		
Ordered By: Greg Coleson 2157 Edinburg Ave Cardiff, CA 92007 Attn: gcoleson@gr 404-217-3675		4	Property Owner/Party of Interes Greg Coleson 2157 Edinburg Ave Cardiff, CA 92007 Attn: gcoleson@gmail.com 404-217-3675		Report Sent To: Greg Colesor 2157 Edinbur Cardiff, CA 92 Attn: gcoleso 404-217-3675	g Ave 2007 m@gmail.com
The following rec Report dated	ommendations on 09/11/2024		designated property, as o		troying Pests and I/or have not be	
2A Recommendation	is completed by th ontrol Board's Rule	nis firm tha	are in accordance with th t are considered secondar gulations including Person	ry and substandard	measures under	
Cost of work com	pleted:			Cost: \$		2,988.00
				Inspection	Fee: \$	0.00
				Other: \$		0.00
				Total: \$	2	2,988.00
Recommendatior None Not	s not completed b ed	y this firm:				
				Estimated	Cost: \$	
Remarks:						A.
fou are entitled to a	obtain copies of all	reports and	d completion notices on this	property reported to P	oard turing the pr	efeeding two years upon pay

search fee to: The Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California 95815-3831. NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708 or (800) 737-8188 or www.pestboard.ca.gov. 43M-44 (Rev. 10/01)

INVOICE



1518 Sterling Court, Escondido, CA 92029 Tel: (760)233-2055 Fax: (760)233-2090 Toll: (800)420-7378 Email: inbox@kennedypest.com

[DATE	REPORT #	ESCROW #	PROPERTY LOCATION				
(9/24/2024	64717		2157 Edinburg Ave, Cardiff CA 92007				
TO:	Greg Col	eson						
	2157 Edi	nburg Ave						
	Cardiff, C	CA 92007						
	ATTN: go	oleson@gm	iail.com					
			624704	09/23/2024	Completion	\$2,988.00		
			624806	09/24/2024	CrAdjustment	-\$2,988.00		
					Balance Due:	\$0.00		

RETAIN THIS COPY FOR YOUR RECORDS

DUE AND PAYABLE WITHIN 10 DAYS

1.5% per month charged on all past due accounts. This is an annual percentage rate of 18% (Interest charged persuant to the Robinson-Patman Act)

NOTICE: "Under the Mechanics'Lien law, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property but is not paid for his work or supplies, has the right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your own contractor in full, if the subcontractor, laborer, or supplier remains unpaid."

THANK YOU FOR YOUR BUSINESS

Transaction Successful

Transaction Receipt		
Merchant:	Kennedy Pest Control Inc - (Escondido, CA)	
Date/Time:	09/24/2024 1:58:30 PM PDT	
Transaction ID: 9965581176		
Transaction Type:	Card Sale	
Entry Method:	Keyed	
Amount:	\$2,988.00	
Credit Card Information		
СС Туре:	Visa	
CC Number:	**************0696	
Auth. Code:	05567D	
Processor:	First MCS Nashville	

Billing InformationShipping InformationGreg Coleson
, 92007
USUS

WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

BUILDING NO.	STREET, CITY, STATE,	ZIP			Date of Inspection	No. of Pages
2157	Edinburg	Ave,	Cardiff CA 9200	7	9/11/2024	7
N PE	NNEDY ST NTROL	Tel: Toll:	8 Sterling Court, E (760)233-2055 F (800)420-7378 il: inbox@kennedy	ax: (760)233-2090	
Firm Registration N	No. PR 1932	2	Report No. 64717		Escrow No.	
Ordered By:			Property Owner/Party of Interest		Report Sent To:	
Greg Coleson 2157 Edinburg Ave Cardiff, CA 92007 Attn: gcoleson@gmail.com 404-217-3675			Greg Coleson 2157 Edinburg Ave Cardiff, CA 92007 Attn: gcoleson@gmail.com 404-217-3675	2157 Edinburg Ave 2157 Edinburg Ave Cardiff, CA 92007 Cardiff, CA 92007 Attn: gcoleson@gmail.com		
COMPLETE REPORT	LIMIT	ED REPORT	SUPPLEMENTAL RE	EPORT	REINSPECTION REPORT]
General Description: Occupied, furnished	General Description: Inspection Tag Posted: Occupied, furnished, two story, single family residence, composition roof. Exterior					
Other Tags Posted: None noted						
An inspection has a steps, detached de	been made to the str ecks and any other	ucture(s) s structures	shown on the diagram in accordance s not on the diagram were not ins	with the Structura pected.	I Pest Control Act. Detached po	orches, detached
Subterranean Term If any of above box		/wood Tern dicates tha	nites 🔀 Fungus/Dryrot 🗋 t there were visible problems in acces	Other Findings ssible areas. Read		

ZA

Inspected by Justin Birks

State License No. FR 51566

Signature

ctural Pest

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceeding two years to obtain copies contact: Stru Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California 95815.

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control board at (916) 561-8708, or (800) 737-8188 or www.pestboard.ca.gov.

2157 Edinburg Ave, Cardiff CA 92007

BUILDING NO. STREET, CITY, STATE, ZIP

9/11/2024 64717

INSPECTION DATE REPORT NO.

A. Certain areas are recognized by the industry as inaccessible and/or for other reasons not inpsected. These include but are not limited to: inaccesible and/or insulated attics or portions thereof, attics with less then 18" clear crawl space, the interior of hollow walls; spaces between a floor or porch deck and the ceiling below; area where there is no access without defacing or tearing out lumber, masonary or finiushed work; areas behind stoves, refrigerators or beneth floor coverings, furnishings; areas where encumbrances and storage, condidtions or locks makes inspection impractical, portions of the sub area concealed or made inaccessible by ducting or insulation, area beneath wood floors over concrete, and areas concealed by heavy vegetation. All inspections are done from the ground level only unless otherwise indicated. Although we make visual examinations, we do not deface or probe window/door frames or decorative trims. Unless otherwise specified in this report we do not inspect fences, sheds, dog houses, detached patios, detached wood decks, wood retaining walls or wood walkways. We assume no responsibility for work done by anyone else, for damage to the stucture or contents during our inspection, or for infestation, infection, adverse conditions or damage undetected due to inaccessibility or non-disclosure by the owner/agent/tenant.

B. Slab floor construction has become more prevalent in recent yeras. Floor covering may conceal cracks in the slab that will allow infestation to enter. Infestation in the walls may be conceald by plaster so that a diligent inspection may not disclose the true condition. These areas are not practical to inspect because of health hazards, damage to the structure; or inconvenience. They were not insected unless described in this report. We recommend further inspection if there is any question about the above noted areas. Ref: Structual Pest Control Act, Article 6, Section 8516(b), paragraph 1990(i). Amended effective March 1, 1974. Inspection is limited to disclosure of wood destroying pests or organisms as set forth in the Structural Pest Control Acr, Article 6, Section 8516(b), Paragraph 1990-1991

C. This company will reinspect repairs done by others within four mounths of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done withing ten (10) workings days of the request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be nexessary. Any guarantees must be received from parties performing repairs.

D. This company is not responsible for work completed by others, recommend or not, including by Owner. Contractor bills should be submitted to Escrow as certification of work completed by others. Kennedy Pest Control does not comment on workman-ship done by others. Intrested parties must satisfy themsleves as to the quality or apperance of work which is not completed by our company.

E. This report includes findings related to the presence/non-prescence of wood destroying organisms and/or visble signs of leaks in the accessible portions of the roof. The exterior surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractors' State License Board.

F. Second story stall showers are inspected but not water tested unless there is evidence of leaks in the ceiling below. Ref: Structural Pest Control Rules and Regulations, Sec 5816G. Sunken or below grade showers or tubs are not water tested due to their construction.

G. During the course of/or after the opening of walls or any previously concealed areas, should any further damge or infestation be found, a supplementary report will be issued. Any work completed in these areas would be at the Owner's direction and additional expense.

H. During the process of treatment or replacement it may be necessary to drill holes through

PAGE OF STANDARD INSPECTION REPORT ON PROPERTY AT:

2157	Edinburg Ave, Cardiff CA 92007	9/11/2024	64717
BUILDING NO.	STREET, CITY, STATE, ZIP	INSPECTION DATE	REPORT NO

ceramic tiles or other floor coverings; These holes will then be sealed with concrete. We will exercise due care but assume no responsibility for cracks, chipping or other damge to floor coverings. We don not re-lay carpeting.

I. We assume no responsibility for damage to any Plumbing, Gas or Electrical lines, etc., in the process of pressure treatment of concrete slabs or replacement of concrete or structural timbers.

J. When a fumigation is recommend we will exercise all due care but assume no responsibility for damage to Shrubbery, Trees, Plants, TV Antennas or Roofs. A FUMIGATION NOTICE will be left with, or mailed to the Owner of this prperty, or his designated Agent. Occupant must comply with instructions contained in the Fumigation Notice. During fumigation and aeration, the possibility of burglary exists as it does any time you leave your home. Therefore, we recommend that you take any steps that you feel necessary to prevent any damges to your property. We also recommend that you contact your insurance agent and verify that you have insurance to protect againist any loss, damage or vandalism to your property. The company does not provide any on site security except as required by state or local ordinance and does not assume any reponsdibility for care and custody of the property in case of vandalism, breaking or entering.

Natural gas service to the home must be disconnected before fumigation can commence. Kennedy Pest Control Inc. will arrange for gas disconnection prior to fumigation, however the owner or owenr's agent must contact the local gas company for the restoration of gas service.

Kennedy Pest Control Inc. or it's sub-contractors cannot be held liable for delays caused by disconnection or restoration of gas service not being completed.

K. If you should have any questions regarding this report, please call or come by the office any weekday between 8:00am and 5:00pm

We also provide information about additional services for the control of household pests such as Ant, Fleas, etc.

L. I agree to pay reasonable attorny's fees if suit is required by Kennedy Pest Control to enforce any terms of this contract, together with the costs of such action, whether or not suit proceeds to judgement.

M. The total amount this contract is due and payable upon completion of work unless otherwise specified. A finance charge computed

at a monthly rate of 1.5% of the unpaid balance (annual percentage rate of 18%) will be added to all accounts past due.

N. If this report is used for escrow purposes, then it is agreed that this inspection report and completion, if any, is part of the Escrow

Transaction. However, if you received written or verbal instructions from any interested parties involved in the escrow (agents, principals,

etc.) to not pay our invoice at close of escrow, you are instructed by us not to use these documents to satisfy any conditions or terms

of your escrow for purposes of closing the escrow. Further, you are instructed to return all of our documents and the most current mailing

address you have on file for the property owner.

O. Owner/agent/tenant acknowledges and agrees that inspection of the premises will not include any type of inspection for the presence or non-presence of asbestos and that this report will not include any findings or opinions

2157	Edinburg Ave, Cardiff CA 92007	9/11/2024	64717
BUILDING NO	STREET, CITY, STATE, ZIP	INSPECTION DATE	REPORT NO
asbestos specifica work. Fu premises cause a for the cl asbestos against h any way and hold and all cl which is	g the presence or non-presence of s in, upon, or about the premises, we recommend that illy licensed to engage in asbestos related rther, should we discover the presence of asbestos du s or should our inspection of the premises release of asbestos dust or particles, owner/agent/ten eanup, removal and disposal of the s and the cost thereof. Owner/agent/tenant hereby agr Kennedy Pest Control which are in related to the presence of asbestos on the premises a this company harmless from any laims of any nature asserted by any third party, includi in any way related to the presence tos on the premises.	uring our inspection of ant shall be solely res rees to waive any and and further agrees to i	[:] the ponsible all claims ndemnify

P. **NOTICE**: Reports on this structure prepared by various registered companies should list the same findings (i.e. Termite infestations, termite damage, fungus damage, etc.) However, recommendations to correct these findings may vary from company to company. You have the right to seek a second opinion from another company.

Q. If any infestation, infection or damage is discovered in a concealed area during the course of performing any recommendation in this report, this company will file a supplemental report. This company is not responsible for controlling suck infestations or infections nor repairing such damage.

R. This company makes no gurantee or warranty, express or implied, regarding future infections or adverse conditions or conditions present but not evident at time of inspection.

S. Local treatment is not intended to be an entire structure treatment method. If infestations of wood-destroying pests extend or exist beyond the area(s) of local treatment, they may not be exterminated.

This is a structural pest control inspection report not a building inspection report, therefore no opinion is being rendered regarding the structural integrity of the building. The following areas were not inspected, as indicated in section #1990, paragraph (j) of the Stuctural Pest Control Act and Rules and Regulations, furnished interiors, inaccessible attics, insulated attics, and portions thereof the interior of hollow walls, spaces between a floor or porch deck, the ceiling or soffit below stall showers over finished buttresses and similiar areas to which there is no access without defacing or tearing out lumber, masonry and finished work, bulit-in cabinet work floor beneath coverings, areas where storage condidtions or locks make inspection impractical.

This wood destorying pest and organism report does not include mold or any mold like conditions. Molds, sometimes called mildew, are not wood destroying organisms. Branch III licenses do not have a duty under the Structural Pest Control Act and related regulations to classify molds as harmful to human health or not harmful to human health. No reference will be made to mold or mold like conditions. Mold is outside the scope of the report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions please contact the approriate mold professional.

PAGE OF STANDARD INSPECTION REPORT ON PROPERTY AT

2157	Edinburg Ave, Cardiff CA 92007	9/11/2024	64717
BUILDING NO.	STREET, CITY, STATE, ZIP	INSPECTION DATE	REPORT NO.

It is the owners responsibility to disclose any knowledge of conditions which are not visible during the course of a normal inspection.

This firm will use commonly available material for work performed by this company, but does not guarantee to match materials no longer available or wood requiring custom milling. Bids for wood reapir include prime coat to outside wood. This firm will not stain or paint inside or outside repairs. **Prime coat only!**

This firm reserves the right to substitute materials due to availablity and/or discontinued materials.

IMPORTANT NOTICE: If persons other than this firm are to complete repairs it is recommended that the lender be consulted for guarantee requirements prior to commencement of work by others. Kennedy Pest Control Inc. will not make any statement as to the quality of workmanship nor will we guarantee work done by others. If all items are not completed by this firm, our price per item may vary from the original bid and warranty will be limited to specfiic areas.

Kennedy Pest Control Inc. does not guarantee work performed by others. Such guarantees should be obtained from those performing the repairs. Kennedy Pest Control Inc. only certifies the absence of infestation of infection. If it is found that others have concealed or hidden the infestations or infections during the course of their repairs, it will be the responsibility of the interested parties to pursue the responsible parties.

NOTICE: The charge for service that this company subcontracts to another registered company may include the companys charges for arranging and administering such services that are in addition to the direct costs associated with paying the subcontractor. You may accept this companys bid or you may contract directly with another registered company licensed to perform the work. If you choose to contract directly with another registered company, this firm will not in any way be responsible for any act or omission in the performance of work that you directly contact with another to perform.

Wood windows are visually inspected, and not opened. To determine the integrity of wood windows, you should contact a licensed window contractor.

The exterior surface of the roof was not inspected. If you want the water tightness of the roof to be determined, you should contact a roofing contractor who is licensed by the contractors state license board.

Built in cabnets are not inspected.

It is unlawful for a handyman to perform work in excess of \$500

PAGE OF STANDARD INSPECTION REPORT ON PROPERTY AT

2157	Edinburg Ave, Cardiff CA 92007	9/11/2024	64717
BUILDING NO	STREET, CITY, STATE, ZIP	INSPECTION DATE	REPORT NO

This is a limited inspection and report, limited to pest identification as per the request of Greg Coleman.

THIS IS A SEPARATED REPORT WHICH IS DEFINED AS SECTION 1/SECTION 2 CONDITIONS EVIDENT ON THE DATE OF INSPECTION. SECTION 1 CONTAINS ITEMS WHERE THERE IS VISIBLE EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION. SECTION 2 ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION, BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND. FURTHER INSPECTION ITEMS ARE DEFINED AS

RECOMMENDATIONS TO INSPECT AREA(S) WHICH DURING THE COMPLETE INSPECTION, DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE THE INSPECTION AND CANNOT BE DEFINED AS SECTION 1 OR SECTION 2.

IMPORTANT NOTICE: DUE TO EPA AND HUD REQUIREMENTS, IF YOUR STRUCTURE WAS BUILT BEFORE 1978, YOU MUST NOTIFY OUR OFFICE (800)420-7378. STRUCTURES BUILT BEFORE 1978 REQUIRE LEAD-RENOVATION PROTOCOL BE IMPLEMENTED WHEN COMPONANTS WITH PAINTED SURFACE ARE DISTURBED.

Drywood Termites:

ITEM 2A Evidence of drywood termites noted in exterior, as indicated on diagram.

RECOMMENDATION: Fumigate the entire structure for the eradication of drywood termites using an approved fumigant (Vikane). Mask or remove fecal pellets in accessible areas. ** Two (2) year warranty for drywood termites **

Tile roof repair service is not included in this price but may be available upon request. ****** This is a Section 1 Item ******

Plants and shrubs must be trimmed at least 12 inches from structure prior to fumigation. Plant damage will occur during the course of performing the fumigation. Kennedy Pest Control offers no warranty on vegetation. A fumigation notice and fact sheet will be sent to, or left with the owner of this property, or his/her designated agent, which gives necessary information regarding procedures for fumigation. This form MUST be signed and returned to Kennedy Pest Control three (3) working days prior to scheduled fumigation date. Fumigation cannot commence without signed forms and keys. IMPORTANT Prior to fumigation this company must be notified of any construction elements, conduits, drains, or vacuum systems that could allow passage of the fumigation, owner or agent MUST contact local gas company to have gas service reconnected after fumigation process is complete. Fumigation cannot commence without gas service being disconnected. Kennedy Pest Control cannot be held liable for costs associated with delays caused by gas company. Electricity MUST be available during the course of fumigation.

PAGE OF STANDARD INSPECTION REPORT ON PROPERTY AT:

2157 Edinburg Ave, Cardiff CA 92007

BUILDING NO.

STREET, CITY, STATE, ZIP

9/11/2024 64717

INSPECTION DATE

REPORT NO.

OCCUPANTS CHEMICAL NOTICE

Kennedy Pest Control will use pesticide chemical(s) specified below for the control of wood destroying pests or organisms in locations identified in this Structural Pest Control report.

(1) The pesticide(s) proposed to be used and the active ingredients(s)

A. Chloropicrin: Used as warning agent with Vikane Gas Fumigant.

B. Vikane Gas Fumigant: Sulfuryl Floride 99.8%, Inert ingredients 0.2%

C. Fuse Foam: Fipronil 0.005%/Imidacloprid.025%, Inert ingredients 99.97%

D. Wisdom Flowable: bifenthrin 7.9%, Inert ingredients 92.1%

(2) "State law requires that you be given the following information: CAUTION-PESTICIDES ARE TOXIC CHEMICALS. Structural Pest Controm Companies are registered and regulated by the Structural Pest Control Board, and applypesticides which are registered and approved for use by California Department of Pesticide Regulation and the United States EnvironmentalProtection Agency. Registration is granted when the State finds that based on existing scientific evidence there no appreciable risks if proper use conditiopns are followed or that the risks are outweighed by the benifits. The degree of exposure, so exposure should be minimized."

"If within 24 hours following application you experience symptoms similar to common seasonal illness comparable to the flu or any slowed movement, garbled speech or dizziness contact your physician or poison control center and Kennedy Pest Control."

For further information, contact any of the following:

Kennedy Pest Control. San Diego County Health Department San Diego County Agriculture Commisioner Poison Control Center	(800) 420-7378
San Diego County Health Department	(800) 876-4766
San Diego County Agriculture Commisioner	(858) 694-2739
Poison Control Cénter	(800) 876-4766
Structural Pest Control	56 - 65
2005 Evergreen St. Ste. 1500 Sacramento, CA 95815 (916) 561-8708

Persons with respiratory or allergic conditions, or other who may be concerned about their health relative to this chemical treatment, should contact their physician concerning occupancy during and after chemical treatment PRIOR TO SIGNING THIS NOTICE.

NO CHEMICAL APPLICATION WILL BE PERFORMED UNTIL SUCH A TIME THAT THIS NOTICE IS RETURNED to KENNEDY PEST CONTROL. HAVING READ THE INSTRUCTIONS, I, THE UNDERSIGNED, ACCEPT RESPONSIBILITY FOR UNDERSTANDING ALL THE AFOREMENTIONED.

OWNER/OCCUPANT

DATE

OWNER/OCCUPANT

DATE



1518 Sterling Court, Escondido, CA 92029 Tel: (760)233-2055 Fax: (760)233-2090 Toll: (800)420-7378 Email: inbox@kennedypest.com

WORK AUTHORIZATION CONTRACT

Address of Property: 2157 Edinburg Ave, Cardiff CA 92007 Inspection Date: 9/11/2024 Report #: 64717 Title Co. & Escrow #:

SECTION 1

2A \$ 2988.00

SECTION 2

FURTHER INSPECTION

We Authorized the Following Section 1 Items to be Performed.	We Authorized the Following Section 2 Items to be Performed,		We Authorized the Following Items for Further Inspection.		
2A			·		
		v			
Proposed Cost Section 1: \$2,988.00	Proposed Cost Section 2: Total:	\$0.00 \$2,988.00	Proposed Cost Fur.Insp.:	\$0.00	

NOTICE TO OWNERS: Under California Mechanics Lien Law any structural pest control company which contracts to do work for youany contractor, subcontractor, laborer, supplier or other person who helps to improve your property but is not paid for his orher work or supplies has a right to enforce a claim against your property. This means that, after a court hearing, yourproperty could be sold by the court officer and the proceeds of the sale used to satisfy the indebtedness. This can happeneven if you have paid your structural pest control company in full, if the subcontractor, laborer, or supplier remains unpaid. To preserve their right to file a claim or lien against your property, certain claimants such as contractors or materialsuppliers are required to provide you with a document entitled "Preliminary Notice." A Preliminary Notice is not a lienagainst your property. Its purpose is to notify you of persons who may have a right to file a lien against your property ifthey are not paid.

I have read this work authorization contract and WDO inpection report it refers to. SIGNED WORK AUTHORIZATION CONTRACT MUST BE RECEIVED BEFORE WORK WILL BE SCHEDULED. I have read and understand the terms of this work authorization contract and hereby agree to all

APPROVED AND READ BY:

DATE

ACCEPTED FOR: KENNEDY PEST CONTROL, INC. DATE



1518 Sterling Court, Escondido, CA 92029 Tel: (760)233-2055 Fax: (760)233-2090 Toll: (800)420-7378 Email: inbox@kennedypest.com

WORK AUTHORIZATION CONTRACT

Address of Property: 2157 Edinburg Ave, Cardiff CA 92007 Inspectión Date: 9/11/2024 Report #: 64717 Title Co. & Escrow #:

CUSTOMER INFORMATION

The total amount of this contract is due and payable upon completion of the work listed above unless otherwise specified. Only the work specified in the contract is being done at this time due to owners/agents wishes. ANY WORK PERFORMED AGAINST AN EXISTING TITLE ESCROW WILL BE THE FINANCIAL RESPONSIBILITY OF THE PARTY ORDERING THE WORK CONTAINED IN THIS CONTRACT, IN THE EVENT OF A CANCELLED ESCROW.

Work completed (LABOR) by Kennedy Pest Control shall be warrantied for a period of one year from completion. Toilet or plumbing parts (supplied by this firm), showers, floors or any measures for the control of moisture are warrantied for (30) days only. Localized treatments are warrantied for one year. Only the areas treated are warrantied. Two (2) year warranty on Tent Fumigations.

Customer agrees to hold Kennedy Pest Control harmless for any damage which may occur to plant life, wiring, trees, vines, pets, tile roofs,

plumbing leaks, or changes beyond control of Kennedy Pest Control which may occur during the performance of this work. In case of non-payment by owner, reasonable attorney's fees and costs of collection shall be paid by the owner, whether suit be filled or not. A SERVICE CHARGE OF 1-1/2 PERCENT, PER MONTH WILL BE CHARGED ON ALL BALANCES OVER (30) DAYS. THE 1-1/2 PERCENT,

PER MONTH, EQUALS 18 PERCENT PER ANNUM ON THE UNPAID BALANCES.

All repairs performed by others must be re-inspected by Kennedy Pest Control before a CERTIFICATION will be issued. We do not guarantee work completed by others. Any repairs completed by others must be guaranteed in writing and submitted to Kennedy Pest Control

before a CERTIFICATION will be issued. This firm does not make statements concerning workmanship. Workmanship is only determinable by those paying for or receiving those services.

If at the time of repair(s) on original report the damage is found to be more extensive, a Supplemental report will be given along with a bid for any other corrections that maybe necessary.

A cancellation fee of \$200.00 will be assessed for all work cancelled within 48 hours of scheduled date.

NOTICE TO OWNERS: Under California Mechanics Lien Law, any structural pest control company, any contractor, subcontractor, laborer,

supplier or other person(s) who helps improve your property but is not paid for his or her work or supplies has a right to enforce a claim against

your property. This means that, after a court hearing, your property could be sold by the court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full, if the subcontractor, laborer, or supplier remains unpaid. To preserve their right to file a claim or lien against your property, certain claimants such as contractors or material suppliers are required to provide you with a document entitled " Preliminary Notice." A Preliminary Notice is not a lien against you property. It's purpose is to notify you of person(s) who may have a right to file a lien against your property if they are not paid.

NOTE: Inspection fee is billed separately from any work costs.

Building No. Street City ZIP Date of Inspection Number of Pages 2157 Cardiff 92007 11/14/2024 Edinburg Ave 4 Pest Patrol, Inc. Report #: 19509 9920 Scripps Lake Drive Suite 107 Registration #: PR1612 San Diego CA 92131 Escrow # : (760) 789-5889 office@pestpatrol.com CORRECTED REPORT Ordered by: Property Owner and Party of Interest: Report sent to: Darin Triolo 2157 Edinburg Ave 2157 Edinburg Ave Darin Triolo Cardiff CA 92007 Cardiff CA 92007 United States United States SUPPLEMENTAL REPORT COMPLETE REPORT LIMITED REPORT REINSPECTION REPORT **GENERAL DESCRIPTION:** Inspection Tag Posted: Garage 2 story, slab foundation, single family residence, stucco siding, composition roof, and attached garage. Other Tags Posted: Fumed 10/24 An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected. Other Findings Fungus / Dryrot Subterranean Termites Drywood Termites 🗙 Further Inspection If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked items. **Diagram Not To Scale** 2C 2C 2B 2B 2A 2A 2C 2C 2A 2A 2B 2C 2A 2B 2B 2C 2A 2B 2C Front Door 2C 2C2A 2A 20 2B 20 2A 2B 2C 2A 2A 2B 2C 2C Inspected By: Eliot Pierce FR53722 State License No. Signature:

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California, 95815-3831.

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov. 43M-41 (Rev. 04/2015)

WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

PEST PATROL, INC.

Page 2 of 4 inspection rep	port	,			
2157	Edinburg Ave	Cardiff	CA	92007	
Address of Property Inspe	ected	City	State	ZIP	
11/14/2024		19509			
Date of Inspection	Cor	responding Report No.	E	scrow No.	

WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

This inspection report does not include findings for rats, mice, bats, other rodents or non-wood destroying pest.

PEST PATROL, INC.

Page 3 of 4 inspection repor	t	<i>,</i>			
2157	Edinburg Ave	Cardiff	CA	92007	
Address of Property Inspect	ed	City	State	ZIP	
11/14/2024	195	09			
Date of Inspection	Correspo	nding Report No.		Escrow No.	

THIS IS A SEPARATED REPORT WHICH IS DEFINED AS SECTION I/SECTION II CONDITIONS EVIDENT ON THE DATE OF THE INSPECTION.

SECTION I CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

SECTION II ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

FURTHER INSPECTION ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(s) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

2. DRYWOOD TERMITES:

2A - Section I

FINDING - Evidence of termite damaged wood members noted at time of inspection at fascia as indicated on the diagram.

RECOMMENDATION - Remove and replace and/or repair the damaged wood member(s) as necessary in currently available widths and grades. Minor damage may be filled, or where impractical, reinforcement will be done. If, upon performance of the work, the damage extends into inaccessible areas, a new supplemental report with cost estimate may be issued.

If the paint is provided for us, then painting is included in the price of the bid. If paint is not provided, we will prime the repaired/replaced area only.

2B - Section I

FINDING - Evidence of termite damaged wood members noted at time of inspection at rafter tail as indicated on the diagram.

RECOMMENDATION - Remove and replace and/or repair the damaged wood member(s) as necessary in currently available widths and grades. Minor damage may be filled, or where impractical, reinforcement will be done. If, upon performance of the work, the damage extends into inaccessible areas, a new supplemental report with cost estimate may be issued.

If the paint is provided for us, then painting is included in the price of the bid. If paint is not provided, we will prime the repaired/replaced area only.

2C - Section I

FINDING - Evidence of termite damaged wood members noted at time of inspection at roof sheathing as indicated on the diagram.

RECOMMENDATION - Remove and replace and/or repair the damaged wood member(s) as necessary in currently available widths and grades. Minor damage may be filled, or where impractical, reinforcement will be done. If, upon performance of the work, the damage extends into inaccessible areas, a new supplemental report with cost estimate may be issued.

If the paint is provided for us, then painting is included in the price of the bid. If paint is not provided, we will prime the repaired/replaced area only.

Thank you for selecting us to perform a structural pest control inspection on your property. Should you have any questions regarding this report, please call us directly by the contact information provided on the first page of the inspection report.

Our inspectors have determined that your property will benefit from a safe application of chemicals commonly used for structural pest control. In accordance with the laws and regulations of the State of California, we are required to provide you and your occupants with the following information prior to any application of chemicals to such property.

Please take a few moments to read and become familiar with the content. State law requires that you be given the following information:

CAUTION - PESTICIDES ARE TOXIC CHEMICALS. Structural pest control companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the state finds that based on scientific evidence, there are no appreciable risks weighted by the benefits. The degree of risk depends on the degree of exposure, so exposure should be minimized.

PEST PATROL, INC.

Page 4 of 4 inspection report							
2157	Edinburg Ave	Cardiff	CA	92007			
Address of Property Inspect	ed	City	State	ZIP			
11/14/2024		19509					
Date of Inspection	Corre	esponding Report No.	Escrow No.				

If within 24 hours following application, you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center and your pest control operator immediately.

For further information, contact any of the following agencies in your area:

Poison Control Center(800) 222-1222Agricultural Department(858) 694-2739Health Department(866) 358-2966Structural Pest Control Board(916) 561-87002005 Evergreen Street, Ste. 1500. Sacramento, CA 95815



WORK AUTHORIZATION

Report #: 19509

No work will be performed until a signed copy of this agreement has been received.

Address of Property :	2157 Edinburg Ave		
City:	Cardiff		
State/ZIP:	CA 92007		
The inspection report of the company dated, <u>11/14/2024</u> is incorporated herein by reference as though fully set forth.			

THE COMPANY AGREES

To guarantee all repair completed by this company for one year from date of completion except for caulking, grouting, or plumbing, which is guaranteed for a period of ninety (90) days. We assume no responsibility for work performed by others, to be bound to perform this work for the price quoted in our cost breakdown for a period not to exceed 30 days, to use reasonable care in the performance of our work but to assume no responsibility for damage to any hidden pipes, wiring, or other facilities or to any shrubs, plants, or roof. The quoted price is for all work being performed together. Should only a portion of the work be authorized, rather than the full recommended work, the price may change in cost.

THE OWNER OR OWNER'S AGENT AGREES

All services rendered and any additional services requested upon the completion of the work will be paid within thirty (30) days of their completion. For all properties that will be paid outside of escrow: 1) 30% of the invoice must be paid as a deposit before the work is performed. Any credit card transaction will be subject to a 2% service charge. 2) a card will be put on file, 3) should the invoice not be paid within thirty (30) days after the completion of the work, the card on file will be charged, 4) if the charge does not go through, an interest of one and one-half perfect (1.5%) will be added to the invoice for each month it is not paid. In the case of non-payment by the owner, reasonable attorney fees and costs of collection shall be paid by the owner, whether the suit is filed or not.

In order for a property to be paid through escrow: 1) the property must be in escrow when the work is performed, 2) the buyer(s) must release contingencies before the work is performed, 3) escrow information must be provided including the escrow officer's name and email address. If all three of these conditions are not met, work must be paid for outside of escrow from the person who authorizes the work.

ALL PARTIES AGREE

If any additional work is deemed necessary by the local building inspector, said work will not be performed without additional authorization from owner or owner's agent. This contract price does not include the charge of any Inspection Report fees. Circle the items you wish performed by The Company, below and enter total amount above:

NOTICE TO OWNER

Under the California Mechanics Lien Law, any structural pest control company which contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractor, laborers or suppliers remain unpaid.

To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice." Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

ITEMS				
Prefix	Section I	Section II	Further Inspection	Other
2A	13,190.00	0.00	0.00	0.00
2B	See 2A	0.00	0.00	0.00
2C	See 2A	0.00	0.00	0.00
Total:	13,190.00	0.00	0.00	0.00
	10 100 00			

GRAND TOTAL:

13,190.00



Air Pros, Inc

ESTIMATE	#2218
ESTIMATE DATE	Nov 6, 2024
TOTAL	\$13,900.00

Greg Coleson 2157 Edinburg Ave Cardiff, CA 92007

L (404) 217-3675 🖌 gcoleson@gmail.com

CONTACT US

864 Grand Ave, #247 San Diego, CA 92109

(858) 925-5400 service@airprossd.com

ESTIMATE

Services	qty	unit price	amount	
HVAC Installation to Include:	1.0	\$13,900.00	\$13,900.00	
* Unit 1 - Family Room & Master Bedroom Daikin 17 SEER 18K BTU 2-Zone System Condenser - 2MX18AXVJU Family Room - 12K Air Handler - CTX12AXVJU Master Bedroom - 9K Air Handler - CTX09AXVJU				
* Unit 2 - Remaining 2 Bedrooms Daikin 17 SEER 18K BTU 2-Zone System Condenser - 2MX18AXVJU Each Bedroom - 9K Air Handler - CTX09AXVJU				
 * Warranty: Equipment - 10 years / Labor - 1 year * Condensation from each air handler to drain on the ground outside directly below the air handlers. We will need to figure out how to get the condensation from the family room air handler to the ground given the stairwell on the outside of the house. * Permitting can be included for an additional fee. * 3% fee for payment by credit card. 				
	;	Services subtota	al: \$13,900.00	

Total

\$13,900.00

Thank you for considering Air Pros.

Mark Allen

858-205-1000

License No 1031362

A H BUILDERS & DEVELOPERS

2157 Edinburg Ave Cardiff By The Sea, CA 92007. Dec / 03 / 2024. 1738 Thelborn Way San Diego CA 92154. (619) 403 4634. Julio Cesar Hernandez. Lic # 661525 kpacho0729@gmail.com

During the inspection we found than the existing roof has already reached the limit of life, we do NOT recommend doing any repairs, rather our recommendation would be to replace it with a new one.

"JOB DESCRIPTION "

Roof Type; LOW SLOPE - FLAT ROOF GRANULATED.

- Remove all old metals, Drip edge, T-tops, flashings, saddle flashing (metal around the chimney) / and old flat roof (TWO LAYERS) going down to the existing plywood.
- After removing the entire roof, we will take it in a trailer to the dumpster .
- Install new Item # 2550 GAF GLASS @75 FIBERGLASS BASE SHEET, DOUBLE LAYER- nailed whit 7/8" round metal cap / EG #5.
- Install new drip edge metals, install them around the perimeter of the house and install all new flashings, T-tops, saddle flashing & vents.
- Install new Item # 3021 JM: JIM: SMOOTH torch down -
- Install new Item # 496 JM: APP: WHITE 4.5 MIL: FOR LOW SLOPE APPEX GRANULATED 2,836 sf of roof 20 YEAR WARRANTY.
- After finishing the entire roof, the new metal flashings will be sealed and painted to the new color.

Color # WHITE / OPTIONAL.

PAYMENT METHOD;

1st Payment - \$ 1,000.00 to start.

2nd Payment - \$ 9,000.00 to cover materials.

3rd Payment - \$ 6,500.00 When the work is 100% finished.

TOTAL AMOUNT WILL BE : \$ 16,500.00 This amount covers all materials, labor and Garbage.

PROPOSAL #04848

Thank you.