
Building No. Street Date of Inspection Page 10145 DIAMOND HEAD CT. SPRING VALLEY 91977 08/11/25 1 of 5 Mt. Helix Pest and Termite Control 4401 Twain Ave. Suite 29 San Diego, CA 92120 MT-HELIX Phone: 619-584-6794 Fax: 619-584-3864 www.mthelixpestcontrol.com Registration # PR3799 Report # 2036783 Ordered by: Property Owner and/or Party of Interest: Report sent to: **EUGENIA GARCIA EUGENIA GARCIA EUGENIA GARCIA** 10145 DIAMOND HEAD CT. 10145 DIAMOND HEAD CT. 10145 DIAMOND HEAD CT. **SPRING VALLEY, CA 91977 SPRING VALLEY, CA 91977** SPRING VALLEY, CA 91977 EUGENIA@EUGENIAGARCIA.COM **EUGENIA@EUGENIAGARCIA.COM EUGENIA@EUGENIAGARCIA.COM** H: 619-874-4851 H: 619-874-4851 H: 619-874-4851 COMPLETE REPORT □ LIMITED REPORT X SUPPLEMENTAL REPORT REINSPECTION REPORT [7] Inspection Tag Posted: General Description: TWO STORY CONDOMINIUM UNIT SINK Other Tags Posted: NONE An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected. Diagram is not to scale. Locations are only approximate. Subterranean Termites Drywood Termites X Fungus / Dryrot X Other Findings Further Inspection If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked items. KEY: 1 - Subterranean Termites 2 - Drywood Termites 3 - Fungus/Dryrot 4 - Other Findings 5 - Unknown Further Inspection



Inspected by: Stephen Orton

State License No. OPR 9629

Signature

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California, 95815-3831.

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or <a href="https://www.pestboard.ca.gov">www.pestboard.ca.gov</a>. 43M-41 (REV. 10/01)

Building No. 10145	Street DIAMOND HEAD CT.	City SPRING VALLEY	Zip <b>91977</b>	Date of Inspection 08/11/25	Report # 2036783	Page 2 of 5

STATE LAW REQUIRES THAT YOU BE GIVEN THE FOLLOWING INFORMATION: CAUTION-PESTICIDES ARE TOXIC CHEMICALS. Structural pest control companies are regulated by the Structural Pest Control board, and apply pesticides which are approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the state finds that based on existing scientific evidence there are no appreciable risk if proper conditions are followed or that the risks are outweighed by the benefits. The degree of risk depends on the degree of exposure, so exposure should be minimized.

If within 24 hours of application you experience symptoms similar to common seasonal illness comparable to the flu, headache, dizziness, nausea, tearing, coughing, and nose and throat irritation or develop shortness of breath, double vision, unusual drowsiness and weakness, or tremors contact your physician or poison control center and your pest control operator immediately.

For Further Information Contact The Following: Mt. Helix Pest & Termite Control (619)584-6794; San Diego County Operator (858)694-3900 Poison Control Center (800)222-1222; County Health & Human Services Department (619)515-6555; Agricultural Commissioner (858)694-2741; Structural Pest Control Board 1)Licensing (916)561-8704 2)Admin (916)561-8700 2005 Evergreen St. Suite 1500 Sacramento, CA 95815

One or more of the following chemicals may be applied to your property: Tim-bor® (Disodium Octaborate Tetrahydrate), I Maxx Pro® (Imidacloprid), TERMIDOR® SC (Fipronil), PREMISE FOAM (Imidacloprid)

The following items were not inspected: The interior of hollow walls, inaccessible areas below; areas beneath wood floors over concrete; areas concealed by floor coverings; and areas to which there is no access without defacing or tearing out lumber, masonry, roofing, or finished workmanship; structures (except for wood members abutting the structure) such as fences, gazebos, storage sheds, plumbing sheds, detached decks, and/or porches. Livestock areas were not inspected and are not included in this report. See additional areas on areas not inspected or included in this report. The above mentioned areas in the future may be made accessible by opening walls, remodeling the structure, removing floor coverings, or moving furniture, etc. Further inspection at this time may disclose infestations, infections, or adverse conditions that may require an additional cost. An inspection fee may be charged.

These area(s) is not practical: furnished interiors; inaccessible attics or portions thereof; the interior of hollow walls; spaces between a floor or porch deck and the ceiling or soffit below; stall showers over finished ceilings; such structural segments as porte cochere, enclosed bay windows, buttresses, and similar areas to which there is no access without defacing or tearing out lumber, masonry or finished work; built-in cabinet work; floors beneath coverings, areas where storage conditions or locks make inspection impracticable.

Additional notes on areas not inspected or included in this report: In accordance with the standard practice of the control of wood destroying organisms, certain structural areas are considered inaccessible and impractical to inspect: portions of the attic concealed or made inaccessible by insulation or ducting; portions of the roof cavity concealed due to construction; interior of enclosed boxed eaves; portions of the subarea concealed or made inaccessible by ducting or insulation; second story eaves; enclosed by bay windows; portions

Building No. 10145	Street DIAMOND HEAD CT.	City SPRING VALLEY	Zip <b>91977</b>	Date of Inspection 08/11/25	Report # 2036783	Page 3 of 5
				1	1 1	

of the interior made inaccessible by furnishings with the exception of any specific area(s) noted in the body of this report; areas where locks prevented access; areas concealed by appliances; areas concealed by storage; areas concealed by heavy vegetation. Note:

Inspections are made and reports are issued on the basis of what is visible and accessible at the time of inspection. The absence of visible evidence of wood destroying organisms in the visible and accessible portions of the structure is no assurance the wood destroying organisms are not present in the inaccessible areas nor those future infestations will occur. Therefore, we do not assume any responsibility for the presence of wood destroying organisms, or the damage due to such organisms, in areas that were not visible and accessible at the time of inspection or that may occur in the future.

\*\*\*NOTE\*\*\*: This inspection does not include inspection of electrical, plumbing, heating, or other mechanical systems of the structure. This inspection will not detect building code violations, asbestos, or any other environmental or safety hazards. Should interested parties desire opinions regarding these items, it is recommended that the owner engage the services of a "whole house" inspection company.

\*\*\*NOTE\*\*\*: This is a visual inspection. The inspector did not deface nor probe into finished window or door frames, trim work, floor coverings, walls, ceilings or other finished surfaces.

\*\*\*NOTE\*\*\*: If an exterior inspection was performed, the exterior areas would have been visually inspected from ground level. Areas of the exterior that exhibited signs of infestation, infection or damage from it, will be described in the body of this report.

\*\*\*NOTE\*\*\*: The owner of the property has certain responsibilities regarding the normal maintenance that pertains to the deterrence of wood destroying organisms. These normal maintenance procedures include, but are not limited to; maintenance of the roof, gutters, and downspouts; caulking around doors, windows, vents, tub and shower enclosures; keeping soil levels below the top of the foundation; adjusting sprinklers so that they do not spray onto the structure; keeping stored items (including firewood) at least twelve inches away from the structure; and preventing vegetation or other items from blocking vents.

\*\*\*NOTE\*\*\*: This inspection is for the purpose of identifying wood destroying organisms, it is not intended to discover the presence of hazardous materials.

NOTICE: The charge for the service that this company subcontracts to another person of entity may include the company's charge for arranging and administering such services that are in addition to the direct cost associated with paying the subcontractor.

\*\*\* NOTICE\*\*\*:"" Reports on this structure prepared by various registered companies should list the same findings (i.e. Termite infestations, termite damage, fungus damage, etc.)

However, recommendations to correct these findings may vary from company to company you have the right to seek a second opinion from another company.

This is not a structural damage report. This report reflects conditions, infestations, infections, etc. on the day of the inspection only. Structural damage reported here is limited to those parts or members which are only for support to the structure which, are visibly weakened by wood destroying organisms.

The exterior surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the contractor's state license board.

Building No. 10145	Street DIAMOND HEAD CT.	City SPRING VALLEY	Zip <b>91977</b>	Date of Inspection 08/11/25	Report # 2036783	Page 4 of 5	
-----------------------	-------------------------	-----------------------	---------------------	-----------------------------	------------------	----------------	--

Mold Disclaimer: There may be health related issues associated with the structural repairs reflected in the inspection report referenced by this work authorization contract. These health issues include, but are not limited to the possible release of mold spores during the course of repairs. We are not qualified to and do not render any opinion concerning such health issues or any special precautions. Any questions concerning health issues or any special precautions to be taken prior to or during the course of such repairs should be directed to a certified industrial hygienist before any such repairs are undertaken. By executing this work authorization contract, customer acknowledges that he or she has been advised of the foregoing and has had the opportunity to consult with a qualified professional.

"This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of the request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs."

\*\*\*NOTE\*\*\*: THIS IS A LIMITED INSPECTION AND REPORT AT THE REQUEST OF EUGENIA GARCIA, AND IS LIMITED TO THE FOLLOWING AREA(S): EXTERIOR AREAS ONLY. IN VIEW OF THE FACT THAT THIS IS A LIMITED INSPECTION, IT IS RECOMMENDED THAT THIS COMPANY BE AUTHORIZED TO MAKE A COMPLETE INSPECTION OF THE STRUCTURE AND FURNISH A COMPLETE REPORT.

This is a separated report which is defined as Section I/Section II conditions evident on the date of inspection. Section I contains items where there is visible evidence of active infestation, infection, or conditions that have resulted in or from infestation or infection. Section II items are conditions likely to lead to infestations or infections but where no visible evidence of such was found. Further inspection items are defined as recommendations to inspect area(s) which during the original inspection did not allow the inspector access to complete the inspection and cannot be defined as Section I or Section II.

The structure inspected is a condominium/townhome that may share common sub areas, walls, foundations, attics, or other common elements of construction with adjacent condominium/townhouse type units. The adjacent units were not inspected. No opinion is rendered, nor guarantee implied concerning the presence or absence of infestation of infection in these common areas, or from spreading from these common areas into the inspected unit.

#### SECTION I:

#### (2) DRYWOOD TERMITES

2A. FINDING:

Infestation of Drywood Termites was noted at the ROOF EAVES, JAMBS AT

BALCONY.

RECOMMENDATION:

Due to the nature of these infestations, it will be necessary to seal the entire structure and fumigate it with Vikane (Sulfuryl Fluoride).

Building No. 10145	Street DIAMOND HEAD CT.	City SPRING VALLEY		Date of Inspection	Report #	Page
	James Herborn	SPRING VALLEY	91977	08/11/25	2036783	5 of 5
				1	1	

We will use tear gas (chloropicrin) as a warning agent. The entire structure must be vacant for at least 72 hours for this process. We will use all due caution in our operation, however, we assume no liability for any damage to roof coverings, solar panels, TV antennas or planting adjacent to the structure. The occupants must sign the occupant's fumigation notice and comply with all of the instructions. Tent fumigation is guaranteed for three years.

2B. FINDING:

There is evidence of Drywood Termite damage noted at the ROOF EAVES, JAMBS AT BALCONY.

RECOMMENDATION:

Remove, replace or reinforce all damaged wood members as necessary.

(3) FUNGUS/DRYROT

3A. FINDING: Evidence of fungus damage/dry rot was noted at the ENTRY JAMB AND

BALCONY.

RECOMMENDATION: Remove and replace damaged and infected wood members as needed. If

damage extends into inaccessible area or wall voids, a supplemental

report will be filed. An additional charge may be made.

		WOR	K AUTH	ORIZATION	CONT	RACT		
Building No. Street				City	2	Zip	Date of Inspection	Page No.
10145 DIAMOND H	EAD C1	г.		SPRING VALLE	Υ :	91977	08/11/25	1
	Mt H	lelix Pest ar	nd Termi	to Control				
		Twain Ave.						
K		Diego, CA 9						
MT-HELIX		ne: 619-584-						
Pest & Termite Control		619-584-386						
			7.15					
I .		.mthelixpes		.com				
	Regis	stration # P	K3/99				For Repor	rt # 2036783
ITEMIZED COST BRE	AKDO	OWN (Refer	to items or	the report)				
		Primary Wor	k Bid			Secondary	/ Work Bid	
SECTION 1:		2A: \$2,085.00,	2B: NO BIE	), 3A: NO BID	ı	NONE		
		*** TOTAL:	\$2,085.00					
SECTION 2:		NONE			P	NONE		
<b>FURTHER INSPECTI</b>	ON:	NONE			NONE			
TOTAL:		\$2,085.00			s	0.00		
THIS IS A BINDING CONTR	ACT. II	tems on the rei	port may co	ontain provisions fo	or addition	al costs ov	ver and above the orion	ninal estimate
Please read the report care								giriai cotiriate.
1. This offer is limited to 90	-							
2. If further inspection is re	comm	ended, or if add	ditional wor	rk is required, we w	vill provide	prices or	recommendations for	correction.
Interested parties will be no								
3. Notice to Owner of Mech					rol Board:	Under the	California Mechanics	Lien Law. anv
structural pest control ope								
helps to improve your prop								
means that after a court he								
indebtedness. This can hap								
To preserve their right to fi								
required to provide you wit	th a doo	cument entitled	d "Prelimina	ary Notice". Genera	al contracto	ors and lat	orers for wages do n	ot have to
provide this notice. A Prelin	minary	Notice is not a	lien agains	st your property. Its	s purpose i	s to notify	you of persons who	may have a
right to file a lien against ye	our pro	perty if they a	re not paid.					
4. We will use due caution a	and dili	igence in our o	perations a	and care will always	s be taken	to minimiz	e any damage, but w	e assume no
responsibility for matching								
gutters, plant life, paint or	wall co	verings. There	may be he	alth related issues	associated	with the s	structural repairs refle	ected in the
inspection report reference	ed by th	nis work author	rization cor	ntract. These health	h issues ind	clude but a	are not limited to the	possible release
of mold spores during the	course	of repairs. We	are not qua	alified to and do no	ot render ar	y opinion	concerning such hea	alth issues or
any special precautions. A			_		-			•
of such repairs should be o	lirected	to a Certified	Industrial I	Hygienist before an	ny such rep	airs are u	ndertaken. By executi	ing this work
authorization contract, cus	tomer	acknowledges	that he or s	she has been advis	sed of the fo	oregoing a	nd has had the oppo	rtunity to
consult with a qualified pro	fession	nal.						
5. This report is limited to t	he acc	essible areas o	of the struct	ture shown on the	diagram. Pl	ease refer	to the report for area	is not inspected
and further information.								
6. TERMS OF PAYMENT. W						Notice of	Work Completed. Ac	counts are past
due 30 days after the date of								
7. FOR HOME SALES: We i								
close of escrow. We under		-						eletion of this
work we will pay the full an				,,				
8. We authorize this compa	ny to p	erform items_			for a cor	tract price	e of \$	·
CONTACT PERSON FOR A	CCESS	š:			PHONE #_			-

\_\_\_\_\_DATE \_\_\_\_\_

SIGNATURE OF OWNER/ AGENT / MANAGEMENT CO.\_\_\_\_\_