Candor Pump

Lic. # 1012176
Cell # 951-675-3405

Flow Test/Site Inspection


Notes: Well is located central of the primary driveway. No electricity on site, performed flow test with generator and existing equipment on site. The pump turned on and was operational the entire time of the flow test. Pump moves approx. 6gpm, and did break suction. The pump was pulling right at service factor amps, possibly due to the generator. The booster system found on site was not in an operational condition. A large horizontal tank was just outside of the fenceline. Unsure if the tank and booster are within property boundaries. No samples were collected for testing.

Property Address: 32305 Red Mountain Rd, Hemet, CA 92544

Test Date: 5/1/2026

Test Duration: 2Hours

Productivity: 3.42GPM

Signature:  5/2/2026

DISCLAIMER

FLOW TESTS RESULTS ARE BASED ON ACTUAL GPM FLOW OBSERVED AT THE TIME OF INSPECTION. PRODUCTION OBSERVED COULD BE AFFECTED BY EXISTING PUMP PERFORMANCE, PUMP DEPTH, WELL DEPTH, WATER DEPTH, CLOGGED FRACTURES, PIPING, OR EQUIPMENT ISSUES. RESULTS ARE NOT A GUARANTEE OF LONG-TERM WELL PRODUCTION OR STABILITY; RATHER A REFLECTION OF CURRENT OPERATIONS STATUS OF THE SYSTEM.