WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building Address:	Date of Inspection	Number of Pages
1459 Ross St., Wrightwood, CA 92397	08/21/2026	5

A&C Termite and Pest Solutions
P.O. Box 702
Apple Valley CA 92307
Phone: (760) 912-8155 Fax:

Report # W16219
Lic. Registration # PR 7494
Escrow #

Ordered by:	Property Owner and/or Party of Interest:	Report Sent to:
Michelle Rivera	Trust One Escrow Lilia Gutierrez	Michelle Rivera

COMPLETE REPORT ☑ LIMITED REPORT ☐ SUPPLEMENTAL REPORT ☐ REINSPECTION REPORT ☐

General Description:
Single story wood siding single family residence with a composition roof and an attached garage


Inspection Tag Posted: Sub Area

Other Tags Posted:
None

An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.

Subterranean Termites ☐ Drywood Termites ☐ Fungus / Dryrot ☐ Other Findings ☐ Further Inspection ☐

If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for the details on checked items.



This Diagram is not to scale

Inspected by: Craig A Santifer **State License No.** FR59849 **Signature** _____

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceeding two years.
To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Ste. 1500, Sacramento, California 95815.
NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with the services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www. pestboard.ca.gov

SECOND PAGE OF STANDARD INSPECTION REPORT OF THE PROPERTY LOCATED AT:

Address 1459 Ross St., Wrightwood, CA 92397 08/21/2026 W16219

Date Report #

What Is a Wood Destroying Pest and Organism Inspection Report?

The following explains the scope and limitations of a structural pest control inspection and a Wood Destroying Pest & Organism Inspection Report.

A Wood Destroying Pest & Organism Inspection Report contains finding as to the presence or absence of wood destroying insects or organisms in visible and accessible areas on the date of inspection and contains our recommendations for correcting any infestations, infections, or conditions found. The contents of the wood destroying pest & organism inspection report are governed by the structural pest control act and its rules and regulations.

Some structures may not comply with building code requirements or may have structural, plumbing, electrical, heating and air conditioning, or other defects that do not pertain to this report. This report does not address any such defects as they are not within the scope of the license of the inspector or the company issuing this report.

The following areas are considered inaccessible for purposes of inspection or are not included in a normal inspection report and therefore are excluded in this report: the interior of hollow walls; spaces between an upstairs floor and the ceiling below or a porch deck and soffit below; stall showers over finished ceilings; such structural segments as areas enclosed by bay windows, buttresses, built in cabinet work, areas under floor covering; any areas requiring the removal of storage, furnishings or appliances; any areas to which there is no access without defacing or removing lumber, masonry or finished workmanship.

Note: Inaccessible Areas Clause

Certain areas are recognized by the industry as inaccessible and/or for other reasons not inspected. These areas include, but are not limited to: inaccessible and/or insulated attics or portions thereof, attics with less than 18" clear crawl space, the interior of hollow walls, spaces between a floor or porch deck and the ceiling below, areas where there is no access without defacing or tearing out lumber, masonry or finished work that make inspection impractical, and areas or timbers around eaves that would require use of an extension ladder.

Second Story Eaves & fascia are inspected from ground level only. If further inspection is desired owner is to contact proper tradesman. This company is not responsible for 2nd story issues/repairs.

Certain areas may be inaccessible for inspection due to construction or storage. We recommend further inspection of areas where inspection was impractical. Re: Structural Pest Control Act, Article 6, section 8516 (b), paragraph 1990 (I). Amended effective March 1, 1974. Stall shower, if any, is water tested in compliance with Section 1991 (12) of the Structural Pest Control Act. The absence or presence of leaks through sub-floor, adjacent floors or walls will be reported. This is a report of the condition of the stall shower at the time of inspection only, and should not be confused as a guarantee. Although we make a visual examination, we do not deface or probe into window or door frames, decorative trim, roof members, etc., in search of wood destroying pests or organisms.

"This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs."

NOTE: We do not inspect or certify plumbing, plumbing fixtures, etc.

NOTE: "The exterior surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractors' State License Board."

8514.5. "NOTICE: The charge for service that this company subcontracts to another registered company may include the company's charges for arranging and administering such services that are in addition to the direct costs associated with paying the subcontractor. You may accept A&C Termite and Pest Solutions's bid or you may contract directly with another registered company licensed to perform the work.
If you choose to contract directly with another registered company, A&C Termite and Pest Solutions will not in any way be responsible for any act or omission in the performance of work that you directly contract with another to perform."

"NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company."

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold-like conditions, please contact the appropriate mold professional.

"Local treatment is not intended to be an entire structure treatment method. If infestations of wood-destroying pests extend or exist beyond the area(s) of local treatment, they may not be exterminated."

- Findings and Recommendations continued on next page -

THIRD PAGE OF STANDARD INSPECTION REPORT OF THE PROPERTY LOCATED AT:

Address 1459 Ross St., Wrightwood, CA 92397 08/21/2026 W16219

Date Report #

- Findings and Recommendations continued from previous page -

Substructure: Slab, Raised, Inspected

Stall Shower: Not Tested, Pre Fab

Foundations: Slab, Raised, Inspected

Porches - Steps: Inspected

Ventilation: Adequate Above Grade

Abutments: None Noted

Attic Spaces: Good Access, Insulation caused limited inspection

Garages: Attached, Inspected

Decks - Patios: Inspected

Other Interior: Inspected

Other Exterior: Inspected

NOTE: This is to certify that the above property is free of active infestation or infection in all visible and accessible areas and meets all FHA/VA requirements. FINDINGS: CLEAR $ 150.00 CLEARANCE FEE

FOURTH PAGE OF STANDARD INSPECTION REPORT OF THE PROPERTY LOCATED AT:

Address 1459 Ross St., Wrightwood, CA 92397 08/21/2026 W16219

Date Report #

In accordance with the laws and regulations of the State of California, we are required to provide you with the following information prior to application of pesticides to your property.

"State law requires that you be given the following information: CAUTION--PESTICIDES ARE TOXIC CHEMICALS. Structural Pest Control Companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the state finds that, based on existing scientific evidence, there are no appreciable risks if proper use conditions are followed or that the risks are outweighed by the benefits. The degree of risk depends upon the degree of exposure, so exposure should be minimized."

"If within 24 hours following application you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center (800) 222-1222 and your pest control company immediately."

For further information, contact any of the following:

A&C Termite and Pest Solutions	(760) 912-8155
Poison Control Center	(800) 222-1222
(Health Questions) County Health Dept.	
Orange County	(714) 834-3155
Los Angeles County	(213) 240-8117
San Bernardino County	(800) 782-4264
Riverside County	(951) 358-5000
San Diego County	(619) 229-5400
(Application Info.) County Agriculture Commission	
Orange County	(714) 955-0100
Los Angeles County	(626) 575-5471
San Bernardino County	(909) 387-2105
Riverside County	(951) 955-3045
San Diego County	(858) 694-2739

Structural Pest Control Board (Regulatory Info.) (916) 561-8704
2005 Evergreen Street, Ste. 1500 Sacramento, CA 95815

Address 1459 Ross St., Wrightwood, CA 92397 08/21/2026 W16219

Date Report #

NOTICE TO OWNER

Under the California Mechanics Lien Law any structural pest control company which contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractor, laborers or suppliers remain unpaid.

To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice." Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

If this Contract is to be paid out of escrow the buyers and sellers must agree to provide this company with all escrow billing information required to collect the amount due. The persons signing this contract are responsible for payment, and if escrow does not close within 30 days after the date of completion of work agree to pay in full the amount specified in this work authorization agreement.
ESCROW IS NOT TO USE THIS REPORT OR IT'S COMPLETION (IN PART OR IN WHOLE) TO SATISFY A LENDER, WITHOUT ACKNOWLEDGING PAYMENT DUE IN FULL AT CLOSE OF ESCROW.

NOTE: If the Home Owner fails to pay billing in full, A&C Termite and Pest Solutions will have the right to be paid back for all of its costs and expenses to the extent not prohibited by applicable law. Those expenses include labor and materials, (but not limited to) and all reasonable attorney's fees. If for any reason this account is to be turned over to our collection agency, you will be responsible for all costs of collecting.

A&C Termite and Pest Solutions
P.O. Box 702
Apple Valley CA 92307
Phone: (760) 912-8155

INVOICE

58436

PAGE
1 of 1

JOB NUMBER
W16219

Bill To: Attn: Lilia Gutierrez
Trust One Escrow

,

Remit To: A&C Termite and Pest Solutions
P.O. Box 702
Apple Valley, CA 92307

REFERENCE NO.	SERVICE ADDRESS
	1459 Ross St. Wrightwood, CA 92397

ITEM	DATE	QTY	DESCRIPTION	AMOUNT	TAX AMT	TOTAL
1	08/24/2026		Termite Clearance papers for the above property.			$150.00

PLEASE INCLUDE THE INVOICE NUMBER IN ALL CORRESPONDENCE

Balances that remain unpaid for 30 days may be subject to 1 1/2 % per month interest and/or lien fees.

GRAND TOTAL
$150.00