Canaday Enterprise
DBA Foothill Fireplace Pools and Spa's
PO Box 407
Soulsbyville CA 95372
Lic. #795590

Phone #: 209-533-5005
Fax #: 209-533-9008
E-mail ~ ccs1service@gmail.com

Invoice

Date of Inv.	Invoice #
6/26/2026	BC40949

PAID
07/01/2026

Property Address	Mailing Address
Twila Mitchell Lassen Dr. 29565 Coldsprings CA 650-255-5947	

Service Date	Description	Qty	Price	Total
6/26/2026	Real Estate Inspection		195.00	195.00

Visit Our Showroom - Located: 18677 Eagle Ridge Rd. Sonora
Up Tuolumne Rd. from the Junction Behind National Flooring

Terms	

Subtotal	$195.00
Sales Tax (8.25%)	$0.00
Total	$195.00
Payments/Credits	-$195.00
Balance Due	$0.00

Accounts not paid in full by date due may be subject to finance charges at the maximum legal rate and collections proceedings. Canaday Enterprises, Inc. reserves the right to pursue any and all legal remedies for any unpaid amounts on the property.


144491

Canaday Ent. Inc.
DBA
C.C.S. Installations
(209) 533-5005
P.O. Box 407
Soulsbyville, CA 95372
CA Lic.# 795590

Customer Jeanie Murray
Address 29565 Lassen Dr.
City Coulterville State ___ Zip ___
Phone (209) 985-5258
E-mail ___
Date 6/26/26 Time 9-11
Directions to Home ___

- No. of Stories: 1 2 3 4 • No. of Appliances: 1 2 3 4
- Type of Appliance: ☐Prefab ☐Masonry ☐Stove ☑Insert ☐Furnace
- Fuel Type: ☑Wood ☐Pellet ☐Oil ☐Gas
- Type of Wood Used: ☑Soft ☑Hard ☐Wet ☑Dry
- Last Cleaned: UKN Year(s) Ago ☐Never
- Amount of fuel burned per season: UKN
- Flue Size: ☐8"x8" ☐8"x13" ☐13"x13" ☐8"x17" ☐13"x17" ☑6" Round ☐8" Round ☐ ___
- Outside Chimney Dimensions: ___" x ___"
- Fireplace Opening Size: ___" x ___"
- How did you hear about us? ☐TV ☐Radio ☐Website ☐Newspaper ☐Yellow Pages ☐Direct Mail ☐Social Media ☑Referral ☐Repeat Customer ☐Internet Ad. ☐ ___

CONDITION REPORT



	Satisfactory	Unsatisfactory	Not Applicable
CHIMNEY			
1. Height	/		
2. Chimney Cap / Spark Arrestor	/		
3. Crown / Wash	/		
4. Brickwork / Mortar	/		
5. Flashing	/		
6. Flue Liner	/		
7. Moisture Resistance	/		
FIREPLACE			
8. Smoke Chamber	/		
9. Damper	/		
10. Firebox / Grate	/		
11. Ash Container			/
12. Spark Screen / Doors	/		
13. Tools / Gloves			/
14. Hearth Protection		/	
15.			
STOVE OR FIREPLACE INSERT			
16. Connector Pipe Condition	/		
17. NFPA/IRC Approved Connection and Flue	/		
18. Installation / Thimble / Clearances	/		
OTHER SAFETY CONSIDERATIONS			
19. Fire Ext. / Smoke Detectors / CO Alarms			/
20. Gas / Oil Furnace Flue Liner			/
21. Fire Escape Plan			/

Note: This sheet is the result of a visual inspection done at the time of cleaning. It is

COMMENTS: (1) Hearth is 4" short, Recommend a 12X48 Black metal Hearth extension. (2) Recommend a chimney before firstuse. (3) Estimated cost for Chimney Cleaning and Black metal Hearth extension is $620 includes tax and Labor.

CUSTOMER VERIFICATION

I have read this form and now understand which areas of my chimney system appear to be satisfactory and which areas are not satisfactory.

Signed Per Jeanie Date 6/26/26

NEXT SERVICING SCHEDULED

on Summer 2026 at ___
(month / day / year / time)

The National Fire Protection Association Standard states the fireplace and chimney should be inspected yearly for any structural faults.

Chimney Professional's Signature ___

RECEIPT / INVOICE

DESCRIPTION	PRICE
Real Estate Inspection	$195
SUBTOTAL	