

# WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No. 4266	Street Keefer Road	City Chico	Zip 95973	Date of Inspection 06/20/2017	Number of Pages 4
----------------------	-----------------------	---------------	--------------	----------------------------------	----------------------




**HOUSE DETECTIVE TERMITE CONTROL INC**  
**11 COMMERCE CT. SUITE 10**  
**CHICO CA 95928**  
 (530) 894-7900 (530) 591-7079  
 hdetective@att.net Fax (530) 894-7902

Report # : 11401  
 Registration # : PR5960  
 Escrow # :  
☐ CORRECTED REPORT

Ordered by: Brandi Laffins Remax 1834 Mangrove Ave. Chico CA 95926 United States	Property Owner and/or Party of Interest:	Report sent to:
---	--	-----------------

COMPLETE REPORT <input checked="" type="checkbox"/> LIMITED REPORT <input type="checkbox"/> SUPPLEMENTAL REPORT <input type="checkbox"/> REINSPECTION REPORT <input type="checkbox"/>	
GENERAL DESCRIPTION: One story wood frame single family dwelling.	Inspection Tag Posted: At the water heater <hr/> Other Tags Posted:
An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.	
Subterranean Termites <input type="checkbox"/> Drywood Termites <input type="checkbox"/> Fungus / Dryrot <input checked="" type="checkbox"/> Other Findings <input checked="" type="checkbox"/> Further Inspection <input checked="" type="checkbox"/>	
If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked	

**Diagram Not To Scale**



Inspected By: Gregory D Hosler State License No. OPR10012

Signature: \_\_\_\_\_

# HOUSE DETECTIVE TERMITE CONTROL INC

Page 2 of 4 inspection report

4266	Keefer Road	Chico	CA	95973
Address of Property Inspected		City	State	Zip
06/20/2017		11401		
Date of Inspection		Corresponding Report No.	Escrow No.	

## **WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.**

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

**The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.**

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

**NOTICE:** Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

# HOUSE DETECTIVE TERMITE CONTROL INC

Page 3 of 4 inspection report  
4266 Keefer Road  
Address of Property Inspected  
06/20/2017

Chico  
City  
11401

CA  
State

95973  
Zip

Date of Inspection

Corresponding Report No.

Escrow No.

This is a separated report which is defined as Section I/Section II conditions evident on the date of the inspection. Section I contains items where there is visible evidence of active infestation, infection or conditions that have resulted in or from infestations or infections. Section II items are conditions deemed likely to lead to infestation or infection but where no visible evidence of such was found. Further inspection items are defined as recommendations to inspect area(s) which during the original inspection did not allow the inspector access to complete the inspection and cannot be defined as Section I or Section II.

**SECTION I** CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

**SECTION II** ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

**SECTION III / FURTHER INSPECTION** ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(S) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

## 3. FUNGUS / DRYROT:

### 3A - Section I

**FINDING:** Fungus damage was found to the wood trim.

**RECOMMENDATION:** Remove the damaged wood members and replace with new material. Prime paint only.

### 3B - Section I

**FINDING:** Fungus damage was found to the 4x6 support post.

**RECOMMENDATION:** Remove the damaged wood members and replace with new material. Prime paint only.

### 3C - Section I

**FINDING:** Fungus damage was found to the support joist, beams and decking on the rear patio.

**RECOMMENDATION:** Lift up roofing to allow for repairs. Remove the damaged wood members and replace with new material. Prime paint only. Re-install roofing.

### 3D - Section I

**FINDING:** Fungus damage was found to a section of roof eaves.

**RECOMMENDATION:** Lift up the roofing to allow for repairs. Remove the damaged wood members and replace with new material. Prime paint only. Re-install roofing.

## 4. OTHER FINDINGS:

### 4A - Section II

**FINDING:** The toilet was found to be loose in the hall bathroom.

**RECOMMENDATION:** Remove the toilet for further inspection. If no damage is exposed, reset the toilet on a new wax ring. The tub faucet cover in this bathroom was also loose.

## 5. FURTHER INSPECTION:

### 5A - Section III

**FINDING:** Portions of the subarea were inaccessible due to rigid heating ducts blocking access.

**RECOMMENDATION:** Further inspection will be performed upon request after proper access has been provided.

# HOUSE DETECTIVE TERMITE CONTROL INC

Page 4 of 4 inspection report

4266 Keefer Road

Chico

CA

95973

Address of Property Inspected

City

State

Zip

06/20/2017

11401

Date of Inspection

Corresponding Report No.

Escrow No.

## NOTES

### Note A

Guarantee: All work performed is guaranteed fro a period of one (1) year from the date of completion, unless specifically mentioned elsewhere herein; except plumbing, grouting, or caulking which is guaranteed for 90 days.





Front of the structure.



3 A - Damaged trim.



3 B - Damaged post.



3 C - Damaged joist.





3 C - Damaged beam.



3 C - Damaged decking.



3 C - Damaged beam.



3 D - Damaged eaves.



# INVOICE / STATEMENT

## HOUSE DETECTIVE TERMITE CONTROL INC

11 COMMERCE CT. SUITE 10  
CHICO CA 95928  
(530) 894-7900 (530) 591-7079  
hdetective@att.net Fax (530) 894-7902

Date: 06/20/2017  
Report Number: 11401  
Invoice Number: 11401-1  
Escrow Number:

Property Inspected: 4266 Keefer Road  
Chico, CA 95973

Bill To: Brandi Laffins  
Remax  
1834 Mangrove Ave.  
Chico, CA 95926  
United States  
  
brandi@laffins.com

Inspection:	\$ 150.00
<b>Invoice Total:</b>	<b>\$ 150.00</b>
Payments:	\$ 0.00
Additional Charge:	\$ 0.00
<b>Total Due:</b>	<b>\$ 150.00</b>

Description of Service  
Original inspection fee

RETAIN THIS COPY FOR YOUR RECORDS

### THANK YOU FOR YOUR BUSINESS

CUT HERE

CUT HERE

CUT HERE



# INVOICE / STATEMENT

## HOUSE DETECTIVE TERMITE CONTROL INC

11 COMMERCE CT. SUITE 10  
CHICO CA 95928  
(530) 894-7900 (530) 591-7079  
hdetective@att.net Fax (530) 894-7902

Date: 06/20/2017  
Report Number: 11401  
Invoice Number: 11401-1  
Escrow Number:

Property Inspected: 4266 Keefer Road  
Chico, CA 95973

Bill To: Brandi Laffins  
Remax  
1834 Mangrove Ave.  
Chico, CA 95926  
United States  
  
brandi@laffins.com

Inspection:	\$ 150.00
<b>Invoice Total:</b>	<b>\$ 150.00</b>
Payments:	\$ 0.00
Additional Charge:	\$ 0.00
<b>Total Due:</b>	<b>\$ 150.00</b>

Description of Service  
Original inspection fee

RETURN THIS COPY WITH REMITTANCE

### THANK YOU FOR YOUR BUSINESS



# HOUSE DETECTIVE TERMITE CONTROL INC

Page 1 of 1

11 COMMERCE CT. SUITE 10

CHICO CA 95928

(530) 894-7900 (530) 591-7079  
hdetective@att.net Fax (530) 894-7902

## WORK AUTHORIZATION

Report #: 11401

**No work will be performed until a signed copy of the agreement has been received**

Address of Property : 4266 Keefer Road  
City: Chico  
State/Zip: CA 95973

The inspection report of the company dated, 06/20/2017 is incorporated herein by reference as though fully set forth.

The company is authorized to proceed with the work outlined in the items circled below from the Termite Inspection Report for the property inspected, for a total sum of \$                     . This total amount is due and payable within 30 days from completion repair work and/or chemical application.

### THE COMPANY AGREES

To guarantee all repair completed by this company for one year from date of completion except for caulking, grouting, or plumbing, which is guaranteed for a period of **ninety (90) days**. We assume no responsibility for work performed by others, to be bound to perform this work for the price quoted in our cost breakdown for a period not to exceed 30 days, to use reasonable care in the performance of our work but to assume no responsibility for damage to any hidden pipes, wiring, or other facilities or to any shrubs, plants, or roof.

### THE OWNER OR OWNER'S AGENT AGREES

To pay for services rendered in any additional services requested upon completion of work to pay a service charge of one and one-half percent (1 1/2%) interest per month, or portion of any month, annual interest rate of eighteen percent (18%) on accounts exceeding the ten (10) day full payment schedule. The Owner grants to The Company a security interest in the property to secure payment sum for work and inspection fee completed. In case of non-payment by The owner, reasonable attorney fees and costs of collection shall be paid by owner, whether suit be filed or not.

### ALL PARTIES AGREE

If any additional work is deemed necessary by the local building inspector, said work will not be performed without additional authorization from owner or owner's agent. This contract price does not include the charge of any Inspection Report fees. Circle the items you wish performed by The Company, below and enter total amount above:

### NOTICE TO OWNER

Under the California Mechanics Lien Law, any structural pest control company which contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractor, laborers or suppliers remain unpaid.

To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice." Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

ITEMS				
Prefix	Section I	Section II	Further Inspection	Other
3A	110.00	0.00	0.00	0.00
3B	190.00	0.00	0.00	0.00
3C	1,090.00	0.00	0.00	0.00
3D	250.00	0.00	0.00	0.00
4A	0.00	150.00	0.00	0.00
5A	0.00	0.00	Upon request	0.00
Total:	1,640.00	150.00	0.00	0.00
Grand Total:	1,790.00			

Property Owner: \_\_\_\_\_ Date: \_\_\_\_\_ Inspected By: \_\_\_\_\_ Date: \_\_\_\_\_  
Owner's Agent: \_\_\_\_\_ Date: \_\_\_\_\_