



Email: precisionpump@comcast.net

Kao Saechao

23 February 2018

RE: 5508 California Street

Dear Kao;

The well test has been completed at the above property. The invoice and laboratory results are attached. The details of the test are below.

Upon arrival there was not water to the house. System was not working. Checked out the entire system and found that the starter capacitor inside the control box was blown. We replaced with a new Grundfos 3/4 hp control box. There is a 30/50 pressure switch that is in good shape. There is an 85-gallon Aqua Pod Jacuzzi tank, date code 11/19/03. There is a pressure gauge that is not reading. It is holding 22 psi. All galvanized pipe near the well head is covered by a building. The piping near the 85 gallon tank is insulated.

Time	Length of Test	meter reading	Clarity
8:15 AM	28 seconds	371020	clear
8:30 AM	29 seconds	371330	clear
8:45 AM	29 seconds	371640	clear
9:00 AM	29 seconds	371950	clear
9:15 AM	29 seconds	372260	clear
9:30 AM	29 seconds	372570	clear
9:45 AM	29 seconds	372890	clear
10:00 AM	29 seconds	373200	clear
10:15 AM	29 seconds	373520	clear
10:30 AM	29 seconds	373830	clear
10:45 AM	29 seconds	374140	clear

At this time the well is producing approximately 20 gpm. Please call with any questions.

Sincerely,

John P. Riley IV
General Manager



PO Box 2024
 Oroville, CA. 95965
 (530) 533-4944 Phone (530) 533-6184 Fax
 License 862386

Invoice

DATE	INVOICE #
2/23/2018	8161

PAID
02/23/2018

BILL TO
Kao Saechao

TERMS	PROJECT
	5508 Californi...

DESCRIPTION	QUANTITY	RATE	AMOUNT
Well Test		350.00	350.00
Lab Tests-Bacterial		75.00	75.00
Control Box 3/4 Grundfos		96.00	96.00T
Sales Tax		7.25%	6.96

We also accept MasterCard, Visa and Discover.		Total	\$527.96
-----------------------------------------------	--	--------------	----------

Payment due upon receipt unless prior payment arrangements have been made.

Any balance not paid by the due date is subject to a 1% per month service charge. If it remains unpaid for 30 days, seller may refer to a collection agency or assignee. Balance may be increased by the amount equal to the collection charge or sale amount to such assignee (33% of the balance due) or reasonable attorney fees as set by court.

Payments/Credits	-\$527.96
Balance Due	\$0.00

Any dispute in this agreement shall be resolved in the Butte County Superior Court, Oroville District.



www.basiclab.com

2218 Railroad Avenue
Redding, California 96001

voice 530.243.7234
fax 530.243.7494

3860 Morrow Lane, Suite F
Chico, California 95928

voice 530.894.8966
fax 530.894.5143

PRECISION PUMP
POST OFFICE BOX 2024
OROVILLE, CA 95965

Sampled By: MICAH STOREY
Client Contact: JOHN RILEY
Phone: (530) 712-7041
Fax: (530) 533-6184

Lab No: 18B0949
Reported: 02/23/18
System Number:
Regulator:
P.O. #

GENERAL TESTING 5508 CALIFORNIA STREET

Coliform Analysis Report

Standard Total Coliform & E.coli

Analysis	Result	Chlorine (mg/l)	Sample Receipt Temp (C)*	Set Up	Read Out	Method
WELLHEAD (18B0949-01) Grab Sampled: 02/22/18 10:45 Received: 02/22/18 11:38						
Total Coliforms	Absent		16.9	02/22/18 14:30	02/23/18 08:30	Colilert
E. Coli	Absent		16.9			

Notes and Definitions

Coliforms are bacteria that are naturally present in the environment and are used as an indicator that other, potentially-harmful, bacteria may be present.

The presence of Fecal coliforms and/or *E. coli* indicates that the water may be contaminated with human or animal wastes. Microbes in these wastes can cause short-term effects, such as diarrhea, cramps, nausea, headaches, or other symptoms. They may pose a special health risk for infants, young children, some of the elderly, and people with severely compromised immune systems.

* Sample Receipt Temp: According to 40 CFR 141.21, systems are encouraged but not required to hold samples below 10 degrees C during transit.

Approved By

Basic Laboratory Inc
California ELAP Cert #1677 and #2718