

SELLER REAL ESTATE CONDITION REPORT

Re: 1909 Huntington Lane, Redondo Beach, CA 90278

INCLUSIONS AND EXCLUSIONS: Check **N/A** if not present on property, **Yes** if included with property and **No** if excluded from the sale. (Be sure items included are consistent with listing agreement.)

Property	N/A	Yes	No	Condition/Age	Property	N/A	Yes	No	Condition/Age
Oven and Range		Х		Good 2 Years	Water Softener	Х			
Vent Fans		Х		Good 2 Years	Water Heater		Х		Good 2 Years
Refrigerator		X		Good 2 years	Garage Door Opener		Х		Good 2 Years
Microwave		х		Good 2 Years	Window AC Units	х			0000 2 10010
Dishwasher		Х		Good 2 Years	Pool	x			
Washing Machine			Х	0000 Z 10010	Pool Equipment	х			
Clothes Dryer			Х		Humidifier	x			
Disposal		Х		Good 2 Years	Smoke Alarms		х		Good 2 Years
Trash Compactor	Х				Sump Pump(s)	х			
Ceiling Fan(s)	X				Attached Antenna	×			
Fireplace Equipment		Х		Good 2 Years	Storm Windows		Х		Good 2 Years
Fireplace Insert	Х				Screens		х		Good 2 Years
Wood burning Stove	X				Window Treatment		X		Good 2 Years
Incinerator	Х				Other	X			Good 2 Teals
Solar Equipment	×				Other	x			

STRUCTURAL: Have any of the following conditions occurred?

A. Basement	Yes No		Yes	No
Water in Basement	х	Shifting/Settling		х
Flooding	х	Repairs Made/Completed		x
Leakage	x	Repairs Warranted / In Writing		х
Dampness	Y	Repairs Made with Permit		x
Floor/Walls Cracked	x	Repairs Made to Sump Pump		Y
Bulges	X			^

Explain all	''Yes"	responses:
-------------	--------	------------

N/A

B. Roof	Yes	No		Yes	No
Original Roof	х		Roof Suffered From Ice Damage		Х
Roof Ever Leaked		х	Repairs Made/Completed		х
Gutter Ever Leaked		Х	Repairs Warranted / In Writing		x
Gutter Ever Backed Up		х	Repairs Made with Permit		х
Other:		х	Roof Age (years): 2 Years Old		

Explain all "Yes" responses:

Original Roof - House was purchased brand new in March 2019

C. Wood Destroying Organisms					
Are you aware of any evidence of:	Yes	No		Yes	No
Wood rot		х	Powder Post Beetles		х
Mildew		х	Other Insect Infestation		х
Vermin		х	Repairs Made / Completed		х
Rodents		х	Repairs Warranted / in Writing		х
Carpenter Ants		х			

Explain all "Yes" responses:

N/A

D. Windows Do you have:					
	Yes	No		Yes	No
Thermopane Windows	x		Brick Molding Dry Rot		х
Broken Windows		х	Repairs Made / Completed		х
Broken Seals		х	Repairs Warranted / In Writing		×
Sill Dry Rot		х			

Explain all "Yes" responses:

New windows in March 2019 when house was purchased.

E. Asbestos		
To the best of your knowledge:	Yes	No
Is any boiler, pipe, duct, tank, furnace or load supporting structural member insulated or fireproofed with asbestos?		x

Explain "Yes" response and provide location:

N/A

F. Siding Do you have:	V	NI-		V	N.
	Yes	<u>No</u>		Yes	No
Hardboard Siding (LP, GP, Masonite, etc.)	2.4	Х	Synthetic Stucco (EIFS)		x
Wood Siding		х	Repairs Made / Completed		Х
Aluminum Siding		×	Repairs Warranted / In Writing		Х
Vinyl Siding		X	Repairs Made with Permit		Х
Hard Stucco	Х				

Explain all "Yes" responses:

Hard stucco siding - New when purchased house in March 2019

MECHANICAL: Please provide answers to questions below.

G. Electrical		Yes	No
Additions to Original Installation?			Х
If yes, was work performed by licens	sed contractor?		х
Were permits taken out?	N/A		х
Type of Service: ☐ Fuses	☐ Circuit Breakers ☐ Other:		
Explain all "Yes" responses: N/A			
H. Plumbing		Yes	No
Are there any leaks?			Х
Have there been any additions?			Х
Were permits taken out on work/add			X
Are there any issues with the Plumbi	ng Fixtures?		X
Explain all "Yes" responses: N/A			
I. Heating			
Age of Furnace (years): New with	house in March 2019		
Type of Furnace:	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
₭ Forced Air ☐ Gra	avity 🗆 Boiler 🗆 Heat Pump 🗀 Other		
Fuel Type			
I ☐ Gas ☐ LP Tank	☐ Oil ☐ Wood/Coal Size of Tank:		
Buried Fuel Tanks:			
☑ No ☐ Yes	Type & Location:		
J. Cooling			
Air Condition: No	☐ Yes Wired for Air Condition - Unit not installed		
	☐ Yes Wired for Air Condition - Unit not installed.		
Type of System: N/A			
☐ Central ☐ Wi	ndow Unit Number of Units () Age: ()		
K. Sewer			
IV. OCWEI			
System Type: ☑ Municipal ☐ Sep ☐ Conventional	otic □ Holding Tank □ Mound □ Treatment System		
Has your sewer ever backed up? Date of last pump: / /	☑ No ☐ Yes Date of last inspection: / / N/A		

L. Water				
System Type:	√ Municipal	☐ Shared Well (Please provide copies of Shared Well Agreement.)		
System Type.	☐ Private Well	☐ Point Well		
	☐ Drilled Well	□ Pit		
Ago of Mall Domes	N/A			
Age of Well Pump	-			
Date last pressure	e test: / /	Date of last recharge: / /		
M. Land & Site				
To the best of your	knowledge:		Yes	No
Are there any unp				X
		nned assessments? Type:		X
Is property locate				X
	ts on the lot lines?			X
Any easements or				X
Drainage problem				X
Sub-soil problems: Standing water pr				X
Tested for Radon?				 ^
		Please include copy of test results i	f	X
available.		Trouse mediate copy of test results i	'	
	N/A			
N. Solar Panels To the best of your l	knowledge:		Yes	No
		f yes, please answer questions below)	165	X
Are the solar pane				X
Are the solar pane	ls leased?			X
	iding loan for the so			Х
	ls functioning prope			X
	s staying with the h			X
Does your solar pa	nel system have bat	teries?		X
f "yes", please prov will be removing the		olar panel agreement and if the panels are being removed p	lease advise	e who
MISCELLANEOUS: F	Please answer to que	estions below.		
Are you aware of the f YES, please explai		in any location on the property? ☐ Yes	XI No	

	ere beei lease ex	n any insurance claims filed on your home in the past 5 years? oplain: N/A	☐ Yes	⊠ No
Are you If YES, p		of a fire occurring in any location on the property? splain: N/A	□ Yes	⊠ No
Are ther		roblem areas that exist in or on this property not covered by the q	uestions above	:?
If "Yes",	please	explain: N/A		
CHINESE	DRYW	ALL: Please answer questions below.		
				ag dafactiva danval
imported volatile d	l from c organic	period of building material shortages some homes were built or or manufactured in China. Defective drywall reportedly emits leve compounds that cause corrosion of air conditioner and refriger or wiring, and other household items, as well as, create noxious odd	els of sulfur, me ator coils, copp	ethane, and/or other per tubing, electrica
imported volatile o wiring, co	I from o organic ompute r home	or manufactured in China. Defective drywall reportedly emits level compounds that cause corrosion of air conditioner and refriger. It wiring, and other household items, as well as, create noxious odd built or remodeled since 2001?	els of sulfur, me ator coils, copp	ethane, and/or other per tubing, electrica
imported volatile d wiring, co Was you of yes, ple	I from or organic ompute r home	or manufactured in China. Defective drywall reportedly emits level compounds that cause corrosion of air conditioner and refriger, rewiring, and other household items, as well as, create noxious odd built or remodeled since 2001? Yes X No swer the following questions by circling the appropriate answer:	els of sulfur, me ator coils, copp ors which may al	ethane, and/or other per tubing, electrical lso pose health risks
imported volatile o wiring, co	I from o organic ompute r home	or manufactured in China. Defective drywall reportedly emits level compounds that cause corrosion of air conditioner and refriger. It wiring, and other household items, as well as, create noxious odd built or remodeled since 2001?	els of sulfur, me ator coils, copp ors which may al or other unusua	ethane, and/or other per tubing, electrical lso pose health risks.
imported volatile of wiring, co Was your If yes, pla YES	I from or organic ompute or home ease ans	r manufactured in China. Defective drywall reportedly emits level compounds that cause corrosion of air conditioner and refrigers rewiring, and other household items, as well as, create noxious odd built or remodeled since 2001? Yes X No swer the following questions by circling the appropriate answer: Does the home or certain rooms have either a sulfur-like odor of Have there been repeated failures of the A/C evaporator coils (unit)? Are you or your household aware of visual evidence of dark or least the content of the co	els of sulfur, me ator coils, copp ors which may al or other unusua located in the a	ethane, and/or other per tubing, electrical lso pose health risks l odors? ir handler
imported volatile o wiring, co Was you If yes, pla YES YES	I from or organic ompute r home ease and NO	r manufactured in China. Defective drywall reportedly emits level compounds that cause corrosion of air conditioner and refrigers r wiring, and other household items, as well as, create noxious odd built or remodeled since 2001? Yes No swer the following questions by circling the appropriate answer: Does the home or certain rooms have either a sulfur-like odor of Have there been repeated failures of the A/C evaporator coils (lunit)? Are you or your household aware of visual evidence of dark or I Freon lines in the home? Are you or your household aware of other metallic surfaces (silf fixtures, accessible plumbing lines, exposed plumbing fixtures, wiring, metal door hinges, electrical components, etc.) showing	els of sulfur, me ator coils, copp ors which may al located in the a black corrosion verware, mirror brass compone	ethane, and/or other ber tubing, electrical so pose health risks. I odors? ir handler of copper es, chrome ents, electrical
imported volatile of wiring, co Was you Was you YES YES YES	I from or organic ompute or home ease ans NO NO	r manufactured in China. Defective drywall reportedly emits level compounds that cause corrosion of air conditioner and refrigers rewiring, and other household items, as well as, create noxious odd built or remodeled since 2001? Yes XI No swer the following questions by circling the appropriate answer: Does the home or certain rooms have either a sulfur-like odor of Have there been repeated failures of the A/C evaporator coils (unit)? Are you or your household aware of visual evidence of dark or I Freon lines in the home? Are you or your household aware of other metallic surfaces (silfixtures, accessible plumbing lines, exposed plumbing fixtures, wiring, metal door hinges, electrical components, etc.) showing home?	els of sulfur, me ator coils, copp ors which may all or other unusua located in the a plack corrosion verware, mirror brass compone g signs of corro	ethane, and/or other ber tubing, electrical so pose health risks. I odors? ir handler of copper es, chrome ents, electrical
imported volatile of wiring, co Was your If yes, plo YES YES YES	I from or organic ompute or home ease ans NO NO NO	r manufactured in China. Defective drywall reportedly emits level compounds that cause corrosion of air conditioner and refrigers r wiring, and other household items, as well as, create noxious odd built or remodeled since 2001? Yes No swer the following questions by circling the appropriate answer: Does the home or certain rooms have either a sulfur-like odor of Have there been repeated failures of the A/C evaporator coils (lunit)? Are you or your household aware of visual evidence of dark or I Freon lines in the home? Are you or your household aware of other metallic surfaces (silf fixtures, accessible plumbing lines, exposed plumbing fixtures, wiring, metal door hinges, electrical components, etc.) showing	els of sulfur, me ator coils, copp ors which may all or other unusual located in the a plack corrosion verware, mirror brass compone g signs of corro your home?	ethane, and/or other ber tubing, electrical so pose health risks. I odors? ir handler of copper es, chrome ents, electrical sion in the unicipality, or

LEAD PAINT – SAFE HANDLING: (applicable to homes constructed prior to 1978)

Notice: Effective April 2010, Federal law now requires that contractors performing renovation of six square feet or more of painted surfaces in an interior room or more than twenty square feet of painted surfaces on the exterior of a home, be lead certified and follow specific work practices to prevent lead contamination. Lead contamination poses a health risk if not handled properly. (For more information regarding safe lead practices, please consult your TRC Personal Move Manager)

Our initials indicate that we have not employed a contractor for renovations as described above since the law's inception and should we be required to complete any repairs or make any improvements that require a contractor, we will provide documentation to TRC verifying that said contractor holds the proper lead certification.

PERMITS:

Our initials indicate that all municipal permits taken out with the intention of performing work on the above referenced property, have been closed out with the appropriate municipal authority. We further understand that should TRC discover open permits which result in fines and/or inhibits the transfer of title, we will be responsible for the payment of such fines and/or resolution to allow for transfer of title.

PRIVATE TRANSFER FEES:

Mur initials indicate that there are no known development covenants providing for "private transfer fees* to be assessed by a homeowners association, builder, or any other party. We understand that should TRC discover any such fee, we will be responsible for payment of any outstanding amounts owed.

OWNER'S ACKNOWLEDGMENT

Owner acknowledges that the above Property information has been provided. Owner warrants that such information is accurate, true and complete, to the best of owner's knowledge and that owner has no notice of knowledge of any additional defect or problem with the Property that has not been set forth herein.

additional defect of	or problem with
Malle	05/17/2021
Michael Magee	Date
Melissa Magee	05/17/2021
Melissa Magee	Date

Buyer's Acknowledgement of receipt of this Condition Report

Date: _____ Buyer's Initials: _____