


STANDARD NOTICE OF WORK COMPLETED AND NOT COMPLETED

NOTICE - All recommendations may not have been completed - See below - Recommendations not completed.
This form is prescribed by the Structural Pest Control Board.

Building No. 1211	Street Mariah Lane	City Paso Robles	Zip 93446	Date of Completion 02/20/23
 <p>KEY TERMITE and PEST CONTROL PO Box 969, Atascadero, CA 93423-0969 805-466-2451 / 805-466-8026 fax / 800-548-5599</p>			<p>A LICENSED PEST CONTROL OPERATOR IS AN EXPERT IN HIS/HER FIELD. ANY QUESTIONS RELATIVE TO THIS REPORT SHOULD BE REFERRED TO HIM/HER.</p> <p style="text-align: right;">Report #: 104215</p>	
Ordered by: Jeremy Howard 1211 Mariah Lane Paso Robles, CA 93446		Property Owner and/or Party of Interest: Jeremy Howard 5490 Jardine Road Paso Robles, CA 93446		Completion sent to: Remax Parkside Kyler Hamann 711 12th Street Paso Robles, Ca 93446

The following recommendations on the above designated property, as outlined in the Wood Destroying Pests and Organisms Inspection Report dated 01/30/23 have been and/or have not been completed.

Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and Regulations: 3A, 3B, 3C, 3D, 3E, 4A, 4B.								
Recommendations completed by this firm that are considered secondary and substandard measures under Section 1992 of the Structural Pest Control Board's Rules and Regulations including person requesting secondary measure:								
Cost of work completed: <table style="width: 100%; margin-left: 400px; margin-top: 10px;"> <tr> <td style="text-align: right;">Cost: \$</td> <td style="text-align: right; border-bottom: 1px solid black;">2,894.00</td> </tr> <tr> <td style="text-align: right;">Inspection Fee: \$</td> <td style="text-align: right; border-bottom: 1px solid black;">0.00</td> </tr> <tr> <td style="text-align: right;">Other: \$</td> <td style="text-align: right; border-bottom: 1px solid black;">0.00</td> </tr> <tr> <td style="text-align: right;">Total: \$</td> <td style="text-align: right; border-bottom: 3px double black;">2,894.00</td> </tr> </table>	Cost: \$	2,894.00	Inspection Fee: \$	0.00	Other: \$	0.00	Total: \$	2,894.00
Cost: \$	2,894.00							
Inspection Fee: \$	0.00							
Other: \$	0.00							
Total: \$	2,894.00							
Recommendations not completed by this firm: 4C, 4D. <table style="width: 100%; margin-left: 400px; margin-top: 20px;"> <tr> <td style="text-align: right;">Estimated Cost: \$</td> <td style="text-align: right; border-bottom: 1px solid black;">294.00</td> </tr> </table>	Estimated Cost: \$	294.00						
Estimated Cost: \$	294.00							
Remarks: UNLESS OTHERWISE STATED IN THIS REPORT, ALL WORK COMPLETED BY THIS COMPANY IS GUARANTEED FOR TWO YEARS FROM THE DATE OF COMPLETION AGAINST DEFECTS IN MATERIALS OR WORKMANSHIP. STRUCTURAL FUMIGATION AND "PERIMETER PLUS" SUBTERRANEAN TERMITE TREATMENT IS GUARANTEED FOR FIVE YEARS.								

Signature _____  _____

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, CA, 95815-3831
 NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov. 43M-41 (REV. 10/01)