

ENERGY/WATER CONSERVATION INSPECTION FORM

(Pursuant to Chico Municipal Code Chapter 16.60)

This form must be filed with City of Chico Building Division: P.O. Box 3420, Chico 95927 / 411 Main St., Chico / FAX: 530-895-4726

Property Location: 912 Salem St

Send Certificate To: Text
(Include Email)

APN: _____

Text

of Buildings 1 # of Units 1 Use of Property - Single Family: Multifamily: Condo:

REQUIRED CONSERVATION MEASURES TO BE INSTALLED IN ORDER OF PRIORITY, ITEMS 1-9 (Credit towards maximum expenditure for items 1. through 9. installed within last 42 months.)	Existing	Installed	Exempt	COST
1. Ceiling insulation of minimum thermal resistance value R-30 is installed (regardless of cost). <u>EXEMPTIONS:</u> a. Dwelling does not have attic, attic is inaccessible, not responsible for shared attic space. (Circle one) b. Headroom is less than 30 inches at attic peak. c. Electrified "knob & tube" wiring is present.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
See page 2				
2. All major cracks, joints, doors, windows, and other openings in building exteriors are caulked, weather stripped or otherwise sealed to limit air filtration.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
See page 2				
3. All sink and lavatory faucets are fitted with 2.75 gallon/minute or less faucets or an aerator.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4. All shower fixtures are fitted with in-line shower restrictors or low flow shower heads with a maximum water flow rate of 3-gallons per minute. <u>EXEMPTIONS:</u> a. Existing shower head has flow rate of less than 3 gallons per minute due to reduced water pressure. b. Shower head and arm are of a ball joint type which is connected within a wall.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5. All toilets are low-flow toilets rated at 1.6 gallons per flush or less. <u>EXEMPTION:</u> State reason, unfeasible, ie. flooring will need to be replaced, etc. - _____	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6. Thermostats are programmable. <u>EXEMPTION:</u> State reason, ie. wall heater - _____	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
7. Exposed hot & cold water pipes within 5 feet of water heaters located in unconditioned spaces are insulated at a minimum thermal resistance rating of R-3.	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Located in home
8. All domestic storage water heaters insulated with external insulation blanket rated at a minimum thermal resistance of R-6. <u>EXEMPTION:</u> a. Interior thermal resistance rating of water heater at least R-12. b. Impractical to wrap heater because distance between heater and wall less than 2 inches. c. Manufacturer's instructions for water heater preclude installation of external blanket, ie. tankless.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
9. All ducts in accessible areas have been visually inspected, are intact, and functioning properly. <u>EXEMPTION:</u> State reason, ie. wall heater - _____	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
10. Optional - Other conservations measures have been installed within the last 10 years. Items 10.a. through 10.d. require a finalized City of Chico Building Permit to receive credit towards maximum cost expenditure. Ceiling insulation must be compliant before credit is granted for these items. List permit number & finalized date below.				
a. Replace single-pane with dual-paned windows b. New, more efficient HVAC c. Tankless or solar water heater d. Photovoltaic Solar Panels Other: Please list _____			<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
				Permit # _____ Finalized date _____

Total Cost of Installed Measures : _____

I hereby certify this property to be in compliance with Chapter 16.60 of the Chico Municipal Code Chapter 16.60.

Date: 7/31/23

City Certified Inspector Signature

David Maffei
Print Name

Item 1:

-More insulation is needed throughout the entire attic.

Item 2:

-Daylight could be seen around the front and back doors. This means the weather stripping was not sealing tightly against the door. Adjust the current weather stripping or add more to make a proper seal.