


# WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No. 527	Street Valley Dr	City Crestline	ZIP 92325	Date of Inspection 01/03/2022	Number of Pages 5
<b>Aubrey's Termite &amp; Pest Control</b> P.O. Box 6404 Crestline CA 92325 (909) 338-3127 (909) 633-4869 aubreysstermite@yahoo.com				Report # 1843 Registration #: PR5688 Escrow #: <input type="checkbox"/> CORRECTED REPORT	
Ordered by: Gregg Grant San Moritz Realty Crestline CA 92325 WORK: (909) 338-1861 gragggrant@aol.com		Property Owner and/or Party of Interest:		Report sent to: Gregg Grant San Moritz Realty Crestline CA 92325 WORK: (909) 338-1861 gragggrant@aol.com	
COMPLETE REPORT <input checked="" type="checkbox"/> LIMITED REPORT <input type="checkbox"/> SUPPLEMENTAL REPORT <input type="checkbox"/> REINSPECTION REPORT <input type="checkbox"/>					
GENERAL DESCRIPTION: SINGLE STORY, LOFT, RAISED FOUNDATION, FURNISHED, VACANT, COMPOSITION ROOF, WOOD DECK(S), SINGLE FAMILY RESIDENCE					
An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.					
Subterranean Termites <input type="checkbox"/> Drywood Termites <input type="checkbox"/> Fungus / Dryrot <input checked="" type="checkbox"/> Other Findings <input checked="" type="checkbox"/> Further Inspection <input type="checkbox"/>					
If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked items.					

Diagram Not To Scale



YOUR COPY

Inspected By: Daniel Aubrey State License No. OPR11701 Signature: Daniel Aubrey

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California, 95815-3831.

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov.

43M-41 (Rev. 04/2015)

## AUBREY'S TERMITE & PEST CONTROL

Page 2 of 5 inspection report

527

Valley Dr

Crestline

CA

92325

Address of Property Inspected

City

State

ZIP

01/03/2022

1843

Date of Inspection

Corresponding Report No.

Escriw No.

**WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.**

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

**The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.**

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. **OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.**

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

**NOTICE:** Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This Wood Destroying Pest & Organisms Report **DOES NOT INCLUDE MOLD** or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

## AUBREY'S TERMITE & PEST CONTROL

Page 3 of 5 inspection report  
527 Valley Dr Crestline CA 92325  
Address of Property Inspected City State ZIP  
01/03/2022 1843 Escrow No.  
Date of Inspection Corresponding Report No.

**SECTION I: CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.**

**SECTION II: ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.**

**FURTHER INSPECTION: ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(S) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.**

**NOTE: AUBREY'S TERMITE AND PEST CONTROL DOES NOT WARRANTY NOR IS RESPONSIBLE FOR WORK THAT IS DONE/COMPLETED BY OTHERS.**

**IF AT ANY TIME DURING REPAIRS IT IS DEEMED THAT PERMITS OR ENGINEERING IS REQUIRED BY THE LOCAL BUILDING INSPECTOR, THIS BID DOES NOT INCLUDED SUCH FEES IF ANY.**

**DUE TO RECENT PRICE INCREASES AND AVAILABILITY OF BUILDING MATERIALS, PRICES QUOTED HEREIN ARE SUBJECT TO CHANGE WHEN WORK IS ACTUALLY ORDERED**

**WHEN CONTRACTOR OR OTHERS ARE DOING REPAIRS NOTED ON THIS REPORT, THEIR WARRANTY ON WORK DONE NEEDS TO BE DISCLOSED AND OR SUBMITTED TO ESCROW. ANYONE WHO IS A PARTY TO THIS TRANSACTION NEEDS TO BE AWARE THAT AUBREY'S TERMITE & PEST DOES NOT WARRANTY NOR IS RESPONSIBLE FOR WORK DONE BY OTHERS**

### 3. FUNGUS / DRYROT:

#### 3A - Section I

**FINDING: EVIDENCE OF FUNGUS AND/OR DRY ROT DAMAGE WAS NOTED AT DECKING & JOIST AS MARKED ON DIAGRAM.**

**RECOMMENDATION: OPEN DECK TO FURTHER PRICE REPAIR, REMOVAL OR REPLACEMENT OF DAMAGED OR INFECTED WOOD MEMBERS. UPON OPENING, IF DAMAGE EXTENDS BEYOND OR INTO AREAS NOT ACCESSIBLE AT THE TIME OF OUR ORIGINAL INSPECTION, THEN WE WILL ISSUE A SUPPLEMENTAL REPORT WITH FURTHER FINDINGS AND RECOMMENDATIONS AND ADDITIONAL BID, IF ANY. THIS BID DOES NOT INCLUDE PAINT UNLESS OTHERWISE SPECIFIED.**

#### 3B - Section I

**FINDING: EVIDENCE OF FUNGUS AND/OR DRY ROT DAMAGE WAS NOTED AT SIDING AS MARKED ON DIAGRAM.**

**RECOMMENDATION: DAMAGED OR INFECTED WOOD MEMBERS BE REPAIRED, REMOVED OR REPLACED. UPON REMOVAL, IF DAMAGE EXTENDS BEYOND OR INTO AREAS NOT ACCESSIBLE AT THE TIME OF OUR ORIGINAL INSPECTION, THEN WE WILL ISSUE A SUPPLEMENTAL REPORT WITH FURTHER FINDINGS AND RECOMMENDATIONS AND ADDITIONAL BID, IF ANY. THIS BID DOES NOT INCLUDE PAINT UNLESS OTHERWISE SPECIFIED.**

#### 3C - Section I

**FINDING: EVIDENCE OF FUNGUS AND/OR DRY ROT DAMAGE WAS NOTED AT POST AS MARKED ON DIAGRAM.**

**RECOMMENDATION: DAMAGED OR INFECTED WOOD MEMBERS BE REPAIRED, REMOVED OR REPLACED. UPON REMOVAL, IF DAMAGE EXTENDS BEYOND OR INTO AREAS NOT ACCESSIBLE AT THE TIME OF OUR ORIGINAL**

## AUBREY'S TERMITE & PEST CONTROL

Page 4 of 5 inspection report

527

Valley Dr

Crestline

CA

92325

Address of Property Inspected

City

State

ZIP

01/03/2022

1843

Date of Inspection

Corresponding Report No.

Escrow No.

INSPECTION, THEN WE WILL ISSUE A SUPPLEMENTAL REPORT WITH FURTHER FINDINGS AND RECOMMENDATIONS AND ADDITIONAL BID, IF ANY. THIS BID DOES NOT INCLUDE PAINT UNLESS OTHERWISE SPECIFIED.

### 4. OTHER FINDINGS:

#### 4A - Section II

**FINDING:** EVIDENCE OF EARTH TO WOOD CONTACT WAS NOTED AT LOAD POST AS MARKED ON DIAGRAM.

**RECOMMENDATION:** IT IS RECOMMENDED THAT THE EARTH IN CONTACT WITH WOOD BE LOWER TO BREAK THE EARTH TO WOOD CONTACT. UPON REMOVAL, IF DAMAGE EXTENDS BEYOND OR INTO AREAS NOT ACCESSIBLE AT THE TIME OF OUR ORIGINAL INSPECTION, THEN WE WILL ISSUE A SUPPLEMENTAL REPORT WITH FURTHER FINDINGS AND RECOMMENDATIONS AND ADDITIONAL BID, IF ANY.

#### 4B - Section II

**FINDING:** EVIDENCE OF EXCESSIVE MOISTURE CONDITION WAS NOTED AT SUBAREA DUE TO WATER LEACHING IN AS MARKED ON DIAGRAM.

**RECOMMENDATION:** NONE AT THIS TIME. AUBREY'S TERMITE & PEST CONTROL RECOMMENDS ANYONE THAT IS A PARTY TO THIS TRANSACTION THAT HAS QUESTIONS OR CONCERNS SHOULD CONTACT A LICENSED TRADESMEN TO SATISFY THEMSELVES PRIOR TO THE CLOSE OF ESCROW.

#### 4C - Section II

**FINDING:** EVIDENCE OF EARTH TO WOOD CONTACT WAS NOTED AT FRONT DECK BEAMAS MARKED ON DIAGRAM.

**RECOMMENDATION:** IT IS RECOMMENDED THAT THE EARTH IN CONTACT WITH WOOD BE LOWERED TO BREAK THE EARTH TO WOOD CONTACT. UPON REMOVAL, IF DAMAGE EXTENDS BEYOND OR INTO AREAS NOT ACCESSIBLE AT THE TIME OF OUR ORIGINAL INSPECTION, THEN WE WILL ISSUE A SUPPLEMENTAL REPORT WITH FURTHER FINDINGS AND RECOMMENDATIONS AND ADDITIONAL BID, IF ANY.

#### 4D - Section I

**FINDING:** EVIDENCE OF CARPENTER ANTS WAS NOTED AT SUBFLOOR IN SUBAREA AS MARKED ON DIAGRAM.

**RECOMMENDATION:** SINCE INFESTATION DOES NOT APPEAR TO EXTEND INTO INACCESSIBLE AREAS, IT IS RECOMMENDED THAT THE INFESTED AREA (S) BE LOCALLY TREATED WITH A STATE REGISTERED CHEMICAL SUCH AS, TIMBOR (ACTIVE INGREDIENT, DISODIUM OCTABORATE TETRAHYDRATE), PREMISE 2 (ACTIVE INGREDIENT, IMADACLOPRID), PREMISE FOAM (ACTIVE INGREDIENT, IMADACLOPRID), DRAGNET SFR (ACTIVE INGREDIENT, PERMETHRIN), AND OR TERMIDOR SC, (ACTIVE INGREDIENT, FIPRONIL FOR THE CONTROL OF CARPENTER ANTS OWNER/AGENT UNDERSTANDS THAT THIS IS A SPOT TREATMENT AND ONLY AND THE AREAS OF ACTUAL TREATMENT CAN BE WARRANTED.

**PLEASE BE ADVISED THAT ANYTIME A CUSTOMER ORDERS A RE-INSPECTION, OR NEEDS TO MEET THE INSPECTOR AT THE PROPERTY AFTER INITIAL INSPECTION THERE WILL BE A FEE UNLESS NOTED OTHERWISE.**

Thank you for selecting us to perform a structural pest control inspection on your property. Should you have any questions regarding this report, please call us directly by the contact information provided on the first page of the inspection report.

Our inspectors have determined that your property will benefit from a safe application of chemicals commonly used for structural

## AUBREY'S TERMITE & PEST CONTROL

Page 5 of 5 Inspection report

Address of Property Inspected

Valley Dr

Crestline

CA

92325

Date of Inspection

1843

City

State

ZIP

Corresponding Report No.

Escrow No.

pest control. In accordance with the laws and regulations of the State of California, we are required to provide you and your occupants with the following information prior to any application of chemicals to such property.

Please take a few moments to read and become familiar with the content. State law requires that you be given the following information:

**CAUTION - PESTICIDES ARE TOXIC CHEMICALS.** Structural pest control companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the state finds that based on scientific evidence, there are no appreciable risks weighted by the benefits. The degree of risk depends on the degree of exposure, so exposure should be minimized.

If within 24 hours following application, you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center and your pest control operator immediately.

For further information, contact any of the following agencies in your area:

Poison Control Center  
Agricultural Department  
Health Department  
Structural Pest Control Board

(800) 222-1222  
(909) 387-2105  
(800) 722-4794  
(916) 561-8700  
2005 Evergreen Street, Ste. 1500. Sacramento, CA 95815

Aubrey's Termite & Pest Control

(909) 338-3127

Aubrey's Termite & Pest Control  
P.O. Box 6404  
Crestline CA 92325  
(909) 338-3127 (909) 633-4869  
aubreystermite@yahoo.com

Page 1 of 1

## WORK AUTHORIZATION

Report #: 1843

No work will be performed until a signed copy of this agreement has been received.

Address of Property: 527 Valley Dr

City: Crestline

State/ZIP: CA 92325

The inspection report of the company dated, 01/03/2022 is incorporated herein by reference as though fully set forth.

The company is authorized to proceed with the work outlined in the items circled below from the Termite Inspection Report for the property inspected, for a total sum of \$ \_\_\_\_\_. This total amount is due and payable within 30 days from completion repair work and/or chemical application.

### THE COMPANY AGREES

To guarantee all repair completed by this company for one year from date of completion except for caulking, grouting, or plumbing, which is guaranteed for a period of ninety (90) days. We assume no responsibility for work performed by others, to be bound to perform this work for the price quoted in our cost breakdown for a period not to exceed 30 days, to use reasonable care in the performance of our work but to assume no responsibility for damage to any hidden pipes, wiring, or other facilities or to any shrubs, plants, or roof.

### THE OWNER OR OWNER'S AGENT AGREES

To pay for services rendered in any additional services requested upon completion of work to pay a service charge of one and one-half percent (1 1/2%) interest per month, or portion of any month, annual interest rate of eighteen percent (18%) on accounts exceeding the ten (10) day full payment schedule. The Owner grants to The Company a security interest in the property to secure payment sum for work and inspection fee completed. In case of non-payment by The owner, reasonable attorney fees and costs of collection shall be paid by owner, whether suit be filed or not.

### ALL PARTIES AGREE

If any additional work is deemed necessary by the local building inspector, said work will not be performed without additional authorization from owner or owner's agent. This contract price does not include the charge of any Inspection Report fees. Circle the items you wish performed by The Company, below and enter total amount above:

### NOTICE TO OWNER

Under the California Mechanics Lien Law, any structural pest control company which contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractors, laborers or suppliers remain unpaid. To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice." Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

**PLEASE BE ADVISED THAT ANYTIME A CUSTOMER ORDERS A RE-INSPECTION OR ONE IS NEEDED, NEEDS TO MEET THE INSPECTOR AT THE PROPERTY AFTER INITIAL INSPECTION THERE WILL BE A FEE UNLESS NOTED OTHERWISE.**

### ITEMS

Prefix	Section I	Section II	Further Inspection	Other
3A	225.00 (OPEN FOR PRICING ONLY)	0.00	0.00	0.00
3B	565.00	0.00	0.00	0.00
3C	165.00	0.00	0.00	0.00
4A	0.00	NO BID	0.00	0.00
4B	0.00	OWNER/BUYER	0.00	0.00
4C	0.00	NO BID	0.00	0.00
4D	425.00	0.00	0.00	0.00
Total:	1,380.00	0.00	0.00	0.00
Grand Total:	1,380.00 (APPROX)			

Property Owner:

Date:

Inspected By:

Date:

Owner's Agent:

Date: