STANDARD NOTICE OF WORK COMPLETED AND NOT COMPLETED NOTICE: All recommendations may not have been completed - See below - Recommendations not completed. This form is prescribed by the Structural Pest Control Board.

not been completed.	09/12/2022
Remax Crown Realty Nabors Realty Group Frettra De Silva 101 Windchime Irvine, CA 92603 Fax: Fax: Fax: Fax: Fax: Fax: Fax: Fax: Recommendations on the above designated property, as outlined in the Wood Destroying pests and Organisms Inspection not been completed. Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and Regulation	Report Number: 424456
The following recommendations on the above designated property, as outlined in the Wood Destroying pests and Organisms Inspection not been completed. Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and Regulation	nt To:
not been completed. Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and Regulation	
Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and Regulations:	
Cost of work completed: Cost: \$2,225.00 Inspection Fee: \$0.00 Other: \$0.00 Total: \$2,225.00	
Recommendations not completed by this firm: 4A	

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years upon payment of a search fee to: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, CA 95815-3831

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with service performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov.

This is to certify that the property described herein is now free and clear of evidence of active infestation or infection in the visible and accessible areas inspected in our original report.

43M-44 (Rev.10/01)