# **Property Disclosure**

Case Number: 048-452685 Insurability: Insurable with Repair Escrow (IE)

Property Address: 21265 Pine Ridge Ave

Apple Valley, CA 92307

#### **MPR Property Repairs**

Repair / Replace Exterior Exposed and Damaged Wood

Repair / Replace Drywall and Ceilings

Repair / Replace Block Wall

Repair / Replace Garage Door

Repair / Replace Patio Roof

Repair / Replace Fireplace

Repair / Replace Flooring - Exposed Sub-floor

Repair / Replace Kitchen and Bathroom Cabinets

## **Property Disclosures**

The subject has a solar panel system to supplement electrical service. It is unknown if they are leased or owned and if the previous owner had a loan, specifically on the solar panels - Buyer to complete their due diligence and gather all information on this property.

Property is NOT located in a FEMA Special Flood Hazard Area. It is the buyers responsibility to verify additional information regarding flood zones and insurance.

Property does not have a Homeowners Association (HOA).

Property built before 1978 - Lead Based Paint addendum required

Property is being sold in As-Is condition, but if any personal property item is present. it may or may not be removed prior to

closing of sale

Property serviced by a Non-Public Utility: Septic Tank/ Typical

Property is listed as Insurable with Repair Escrow (IE): Less then \$10,000 in Estimated MPR Repairs - Final repair escrow amount to be determined by the buyer's appraisal

#### **General Disclosures**

**All HUD Homes are sold in their AS-IS condition:** HUD will not make any repairs nor allow the purchaser to complete any repairs prior to closing. **FOR YOUR PROTECTION GET A HOME INSPECTION** 

Permission to activate utilities for purposes of the home inspection may be requested from the HUD Field Service Manager after the HUD-9548 sales contract is executed by the seller. Fees for activation may apply.

Properties being purchased with FHA insured financing will require a termite inspection and possible treatment. Should the purchaser elect to change their financing to a type other than FHA insured AFTER the inspection and/or treatment has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection and treatment prior to closing.

Properties built prior to 1978 and being purchased with FHA insured financing will require a lead-based paint inspection and possible stabilization. Should the purchaser elect to change their financing to a type other than FHA

## **General Disclosures**

insured AFTER the inspection and/or stabilization has begun, the purchaser will be responsible for reimbursing HUD for the cost of the inspection ,stabilization and clearance letter prior to closing.

This information is accurate based on the data available at the time of listing, and is deemed reliable but not guaranteed. All information should be independently verified.