

# WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

BUILDING NO. <b>3931</b>	STREET, CITY, STATE, ZIP <b>Granite Falls Dr, Ceres CA 95307</b>	Date of Inspection <b>4/19/2022</b>	No. of Pages <b>4</b>
-----------------------------	---	--	--------------------------



## **BEST PEST**

### **MANAGEMENT**

**P.O. Box 1348**  
**Riverbank, CA 95367**  
**Tel: (209) 497-5777**  
**Website: www.bestpest209.com**  
**Email: info@bestpest209.com**

Firm Registration No. <b>PR 8106</b>	Report No. <b>9945</b>	Escrow No.
Ordered By: LLB Inspection Services #1 Certified Inspector Central Valley, CA 95350 Attn: Lloyd Brown	Property Owner/Party of Interest	Report Sent To: LLB Inspection Services #1 Certified Inspector Central Valley, CA 95350 Attn: Lloyd Brown

COMPLETE REPORT      
 LIMITED REPORT      
 SUPPLEMENTAL REPORT      
 REINSPECTION REPORT

General Description: <b>TWO STORY SINGLE FAMILY RESIDENCE OCCUPIED</b>	Inspection Tag Posted: <b>GARAGE</b>
	Other Tags Posted: <b>None</b>

An inspection has been made to the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.

Subterranean Termites      
 Drywood Termites      
 Fungus/Dryrot      
 Other Findings      
 Further Inspection

If any of above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked items.


**Received** 6 Pages

---

**Buyer** Date

---

**Buyer** Date



Inspected by Steven Nixon State License No. FR61450 Signature 

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California 95815.  
 NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control board at (916) 561-8708, or (800) 737-8188 or www.pestboard.ca.gov.

43M-41 (Rev. 04/2015)

3931	Granite Falls Dr, Ceres CA 95307	4/19/2022	9945
BUILDING NO.	STREET, CITY, STATE, ZIP	INSPECTION DATE	REPORT NO.

THIS IS A SEPARATED REPORT WHICH IS DEFINED AS SECTION 1/SECTION 2 CONDITIONS EVIDENT ON THE DATE OF INSPECTION.

SECTION 1 CONTAINS ITEMS WHERE THERE IS VISIBLE EVIDENCE OF ACTIVE WOOD DESTROYING PESTS OR ORGANISMS OR CONDITIONS THAT HAVE RESULTED IN OR FROM WOOD DESTROYING PEST OR ORGANISMS.

SECTION 2 ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO WOOD DESTROYING PESTS OR ORGANISMS, BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

FURTHER INSPECTION ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(S) WHICH DURING THE COMPLETE INSPECTION, DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE THE INSPECTION AND CANNOT BE DEFINED AS SECTION 1 OR SECTION 2.

NOTE: The exterior wood members were noted to be freshly painted and no stains and/or damage was visibly noted at the time of inspection.

**Other - Exteriors:**

ITEM 11A Fungus has damaged the fascia board/barge rafter at the eaves.

RECOMMENDATION Remove the damaged fascia board/barge rafter for further inspection. If no further damage is exposed, replace with new material.

\*\*\*\*\* This is a Section 1 Item \*\*\*\*\*

**THE EXTERIOR SURFACE OF THE ROOF WILL NOT BE INSPECTED. IF YOU WANT THE WATER TIGHTNESS OF THE ROOF DETERMINED, YOU SHOULD CONTACT A ROOFING CONTRACTOR WHO IS LICENSED BY THE CONTRACTORS STATE LICENSING BOARD.**

**NOTICE: The charge for service that this company subcontracts to another registered company may include the company's charges for arranging and administering such services that are in addition to the direct costs associated with paying the subcontractor. You may accept BEST PEST MANAGEMENT bid or you may contract directly with another registered company licensed to perform the work. If you choose to contract directly with another registered company, BEST PEST MANAGEMENT. will not in any way be responsible for any act or omission in the performance of work that you directly contract with another to perform.**

**"NOTICE: REPORTS ON THIS STRUCTURE PREPARED BY VARIOUS REGISTERED COMPANIES SHOULD LIST THE SAME FINDINGS (i.e. TERMITE INFESTATIONS, TERMITE DAMAGE, FUNGUS DAMAGE etc.) HOWEVER, RECOMMENDATIONS TO CORRECT THESE FINDINGS MAY VARY FROM COMPANY TO COMPANY. YOU HAVE A RIGHT TO SEEK A SECOND OPINION FROM ANOTHER COMPANY"**

3931

Granite Falls Dr, Ceres CA 95307

4/19/2022

9945

BUILDING NO.

STREET, CITY, STATE, ZIP

INSPECTION DATE

REPORT NO.

This company will reinspect repairs done by others within four months of the original inspection. A charge, in any, can be no greater than the original inspection fee for each reinspection report. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs. This company does not guarantee work performed by other.

IN THE EVENT LOCALIZED TREATMENT IS RECOMMENDED IN THIS REPORT: Local treatment is not intended to be an entire structure treatment method. If infestations of wood destroying pests extend or exist beyond the area(s) of local treatment, they may not be exterminated.

**ASBESTOS - \*\*IMPORTANT NOTE FOR ALL PARTIES REGARDING THIS PROPERTY\*\***

Notice to customer and buyers having repairs done - Some residential structures are constructed with material that may contain material manufactured with asbestos. Our company is not qualified or certified to identify these materials. If the owner or interested parties are aware of, interested in, or concerned about this condition, they should contact the appropriate agencies that are qualified or certified in this field.

**Prices quoted are for this company to complete all items in this report. If all items are not requested to be completed by this company the bids are subject to change. Our bid for linoleum and tile are for a standard grade FHA material. Any upgrade in material which may be desired by owner will have additional charges. This companies minimum charge to perform work at any property is \$375.00**

During the process of treatment or replacement it may be necessary to drill holes through ceramic tiles or other floor coverings; These holes will then be sealed with concrete. We will exercise due care but assume no responsibility for cracks, chipping or other damage to floor coverings. We do not re-lay carpeting pulled back for treatment or repairs.

We assume no responsibility for damage to any Plumbing, Gas, or Electric lines, etc., that may become damaged in the process of pressure treatment of concrete slabs or replacement of concrete or structural wood members.

Work performed by our company will be guaranteed for a period of one year from date of completion. Fumigations for the control of drywood termites will be guaranteed for a period of three years. Plumbing and maintenance repairs are guaranteed for 30 days.

ALL REPAIRS COMPLETED BY OTHERS MUST BE REINSPECTED BY BEST PEST MANAGEMENT BEFORE A CERTIFICATION WILL BE ISSUED. THE RE INSPECTION WILL ONLY CERTIFY THE ABSENTS OR INFESTATION OR INFECTION IN THE ACCESSIBLE AND VISIBLE AREAS. WE DO NOT GUARANTEE WORK COMPLETED BY OTHERS, NOR DOES THIS FIRM MAKE ANY STATEMENTS CONCERNING WORKMANSHIP OF THOSE REPAIRS. WORKMANSHIP IS ONLY DETERMINABLE BY THOSE PAYING FOR OR RECEIVING THOSE SERVICES. A RE INSPECTION OF SPECIFIC ITEMS ON THE REPORT OR OF ANY OTHER CONDITION PERTAINING TO THIS STRUCTURE CAN BE DONE AT AN ADDITIONAL COST PER REQUEST. THIS RE INSPECTION MUST BE DONE WITHIN 4 MONTHS OF THE ORIGINAL.

3931

Granite Falls Dr, Ceres CA 95307

4/19/2022

9945

BUILDING NO.

STREET, CITY, STATE, ZIP

INSPECTION DATE

REPORT NO.

**This property was not inspected for the presence or absence of health related molds or fungi. By California law, we are neither qualified, authorized, nor licensed to inspect for health related molds or fungi.**

**The Structural Pest Control board Mold Policy Statement is as follows:**

**"Molds, sometimes called mildew, are not wood-destroying organisms. Branch 3 licensees do not have a duty under the Structural Pest Control Act and related regulations to classify molds as harmful to human health or not harmful to human health. This does not modify the Structural Pest Control Act or related regulations."**

STATE LAW REQUIRES THAT YOU BE GIVEN THE FOLLOWING INFORMATION CAUTION PESTICIDES ARE TOXIC CHEMICALS. STRUCTURAL PEST CONTROL OPERATORS ARE LICENSED AND REGULATED BY THE STRUCTURAL PEST CONTROL BOARD, AND APPLY PESTICIDES WHICH ARE REGISTERED AND APPROVED FOR USE BY CALIFORNIA DEPARTMENT OF FOOD AND AGRICULTURE AND THE UNITED STATES ENVIRONMENTAL PROTECTION AGENCY. REGISTRATION IS GRANTED WHEN THE STATE FINDS THAT BASED ON EXISTING SCIENTIFIC EVIDENCE THERE ARE NO APPRECIABLE RISKS IF PROPER USE CONDITIONS ARE FOLLOWED OR THAT THE RISKS ARE OUTWEIGHED BY THE BENEFITS. THE DEGREE OF RISK DEPENDS UPON THE DEGREE OF EXPOSURE, SO EXPOSURE SHOULD BE MINIMIZED.

IF WITHIN 24 HOURS FOLLOWING APPLICATION YOU EXPERIENCE SYMPTOMS SIMILAR TO COMMON SEASONAL ILLNESS COMPARABLE TO THE FLU, CONTACT YOU PHYSICIAN OR POISON CONTROL CENTER AND YOU PEST CONTROL OPERATOR IMMEDIATELY.

**FOR FURTHER INFORMATION CONTACT ANY OR THE FOLLOWING:**

BEST PEST MANGEMENT - (209) 497-5777  
POISON CONTROL CENTER - (800) 876-4766

**COUNTY HEALTH DEPARTMENT**

SAN JOAQUIN COUNTY HEALTH OFFICE - (209) 468-3411  
STANISLAUS COUNTY HEALTH OFFICE - (209) 558-8804  
MERCED COUNTY HEALTH OFFICE - (209) 381-1100

**COUNTY AGRICULTURE COMMISSIONER**

SAN JOAQUIN COUNTY - (209) 468-3300  
STANISLAUS COUNTY - (209) 525-4730  
MERCED COUNTY -(209) 385-7411  
STRUCTURAL PEST CONTROL BOARD - (800) 737-8188

One or more of the following chemicals may be applied to your property: AggresZor 75 (Imidacloprid) Premise 75 Insecticide (Imidacloprid) - Tim-Bor (Disodium Octaborate Tetrahydrate) Termidor (Fipronil) - Vikane (Sulfuryl Fluoride) - I-MaxxPro (Imidacloprid) Termidor HE (Fipronil) Termidor SC (Fipronil) Premise Foam (Imidiclorprid) Termidor Dry Dust (Fipronil)

NOTE: Choropicrin is used as a "Warning Agent" on all structural fumigations.



P.O. Box 1348  
 Riverbank, CA 95367  
 Tel: (209) 497-5777  
 Website: www.bestpest209.com  
 Email: info@bestpest209.com

## WORK AUTHORIZATION CONTRACT

Address of Property: 3931 Granite Falls Dr, Ceres CA 95307  
 Inspection Date: 4/19/2022  
 Report #: 9945  
 Title Co. & Escrow #:

SECTION 1 11A \$ 950.00	SECTION 2	FURTHER INSPECTION
----------------------------	-----------	--------------------

We Authorized the Following  
Section 1 Items to be Performed.

11A \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

We Authorized the Following  
Section 2 Items to be Performed.

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

We Authorized the Following  
Items for Further Inspection.

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Proposed Cost Section 1:           \$950.00          

Proposed Cost Section 2:           \$0.00          

Proposed Cost Fur.Insp.:           \$0.00          

**Total:**           \$950.00          

If all items above are not being requested to be completed by Best Pest Management, indicate below the items you are requesting to have completed.

Items: \_\_\_\_\_

Total Cost: \_\_\_\_\_

Printed Name: \_\_\_\_\_ Signature: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Email Address: \_\_\_\_\_

I have read this work authorization contract and WDO inspection report it refers to.  
**SIGNED WORK AUTHORIZATION CONTRACT MUST BE RECEIVED BEFORE WORK WILL BE SCHEDULED.**  
 I have read and understand the terms of this work authorization contract and hereby agree to all

APPROVED AND READ BY:

DATE

ACCEPTED FOR:

BEST PEST MANAGEMENT

DATE



P.O. Box 1348  
Riverbank, CA 95367  
Tel: (209) 497-5777  
Website: www.bestpest209.com  
Email: info@bestpest209.com

## WORK AUTHORIZATION CONTRACT

Address of Property: 3931 Granite Falls Dr, Ceres CA 95307  
Inspection Date: 4/19/2022  
Report #: 9945  
Title Co. & Escrow #:

### Terms of Payment

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

I am authorizing Best Pest Management to complete the items listed on page 1 of this contract in the amount of \$\_\_\_\_\_.

After Best Pest Management completes the repairs, payment will be billed as follows:

A) \_\_\_\_\_ Paid upon completion by cash/check/credit card.

B) \_\_\_\_\_ Paid through escrow.

Escrow # \_\_\_\_\_ Close of escrow date: \_\_\_\_\_

Escrow Officer & Company: \_\_\_\_\_

Escrow Officer Phone Number & Email address:  
\_\_\_\_\_

I further agree if for any reason escrow does not close or cancels without paying the total amount due, **I will** be responsible for payment at such time.

X \_\_\_\_\_

**NOTICE TO OWNERS:** Under California Mechanics Lien Law any structural pest control company which contracts to do work for you any contractor, subcontractor, laborer, supplier or any other person who helps to improve your property but is not paid for his or her work or supplies has a right to enforce a claim against your property. This means that, after a court hearing, your property could be sold by the court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full, if the subcontractor, laborer, or supplier remains unpaid. To preserve their right to file a claim or lien against your property, certain claimants such as contractors or material suppliers are required to provide you with a document entitled "Preliminary Notice". A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.