



**INVOICE**  
**1209-072438**

3612 Ocean Ranch Blvd  
Oceanside CA 92056  
phone: 877-499-7378  
fax: 877-584-7378

Billing: \_\_\_\_\_ Service Address: \_\_\_\_\_

Marti Rosenstein  
1369 Ranch Road  
**Encinitas CA 92024**

Rosenstein Residence  
1369 Ranch Road  
Encinitas CA 92024

Inspection / Doc Fee	
Annual Service Agreement	
Repairs	
Work Completed	\$1865.00
Other Cost	
<b>Total Due</b>	<b>\$1,865.00</b>

Phone:  
Fax:  
Contact: **Accounts Payable**  
Escrow# \_\_\_\_\_ Report# **122942**  
  
County  SD  Riv  OR  LA  SB  Ven

Work Completed: \_\_\_\_\_

Termite treatment and repairs 8/26/2024  
  
2A Drywood termites locally treated in attic woodwork an area of approximately 4'x8'.  
  
3A Dryrot / fungus damage removed and replaced in (1) 6x6x12 resawn balcony post.  
  
3B Dryrot / fungus damage removed and replaced in (1) 4x4x4 balcony rail post.  
  
One Year Warranty to Locally Treated Area Expires 8/26/2025

Chemicals Used: \_\_\_\_\_

Bora-Care 16 Galon  
Premise Foam 8 oz.

**PAYMENT DUE UPON RECEIPT** Date: August 26, 2024

MAKE CHECK PAYABLE AND REMIT TO:



3612 Ocean Ranch Blvd  
Oceanside CA 92056  
phone: 877-499-7378

CARD#: \_\_\_\_\_ EXP. DATE: \_\_\_\_\_  
AMOUNT: \_\_\_\_\_ BILLING ZIP: \_\_\_\_\_  
NAME: \_\_\_\_\_  
SIGNATURE: \_\_\_\_\_



TO PAY BY CREDIT CARD: Circle Type

Invoice No: **1209-072438**  
**Invoice Total: \$1,865.00**

TO ENSURE PROPER CREDIT TO YOUR ACCOUNT, WRITE YOUR INVOICE NUMBER ON YOUR CHECK & RETURN THIS STUB WITH YOUR PAYMENT.

NOTICE - All recommendations may not have been completed - See below - Recommendations not completed.

This Form is prescribed by the Structural Pest Control Board.

Building No.	Street	City	Zip	Date of Completion
1369 Ranch Road		Encinitas	92024	8/26/2024

## PestgonTermite

3612 Ocean Ranch Blvd Oceanside CA 92056 (877) 499-7378

Ordered By <b>Marti Rosenstein</b> ph. 760-632-7742 fax shamartr@hotmail.com	Billing <b>Marti Rosenstein</b> 1369 Ranch Road Encinitas CA 92024  Phone: Fax:	Completion sent to: <b>Marti Rosenstein</b>
--	---	--

The following recommendations on the above designated property, as outlined in Wood Destroying Pests and Organisms Inspection Report #122942 dated 7/29/2024 have been and/or have not been completed.

Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and regulations:

3A Dryrot / fungus damage removed and replaced in (1) 6x6x12 resawn balcony post.

3B Dryrot / fungus damage removed and replaced in (1) 4x4x4 balcony rail post.

Recommendations completed by this firm that are considered secondary and substandard measures under Section 1992 of the Structural Pest Control Board's Rules and Regulations including person requesting secondary measure: Marti Rosenstein

2A Drywood termites locally treated in attic woodwork an area of approximately 4'x8'.

Cost of work completed:

Work Completed	\$1865.00
Other Cost ( See Remarks )	
<b>Total Due</b>	<b>\$1,865.00</b>

Recommendations not completed by this firm

Remarks

You are entitled to obtain copies of all reports and completion notices on this property reported to the Board during the preceding two years upon payment of a search fee to : Structural Pest Control Board 2005 Evergreen St. Ste 1500 Sacramento Ca 95815-3831. NOTE: Questions or problems concerning the above report should be directed to the manager of this company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at 800-737-8188 or www.pestboard.ca.gov.