

**COOPER POOL AND SPA SERVICE**

PO BOX 635  
OJAI, CA 93024 US  
(805)746-3026  
cooperpoolandspa@gmail.com

**INVOICE**

**BILL TO**  
CLINTON HAUGAN

**INVOICE #** 7958  
**DATE** 08/20/2021

**TERMS** Due on receipt

ITEM	QTY	RATE	AMOUNT
POOL INSPECTION FOR 1157 MORENO DR			120.00
PUMP - POOR CONDITION. 3/4 HSP RUNS VERY ROUGH. ESTIMATED COST TO REPLACE IS \$1,400			
FILTER- POOR CONDITION. OLD SAND FILTER LEAKING FROM MANIFOLD. FILTER NEEDS TO BE REPLACED. ESTIMATED COST IS \$1,800			
HEATER - NONE PRESENT			
AUTOMATION - NONE PRESENT			
COPING- POOR CONDITION ESTIMATED COST OF NEW COPING ( CALL POOL BUILDER)			
TILE - POOR CONDITION ESTIMATED COST TO RETILE \$3,000			
SURFACE - POOR CONDITION ESTIMATED COST TO RESURFACE IS \$10,000			
PLUMBING & VALVES - POOR CONDITION ESTIMATED COST OF NEW PLUMBING ( CALL POOL BUILDER)			
LIGHTS - NON OPERATIONAL			
WATER CHEMISTRY - POOR			
COVER - NONE PRESENT			
POOL SWEEP - NON OPERATIONAL ESTIMATED COST TO REPLACE \$600			
MISC. POOL NEEDS A SAFETTY MAIN DRAIN			

BALANCE DUE

**\$120.00**