

The UPS Store # 3568  
40729 Village Dr  
Big Bear Lake 92315  
Phone (909) 878 4747  
Fax (909) 878-4647



# FAX

To MARK MEYER

From TOM BEFORT

Company COMPAS

Department CEMILNEY KKRRAKITTS

Fax number 800 037 3250

Fax number \_\_\_\_\_

Tel number \_\_\_\_\_

Tel number 909 800 5092

Date OCT 23 2019

Date \_\_\_\_\_

Total Pages \_\_\_\_\_

Job number \_\_\_\_\_

EXTRA FEE: **FAA 800 637 3250**

NAME: **MARK MEYER** PHONE: **310 365 8565**

ADDRESS: **661 Modoc**

CITY: **BIG BEAR LAKE CA** STATE: **CA** ZIP:

DATE: **Oct 22, 2019** TIME:  AM/PM:

#Fireplace	W/Stone	W/Insul		
Gas Log	Gas Stove	Gas Insert		
Furnace	Gas LP	Gas Nat.	HP	Wood
Chimney #1 OD	Gap	Y	N	SS Galv Slab Cop Flue Size
Chimney #2 OD	Gap	Y	N	SS Galv Slab Cop Flue Size
Chimney #3 OD	Gap	Y	N	SS Galv Slab Cop Flue Size
FP #1 W	H	D	FP #2 W	H D
FP #3 W	H	D	FP #4 W	H D

The National Fire Protection Association recommends that all chimneys be inspected annually and cleaned as necessary.

NEXT SERVICE RECOMMENDED IN \_\_\_\_\_ OF \_\_\_\_\_

**VERTICAL MASONRY CHIMNEY FIREPLACE SYSTEM**

**VERY DIRTY CREOSOTE BUILD UP. PRYED AND OPENED WARPED DAMPER SWEEP - VISUALLY EVALUATE - PERFORM A LEVEL ONE INSPECTION FOUND REAR KERFOOT WALL MISSING JOINT. NEED TO CLEAN, RIGHT KERFOOT STONE 1 SLOPE. SHOULDER AREA IS LETTING WATER PENETRATE INTO RAJIKS, SHOULDER AREA NEED RECONSTRUCT. DAMPER IS WARPED WON'T OPEN OR CLOSE.**


**COST FOR REPAIRS \$1650.00**

Service Technician: **TOM BEFOR** DATE:

**DISCLAIMER** This sheet is the result of an inspection done at the time of our service to the NFPA inspection level marked. It is intended as a convenience to our clients, it is not intended as a certificate of safety. Since conditions of use are beyond our control and / or defects may exist that are hidden we make no warranty of safety or function of any appliance, chimney, or vent, and none is to be implied.

**CUSTOMER VERIFICATION** I acknowledge the satisfactory completion of the work as described on this form and agree to hold harmless CHIMNEY KKRRIKITT'S and any of its officers or agents. I further agree that the balance as stated is correct and I agree to pay any balance owed within 30 days of the date of service. I also agree to pay a \$10.00 billing fee if this work is not paid for at the time the service is rendered. I agree that if I do not pay the balance as specified within 30 days of the date of service I will pay any reasonable costs of collection including but not limited to attorney's fees.

Client Signature: \_\_\_\_\_ Date: \_\_\_\_\_



DESCRIPTION	PRICE
Sweep the pot	\$180.00
+ Add Billing Fee	
NFPA inspection Level 1 or 2 or 3 performed	
No Inspection Performed	
All Accounts Due & Payable Upon Completion of Work 1 1/2% Interest Added Per Month	
<b>Total Cost</b>	<b>\$180.00</b>

**PLEASE PAY SERVICEMAN UPON COMPLETION OF WORK**  
OF \$10.00 BILLING FEE TO APPLY

Copyright 2002

WOOD • GAS • PELLET



**Tom Befor**  
Solid Fuel Specialist

Licensed #21358 • Certified #2833



**1-800-NO-2-SOOT**  
or **800-662-7668**

**CHIMNEY KKRRIKITT'S**

Smokes or Broke? Chimney Sweep and Repair Services



Don't Jeopardize Lives



Headquarters: PO Box 1954 • Big Bear Lake, CA 92315

Billing Instructions: **MARK MEYER**  
**9126 Gerald Ave**  
**Northridge CA 91344**