



**SHERWOOD
INSPECTIONS, INC.**
TERMITE SPECIALISTS

INVOICE / STATEMENT

Sherwood Inspections, Inc.
PO Box 3701
Thousand Oaks CA 91362
(805) 409-7525
office@sherwoodinspections.com

Date: 05/23/2024
Report Number: 11145
Invoice Number: 11145-1
Escrow Number:

Property 141 Allen Ct.
Inspected: Newbury Park, CA 91320

Bill To: Jacky Miviam Schoenfeld-Cohen
141 Allen Ct.
Newbury Park, CA 91320

(929) 676-8146
doroniyam@gmail.com

Contract: \$	2,000.00
Invoice Total: \$	2,000.00
Payments: \$	0.00
Total Due: \$	2,000.00

Discount 200 -
#1800
Paid in Full
5/23/24
ILQ

Venmo @sherwoodinspections Zelle: (805) 338-0364 Credit card: Request a link via email

RETAIN THIS COPY FOR YOUR RECORDS
THANK YOU FOR YOUR BUSINESS!
CUT HERE

CUT HERE

CUT HERE



**SHERWOOD
INSPECTIONS, INC.**
TERMITE SPECIALISTS

INVOICE / STATEMENT

Sherwood Inspections, Inc.
PO Box 3701
Thousand Oaks CA 91362
(805) 409-7525
office@sherwoodinspections.com

Date: 05/23/2024
Report Number: 11145
Invoice Number: 11145-1
Escrow Number:

Property 141 Allen Ct.
Inspected: Newbury Park, CA 91320

Bill To: Jacky Miviam Schoenfeld-Cohen
141 Allen Ct.
Newbury Park, CA 91320

(929) 676-8146
doroniyam@gmail.com

Contract: \$	2,000.00
Invoice Total: \$	2,000.00
Payments: \$	0.00
Total Due: \$	2,000.00

Venmo @sherwoodinspections Zelle: (805) 338-0364 Credit card: Request a link via email

RETURN THIS COPY WITH REMITTANCE
THANK YOU FOR YOUR BUSINESS!

VERY IMPORTANT



VERY IMPORTANT

DON'T THROW AWAY

STRUCTURAL PEST CONTROL BOARD
Control de Pestes Estructurales

NOTICE/AVISO

THIS BUILDING IS SAFE FOR RE-ENTRY ON:
Se puede entrar a este edificio después de:

DATE/FECHA 5-23-24 TIME/HORA 9:00 am

FUMIGANT USED: METHYL BROMIDE ||
Fumigante utilizado: SULFURYL FLUORIDE | VIKANE
(Product Name)

WARNING AGENT:
Odorizante de Noticia de Peligro: **CHLOROPICRIN**

BRANCH 1 LICENSEE NAME/
Nombre de la Licencia de Categoría 1: JUAN PABLO QUEZADA

LICENSE NO./ *Número de Licencia:* FR 37824

COMPANY NAME/
Nombre de la Compañía: BEST CARE FUMIGATION SERVICES, INC.

COMPANY REGISTRATION NO./
Número de Registro de la Compañía: PR9176

COMPANY ADDRESS/
Dirección de la Compañía: 2237 S. STATHAM BLVD. OXNARD, CA.

COMPANY TELEPHONE NO./
Teléfono de la Compañía: 1-805-487-5701

43M-42 (Rev. 5/07)

GAS COMPANY WILL NEED TO SEE THIS TO RESTORE SERVICE

TERMITE

inspector mark...

STANDARD NOTICE OF WORK COMPLETED AND NOT COMPLETED

NOTICE - All recommendations may not have been completed - See below - Recommendations not completed.
This form is prescribed by the Structural Pest Control Board.

Building No. 141	Street Allen Ct.	City Newbury Park	ZIP 91320	Date of Completion 05/23/2024
---------------------	---------------------	----------------------	--------------	----------------------------------



Sherwood Inspections, Inc.
 PO Box 3701
 Thousand Oaks CA 91362
 (805) 409-7525
 office@sherwoodinspections.com

Report # : 11145 - 1
 Registration # : PR 8855
 Escrow # :
 CORRECTED REPORT

Ordered By:	Property Owner and/or Party of Interest: Jacky Miviam Schoenfeld-Cohen 141 Allen Ct. Newbury Park CA 91320 doroniyam@gmail.com	Completion Sent To:
-------------	--	---------------------

The following recommendations on the above designated property, as outlined in Wood Destroying Pests and Organisms Inspection Report dated 05/06/2024 have been and/or have not been completed.

Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and Regulations:
 11A

Recommendations completed by this firm that are considered secondary and substandard measures under Section 1992 of the Structural Pest Control Board's Rules and Regulations including person requesting secondary measure:

Cost of work completed:

Cost:	\$	2,000.00
Inspection Fee:	\$	0.00
Other:	\$	0.00
Total:	\$	2,000.00

Recommendations not completed by this firm:

Estimated Cost: \$ _____

Remarks:
Three year retreatment guarantee on the fumigation

Inspected By: Kevin Marsden State License No. OPR 7402 Signature:

You are entitled to obtain copies of all reports and completion notices on this property reported to the Board during the preceding two years upon payment of a search fee to: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California, 95815.
 NOTE: Questions or problems concerning the above report should be directed to the manager of this company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov. 43M-44 (Rev.10/01)