

WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No. 132	Street Eighth St	City Manhattan Beach	ZIP 90266	Date of Inspection 04/13/2023	Number of Pages 6
---------------------	---------------------	-------------------------	--------------	----------------------------------	----------------------



All City Termite
 10565 Bloomfield St
 Los Alamitos CA 90720
 (310) 796-0822
 allcity@allcitytermite.net

Report # : 10337
 Registration # : PR 2130
 Escrow # :
 CORRECTED REPORT

Ordered by:	Property Owner and/or Party of Interest: Cindy Newman 132 Eighth St Manhattan Beach CA 90266	Report sent to:
-------------	---	-----------------

COMPLETE REPORT LIMITED REPORT SUPPLEMENTAL REPORT REINSPECTION REPORT


GENERAL DESCRIPTION: TWO STORY SINGLE FAMILY HOME, ATTACHED GARAGE	Inspection Tag Posted:
	Other Tags Posted:

An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.

Subterranean Termites Drywood Termites Fungus / Dryrot Other Findings Further Inspection

If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked items.

Diagram Not To Scale



Inspected By: Renato Sanchez State License No. _____ Signature: _____

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California, 95815-3831.

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov. 43M-41 (Rev. 04/2015)

ALL CITY TERMITE

Page 2 of 6 inspection report

132	Eighth St	Manhattan Beach	CA	90266
Address of Property Inspected		City	State	ZIP
04/13/2023	10337			
Date of Inspection	Corresponding Report No.		Escrow No.	

A. Certain areas are recognized by the industry as inaccessible and/or for other reasons not inspected. These included but are not limited to: inaccessible and/or insulated attics or portions thereof, attics with less than 18" clear crawl space, the interior of hollow walls, spaces between floor or porch deck and the ceiling below, areas where there is no access without defacing or tearing out lumber, masonry or finished work; areas behind stoves, refrigerators or beneath floor coverings, furnishings, areas where encumbrances and storage, conditions or locks make inspection impractical, portions of the subarea concealed or made inaccessible by ducting or insulation, area beneath wood floors over concrete, and areas concealed by heavy vegetation. Areas or timbers around eaves, (second story or above) that cannot be reached without the use of extension ladder. They were visually inspected from ground level only. Although we make visual examinations, we do not deface or probe window/door frames or decorative trims. Unless otherwise specified in this report, we do not inspect fences, sheds, dog houses, detached patios, detached wood decks, wood retaining walls or wood walkways. We assume no responsibility for work done by anyone else, for damage to structure or contents during inspection, or for infestation, infection, adverse conditions or damage undetected due to inaccessible or non-disclosure by owner/agent/tenant.

B. Slab floor construction has become more prevalent in recent years. Floor covering may conceal cracks in the slab that will allow infestation to enter. Infestations in the walls may be concealed by plaster so that a diligent inspection may not disclose the true condition. These areas are not practical to inspect because of health hazards, damage to the structure; or inconvenience. They were not inspected unless described in this report. We recommend further inspection if there is any question about the above noted areas. Ref: Structural Pest Control Act, Article 6, Section 8516(b), paragraph 1990(i). Amended effective March 1, 1974. Inspection is limited to disclosure of wood destroying pests or organisms as set forth in the Structural Pest Control Act, Article 6, Section 8516(b), Paragraph 1990-1991.

C. A re-inspection will be performed, if requested within four (4) months from date of original inspection, on any corrective work that we are regularly in the business of performing. If CERTIFICATION is required, then any work performed by others must be CERTIFIED by them. There is a re-inspection fee.

D. This company is not responsible for work completed by others, recommended or not, including by Owner. Contractor bills should be submitted to Escrow as certification of work completed by others.

E. The exterior surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

F. TESTING

F. Second story stall showers are inspected but not water tested unless there is evidence of leaks in ceiling below. Ref: Structural Pest Control Rules and Regulations, Sec. 8516G. Sunken or below grade showers or tubs are not water tested due to their construction.

G. During the course of/or after opening walls or any previously concealed areas, should any further damage or infestation be found, a supplementary report will be issued. Any work completed in these areas would be at Owner's direction and additional expense.

H. During the process of treatment or replacement it may be necessary to drill holes through ceramic tiles or other floor coverings; These holes will then be sealed with concrete. We will exercise due care but assume no responsibility for cracks, chipping or other damage to floor coverings. We do not re-lay carpeting.

I. We assume no responsibility for damage to any Plumbing, Gas or Electrical lines, etc., in the process of pressure treatment of concrete slabs or replacement of concrete or structural timbers.

J. When a fumigation is recommended we will exercise all due care but assume no responsibility for damage to Shrubbery, Trees, plants, TV Antennas or Roofs. A FUMIGATION NOTICE will be left with, or mailed to the Owner of this property, or his designated Agent. Occupant must comply with instructions contained in Fumigation Notice. During fumigation and aeration, the possibility of burglary exists as it does any time you leave your home. Therefore, we recommend that you take any steps that you feel necessary to prevent any damage to your property. We also recommend that you contact your insurance agent and verify that you have insurance coverage to protect against any loss, damage or vandalism to your property. The company does not provide any onsite security except as required by state or local ordinance and does not assume any responsibility for care and custody of the property in case of vandalism, breaking or entering.

K. Your termite report and clearance will cover EXISTING infestation or infection which is outlined in this report. If Owner of property desires coverage of any new infestation it would be advisable to obtain a Control Service Policy which would cover any new infestation for the coming year.

L. If you should have any questions regarding this report, please call or come by our office any weekday between 8:00 a.m. and 5:00 p.m.

M. I agree to pay reasonable attorney's fees if suit is required by this COMPANY to enforce any terms of this contract, together with the costs of such action, whether or not suit proceeds to judgement.

ALL CITY TERMITE

Page 3 of 6 inspection report

132	Eighth St	Manhattan Beach	CA	90266
Address of Property Inspected		City	State	ZIP
04/13/2023	10337			
Date of Inspection	Corresponding Report No.		Escrow No.	

N. The total amount of this contract is due and payable upon completion of work unless otherwise specified. A finance charge computed at a Monthly rate of 1.5% of the unpaid balance (annual percentage rate of 18%) will be added to all accounts past due.

O. If this report is used for escrow purposes then it is agreed that this inspection report and Completion, if any, is part of the ESCROW TRANSACTION. However, if you received written or verbal instructions from any interested parties involved

in this escrow (agents, principals, etc.) to not pay our invoice at close of escrow, you are instructed by us not to use these documents to satisfy any conditions or terms of your escrow for purposes of closing the escrow. Further, you are instructed to return all of our documents and the most current mailing address you have on file for the property owner.

P. Owner/agent/tenant acknowledges and agrees that inspection of the premises will not include any type of inspection for the presence or non-presence of asbestos and that this report will not include any findings or opinions regarding the presence or non-presence of asbestos in, upon or about the premises, we recommend that you contact a contractor specifically licensed to engage in asbestos related work. Further, should we discover the presence of asbestos during our inspection of the premises or should our inspection of the premises cause a release of asbestos dust or particles, owner/agent/tenant shall be solely responsible for the cleanup, removal and disposal of the asbestos and the cost thereof. Owner/agent/tenant hereby agrees to waive any and all claims against this Company which are in any way related to the presence of asbestos on the premises and further agrees to indemnify and hold this company harmless from any and all claims of any nature asserted by any third party, including this Company's employees, which is in any way related to the presence of asbestos on the premises.

Q. There may be health related issues associated with the findings reflected in this report. We are not qualified to and do not render an opinion concerning any such health issues. The inspection reflected by this report was limited to the visible and accessible areas only. Questions concerning health related issues, which may be associated with the findings or recommendations reflected in this report, the presence of mold, the release of mold spores concerning indoor air quality should be directed to a Certified Industrial Hygienist. THIS COMPANY IS NOT RESPONSIBLE FOR MOLD AND OR MILDEW. YOU MUST CONTACT A LICENSED CONTRACTOR IS THAT FIELD FOR EVALUATION.

ALL CITY TERMITE

Page 4 of 6 inspection report

132	Eighth St	Manhattan Beach	CA	90266
Address of Property Inspected		City	State	ZIP
04/13/2023	10337			
Date of Inspection	Corresponding Report No.		Escrow No.	

SECTION I CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

SECTION II ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

FURTHER INSPECTION ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(S) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

10. OTHER - INTERIOR

10A - Section I

Evidence of drywood termite infestation noted.

RECOMMENDATION:

Fumigation with active ingredient Sulfuryl Fluoride and Chloropicrin. This is guaranteed for 100% extermination of drywood termites.

A TWO YEAR LIMITED WARRANTY ON THE FUMIGATION DONE BY THIS COMPANY, GIVEN UPON NOTICE OF COMPLETION.

11. OTHER - EXTERIOR

11A - Section I

Evidence of drywood termite infestation noted.

RECOMMENDATION:

Fumigation with active ingredient Sulfuryl Fluoride and Chloropicrin. This is guaranteed for 100% extermination of drywood termites.

A TWO YEAR LIMITED WARRANTY ON THE FUMIGATION DONE BY THIS COMPANY, GIVEN UPON NOTICE OF COMPLETION.

11B - Section I

DRYWOOD TERMITE AND ROT DAMAGE NOTED TO: BEAMS, RAILS, DECKING, SIDING, TRIM AND JAMBS.

RECOMMENDATION:

Remove and replace with new material as needed, primer *only*.

NOTE: If during the course of our work additional damage is found a supplemental report will be issued and additional costs will be given at that time.

Timbers which are not structurally weakened will be repaired with a wood filler. Painting not included.

ALL CITY TERMITE

Page 5 of 6 inspection report

132	Eighth St	Manhattan Beach	CA	90266
Address of Property Inspected		City	State	ZIP
04/13/2023	10337			
Date of Inspection	Corresponding Report No.		Escrow No.	

PESTICIDES ARE THE PRODUCTS ALL CITY TERMITE CO., INC USES TO CONTROL THE TARGET PEST LISTED IN YOUR INSPECTION. PESTICIDES MAKE A BETTER LIFE FOR ALL OF US. THEY HELP CONTROL DISEASE CARRIERS THUS PROTECTING YOUR HEALTH AND PROPERTY, YOUR ALL CITY TERMITE CO., INC TECHICIAN IS A STATE CERTIFIED APPLICATOR AND IS CONSTANTLY BEING UPGRADED BY OUR TRAINNING SESSIONS. IF YOU HAVE ANY QUESTIONS PLEASE CALL THE FOLLOWING NUMBER 310-796-0822

STATE LAW REQUIRES THAT YOU BE GIVEN THE FOLLOWING INFORMATION CAUTION PESTICIDES ARE TOXIC CHEMICALS. STRUCTURAL PEST CONTROL COMPANIES ARE REGISTERED AND REGULATED BY THE STRUCTURAL PEST CONTROL BOARD, AND APPLY PESTICIDES WHICH ARE REGISTERED AND APPROVED FOR USE BY CALIFORNIA DEPARTMENT OF PESTICIDE REGULATION AND THE UNITED STATES ENVIRONMENTAL PROTECTION AGENCY. REGISTRATION IS GRANTED WHEN THE STATE FINDS THAT BASED ON EXISTING SCIENTIFIC EVIDENCE THERE ARE NOT APPRECIABLE RISKS IF PROPER USE CONDITIONS ARE FOLLOWED OR THAT THE RISKS ARE OUTWEIGHED BY THE BENEFITS. THE DEGREE OF RISK DEPENDS UPON THE DEGREE OF EXPOSURE, SO EXPOSURE SHOULD BE MINIMIZED.

IF WITHIN 24 HOURS FOLLOWING APPLICATION YOU EXPERIENCE SYMPTOMS SIMILAR TO COMMON SEASONAL ILLNESS COMPARABLE TO THE FLU, CONTACT YOUR PHYSICIAN OR POISON CONTROL CENTER (800) 876-4766 AND YOUR ALL CITY TERMITE CO., INC OPERATOR IMMEDIATLY.

FOR FURTHER INFORMATION, CONTACT ANY OF THE FOLLOWING: ALL CITY TERMITE CO., INC.....310-796-0822 POISON CONTROL CENTER.....800-876-4766 FOR HEATH QUESTIONS- The County Health Department

Los Angeles.....800-427-8700/ ORANGE COUNTY 714-834-7700

FOR APPLICATION INFORMATION- The County Agriculture Commissioner

Los Angeles County.....626-575-5466/Orange County 714-447-7100 Riverside

County.....951-955-3000

San Bernadino County.....909-387-2105

San Diego County.....858-694-8980

FOR REGULATORY INFORMATION- The Structural Pest Control Board:

1418 Howe Avenue, Suite 18, Sacramento, CA 95825-3204...800-737-8188

PERSONS WITH RESPIRATORY OR ALLERGIC CONDITIONS, OR OTHERS WHO MAY BE CONCERNED ABOUT THEIR HEALTH RELATIVE TO THIS CHEMICAL TREATMENT, SHOULD CONSIDER ALLOWING ADDITIONAL TIME OUT BEFORE RE-OCCUPANCY ABOVE NORMAL RECOMMENDED TIME OUT OF 2-4 HOURS AND SHOULD CONTACT THEIR PHYSICIAN CONCERNING OCCUPANCY DURING AND AFTER CHEMICAL TREATMENT PRIOR TO SIGNING THIS NOTICE.

TERMITICIDE USED AND THE ACTIVE INGREDIENTS

- DEMON MAX (Cypermethrin 0.50%)
- INVADER HPX (2-(1-methylethoxy) phenyl methylcarbamate)
- DRIONE (Pyrethrins, Piperoyl Butoxide, Technical, Amorphous Silica Gel
- TIM BOR (Disodium octaborate tetrahydrate, 98%)
- TERMIDOR SC (Fipronil:5-amino-1-(2,6-dichloro-4(trifluoromethyl) phenyl)-4-(1R, S,)-(trifluoromethyl)sulfinyl) -1 -H-pyrazole-3-carbonitrile 9.1%) - Dagnet Ft Termiticed. Permethrin 36.8%
- Cy-Kick Cyfluthrin 0.1%
- Phanmen (clorfenapyr: 4-broms-2-(4-clorophenly-1-(exhoxymethy) 5-trifluoromethyl)-1H-pyrrole-3-carbonitrile

ARTICLE 2.5 Pesticides 8538

(a) A registered structural pest control company shall provide the owner, or owner's agent, and tenant of the premises for which the work is to be done with clear written notice which contains the following statements and information using works with common and everyday meaning:

(1) The pest to be controlled.

(2) The pesticide or pesticides proposed to be used, and the active ingredient or ingredients..

(3) "State law requires that you be given the following information:CAUTION--PESTICIDES ARE TOXIC CHEMICALS. Structural Pest Control Companies are registered and regulated by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the state finds that, based on existing scientific evidence, there are no appreciable risks if proper use conditions are followed or that the risks are outweighed by the benefits. The degree of risk depends upon the degree or exposure, so exposure should be minimized.

ALL CITY TERMITE

Page 6 of 6 inspection report

132	Eighth St	Manhattan Beach	CA	90266
Address of Property Inspected		City	State	ZIP
04/13/2023	10337			
Date of Inspection	Corresponding Report No.		Escrow No.	

"If within 24 hours following application you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control centers(THIS STATEMENT SHALL BE MODIFIED TO INCLUDE ANY OTHER SYMPTOMS OF OVER EXPOSURE WHICH ARE NOT TYPICAL OF INFLUENZA.)



All City Termite
 10565 Bloomfield St
 Los Alamitos CA 90720
 (310) 796-0822
 allcity@allcitytermite.net

WORK AUTHORIZATION

Report #: 10337

No work will be performed until a signed copy of this agreement has been received.

Address of Property : 132 Eighth St
 City: Manhattan Beach
 State/ZIP: CA 90266

The inspection report of the company dated, **04/13/2023** is incorporated herein by reference as though fully set forth. The company is authorized to proceed with the work outlined in the items circled below from the Termite Inspection Report for the property inspected, for a total sum of \$ _____. This total amount is due and payable within 30 days from completion repair work and/or chemical application.

C U S T O M E R I N F O R M A T I O N 1)The total amount of this contract is due and payable upon completion of the work listed above unless otherwise specified.Only the work specified in the contract is being done at this time due to owners wishes. ANY WORK PERFORMED AGAINST AN EXISTING TITLE ESCROW WILL BE THE FINANCIAL RESPONSIBILITY OF THE PARTY ORDERING THE INSPECTION REPORT, IN THE EVENT OF A CANCELLED TITLE ESCROW. 2)Work completed (LABOR) by operator shall be guaranteed for a period of one year from completion. Toilet plumbing (parts supplied by this firm), showers, floors or any measures for the control of moisture are guaranteed for (30) days only.Chemical treats are guaranteed for one year. Only the areas treated are guaranteed. 3) Customer agrees to hold company harmless for any damage which may occur to plant life, wiring, trees, vines, pets, tile roofs, plumbing leaks, or changes beyond control of the company which may occur during the performance of this work. In case of non-payment by owner, reasonable attorney's fees and costs of collection shall be paid by the owner, whether suit be filled or not. A SERVICE CHARGE OF 1-1/2 PERCENT, PER MONTH WILL BE CHARGED ON ALL BALANCES OVER (30) DAYS. THE 1-1/2PERCENT, PER MONTH, EQUALS 18 PERCENT PER ANNUM ON THE UNPAID BALANCES. 4) Any additional damage found while work is being performed will be supplemented by a report as to additional findings and costs. Any work completed in these areas would be at the Owner's direction and additional expense. 5) All repairs performed by others must be re-inspected by OUR COMPANY before a CERTIFICATION will be issued. We do not guarantee work completed by others. Any repairs completed by others must be guaranteed in writing and submitted to OURCOMPANY before a CERTIFICATION will be issued. This firm does not make statements concerning workmanship. Workmanship is only determinable by those paying for or receiving those services. 6) If at the time of repairs to decks, the damage is found to be more extensive, a Supplemental report will be given along with a bid for any other corrections that maybe necessary. 7) A re-inspection of specific items on the report or of any other conditions pertaining to this structure can redone at an ADDITIONAL COST PER TRIP. The re-inspection must be done within (4) months of the original inspection. 8) Our inspectors are not equipped with 40 ft. ladders therefore all two story building will not be inspected at the eaves unless requested. 9) MOLD DISCLAIMER: There may be health related issues associated with the structural repairs reflected in the inspection report referenced by this work authorization contract. These health issues include but are not limited to the possible release of mold spores during the course of repairs. We are not qualified to and do not render any opinion concerning such healthiness or any special precautions. Any questions concerning health issues or any special precautions to be taken prior to or during the course of such repairs should be directed to a Certified Industrial Hygienist before any such repairs are undertaken. By executing this work authorization contract, customer acknowledges that he or she has been advised of the forgoing and has had the opportunity to consult with a qualified professional. 10) NOTICE TO PROPERTY OWNERS : (Section 7018 of the California Contractors License Law, Business & Professional Code Div. 3,Chap. 9) Provides under the Mechanic's Lien Law any contractor, subcontractor, laborer, supplier or other person who helps to improve your property but is not paid for his work or supplies has a right to enforce a claim against your property. This means that, after a court hearing, your property could be sold by the court officer and the proceeds of the sale used to satisfy the-indebtedness. This can happen even if you have paid your own contractor in full, if the subcontractor, laborer, or supplier remains-unpaid. ** NOTE ** : Inspection fee is billed separately above any work costs.

ITEMS

Prefix	Section I	Section II	Further Inspection	Other
10A	1,650.00	0.00	0.00	0.00
11A	SEE 10A	0.00	0.00	0.00
11B	5,395.00	0.00	0.00	0.00
Total:	7,045.00	0.00	0.00	0.00
GRAND TOTAL:	7,045.00			

Property Owner: _____ Date: _____ Inspected By: _____ Date: _____
 Owner's Agent: _____ Date: _____