
Pre-Sale Inspection Report

1 message

City of Compton Pre-Sale Inspection Report

1. Obtain necessary permits for repairs or replacements listed.

EXTERIOR:

- Remove trash and debris away from the property.
- Cut tall grass; trim trees; vegetation away from building.
- Weather protection (paint) has deteriorated.
- Repair or replace dry-rot: Exterior window sill/rafter tail
- Repair or replace broken window(s).
- Repair damaged exterior walls.
- Seal and/or weatherproof exposed wood: damaged rafter tail on west side/ interior framing around door ways throughout dwelling
- Repair holes in paved surfaces (unsafe): side walkway trip hazard.
- Obtain necessary approvals and permits for:
 - [x] Addition/alteration: Legalize window replacement(s)/ Legalize or demolish room addition(s): 2 rear south bathroom and room/
 - [] Remodel
 - [x] New structure: storage shed at rear south west of property must be max 120sqft and meet minimum setback distance (3ft from property line/ 6ft from existing structures)
 - [x] Garage conversion: Restore garage back to its original use.
 - [] As-builts
 - [x] Electrical
 - [x] Plumbing
 - [] Mechanical
 - [] Other

ELECTRICAL:

- Main meter service panel and/or sub-panel(s)
- Provide proper bonding of water and gas piping
- Provide minimum clearance in front of panel(s) (30" x 36")
- Label ALL circuit breakers
- Correct unsafe/hazardous wiring: provide breaker slot covers.
- ANY electrical repairs and/or work MUST be done by a California licensed contractor or a qualified electrical journeyman.

WATER HEATER:

- Pressure relief drain line MUST extend outside of the building or to an APPROVED location.

PLUMBING:

- Corrugated p-trap is not permitted for use with kitchen and bathroom sink/lavatories. Must use smooth wall piping.
- Unpermitted drain waste pipe was witnessed above ground/exposed at rear east side of building.

MECHANICAL:

- Corrugated duct is not permitted for use with kitchen range hood. Must use minimum 6in round smooth metal duct that terminates to the exterior of the building.

MISCELLANEOUS:

- Repair or replace interior door(s): door trim/molding missing throughout dwelling.
- Submit construction One (1) sets of drawings for unpermitted work.

Please do not reply to this automated email. All resubmittals should be done using our online portal at www.citizenserve.com/compton re-review. Furnishing the above requested information will help expedite the approval of your application.

