

STANDARD NOTICE OF WORK COMPLETED AND NOT COMPLETED

NOTICE - All recommendations may not have been completed - See below - Recommendations not completed.
This form is prescribed by the Structural Pest Control Board.

Building No.	Street	City	Zip	Date of Completion
32243	Via Cirillo	Temecula	92592-3845	05/01/23
<h2 style="margin: 0;">Black Knight Termite & Pest Control</h2> <p style="margin: 0;">39433 Colleen Way Temecula, CA 92592 Tel 951-694-8100 Fax 951-693-0988 Registration #: PR4946</p>				<p style="font-size: small; margin: 0;">A LICENSED PEST CONTROL OPERATOR IS AN EXPERT IN HIS/HER FIELD. ANY QUESTIONS RELATIVE TO THIS REPORT SHOULD BE REFERRED TO HIM/HER.</p> <p style="margin: 0;">Report #: 18851</p>
Ordered by: Realty One Group April Greer 41463 Margarita Rd #100 Temecula, CA 92591 951-522-0518		Property Owner and Party of Interest: 32243 Via Cirillo Temecula, CA 92592-3845 951-000-0000		Completion sent to: Realty One Group April Greer 41463 Margarita Rd #100 Temecula, CA 92591 951-522-0518

The following recommendations on the above designated property, as outlined in the Wood Destroying Pests and Organisms Inspection Report dated 04/06/23 have been and/or have not been completed.

Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and Regulations: 3A, 3B.								
Recommendations completed by this firm that are considered secondary and substandard measures under Section 1992 of the Structural Pest Control Board's Rules and Regulations including person requesting secondary measure:								
Cost of work completed: <table style="width: 100%; margin-left: 200px; border-collapse: collapse;"> <tr> <td style="text-align: right;">Cost: \$</td> <td style="text-align: right; border-bottom: 1px solid black;">450.00</td> </tr> <tr> <td style="text-align: right;">Inspection Fee: \$</td> <td style="text-align: right; border-bottom: 1px solid black;">125.00</td> </tr> <tr> <td style="text-align: right;">Other: \$</td> <td style="text-align: right; border-bottom: 1px solid black;">0.00</td> </tr> <tr> <td style="text-align: right;">Total: \$</td> <td style="text-align: right; border-bottom: 3px double black;">575.00</td> </tr> </table>	Cost: \$	450.00	Inspection Fee: \$	125.00	Other: \$	0.00	Total: \$	575.00
Cost: \$	450.00							
Inspection Fee: \$	125.00							
Other: \$	0.00							
Total: \$	575.00							
Recommendations not completed by this firm: 4A, 4B. <table style="width: 100%; margin-left: 200px; border-collapse: collapse; margin-top: 20px;"> <tr> <td style="text-align: right;">Estimated Cost: \$</td> <td style="text-align: right; border-bottom: 1px solid black;">0.00</td> </tr> </table>	Estimated Cost: \$	0.00						
Estimated Cost: \$	0.00							
Remarks: NOTE - SECTION ONE CLEARANCE ONLY. THIS IS TO CERTIFY THAT THE PROPERTY DESCRIBED HEREIN IS NOW FREE OF EVIDENCE OF ACTIVE INFESTATION OR INFECTION IN THE VISIBLE AND ACCESSIBLE AREAS.								

Signature _____

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, CA, 95815-3831
 NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov. 43M-41 (REV. 10/01)