



Outdoor replaced with GFCI and
Weatherproof enclosure

Garage outlet replaced with GFCI.
And the polarity issue resolved.



Kitchen and both Bathrooms replaced with GFCI outlets.

