

Repair List based on the Inspection Report dated 7/29/26 for:
5631 Lake Park Way #6, La Mesa, CA 91942

1. 7.7.1 - Carbon monoxide detectors installed.
2. 8.5.3 - Installed threshold where missing between upstairs bathroom and primary walk-in closet.
3. 8.8.1 - Outer stair handrail re-installed. The seller had removed it as a personal preference.