## Improvements made to this house within the

## past two years

1. New roof guaranteed for 50 years

2. New heating and air conditioning with new ducts guaranteed for 10 years

- 3. New vinyl flooring with baseboard installed
- 4. Six new doors with door jams installed throughout the house
- 5. New kitchen cabinets
- 6. Corian cabinet counter tops
- 7. Range hood exhaust fan
- 8. New 18 gauge stainless steel sink (Kolher)
- 9. New kitchen sink faucet
- 10. Kitchen ceramic tile and entrance foyer
- 11. New 1.25 hp. garbage disposal (American Standard)
- 12. New range and dish washer (Whirlpool)
- 13. New electrical sockets through the house
- 14. New lighting in three bedrooms and the hallway
- 15. New linen closet doors
- 16. Removed all "popcorn" from the ceiling and repaired all holes
- 17. New paint on walls and ceiling
- 18. New family room ceiling fan
- 19. New access port to the patio
- 20. New kitchen recessed ceiling lights
- 21. New tub and fixtures in the master bathroom
- 22. New toilet in the master bathroom
- 23. New faucets in the master bathroom sink
- 24. New bathroom medicine cabinet
- 25. new shelving behind the toilet
- 26. new exhaust fan
- 27. 2<sup>nd</sup> bathroom added new medicine cabinet
- 28. New mounts for the toilet
- 29. New caulking around all fixtures and tub
- 30. New exhaust fan

31. All closet doors have been painted

32. All-house fan cleaned and serviced

33. Smoke detector installed in hallway

34. Storage room has been rebuilt and new flooring added with baseboards and shelving

35. New garage door installed with two remote controls

36. All wooden parts of the outside of the house has been painted

- 37. All trees and bushes trimmed to insurance requirements
- 38. Concrete pads have been poured in the front, side, and back yards
- 39. Concrete walkways are from the front yard to the back yard
- 40. New plants and trees planted in the back yard

41. All copper piping throughout the house installed and permitted in 2008

42. Shoji screen rebuilt in the patio as a room separator

- 43. New blinds installed throughout the house except kitchen
- 44. New side entrance door with new door jams
- 45. New evaporative cooler installed in patio
- 46. New winter cover for the evaporative cooler
- 47. Both patio ceiling fans refurbished
- 48. Two remote motion control back yard lights
- 49. New water pressure regulator
- 50. New outside patio light installed
- 51. Outside parameter fence repaired and painted
- 52. RV parking gate repaired and repainted

53.