

# El Dorado Septic Service, Inc.

PO Box 488  
 Soulsbyville, CA 95372  
 Phone (209) 536-1925  
 Fax (209) 536-1910

Contractors License  
 A-856356

# Estimate

DATE	ESTIMATE NO.
10/7/2024	14813
<b>Expiration Date</b>	<b>10/17/2024</b>

Bill To:
Stephanie Bishop 17932 Robin Rd Twain Harte, Ca 95383

Service Address:
Bishop / 17932 Robin Rd. Twain Harte, CA 95383

IT...	NOTES	QTY/HRS	PRICE	TOTAL
S&S	<p>Site &amp; Soil Evaluation to determine how repairs can be made to the septic system:</p> <ol style="list-style-type: none"> <li>Submit a preliminary plot plan to the Tuolumne County Community Resources Agency for the purpose of obtaining a septic system repair permit.</li> <li>El Dorado Septic Service will dig test holes to allow TCCRA inspector to perform a soil profile analysis.</li> </ol> <p>No repairs are done at this service, this is just an evaluation to determine new leach field.                      All repairs will be contingent upon TCCRA findings.</p> <p>An estimate for repairs to follow.</p>	1	1,925.00	1,925.00
Esti...	This is only an estimate of the anticipated cost for performing the work, as described. This cost may be subject to modification as a result of unforeseen circumstances encountered during the course of excavation and installation.			
TCEH	This proposal is subject to the approval and any additional requirements mandated by Tuolumne County Community Resources Agency. If the work is subjected to additional factors, required by TCCRA, EDSSI will submit a bill for costs incurred up to that point, and provide a revised estimate for approval by customer.			
We...	Please note that all work will be contingent on weather conditions. If it is necessary to postpone due to weather, repairs will be completed as soon as circumstances allow. Thank you for your cooperation and understanding.			
Trees	El Dorado Septic Service, Inc. is not responsible for any damage or death to any trees, shrubs, bushes and / or landscape.			
Con...	El Dorado Septic Service, Inc. may / will remove concrete or asphalt and gravel (in driveway's) to perform troubleshooting or repairs. El Dorado Septic Service, Inc. is not and will not replace concrete or asphalt that may be removed or damaged during the troubleshooting or repair.			
Rocks	Should EDSSI encounter large rocks or boulders, or any other unforeseen underground obstruction or complication, job may be subject to additional cost due to the amount and type of work required to remove or work around such items. EDSSI will discuss this with the customer at that time.			

To succeed in life, you need three things: a wishbone, a backbone, and a funny bone.

Sales Tax (7.25%)	\$0.00
-------------------	--------

**This is only an estimate, not a guarantee, of the cost of the work to be completed. As there may be variables or circumstances beyond our present knowledge, this estimate could change.**

<b>TOTAL</b>	<b>\$1,925.00</b>
--------------	-------------------

AUTHORIZATION TO DO WORK \_\_\_\_\_