TOWN OF PARADISE ONSITE WASTEWATER MANAGEMENT ZONE EVALUATION REPORT

| | | Permit Number: | OS18-02906 |
|---------------------|---|-------------------|---|
| | | AP Number: | 051-145-057-000 |
| | | Property Address: | 6332 OAK WAY |
| | | Occupancy Type: | Single Family |
| Primary Contact: | LELAND LEFEBVRE LEFEBVRE LELAND L & GINA M 6332 OAK WAY PARADISE, CA 95969 | Evaluation Date: | 04/18/2018 |
| | | Evaluator: | ERIC HEGENBART HEGENBART SEPTIC TANK CLEANING |

Evaluation Results

| Pump Only No |) |
|--|---------|
| Access Risers in Place Ye | 5 |
| Sanitary Tee - Inlet Ye | 6 |
| Scum Depth, Inlet Compartment | Inches |
| Sludge Depth, Inlet Compartment 18 | Inches |
| Structural Tank Condition Good | l |
| Liquid from Operating Level Norma | |
| Baffle Condition Good | l |
| Tank Volume 1500 | Gallons |
| Volume of Waste Pumped 1500 | Gallons |
| Riser Condition Good | l |
| Sanitary Tee - Outlet Ye | 3 |
| Scum Depth, Outlet Compartment | Inches |
| Sludge Depth, Outlet Compartment 14 | Inches |
| Tank Material Concrete |) |
| Septic Tank Pumping Required Ye | 5 |
| Was Septic Tank Pumped Ye | 5 |
| Depth to Septic Tank Access Lid - Inlet 18 | Inches |
| Depth to Septic Tank Access Lid - Oulet 18 | Inches |
| Effluent Pump Ye | 5 |
| Waste Deposited at Landfill Station Ye | 5 |
| Effluent Line Diverter Valve No |) |
| Well on Property No. |) |
| Common Area/Community Absorption Field No |) |
| Absorption Field Type Standard | l |
| Surfacing Effluent No |) |
| Hydraulic Load Test Ye | 6 |
| Hydraulic Load Test - Results Excellen | t |
| Down Slope Seepage No |) |
| Saturated Absorption Field No. |) |
| Multiple Systems |) |

Evaluator Comments

Pump, floats and alarm working

Location Sketch

