

Received & Read
12/14/2018



DocuSigned by:
[Redacted]
6F8AF0D53C1A4F1...

Domenic's Septic Service, Inc.

P.O. Box 7848 Chico, CA 95927

(530) 345-1585 Phone

(530) 345-5879 Fax

CA Lic# 780811

SEPTIC SYSTEM INSPECTION REPORT

December 6, 2018

Property Address: 827 W. 2nd Ave, Chico

Sent To: [Redacted]

Septic Inspection: X Passed / Failed Total DUE \$675.00 INVOICE #18-0962

1 Tank located: Tank is approximately a 1000 gallon 2-chamber concrete septic tank.

Condition of Septic Tank: Excellent ___ Good X Poor ___

The Inlet Pipe: Is in place and in working order at this time.

The Outlet Pipe: Is in place and in working order at this time.

The Leach Lines: Are in working order at this time.

The Septic System was inspected on 12/05/2018 Tank was pumped at the time of this inspection.

The septic tank should be pumped every 3-5 years to ensure proper working conditions.

Additional notes and/or recommendations:

NOTE:

Domenic's Septic Service, Inc: JS/*Robert Perkins*

I declare that the information herein is true and correct to the best of my knowledge. This report is based on septic tank performance and visible condition performance at the time of inspection. We have located all septic tanks that have been disclosed to us. It is possible that there are additional tanks, in use or abandoned, on said property.

No guarantee is expressed or implied against future problems.