CHICO SEPTIC SERVICE

815 Sheridan Ave. • Chico, CA 95926 • (530) 343-6340 • FAX (530) 899-8769

SEPTIC TANK INSPECTION REPORT

| PROPERTY ADDRESS 337 Stonebridge | DATE 2-22-18 |
|--|--|
| INSPECTION REPORT SENT TO: JOHNESE KAMINSKI FAX | Title Company Escrow Officer Escrow Number |
| SEPTIC INSPECTION PASSED FAILED | TOTAL DUE \$ \$435 02 |
| SEPTIC TANK & LEACH LINES | |
| Tank #1 is gallons Tank #1 is: X A two-chamber concrete tank A two-chamber concrete gides | Sludge Depth: 164 Scum Depth: 164 |
| A two chamber concrete sides and 2x12 redwood lid A two chamber poly tank | Tank Condition: Good Fair |
| The inlet pipe is in place & working broken, needs repair in place & working broken, needs repair broken, needs repair | Poor |
| The leach lines appear to be: in working order at this time /0 0% in marginal working order at this time | Failed |
| The septic system was inspected on $2-22-18$ | |
| It:was pumpedne | |
| Additional Notes and/or Recommendations: | map attached |
| | Front of House |
| Chico Septic Service Cont. Lic. #970202 | |

I declare that the information herein is true and correct to the best of my knowledge. This report is based on septic tank performance and visible condition performance at the time of inspection. We have located all septic tanks that have been disclosed



CHICO SEPTIC

337 Stonebridge Dr. Chico CA

