Docusign Envelope ID: 17D30BA3-4914-4D87-945F-6B18A21BF183

Initial S. W.

Hydrotec Solutions 2 / Dobrich Septic Service, Inc.
PO Box 974
Paradise, CA 95967

Invoice

Date	Invoice #
10/14/2025	17572

Bill To	Ship To
Shari Dixon 121 W. 4TH AVE CHICO, CA 95926	5100 Warnke Ln Paradise, CA 95969 Shari.wbrealty@gmail.com 530-966-5902

S.O. No.	P.O. No.	Terms	Project
14727	10/08/2025		5100 Warnke - Dixo...

Item	Description	Ordered	Prev. Invo...	Invoiced	U/M	Rate	Amount
02 Septic Ev...	Septic Evaluation With Water Wagon	1	0	1		175.00	175.00
00.0	Inspected 1500 gallon concrete tank, the water level was normal. The tank is in good condition. The leach lines were tested and were in good condition at the time of the test.					0.001	0.00
00.2	* This hydraulic test of the effluent line does not constitute a full hydraulic load test of the dispersal field. A full hydraulic load test can only be effectively done with more water and when the system has been in continual use.			1	ea	0.0001	0.00
00 note	This Onsite Wastewater Treatment and Disposal System Evaluation Report is a true and complete record of the septic system on the date of evaluation. No warranty is given or implied regarding the remaining life of the system. I certify that this Onsite Wastewater Treatment and Disposal System Evaluation Report reflects conditions on the parcel(s) during the routine maintenance or inspection of the Onsite Wastewater Treatment and Disposal System.					0.001	0.00

Thank you for your business.

Total	$175.00
Payments/Credits	$0.00
Balance Due	$175.00

Phone #	E-mail
530-873-0199	dobrichsepticinc@gmail.com