Attached are the final work orders from the contractor showing both remodels – the first and principal work was done in 1997; the second phase in early 1998 for redoing the master bathroom and .... The French window doors in master bedroom. Please note on pages 2 and 6 it mentions the French doors.

Regarding your questions:

The first remodel gutted the entire house, leaving only the windows and bathroom doors.

- Kitchen and baths were remodeled
- Laundry was moved to garage
- Raised living room and family room ceilings
- Skylights added
- New electrical system (was added successively can't find the change order)
- New heating ducts with new heating unit
- New water heater
- New drainage gutters and downspouts
- New driveway + garage floor repair
- Added drainage in patios, replaced brickwork
- Replaced kitchen French windows and frames; repaired a few broken glass windows around the house
- All new flooring: New hardwood floors and carpet; new floor tiles in end hallway (Missions) bathroom.

Second remodel: new master bedroom bath remodel + French doors replacement