



# AGENT VISUAL INSPECTION DISCLOSURE

(CALIFORNIA CIVIL CODE § 2079 ET SEQ.)

For use by an agent when a transfer disclosure statement is required or when a seller is exempt from completing a TDS (C.A.R. Form AVID, Revised 12/21)

This inspection disclosure concerns the residential property situated in the City of Temecula, County of Riverside, State of California, described as 44896 Trotsdale Dr ("Property").

This Property is a duplex, triplex, or fourplex. This AVID form is for unit # \_\_\_\_\_. Additional AVID forms required for other units.

Inspection Performed By (Real Estate Broker Firm Name) Shear'Ree Realty Group

California law requires, with limited exceptions, that a real estate broker or salesperson (collectively, "Agent") conduct a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of certain properties offered for sale and then disclose to the prospective purchaser material facts affecting the value or desirability of that property that the inspection reveals. The duty applies regardless of whom that Agent represents. The duty applies to residential real properties containing one-to-four dwelling units, and manufactured homes (mobilehomes). The duty applies to a stand-alone detached dwelling (whether or not located in a subdivision or a planned development) or to an attached dwelling such as a condominium. The duty also applies to a lease with an option to purchase, a ground lease or a real property sales contract of one of those properties.

California law does not require the Agent to inspect the following:

- Areas that are not reasonably and normally accessible
- Areas off site of the property
- Public records or permits
- Common areas of planned developments, condominiums, stock cooperatives and the like.

Agent Inspection Limitations: Because the Agent's duty is limited to conducting a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of only the Property being offered for sale, there are several things that the Agent will not do. What follows is a non-exclusive list of examples of limitations on the scope of the Agent's duty.

**Roof and Attic:** Agent will not climb onto a roof or into an attic.

**Interior:** Agent will not move or look under or behind furniture, pictures, wall hangings or floor coverings. Agent will not look up chimneys or into cabinets, or open locked doors.

**Exterior:** Agent will not inspect beneath a house or other structure on the Property, climb up or down a hillside, move or look behind plants, bushes, shrubbery and other vegetation or fences, walls or other barriers.

**Appliances and Systems:** Agent will not operate appliances or systems (such as, but not limited to, electrical, plumbing, pool or spa, heating, cooling, septic, sprinkler, communication, entertainment, well or water) to determine their functionality.

**Size of Property or Improvements:** Agent will not measure square footage of lot or improvements, or identify or locate boundary lines, easements or encroachments.

**Environmental Hazards:** Agent will not determine if the Property has mold, asbestos, lead or lead-based paint, radon, formaldehyde or any other hazardous substance or analyze soil or geologic condition.

**Off-Property Conditions:** By statute, Agent is not obligated to pull permits or inspect public records. Agent will not guarantee views or zoning, identify proposed construction or development or changes or proximity to transportation, schools, or law enforcement.

**Analysis of Agent Disclosures:** For any items disclosed as a result of Agent's visual inspection, or by others, Agent will not provide an analysis of or determine the cause or source of the disclosed matter, nor determine the cost of any possible repair.

**What this means to you:** An Agent's inspection is not intended to take the place of any other type of inspection, nor is it a substitute for a full and complete disclosure by a seller. Regardless of what the Agent's inspection reveals, or what disclosures are made by sellers, California Law specifies that a buyer has a duty to exercise reasonable care to protect himself or herself. This duty encompasses facts which are known to or within the diligent attention and observation of the buyer. Therefore, in order to determine for themselves whether or not the Property meets their needs and intended uses, as well as the cost to remedy any disclosed or discovered defect, **BUYER SHOULD: (1) REVIEW ANY DISCLOSURES OBTAINED FROM SELLER; (2) OBTAIN ADVICE ABOUT, AND INSPECTIONS OF, THE PROPERTY FROM OTHER APPROPRIATE PROFESSIONALS; AND (3) REVIEW ANY FINDINGS OF THOSE PROFESSIONALS WITH THE PERSONS WHO PREPARED THEM. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF BROKER.**



If this Property is a duplex, triplex, or fourplex, this AVID is for unit # \_\_\_\_\_.  
Inspection Performed By (Real Estate Broker Firm Name) Shear'Ree Realty Group  
Inspection Date/Time: 08/18/2022 11:30 am Weather conditions: Warm, sunny, some clouds  
Other persons present: none

**THE UNDERSIGNED, BASED ON A REASONABLY COMPETENT AND DILIGENT VISUAL INSPECTION OF THE REASONABLY AND NORMALLY ACCESSIBLE AREAS OF THE PROPERTY, STATES THE FOLLOWING:**

Entry (excluding common areas): Wood rot on porch railing; marks on front door; paint discoloration at entry light; marks on cement porch; (Inside)-marks on baseboards, floors & walls, signs of prior drywall patch.

Living Room: Marks on walls, baseboards, flooring & ceiling; hole in drywall near fireplace; TV bracket above fireplace;

Dining Room: Marks on walls, baseboards, & flooring; damage to flooring; signs of prior drywall patch.

Kitchen: Marks on walls, baseboards, flooring & ceiling; significant damage to range-top; damage to cabinets; ceiling lite panel damaged; damage to trim @ French doors.

Other Room: \_\_\_\_\_

Hall/Stairs (excluding common areas): Smoke detector @ hall(1st & 2nd floor); damage to handrail; marks on walls & baseboards; A/C filter is dirty. Damage to carpet at hall bath.

Bedroom # 1: (Master)-Marks on walls & baseboards; carpet needs stretching; TV bracket on wall; multiple "screw" holes on drywall.

Bedroom # 2: (South)-Marks on walls, baseboards, flooring; damage to drywall; carpet needs stretching;

Bedroom # 3: (North)-Marks on walls, baseboards, flooring; damage to drywall; carpet needs stretching; damage to closet doors; stain on carpet.

Bath # 1 : 1/2 bath-marks on floor, baseboards & walls; towel rack missing bar; grout voids at vanity;

Bath # 2 : (Master)-Marks on walls, baseboards, flooring & ceiling; damage at faucet in tub; toilet paper roll missing part; damage to baseboard & floor.

Bath # 3 : (Guest)-Marks on door, walls, baseboards, flooring; toilet paper roll missing; signs of spiders at ceiling above tub; damage to mirror; grout voids at vanity; vanity hardware damaged.

Other Room: \_\_\_\_\_



If this Property is a duplex, triplex, or fourplex, this AVID is for unit # \_\_\_\_\_ .

Other:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Other:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Other:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

See Addendum for additional rooms/structures: \_\_\_\_\_

Garage/Parking (excluding common areas): *Cracked cement & marks, weeds growing in cement cracks, excessive personal property prevents inspection;*

Exterior Building and Yard - Front/Sides/Back: *Front & rear yard have significant dead landscaping & dead palm fronds, & weeds; Garage door, garage seal, and garage trim damaged; Spider webs on stucco exterior; rear patio has cement cracks; pet waste in rear yard; gate hardware missing part.*

Other Observed or Known Conditions Not Specified Above: *Pets odor in home; sign of cockroaches; rear fence in dirt & paint is worn; pool is empty;*

**This disclosure is based on a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of the Property on the date specified above.**

Real Estate Broker (Firm who performed the Inspection) Shear'Ree Realty Group  
By Rebecca Shear'Ree Date \_\_\_\_\_  
(Signature of Associate Licensee or Broker who performed the inspection)

**Reminder: Not all defects are observable by a real estate licensee conducting an inspection. The inspection does not include testing of any system or component. Real Estate Licensees are not home inspectors or contractors. BUYER SHOULD OBTAIN ADVICE ABOUT AND INSPECTIONS OF THE PROPERTY FROM OTHER APPROPRIATE PROFESSIONALS. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF BROKER.**

I/we acknowledge that I/we have read, understand and received a copy of this disclosure.

Buyer \_\_\_\_\_ Date \_\_\_\_\_  
Buyer \_\_\_\_\_ Date \_\_\_\_\_

**I/we acknowledge that I/we have received a copy of this disclosure.**  
(The initials below are not required but can be used as evidence that the initialing party has received the completed form.)

Seller **X** \_\_\_\_\_ / \_\_\_\_\_

Real Estate Broker (Firm Representing Seller) Shear'Ree Realty Group  
By Rebecca Shear'Ree Date \_\_\_\_\_  
(Associate Licensee or Broker Signature)

Real Estate Broker (Firm Representing Buyer) \_\_\_\_\_  
By \_\_\_\_\_ Date \_\_\_\_\_  
(Associate Licensee or Broker Signature)

© 2021, California Association of REALTORS®, Inc. United States copyright law (Title 17 U.S. Code) forbids the unauthorized distribution, display and reproduction of this form, or any portion thereof, by photocopy machine or any other means, including facsimile or computerized formats. THIS FORM HAS BEEN APPROVED BY THE CALIFORNIA ASSOCIATION OF REALTORS®. NO REPRESENTATION IS MADE AS TO THE LEGAL VALIDITY OR ACCURACY OF ANY PROVISION IN ANY SPECIFIC TRANSACTION. A REAL ESTATE BROKER IS THE PERSON QUALIFIED TO ADVISE ON REAL ESTATE TRANSACTIONS. IF YOU DESIRE LEGAL OR TAX ADVICE, CONSULT AN APPROPRIATE PROFESSIONAL. This form is made available to real estate professionals through an agreement with or purchase from the California Association of REALTORS®. It is not intended to identify the user as a REALTOR®. REALTOR® is a registered collective membership mark which may be used only by members of the NATIONAL ASSOCIATION OF REALTORS® who subscribe to its Code of Ethics.

Published and Distributed by:  
REAL ESTATE BUSINESS SERVICES, LLC.  
a subsidiary of the CALIFORNIA ASSOCIATION OF REALTORS®  
525 South Virgil Avenue, Los Angeles, California 90020

**AVID REVISED 12/21 (PAGE 3 OF 3)**

