Payless
Septic Service

SEPTIC SYSTEM INSPECTION REPORT

Date: 08-26-26 Service Person: _____ Invoice #: 17487

Job Address: 10572 Mooney Flat Rd Smartsville

Inspection Requested By: Carson - Martin

Escrow Company: _____ Escrow #: _____

Inspection Fee: 500.00 Tank Pumping Fee: 0 Repairs: 0

System Inspection: ✓ Passed _____ Failed

TANK CONSTRUCTION

_____ Redwood Top ✓ All Cement _____ Steel _____ Fiberglass

Tank baffle intact: ✓ Yes _____ No

Tank inlet elbow intact: ✓ Yes _____ No

Tank outlet elbow intact: ✓ Yes _____ No

Approximate tank size: 1200 Gallons Tank was cleaned: ___ Yes ✓ No

Tank should be cleaned in approximately 3 years

House was ✓ Vacant _____ Occupied

LEACH LINE EVALUATION

✓ Functioning at time of inspection _____ Failed

I declare that the information herein is true and correct to the best of my knowledge and belief. Report is based on performance at the time of inspection. No guarantee is expressed or implied against future problems.

Signature: Sal @ Payless Septic Date: 08-26-26

Scanned with CamScanner

Business Lic. # 33881 Comments & Sketch on back of this report